


Territory Development Department
New Territories North Development Office

Agreement No CE43/96
Main Drainage Channels and
Poldered Village Protection Scheme
for San Tin, NWNT : *Environmental
Impact Assessment Study*

Final Assessment Report

7 April 1999

Reference C1618

For and on behalf of Environmental Resources Management
Approved by: <u>FREEMAN CHEUNG</u>
Signed: <u></u>
Position: <u>Deputy Managing Director</u>
Date: <u>7 April 1999</u>

This report has been prepared by Environmental Resources Management, with all reasonable skill, care and diligence within the terms of the Contract with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client.

We disclaim any responsibility to the client and other in respect of any matters outside the scope of the above.

This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

CONTENTS:

1	INTRODUCTION	1-1
1.1	<i>PREAMBLE</i>	1-1
1.2	<i>OBJECTIVES OF THE EIA STUDY</i>	1-2
1.3	<i>STUDY AREA</i>	1-2
1.4	<i>STRUCTURE OF THE FINAL ASSESSMENT REPORT</i>	1-2
2	EASTERN MDC AND LANDUSE CONTEXT	2-1
2.1	<i>CHANNEL ALIGNMENT</i>	2-1
2.2	<i>PRELIMINARY CHANNEL DESIGN</i>	2-1
2.3	<i>CONSTRUCTION</i>	2-2
2.4	<i>OPERATION</i>	2-2
2.5	<i>LAND USE CONTEXT</i>	2-2
3	ECOLOGY	3-1
3.1	<i>INTRODUCTION</i>	3-1
3.2	<i>ENVIRONMENTAL LEGISLATION AND GUIDELINES</i>	3-1
3.3	<i>STUDY METHODOLOGY</i>	3-4
3.4	<i>BASELINE CONDITIONS</i>	3-8
3.5	<i>EVALUATION OF ECOLOGICAL BASELINE CONDITIONS</i>	3-20
3.6	<i>EASTERN CHANNEL AND POLDERED VILLAGE PROTECTION SCHEME</i>	3-24
3.7	<i>CONCLUSIONS</i>	3-42
4	WATER QUALITY	4-1
4.1	<i>INTRODUCTION</i>	4-1
4.2	<i>ENVIRONMENTAL LEGISLATION AND NONSTATUTORY GUIDELINES</i>	4-1
4.3	<i>BASELINE CONDITIONS AND SENSITIVE RECEIVERS</i>	4-2
4.4	<i>CONSTRUCTION PHASE</i>	4-3
4.5	<i>OPERATION PHASE</i>	4-14
4.6	<i>CONCLUSION</i>	4-17
5	SOLID WASTE MANAGEMENT	5-1
5.1	<i>INTRODUCTION</i>	5-1
5.2	<i>ENVIRONMENTAL LEGISLATION AND NON-STATUTORY GUIDELINES</i>	5-1
5.3	<i>ASSESSMENT METHODOLOGY</i>	5-3
5.4	<i>CONSTRUCTION PHASE</i>	5-3
5.5	<i>OPERATIONAL PHASE</i>	5-15
5.6	<i>REQUIREMENT FOR FURTHER STUDY</i>	5-16
5.7	<i>CONCLUSION</i>	5-17
6	LAND CONTAMINATION	6-1
6.1	<i>INTRODUCTION</i>	6-1
6.2	<i>ENVIRONMENTAL LEGISLATION AND NON-STATUTORY GUIDELINES</i>	6-1
6.3	<i>BASELINE CONDITIONS AND SENSITIVE RECEIVERS</i>	6-2
6.4	<i>CONSTRUCTION PHASE</i>	6-7
6.5	<i>OPERATIONAL PHASE</i>	6-9
6.6	<i>REQUIREMENT FOR FURTHER STUDY</i>	6-9
6.7	<i>CONCLUSION</i>	6-11

7	NOISE	7-1
7.1	INTRODUCTION	7-1
7.2	ENVIRONMENTAL LEGISLATION AND NON-STATUTORY GUIDELINES	7-1
7.3	BASELINE CONDITIONS AND SENSITIVE RECEIVERS	7-2
7.4	CONSTRUCTION PHASE	7-3
7.5	OPERATIONAL PHASE	7-5
7.6	CONCLUSION	7-6
8	AIR QUALITY	8-1
8.1	INTRODUCTION	8-1
8.2	ENVIRONMENTAL LEGISLATION AND STATUTORY REQUIREMENTS	8-1
8.3	BASELINE CONDITIONS AND SENSITIVE RECEIVERS	8-2
8.4	CONSTRUCTION PHASE	8-3
8.5	OPERATIONAL PHASE	8-6
8.6	CONCLUSION	8-6
9	VISUAL AND LANDSCAPE IMPACT ASSESSMENT	9-1
9.1	INTRODUCTION	9-1
9.2	LEGISLATION AND GUIDELINES	9-1
9.3	METHODOLOGY	9-1
9.4	STUDY PARAMETERS AND SCOPE	9-2
9.5	EXISTING LANDSCAPE BASELINE CONDITIONS	9-4
9.6	LANDSCAPE IMPACT	9-5
9.7	EXISTING VISUAL BASELINE CONDITIONS	9-7
9.8	VISUAL IMPACT	9-7
9.9	VISUAL AND LANDSCAPE MITIGATION	9-9
9.10	RESIDUAL AND CUMULATIVE IMPACT	9-9
9.11	SUMMARY	9-9
10	SOCIO-ECONOMIC ISSUES	10-1
10.1	INTRODUCTION	10-1
10.2	BACKGROUND INFORMATION	10-1
10.3	SOCIO-ECONOMIC IMPLICATIONS	10-1
11	ENVIRONMENTAL MONITORING AND AUDIT	11-1
11.1	INTRODUCTION	11-1
11.2	ECOLOGICAL RESOURCES	11-1
11.3	WATER QUALITY	11-2
11.4	NOISE	11-2
11.5	AIR QUALITY	11-2
11.6	WASTE	11-2
12	OVERALL CONCLUSION & IMPLEMENTATION SCHEDULE	12-1

LIST OF ANNEX

ANNEX 1-A	STUDY BRIEF
ANNEX 1-B	WORKING PAPER FOR 35CD WORKS
ANNEX 1-C	WESTERN MDC
ANNEX 3-A	CHANNEL CORRIDOR SURVEY RECORD SHEETS
ANNEX 3-B, C & D	SUMMARY OF RESULTS OF QUANTITATIVE SURVEY OF FLORA AT EASTERN MDC, SAN TIN, 1997-8 AND PLANT SPECIES AND RELATIVE ABUNDANCE RECORD
ANNEX 3-E	BIRD SPECIES RECORDED IN LOK MA CHAU (HONG KONG BIRD REPORT 1990-1995), SAN TIN NULLAHS IN LATE MARCH 1996 (HYDER 1997) AND BIRD SURVEYS WITHIN EASTERN AND WESTERN MDC STUDY AREA APRIL 1997-MARCH 1998, WETLAND DEPENDENT BIRD SPECIES RECORDED ON THE EASTERN CHANNEL STUDY AREA DURING FIELD STUDIES, 1997-1998, WETLAND DEPENDENT BIRD SPECIES RECORDED WITHIN EASTERN AND WESTERN MDC STUDY AREAS, APRIL 1997-MARCH 1998 AND BREEDING BIRD SPECIES WITHIN EASTERN AND WESTERN MDC STUDY AREAS, APRIL 1997-MARCH 1998
ANNEX 3-F	ARDEID USE OF SAN TIN STUDY AREA
ANNEX 3-G, H & I	INVERTEBRATE SPECIES RECORDED AT EACH SECTION ON THE ALIGNMENT OF THE EASTERN MDC
ANNEX 3-J	DETAILS OF CONSTRUCTED WETLAND AT EASTERN MDC
ANNEX 3-K	REFERENCES CITED (CHAPTER 3 AND ASSOCIATED ANNEXES)
ANNEX 6-A	CONTAMINATION ASSESSMENT PLAN
ANNEX 7-A	CONSTRUCTION NOISE CALCULATIONS
ANNEX 7-B	OPERATIONAL NOISE CALCULATIONS

LIST OF FIGURE

- FIGURE 1.1A** LOCATION OF SAN TIN MAIN DRAINAGE CHANNELS AND POLDERED VILLAGE PROTECTION SCHEME WORKS
- FIGURE 2.2A** PRELIMINARY LAYOUT OF EASTERN MDC
FIGURE 2.2B1-4 LAYOUT DETAILS
FIGURE 2.5A SAN TIN OUTLINE ZONING PLAN (No. S/YL-ST/1, 1994)
- FIGURE 3.3A** HABITAT MAP OF EASTERN CHANNEL AREA, SHOWING CHANNEL CORRIDOR SURVEY SECTIONS AND SITES FOR QUANTITATIVE SURVEY
FIGURE 3.3B SURVEY AREAS FOR CHANNEL CORRIDOR SURVEY, HABITAT SURVEY AND BIRD SURVEY
FIGURE 3.6A WATERFOWL IN PONDS ALONG SHENZHEN RIVER 1995 - 1998 (HKBWS)
FIGURE 3.6B 3 KM AND 4 KM FEEDING RADII FROM MAI PO VILLAGE EGRETRY, AND 8 KM FORAGING RADIUS OF BLACK-FACED SPOONBILLS FROM ROOST SITE AT MAI PO MARSHES
FIGURE 3.6C LOCATIONS OF SAN TIN POLDER FLOOD STORAGE POND AND TSING LUNG TSUEN DRAINAGE CHANNEL
FIGURE 3.6D PLAN AND CROSS-SECTION OF TSING LUNG TSUEN DRAINAGE CHANNEL
FIGURE 3.6E LOCATIONS OF MITIGATION SITES IN AND AROUND THE EASTERN CHANNEL
- FIGURE 4.3A** WATER QUALITY SENSITIVE RECEIVERS AND LOCATIONS OF SHENZHEN RIVER WATER QUALITY MONITORING STATIONS
- FIGURE 5.4A** SAMPLING LOCATION FOR SEDIMENT CORE ANALYSIS
- FIGURE 6.3A** LOCATIONS OF TRUCK AND TRAILER STORAGE AREAS
FIGURE 6.3B SAMPLING AND INVESTIGATION LOCATIONS
- FIGURE 7.3A** LOCATION OF REPRESENTATIVE NSRS
- FIGURE 8.3A** LOCATION OF REPRESENTATIVE OF ASRS
FIGURE 8.4A ISOPLETHS OF HOURLY TSP LEVEL
FIGURE 8.4B ISOPLETHS OF HOURLY TSP LEVEL
FIGURE 8.4C ISOPLETHS OF HOURLY TSP LEVEL
- FIGURE 9.3A** VISUAL ENVELOPE OF PROPOSED DEVELOPMENT
FIGURE 9.5A LANDSCAPE IMPACT ASSESSMENT OF EASTERN MAIN DRAINAGE CHANNEL (I)
FIGURE 9.5B LANDSCAPE IMPACT ASSESSMENT OF EASTERN MAIN DRAINAGE CHANNEL (II)
FIGURE 9.5C LANDSCAPE CHARACTER PHOTOGRAPHS
FIGURE 9.5D LANDSCAPE CHARACTER PHOTOGRAPHS
FIGURE 9.7A EXISTING VISUAL QUALITY OF EASTERN MAIN DRAINAGE CHANNEL AREA
FIGURE 9.8A VISUAL IMPACT ASSESSMENT OF EASTERN MAIN DRAINAGE CHANNEL
FIGURE 9.9A GENERAL MITIGATION PROPOSAL
FIGURE 9.9B PHOTOMONTAGE

LIST OF TABLE

TABLE 3.4A	CONSERVATION SIGNIFICANCE OF BIRD SPECIES RECORDED IN THE SAN TIN AREA
TABLE 3.4B	ECOLOGICAL RESOURCES OF IMPORTANCE ON THE EASTERN CHANNEL STUDY
TABLE 3.5A	ASSESSMENT OF ECOLOGICAL VALUE OF HABITATS FOUND IN THE EASTERN CHANNEL AREA
TABLE 3.6A	PERMANENT HABITAT LOSSES DUE TO THE EASTERN CHANNEL AND POLDERED VILLAGE PROTECTION SCHEMES (PVPS) FOR CHAU TAU AND SAN TIN
TABLE 3.6B	POTENTIAL CONSTRUCTION PHASE IMPACTS TO ECOLOGICAL RESOURCES ON THE EASTERN CHANNEL AND PVPS-35CD STUDY AREA
TABLE 3.6C	PROJECTS PROPOSED FOR THE SAN TIN AREA, AND ASSOCIATED WETLAND LOSS
TABLE 3.6D	SCHEDULING OF PROJECTS PROPOSED FOR THE SAN TIN AREA
TABLE 3.6E	POTENTIAL OPERATIONAL PHASE IMPACTS TO ECOLOGICAL RESOURCES ON THE EASTERN CHANNEL STUDY AREA
TABLE 3.6F	COMPARISON OF HABITATS LOST AND HABITATS CREATED/ENHANCED UNDER THE PROJECT
TABLE 4.3A	WATER QUALITY OF THE SHENZHEN RIVER (AT HIGH AND LOW WATER LEVELS) IN DRY SEASON OF 1994
TABLE 4.4A	SHENZHEN RIVER REGULATION PROJECT SEDIMENT ANALYSIS (MG KG ⁻¹)
TABLE 4.4B	SHEN ZHEN RIVER EIA ELUTRIATE TEST RESULTS (MG L ⁻¹)
TABLE 4.4C	KAM TIN RIVER SEDIMENT HEAVY METAL ANALYSIS RESULTS (MG KG ⁻¹ DRY WEIGHT)
TABLE 4.4D	KAM TIN RIVER ELUTRIATE ANALYSIS RESULTS (MG L ⁻¹)
TABLE 5.2A	CLASSIFICATION OF SEDIMENTS BY METAL CONTENT (MG KG ⁻¹ DRY WEIGHT)
TABLE 5.4A	HEAVY METAL CONTENT OF THE SEDIMENT FROM SAN TIN EASTERN MAIN DRAINAGE CHANNELS
TABLE 5.4B	WATER AND ORGANIC CONTENTS OF SEDIMENT FROM SAN TIN EASTERN MAIN DRAINAGE CHANNELS
TABLE 6.3A	POTENTIAL CONTAMINATED LOCATIONS
TABLE 6.3B	POTENTIAL CONTAMINANTS ASSOCIATED WITH LAND USES
TABLE 6.3C	GENERAL PROPERTIES OF HAZARDOUS SUBSTANCES POTENTIALLY FOUND IN STORAGE YARDS
TABLE 7.3A	IDENTIFIED NSRs AND THEIR AREA SENSITIVITY RATING
TABLE 8.2A	HONG KONG AIR QUALITY OBJECTIVES (UG M ⁻³)
TABLE 8.3A	AIR QUALITY OF YUEN LONG FOR 1996 (UG M ⁻³)
TABLE 8.3B	IDENTIFIED ASRs AND SEPARATIONS TO THE CHANNEL
TABLE 8.4A	EMISSION FACTORS
TABLE 9.6A	SUMMARY OF EXPECTED LANDSCAPE IMPACT
TABLE 9.8B	SUMMARY OF EXPECTED VISUAL IMPACT
TABLE 12.1A	IMPLEMENTATION SCHEDULE