



Industrial Activities and Possible Contaminants Identified during the On-Site Survey

Reference No. in Figure1-1	Company Name	Description	Possible Contaminants
1	Bonanza Saw-Mill Ltd.	Saw-mill, wood storage	Less significant
2	Universal Dockyard Ltd.	Shipyards	Petroleum hydrocarbon, heavy metals
3	Yau Wing Co. Ltd.	Ship repair workshop, in-house DG store	Petroleum hydrocarbon, heavy metals
4	Redland Cement Ltd.	Cement manufacturing	Less significant
5	Hong Kong Dredging Ltd.	Office, workshop	Petroleum hydrocarbon, heavy metals
6	Man Wah Ltd.	Bricks and cement packaging	Less significant
7	Kwok Wing Ltd.	Vacant	Insufficient information
8	Hop Fat Metals Tin Wai Warehouse	Vacant	Insufficient information
9	Wing Tai Cheong Saw-Mill	Saw-mill, wood storage	Less significant
10	EI Freight (HK) Ltd.	Cargo storage	Less significant
11	Bonanza Saw-Mill Ltd.	Saw-mill, wood storage	Less significant
12-1	Kei Yip Car Repair	Car repair workshop	Petroleum hydrocarbon, heavy metals
12-2	Kwok Luen	Tyre supplier	Less significant
13	Sing Tai Saw-Mill	Saw-mill, wood storage	Less significant
14	N.A.	Vacant	Insufficient information
15	Rainbow Transportation and Warehouse Ltd.	Warehouse, no DG storage	Less significant
16	Wai Sing Car Repair	Car repair workshop	Petroleum hydrocarbon, heavy metals
17	Wing Wui Co. Ltd.	Cement and bricks manufacturing (ship repair in the past)	Petroleum hydrocarbon, heavy metals
18	Brigantine Services Ltd.	Machine repair workshop	Petroleum hydrocarbon, heavy metals
19	Sam Woo Ship Building Ltd. Sam Woo Engineering Equipment Ltd.	Machine workshop	Petroleum hydrocarbon, heavy metals
20	N.A.	Vacant, abandoned land, signs of uncontrolled waste dumping	Insufficient information
21	Goltens Hong Kong Ltd.	Ship repair workshop	Petroleum hydrocarbon, heavy metals
22	Kwong Hing Cement	Cement manufacturing	Less significant
23	Agincourt Industrial Building	Multi-storey industrial building	Insufficient information



Scale: NTS	Project: Contamination Assessment Plan for Yau Tong Bay	 EHS CONSULTANTS LIMITED
Figure:		
Title: Location of Activities Identified at the Subject Site During Preliminary Assessment		