



(a) Lotus Bridge viewed from southeast, showing arched sections over navigation channel, 35m pier spacing, mangrove plantation on mudflat (foreground), and inundated mudflat (behind mangrove).



(b) Lotus Bridge seen from below, showing pairs of piers, pile caps above mud surface, and slope-covered mudflat.



(c) Mudflat beneath Lotus Bridge showing Grey Herons and Chinese Pond Heron foraging near navigation channel.



(d) View of poor quality mudflat restoration beneath Lotus Bridge, showing construction debris (wheel barrow, trolley, pipe), uneven mud surface, and pile caps above mud surface.

		Designed By <b>ECO</b>	 <b>路政署</b> <b>HIGHWAYS DEPARTMENT</b> 主要工程管理處 Major Works Project Management Office	Consultant <b>ARUP</b> 奧雅納工程顧問 Ove Arup & Partners Hong Kong Limited	Project Title <b>Shenzhen Western Corridor Investigation &amp; Planning</b>	Drawing Title <b>Lotus Bridge in Macau SAR showing mudflats and mangrove plantations</b>	Client Filename	Client Date	
		Drawn By <b>YML</b>		Supported By: Environmental Management Ltd. BMT Asia Pacific Ltd. Urbis Ltd.			Scale N/A		
		Checked By <b>TDD</b>					Drawing No. <b>Figure 9.13</b>		
		In Charge <b>TDD</b>					Drawing Status	Rev. <b>0</b>	
		Date <b>15 Apr 02</b>							
Mark	Date	By	Rev.						