


**View 2: Tung Chung Battery**Existing Conditions



View 2: Tung Chung Battery
With landscape mitigation measures at completion
(view similar after 10 years operation)



Project: Tung Chung Cable Car Project Environmental Impact Assessment Title:

Photomontage (Sheet 2 of 7)

Scale: N.T.S.

File name:

Figure no: 8.24

N:\203842\Eia Report\Figures\Figure8\_24(sht. 2 of 7).ppt