

View 3: San Tau Pier / Beach Existing Conditions



View 3: San Tau Pier / Beach
With landscape mitigation measures at completion
(view similar after 10 years operation)



Tung Chung Cable Car Project
Environmental Impact Assessment

Title:

Photomontage (Sheet 3 of 7)

Scale: N.T.S.

Figure no:

8.24

File name:

N:\203842\Eia Report\Figures\Figure8_24(sht. 3 of 7).ppt