

View 4: Lantau Peak (Lantau Trail)
Existing Conditions



View 4: Lantau Peak (Lantau Trail)
With landscape mitigation measures at completion
(view similar after 10 years operation)



Project: Tung Chung Cable Car Project Environmental Impact Assessment Title:

Photomontage (Sheet 4 of 7)

Scale: N.T.S.

Figure no: 8.24

File name:

N:\203842\Eia Report\Figures\Figure8_24(sht. 4 of 7).ppt