Appendix D2

Aerial Photographs Interpretation

Investigation, Design and Construction

Final Report – Issue 3 382486/16/Issue 3

APPENDIX D2 AERIAL PHOTOGRAPHS INTERPRETATION (API)

Table D2-1
General Site History interpreted from Aerial Photographs taken in1963 to 2002

Date	Aerial Photograph Reference No.	Site History (Interpretation from Historical and Aerial Photographs)
MUP area	a a	
1963	Y10132-3 (3900')	 Channel alignments originally of cultivated land. North-south trending existing channel evident with vegetation along edges
1986	A05507-8 (4000')	No changes observed.
1992	A36407-8 (4000')	 Road to the west of site area formed. No changes in areas MUP01, MUP02 and MUP05. Evidence of buildings constructed on locations of MUP03B, MUP04A and MUP04B.
1996	A43639-40 (3500')	No changes to 1992 photos.
2000	A51071-2 (3000') CN2941-43 (2000')	No changes to site.
2001	CW34004-6 (4000')	 No changes to site.
2002	CW41568-9 (3000')	 No changes to site.
LMH01		
1982	46719 (4000')	 Channel alignment originally of grassland with heavily vegetated hillside to the west
1986	A05592 (4000')	No changes to site.
1990	A24114-5 (4000')	 No changes to site.
1999	A49221 (3500')	 No changes to site.