



Figure 7.6 - MUP05 - Existing semi-natural channel



Figure 7.7 - MUP04A - Existing disturbed channel on lower section of stream




Figure 7.8 - MUP03 - Existing ditch



Figure 7.9 - MUP05 - Channelised downstream section



Figure 7.10 - MUP05 - Existing stream showing well-vegetated north bank