Existing View



(LMH 01) VSR 5


Visually Sensitive Receivers - VSR	Description of Visually Sensitive Receivers	Number of Individuals (Many/ Fair/ Few/ Very Few)	Quality of Existing View (Good / Fair / Poor)	Minimum Distance between VSRs & Impact Source	Degree of Visibility (Full /Partial /Glimpse)	Frequency of View (Very Frequent / Frequent / Occasional / Rare)	Sensitivity to Change (High/Medium /Low)
VSR 5	Residents near river bank @ Lin Ma Hang (Individual Village houses/ Rural Fringe area)	Fair	Good	< 10m	Full	Very Frequent	High

^{*}Refer to Figure No. 8.48: Location of Visual Sensitive Receivers & Zone of Visual Influence Plan



(view towards the river bank)

Existing View



(LMH 01) VSR 6

Visually Sensitive Receivers - VSR	Description of Visually Sensitive Receivers	Number of Individuals (Many/ Fair/ Few/ Very Few)	Quality of Existing View (Good / Fair / Poor)	Minimum Distance between VSRs & Impact Source	Degree of Visibility (Full /Partial /Glimpse)	Frequency of View (Very Frequent / Frequent / Occasional / Rare)	Sensitivity to Change (High/Medium /Low)
VSR 6	Residents near ancestral shrine @ Lin Ma Hang (Individual Village houses/ Rural Fringe area)	Fair	Good	Approx. 20m	Partial	Very Frequent	High

*Refer to Figure No. 8.4B : Location of Visual Sensitive Receivers & Zone of Visual Influence Plan

Title:

Agreement No.CE 6 / 2002 (DS)
Drainage Improvement in Northern New Territories Package C Investigation, Design and Construction

LMH 01 -Visually Sensitive Receivers - VSR 05 & 06

Date: Sept.2006

Scale: Not to scale

Figure No. 8.4B-iii

