

VP4 - Existing View from Walking Trail on Knoll at East of the Site



VP4 - View from Walking Trail on Knoll at East of the Site on day 1 operation (without mitigation)

| Revision | Date | Des cri ption | | Initial |
|----------|----------|----------------------|-------|---------|
| | Designed | Checked | Drawn | Checked |
| Initial | | | | |
| Date | | | | |

Agreement No

CE 21/2012 (WS)

Contract title

DESALINATION PLANT AT TSEUNG KWAN O -FEASIBILITY STUDY

Drawi**ng t**

PHOTOMONTAGES FROM VP4 (ON KNOLL OF WALKING TRAIL AT EAST OF THE SITE) (SHEET 1 OF 2)

Drawing no.

FIGURE 11.19a

KE 11.19a

ale





Revision