



Oil stains observed on the paved ground of the Generator Room.



Diesel oil drums stored in the Generator Room without secondary containment



Oil spills next to the generators.



Generators inside the Generator Room.

Revision	Date	Description	Initial
	Designed	Checked	Drawn
Initial			
Date			

Agreement No.  
CE 21/2012 (WS)

Contract title  
DESALINATION PLANT AT  
TSEUNG KWAN O -  
FEASIBILITY STUDY

Drawing title  
SELECTED SITE PHOTOGRAPHS

Drawing no. FIGURE 8A.3d	Revision
-----------------------------	----------

Scale

