

本署檔號
Our Ref: ()EP660/H1/27
來函檔號
Your Ref:
電話
Tel. No.: 2117 7528
圖文傳真
Fax No.: 2756 8588
電子郵件
E-Mail:
網址
Homepage: <http://www.epd.gov.hk/>

Environmental Protection Department
Environmental Compliance Division
Regional Office (East)
5th Floor, Nan Fung Commercial Centre,
19 Lam Lok Street, Kowloon Bay,
Kowloon, Hong Kong.



環境保護署
環保法規管理科
區域辦事處(東)
香港九龍九龍灣臨樂街
十九號南豐商業中心五樓

AECOM
8/F., Grand Central Plaza, Tower 2,
138 Shatin Rural Committee Road,
Shatin .

29 April 2015

Dear Ms. Naomi Yu,

Subject: Agreement No. CE 10/2014 (CE) Development of Anderson Road Quarry Site
Investigation, Design and Construction
Request for Information fo Chemical Waste Producer and Chemical Spillage Accident

Please be informed that there were two records of registered chemical waste producers in the subject site.

1. DRILTECH GROUND ENGINEERING LIMITED 鑽達地質工程有限公司
Registered on 05/06/2000
Waste type: Spent Lubricating Oil
2. Excel Engineering Company Limited 怡益工程有限公司
Registered on 0706/2012
Waste type: Spent dry cell containing heavy metals, Spent Mineral Oil, Spent Lubricating Oil and asbestos waste
2. All these two registrations were terminated and no record of waste produced.
3. Regarding chemical spillage incident at the subject locations, we do not have any past record.

Yours faithfully,

(Owen W.S. Ng)


Chief Environmental Protection Inspector
for Director of Environmental Protection

Sheets 5, 7 and 8's boundary lies between SI32 and SI35

Active CWP – one (WPN:5213291E230810) is found at concerned areas

Polluter Name EXCEL ENGINEERING COMPANY LIMITED (EP/RE/0000345648) **Primary Responsible Party**
Location PORTION B OF THE SITE AT NEW CLEAR WATER BAY ROAD(WSD CONTRACT: 10/WSD/11)

Polluter Summary		EIE Valid Licence				
Polluter Summary		1 to 1 of 1 records				
Case in Progress						
Completed Case						
Valid Licence						
Invalid Licence						
License	License No	Licensee	Status	Issue Date	Expiry Date	
CWP Licence	5213291E230810	Excel Engineering Company Limited	4 - Issue date is entered	07/06/2012		



Trip Ticket Summary by CWP

Report ID: RT5D008

Date: 28/04/2015 13:41:31
Page 1 of 1

WPN: 5213291E230810

Waste Producer Name: Excel Engineering Company Limited

Producer Date: 01/01/2000 - 28/04/2015

Waste Code: ALL

Major Chemical Wastes of Waste Producer: SPENT BATTERY CELL CONTAINING HEAVY METALS, Spent Mineral Oil, Spent

Lubricating Oil AND ASBESTOS WASTE

Trip Ticket No.	Item No.	Waste Collector Licence No.	Waste Disposal Site Licence	Producer Date	Waste Code	Waste Name	Take Qty	Qty Coll'd (kg / L)	Qty Deliv'd (Kg / L)
1							0	0	0.0
Total (Kg / L)							0	0	0.0

No Inactive WP is found at concerned areas.

Closed CWP– one (WPN:5113291D230602) is found at concerned areas.

Polluter Name	DRILTECH GROUND ENGINEERING LIMITED (EP/RE/0000040602)	Primary Responsible Party	DRILTECH GROUND ENGINEERING LIMITED				
Location	Site Office At Anderson Road, KIn						
Polluter Summary	EIE Invalid Licence						
Polluter Summary	Search Criteria						
Case In Progress	Show Criteria =>						
Completed Case	Search Result						
Valid Licence							
Invalid Licence	1 to 1 of 1 records						
Abatement Notice							
Inspection	Licence	Licence No	Licensee	Status	Issue Date	Expiry Date	Terminate Da
Complaint	CWP Licence	5113291D230602	DRILTECH GROUND ENGINEERING LIMITED	5 - License terminated by EPD	05/06/2000		04/01/2012
Related Special Project							
Polluter Information							



Trip Ticket Summary by CWP

Report ID: RT5D008

WPN: 5113291D230602

Date: 28/04/2015 13:43:33
Page 1 of 1

Waste Producer Name: DRILTECH GROUND ENGINEERING LIMITED

Producer Date: 01/01/2000 - 28/04/2015

Waste Code: ALL

Major Chemical Wastes of Waste Producer: SPENT LUBRICATING OIL

Trip Ticket No.	Item No.	Waste Collector Licence No.	Waste Disposal Site Licence	Producer Date	Waste Code	Waste Name	Take Qty	Qty Coll'd (kg / L)	Qty Deliv'd (Kg / L)
	1						0	0	0.0
Total (Kg / L)							0	0	0.0


*** End of Report ***

No Inactive WP is found for above area.

Sheets 1, 2,3, and 4's boundary lies SI34. No active CWP is found at concerned areas



No inactive CWP is found at concerned areas



No closed CWP is found at concerned areas



消防處

香港九龍尖沙咀東部康莊道1號
消防總部大廈



FIRE SERVICES DEPARTMENT
FIRE SERVICES HEADQUARTERS
BUILDING,
No.1 Hong Chong Road,
Tsim Sha Tsui East, Kowloon,
Hong Kong.

本處檔號 OUR REF. : (53) in FSD GR 6-5/4 R Pt. 9
來函檔號 YOUR REF. : 60328348/NYHN1504131
電子郵件 E-mail : hkfsdenq@hkfsd.gov.hk
圖文傳真 FAX NO. : 2739 5879
電話 TEL NO. : 2733 7741

7 May 2015

AECOM Asia Co. Ltd.
8/F Grand Central Plaza, Tower 2,
138 Shatin Rural Committee Road,
Shatin, Hong Kong.
(Attn: Ms. Naomi YU, Environmental Consultant)

Dear Ms. YU,

**Development of Anderson Road Quarry Site
- Investigation, Design and Construction
Request for Information of Dangerous Goods & Incident Records**

I refer to your letter of 14.4.2015 regarding the captioned request.

Please be advised that neither records of dangerous goods license nor incidents of spillage / leakage of dangerous goods were found in connection with the given conditions of your request at the subject location.

If you have further questions, please feel free to contact the undersigned.

Yours sincerely,

(WONG Ronald)
for Director of Fire Services