



## **Appendix 7-2**

### **Historic Aerial Photos**

**Appendix 7-2-1 - Past Aerial Photos Records**



Past Aerial Photo of Project Site in Year 2014




Past Aerial Photo of Project Site in Year 2009



Past Aerial Photo of Project Site in Year 1999

## Appendix 7-2-2 Site Photos Taken On-site



Location Map of Photos



Photo A1 – View of existing open air car park at the southern portion of Project Site (there was no car repairing facility)



Photo A2 – Existing open air car park is fenced off.



Photo B – View of vacant land and open car park from northern portion of Project Site (no hot spot was identified)



Photo C – View of vacant land at northern portion of Project Site (no hot spot was identified)



Photo D – View of Existing Abandoned Water Pond