



Underground Tunnel Alignment

Location of Plant reinstatement
(Cut Slope 750m²)

Tai Long Wan east landfall area

Temporary access

Figure 3 The location of planting reinstatement in Lai Long Wan Tunnel Portal



**Environmental
Permit No.:
EP-126/2002**