



Reprovisioning of Diamond Hill Crematorium
重置鑽石山火葬場
Environmental Permit number EP-179/2004
環境許可証 EP-179/2004

Note :
Extracted from
Figure 6.2 of the
Approved EIA report
(AEIAR-076/2004)

Figure 6 : S1 to S6 - Subsurface Soil sampling locations for
confirmatory contamination analysis
圖六 S1 至 S6 - 地下土採樣位置 (以供進行污泥驗證分析)

Scale : NTS