

Legend (圖例):

Site / 工地

Tree-Health (Proposed treatment) 樹木 - 健康狀況 (處理建議)





- Dead (remove)
枯死 (移除)
- Very poor health / damaged (remove)
健康非常差 / 損毀 (移除)
- Good health (remove)
健康良好 (移除)
- Good / fair / poor health (retain)
健康良好 / 一般 / 差 (保留)

Landscape Resources 景觀資源

- LR1 - Transport Route
LR1 - 交通路線
- LR2 - Commercial/Residential/Institutional Building Area
LR2 - 商業/住宅/機構樓宇區
- LR3 - Building within Declared Monument
LR3 - 位於法定古蹟範圍內的建築物
- LR4 - Open Space within Declared Monument
LR4 - 位於法定古蹟範圍內的露天空地
- LR5 - Public Park / Recreational Area
LR5 - 公園/文娛區

Tree ID Species Name
樹木編號 物種名稱

T1	Bombax ceiba 木棉
T2	Ficus virens 大葉榕
T3	Nageia nagi 竹柏
T4	Celtis sinensis 朴樹
T5	Mangifera indica 芒果
T6	Aleurites moluccana 石栗
T7	Aleurites moluccana 石栗
T8	Plumeria rubra 紅雞蛋花
T9	Araucaria cunninghamii 花旗杉
T10	Ficus microcarpa 細葉榕
T10A	Ficus microcarpa 細葉榕
T11	Dracaena marginata 馬尾鐵



Project Title: Central Police Station Conservation and Revitalisation Project
工程項目名稱：中區警署保育及活化計劃

Environmental Permit No. : EP-408/2011/C
環境許可證編號 : EP-408/2011/C

Figure 3: Trees within the Project Site Included Proposed Treatment and Photo Record of Tree

圖 3: 位於工地內的樹木包括樹木的建議處理方法及照片記錄

(This figure was prepared based on Figure 1.1 of the report submitted under VEP Application (Register No.: VEP-350/2011))

(本圖是根據更改環境許可證申請文件(申請書編號：VEP-350/2011)所提交的報告圖 1.1 編制)