Issue No.: Issue 1 Issue Date: January 2021

Project No.: 1616



EcoPark Operation

Quarterly Environmental Monitoring & Audit Report (October - December 2020)

27/F, Overseas Trust Bank Building 160 Gloucester Road Wan Chai Hong Kong

> T: +852 2815 7028 F: +852 2815 5399

> > www.asecg.com

Prepared By:

Allied Environmental Consultants Limited

COMMERCIAL-IN-CONFIDENCE

香港灣仔告士打道 160 號海外信託銀行大廈 27 樓

Issue No.:

Issue 1

Issue Date:

January 2021

Project No.:

1616



27/F, Overseas Trust Bank Building 160 Gloucester Road Wan Chai Hong Kong T: +852 2815 7028

www.asecg.com

F: +852 2815 5399

EcoPark Operation

Quarterly Environmental Monitoring & Audit Report (October - December 2020)

Prepared By:

Allied Environmental Consultants Limited

COMMERCIAL-IN-CONFIDENCE

Certified by:

Grace M. H. KWOK
Environmental Team Leader

Verified by:

Sam P. S. TSOI

Independent Environmental Checker

Approved:

Gary C. W. TAM

Principal Environmental Protection Officer Environmental Protection Department

This report has been prepared by Allied Environmental Consultants Limited with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client.

We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above.

This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk

Issue No.: Issue 1
Issue Date: January 2021
Project No.: 1616



EcoPark Operation

Quarterly Environmental Monitoring & Audit Report (October - December 2020) 27/F, Overseas Trust Bank Building 160 Gloucester Road Wan Chai Hong Kong

> T: +852 2815 7028 F: +852 2815 5399

> > www.asecg.com

Prepared By:

Allied Environmental Consultants Limited

COMMERCIAL-IN-CONFIDENCE

Author: Various

Checked:

Joanne W. Y. NG BSc(Hons) MSc MHKIEIA AHKIOA Approved:

Grace M. H. KWOK
BEng(Hons) MHKIEIA MHKIOA MIAIA
MRAPA MISWA BEAM Pro LEED Fellow
BREEAM AP FFHKIQEP CAP HKGBC

This report has been prepared by Allied Environmental Consultants Limited with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client.

We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above.

This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

TABLE OF CONTENTS

LIST (OF FIGURES	iii
LIST (OF TABLES	iii
LIST (OF APPENDICES	iii
EXEC	UTIVE SUMMARY	4
1 Pl	ROJECT BACKGROUND	7
1.1	Project Overview	7
1.2	Operation Programme	7
1.3	Project Organisation and Contact Personnel	8
2 SI	UMMARY OF EM&A REQUIREMENT	11
2.1	Monitoring Parameters	11
2.2	Environmental Quality Performance Limits and EAP	11
2.3	Environmental Audit of Non-Monitored Parameters	12
2.4	Environmental Mitigation Measures	12
2.5	Environmental Requirements in Tenancy Agreements	12
3 O	PERATION STATUS	14
3.1	General	14
3.2	Champway Technology Limited	14
3.3	Hong Kong Biomass (Wood) Collect and Recycle Company Limited	14
3.4	HP Telford Envirotech Group Limited	14
3.5	Chung Yue Steel Group Company Limited	15
3.6	K. Wah Construction Products Ltd.	15
3.7	WEEE.PARK	15
3.8	On Fat Lung Innovative Resources Ltd.	15
3.9	Food Waste Management Group (FWMG) of EPD	16
3.10	E. Tech Management (HK) Limited	16
3.11	Throughput Statistics	16
3.12	Process Review	17
4 IN	MPLEMENTATION STATUS OF ENVIRONMENTAL PROTECTION MEASURES	19
5 M	ONITORING RESULTS	20
5.1	Monitoring Date, Time, Frequency and Duration	20
5.2	Monitoring Methodology, Parameters and Equipment	20
5.3	Results and Graphical Plots of Monitoring Parameters	21
6 SI	UMMARY OF ENVIRONMENTAL AUDIT	22

_AEC

Pro	iect	No.	1616

	k Operation rly Environmental Monitoring & Audit Report (October - December 2020)	ii
6.1	General	22
6.2	Champway Technology Limited	22
6.3	Hong Kong Biomass (Wood) Collect and Recycle Company Limited	23
6.4	HP Telford Envirotech Group Limited	24
6.5	Chung Yue Steel Group Company Limited	24
6.6	K.Wah Construction Products Limited	25
6.7	E. Tech Management (HK) Limited.	25
6.8	WEEE.PARK	26
6.9	On Fat Lung Innovative Resources Limited	26
6.10	Lot T7 (FWMG of EPD)	26
6.11	General Condition of EcoPark	27
	IVIRONMENTAL COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL	
PROSE	CCUTION	29
7.1	New Environmental Complaint, Notification of Summon and Successful Prosecution in the Report 29	rting Period
8 CC	ONCLUSIONS	30

8 CONCLUSIONS

LIST OF FIGURES

Figure 1-1	Location of EcoPark in Tuen Mun Area 38
Figure 1-2	Organisation Chart of UPML
Figure 1-3	Organisation Chart of EM&A Works (Operation)
Figure 2-1	LFG Monitoring Locations within EcoPark
Figure 3-1	Current Lot Usage within EcoPark

LIST OF TABLES

Table 1.1	EM&A Personnel Contact Details
Table 2.1	Operation Phase LFG Monitoring Locations in EcoPark
Table 2.2	Action Levels, Limit Levels and Event and Action Plan for LFG
Table 3.1	Throughput Statistics for the Reporting Quarter
Table 5.1	Sampling Schedule for the Quarterly LFG Monitoring
Table 5.2	Parameters and Measurement Ranges for LFG Monitoring
Table 5.3	Quarterly LFG Monitoring Results in the Reporting Quarter
Table 6.1	Environmental Audit Findings for Champway
Table 6.2	Environmental Audit Findings for HK Biomass
Table 6.3	Environmental Audit Findings for HP Telford
Table 6.4	Environmental Audit Findings for Chung Yue
Table 6.5	Environmental Audit Findings for K.Wah
Table 6.6	Environmental Audit Findings for E. Tech
Table 6.7	Environmental Audit Findings for WEEE.PARK
Table 6.8	Environmental Audit Findings for On Fat Lung
Table 6.9	Environmental Audit Findings for Lot T7
Table 6.10	General EcoPark Audit Findings
Table 8.1	Throughput Statistics for the Reporting Quarter

LIST OF APPENDICES

Appendix 1	Environmental Mitigation Measures (from the Implementation Schedule)
Appendix 2	Environmental Requirements in Tenancy Agreements
Appendix 3	Material and Waste Throughputs
Appendix 3.1	Material and Waste Throughputs of the Reporting Quarter
Appendix 3.2	Updates of Previously-Reported Material and Waste Throughputs
Appendix 4	Calibration Certificate of Infrared Gas Analyser
Appendix 5	Laboratory Test Report and Graphical Plots of LFG Monitoring
Appendix 6	Tenant-Specific Audit Checklists for the Reporting Quarter
Appendix 6.1	Champway Technology Ltd
Appendix 6.2	Hong Kong Biomass (Wood) Collect and Recycle Company Ltd
Appendix 6.3	HP Telford Envirotech Group Ltd
Appendix 6.4	Chung Yue Steel Group Co Ltd
Appendix 6.5	K.Wah Construction Products Ltd
Appendix 6.6	E. Tech Management (HK) Ltd
Appendix 6.7	WEEE.PARK
Appendix 6.8	On Fat Lung Innovative Resources Limited
Appendix 6.9	Lot T7 (FWMG of EPD)
Appendix 6.10	General EcoPark Checklist

EXECUTIVE SUMMARY

General

EcoPark is a key element in the Government's waste management policy that aims at promoting the local recycling industry by providing long-term land at affordable rents, thereby encouraging investment in advanced technology and value-added recycling processes. EcoPark is being developed in two phases at site in Tuen Mun Area 38 as shown in *Figure 1-1*. The contract for the management of EcoPark – Contract No. *EP/SP/102/17 Provision of Management Services for EcoPark 2018* was awarded to Urban Property Management Limited (UPML) by Environmental Protection Department (EPD) effective from 30th October 2018.

UPML, the "Operator" of EcoPark, have appointed Allied Environmental Consultants Ltd. (AEC) as the Environmental Team (ET) to carry out the Environmental Monitoring and Audit (EM&A) works for the operation of EcoPark as required by the EM&A Manual and in accordance with the conditions of the Environmental Permit (EP) (EP-226/2005/F).

This is the fifty-fifth (55th) quarterly EM&A report prepared for the operation phase of EcoPark and covers the quarter from October to December 2020. In the reporting quarter, there were twelve tenants in EcoPark Phase 1 and Phase 2, one operator of Lot T7 in EcoPark Phase 1 and one operator of WEEE.PARK in EcoPark Phase 2. The details are provided as below:

Phase 1 tenants and operator comprise:

- Champway Technology Ltd. (Champway) Waste cooking oil
- 3R Hong Kong International Eco-Pioneer Ltd. (3R) Waste plastics
- Hong Kong Biomass (Wood) Collect and Recycle Co. Ltd. (HK Biomass) Waste wood
- Baguio Waste Management & Recycling Ltd. (Baguio) Waste plastics
- HP Telford Envirotech Group Ltd. (HP Telford) Waste plastics
- Food Waste Management Group (FWMG) of EPD Waste wood

Phase 2 tenants and operator comprise:

- K.Wah Construction Products Ltd. (K.Wah) Waste construction materials/waste glass
- E. Tech Management (HK) Ltd. (E. Tech) WEEE
- On Fat Lung Innovative Resources Ltd. (On Fat Lung) Waste rubber tyres
- Chung Yue Steel Group Company Ltd. (Chung Yue) Waste metals
- Hong Kong Battery Recycling Centre Ltd. (HKBRC) Waste lead-acid batteries
- South China Reborn Resources (Zhongshan) Co. Ltd. (South China) Food waste
- WEEE.PARK operated by Alba Integrated Waste Solutions (Hong Kong) Ltd. (Alba IWS) –
 WEEE
- Rocsky International Ltd. (Rocsky) Waste Paper

Recycling activities of WEEE.PARK in Lots P2-P4, FWMG of EPD in Lot T7 and the following seven active tenants were audited in the reporting quarter: Champway, HK Biomass, HP Telford, K. Wah, E. Tech, On Fat Lung, and Chung Yue. The lots possessed by HKBRC (i.e. Lots P9 & P10), South China (i.e. Lot P12), 3R (i.e. Lots T2 & T3), Baguio (i.e. Lot T6), and Rocsky (i.e. Lots P1, P5, P6 and P7) were inspected but not audited under the EM&A programme during the reporting quarter, as no recycling activities were conducted.

In this reporting quarter, site inspections were conducted by the Operator and the ET on 20th October, 25th November, and 17th December 2020. IEC also carried out random site audits on 20th October and 17th December 2020. A quarterly joint site inspection was carried out by the Operator, the IEC and the ET on 25th November 2020.

Throughput of Materials / Waste Generated

The throughputs of WEEE.PARK and the seven active tenants in the reporting quarter are summarised below. Please note that product output plus waste disposal does not necessarily equal the waste input, due to material losses during processing and material retained within the lots.

Material Type	Waste Input (tonne)	Product Output (4) (tonne)	Waste Disposed (4) (tonne)	
Waste Organic Food	2,234	986	592	
Waste Ferrous Metals	20,430	21,740	148	
Waste Wood	369	341	-	
Waste Electronics	4,216	3,439	487	
Waste Plastics	349	311	-	
Construction Waste	2,193	14 400	0	
Waste Glass	607	14,499	8	
Waste Rubber Tyres n/a		n/a	-	

Notes:

- 1) The throughput data presented above is the best available data and has been rounded off to the nearest whole tonne for presentation.
- 2) The total product output may not be the same as the waste input due to processing of materials that were received before the reporting quarter and were stored within the lots.
- 3) Waste disposal refers to the disposal of general refuse (i.e. packaging) and/or chemical waste.
- 4) Since the recycling of waste glass and construction waste is combined to produce concrete block at K.Wah, the product output and waste disposal from both processes are combined.
- 5) "-" in the column of waste disposal denotes zero quantity; while "n/a" denotes unavailable information at the time of report preparation.

Exceedances of Any Measured Action / Limit Levels

The northern part of EcoPark is located within the 250m Landfill Gas (LFG) Consultation Zone of Shiu Lang Shui Landfill. LFG monitoring during this quarter was undertaken on 25th November 2020 at five locations (three in Phase 1 and two in Phase 2). No exceedance of Action or Limit Level was recorded in the reporting quarter.

Summary of Complaints, Summons and Prosecutions

Number of complaints, summons and successful prosecutions in the reporting quarter are summarised below.

• Complaints: Zero.

- **Summons:** Zero.
- Successful Prosecutions: Zero

Reporting Changes

There is no change in the reporting quarter.

Future Key Issues

As per site inspection on 17th December 2020, all of the operation equipment, recycling materials, wastewater treatment tanks and other facilities of FWMG had been moved out from the Lot T7. It is anticipated that FWMG will be no longer active for recycling activities since December 2020. Lot T7, operating by Ming Hing, would be used for Christmas tree and festive plants recycling between 8th and 11th January 2021 and February 2021. Recycling activity in Lot T7 is anticipated to be resumed in the next inspection period.

1 PROJECT BACKGROUND

1.1 Project Overview

- 1.1.1 In the document "A Policy Framework for the Management of Municipal Solid Waste (2005 –2014)", the government set out a comprehensive policy to support the recycling industry. This included allocating suitable land, encouraging research and development, introducing environmental legislation and providing effective support measures. In May 2013, the Environment Bureau launched "Hong Kong Blueprint for Sustainable Use of Resources 2013 2022", which promised continuing support for the recycling industry.
- 1.1.2 EcoPark was developed to support the local recycling industry by providing long-term land at affordable rents, thereby encouraging investment in advanced technology and value-added recycling processes.
- 1.1.3 EcoPark, as shown in *Figure 1-1*, has been developed in Tuen Mun Area 38 in two phases (Phase1 and Phase 2) under Contract *EP/SP/52/06 Development of EcoPark in Tuen Mun Area 38*, which was awarded to Kaden Construction Ltd by the Environmental Protection Department (EPD) in June 2006. Phase 1 construction was completed in July 2009 and Phase 2 construction was completed in November 2010.
- 1.1.4 The contract for the management of EcoPark Contract No. *EP/SP/102/17 Provision of Management Services for EcoPark 2018* was awarded to Urban Property Management Limited (UPML) by Environmental Protection Department (EPD) effective from 30th October 2018.
- 1.1.5 UPML, the "Operator" of EcoPark, has appointed Allied Environmental Consultants Ltd. (AEC) as the Environmental Team (ET) to carry out the Environmental Monitoring and Audit (EM&A) works for the operation of EcoPark as required by the EM&A Manual and in accordance with the conditions of the Environmental Permit (EP-226/2005/F). Ove Arup & Partners Hong Kong Ltd. (Arup) has been appointed by the EPD as the Independent Environmental Checker (IEC) for the Project. The ET and the IEC carry out the EM&A works for EcoPark as required by the EM&A Manual and in accordance with the conditions of the Environmental Permit (EP).

1.2 Operation Programme

- 1.2.1 In the reporting period, there were twelve tenants in EcoPark, one operator of Lot T7 and one operator of WEEE.PARK:
 - Alba Integrated Waste Solutions (Hong Kong) Ltd. (Alba IWS) for WEEE.PARK, Food Waste Management Group (FWMG) of EPD for Lot T7, and other seven active tenants (Champway, HK Biomass, HP Telford, Chung Yue, K.Wah, E. Tech, and On Fat Lung) who have carried out full recycling operations;
 - One tenant (HKBRC) was without any site operation;
 - One tenant (Baguio) is carrying out building works but without any site operation;
 - One tenant (3R) is undergoing reinstatement work process; and

• Two tenants (Roscky and South China) are under termination.

1.3 Project Organisation and Contact Personnel

1.3.1 Key personnel and contact particulars are summarised in *Table 1.1*.

Table 1.1 EM&A Personnel Contact Details

Position Name		Email Address	Phone No.			
Project Proponent -	Project Proponent – EPD					
Principal EPO Mr. Gary C. W. Tam		garytam@epd.gov.hk	3690 7860			
Operator – UPML						
Project Manager	Ms. Raindy YIP	raindy.py.yip@urban.com.hk	2212 5900			
Park Manager Ms. May WU		may.sm.wu@urban.com.hk	2212 5920			
IEC – Ove Arup						
IEC	Mr. Sam TSOI	sam.tsoi@arup.com	2268 3208			
ET-AEC						
ET Leader	Ms. Grace KWOK	gk@aechk.com	2815 7028			

1.3.2 The organisational structure and lines of communication for the operation of EcoPark with respect to environmental management is given in *Figure 1-2* and *Figure 1-3* respectively.

Figure 1-1 Location of EcoPark in Tuen Mun Area 38



Site Boundary Phase 1 Tenants Phase 2 Tenants

Figure 1-2 Organisation Chart of UPML





Figure 1-3 Organisation Chart of EM&A Works (Operation)



2 SUMMARY OF EM&A REQUIREMENT

2.1 Monitoring Parameters

- 2.1.1 Landfill Gas (LFG) is required to be monitored quarterly at service voids and utility boxes within EcoPark because the northern part of EcoPark lies within the 250m LFG Consultation Zone for Siu Lang Shui Landfill, which is located to the north of EcoPark.
- 2.1.2 Operational LFG monitoring has been carried out in Phase 1 after completion of construction in July 2009, commencing in the August to October 2009 quarter. In Phase 2, monitoring has been carried out after completion of construction in November 2010, commencing in the November 2010 to January 2011 quarter.
- 2.1.3 The location for LFG monitoring was not specified in the EM&A Manual since the final design of EcoPark was not available when the EM&A Manual was approved. Therefore, during a joint site inspection on 27th July 2009, three monitoring locations were identified and agreed as suitable monitoring locations by the former ET (SMEC Asia Ltd.), IEC (Atkins China Ltd.) and the Operator (Serco Guardian Joint Venture). Subsequently, two more monitoring locations in Phase 2 were proposed by the former ET and agreed by the IEC and Operator via email in January 2011. These five monitoring locations are listed in *Table 2.1* and shown in *Figure 2-1*.

Table 2.1 Operation Phase LFG Monitoring Locations in EcoPark

Monitoring Station ID	Туре	Locations
EP1-1	LFG vent pipe	Inside the landscaping area of Administration Building
EP1-2	Service void	PCCW below-ground chamber outside Lot T1
EP1-3	Service void	HGC Broadband below-ground chamber outside Lot T3
EP2-1	Service void	HGC Broadband below-ground chamber outside Lot P1
EP2-2	Service void	HGC Broadband below-ground chamber outside Lot P3

2.1.4 Routine LFG monitoring has been carried out on a quarterly basis. Should EPD alert the Operator that high LFG levels have been detected during monthly monitoring under the Siu Lang Shui Landfill restoration contract, the Operator may be required to increase LFG monitoring to monthly until such time as EPD inform the Operator that quarterly monitoring can be resumed. No detection of high LFG levels under Siu Lang Shui Landfill restoration contract was received from EPD in the reporting quarter.

2.2 Environmental Quality Performance Limits and EAP

2.2.1 The Action/Limit Levels and Event Action Plan (EAP) for LFG are shown in *Table 2.2* below. These refer to LFG detected in excavations, utilities and any enclosed on-site areas. No other A/L Levels or EAPs are specified in the EM&A Manual for the operation phase EM&A.

Level Parameter Action Action Level <19% O₂ Ventilate trench/void to restore O₂ to >19% Oxygen • Stop works (O_2) Limit Level <18% O₂ Evacuate personnel/prohibit entry Increase ventilation to restore O_2 to >19% Post "No Smoking" signs Action Level >10% LEL Prohibit hot works Increase ventilation to restore CH₄ to <10% LEL Methane (CH₄)Stop works Limit Level >20% LEL Evacuate personnel/prohibit entry Increase ventilation to restore CH₄ to <10% LEL Action Level >0.5% CO₂ Ventilate to restore CO₂ to <0.5%

Stop works

Evacuate personnel/prohibit entry

Increase ventilation to restore CO₂ to <0.5%

Table 2.2 Action Levels, Limit Levels and Event and Action Plan for LFG

2.3 Environmental Audit of Non-Monitored Parameters

Limit Level >1.5% CO₂

- 2.3.1 Site inspections provide a direct means to trigger and enforce the environmental protection and pollution control measures specified in the Environmental Impact Assessment (EIA) Report. To examine operational practice, site inspections are to be undertaken by the ET once per month. The monthly inspection shall join with the random site inspection by the IEC where possible. A joint inspection by ET and IEC will be carried out at least once per quarter. Ad hoc site inspections are also carried out if significant environmental problems are identified. In addition, inspections may be required subsequent to receipt of environmental complaint, or as part of the investigation work, as specified in the EAP.
- 2.3.2 The following parameters are required to be audited as part of the operation phase EM&A program:
 - Air Quality

Carbon

Dioxide

 (CO_2)

- Water Quality
- Waste Management
- Land Contamination


2.4 Environmental Mitigation Measures

2.4.1 Environmental mitigation measures applicable to the operation phase EM&A as stated in the Implementation Schedule are summarised in *Appendix 1*.

2.5 Environmental Requirements in Tenancy Agreements

2.5.1 Environmental requirements specified in tenancy agreements are provided in *Appendix 2*.

Figure 2-1 LFG Monitoring Locations within EcoPark



3 OPERATION STATUS

3.1 General

- 3.1.1 The location of lots within EcoPark, the current usage and tenant names are shown in *Figure* 3-1. A summary of waste throughputs is provided in *Section 3.11*. Brief descriptions of the active tenants and operators are provided from *Sections 3.2* to 3.10.
- 3.1.2 In the reporting quarter:
 - HKBRC was without any site operation;
 - Baguio was carrying out building works;
 - 3R was undergoing reinstatement work process; and
 - Rocsky and South China were under termination.

3.2 Champway Technology Limited

- **Lot No.:** T5 (Phase 1)
- **Lot Size:** Approx. 6,000m²
- Activity: Recycling of Organic Waste (Waste Cooking Oil)
- **Recycling Process:** Turn waste cooking oil into biodiesel by extraction, neutralisation, separation and distillation.
- 3.2.1 In this reporting quarter, waste cooking oil was recycled. Bi-monthly samplings for effluent arising from producing biodiesel have been conducted to comply with the requirement of effluent discharge licence.

3.3 Hong Kong Biomass (Wood) Collect and Recycle Company Limited

- **Lot No.:** T4 (Phase 1)
- **Lot Size:** Approx. 5,000m²
- Activity: Recycling of Waste Woods
- **Recycling Process:** Recycle waste woods to wood fuel pellets. Ferrous metals will be separated by magnets.
- 3.3.1 In this reporting quarter, waste wood was recycled.

3.4 HP Telford Envirotech Group Limited

- **Lot No.:** T1 (Phase 1)
- Lot Size: Approx. 5,000m²
- Activity: Recycling of Waste Plastics
- **Recycling Process:** Sorting, shredding and baling of waste plastic

3.4.1 In this reporting quarter, waste plastics were recycled.

3.5 Chung Yue Steel Group Company Limited

• **Lot No.:** P13 (Phase 2)

• **Lot Size:** Approx. 10,000 m²

• Activity: Recycling of Waste Metals

- **Recycling Process:** Turn waste metals into non-ferrous scrap, light ferrous scrap and heavy ferrous scrap by sorting, baling and shearing.
- 3.5.1 In this reporting quarter, waste metals were recycled.

3.6 K. Wah Construction Products Ltd.

- **Lot No.:** P11 (Phase 2)
- **Lot Size:** Approx. 10,000 m²
- Activity: Recycling of Waste Construction Materials/Waste Glass
- Recycling Process: Waste construction materials and waste glass will be crushed and delivered to the concrete mixing plant for blending and poured into block machine for casting. The blocks will then be cured, washed and packaged.
- 3.6.1 In this reporting quarter, waste construction materials and waste glasses were recycled.

3.7 WEEE.PARK

- Lot No.: P2, P3, P4 (Phase 2)
- **Lot Size:** Approx. 30,000 m²
- **Activity:** Recycling of WEEE
- **Recycling Process:** Four major types of WEEE (i.e. refrigerator and freezers, air conditioners, e-scrap, TV and computer screens) will be recycled. The recycling processes include separation of insulation/backlighting/plastics/various metals, recovery of screen/monitor stand/refrigerant/oil/hazardous materials, and shredding of casing.
- 3.7.1 In this reporting quarter, WEEE was recycled.

3.8 On Fat Lung Innovative Resources Ltd.

- **Lot No.:** P8 (Phase 2)
- Lot Size: Approx. 4,400 m²
- Activity: Recycling of Waste Rubber Tyres and WEEE
- **Recycling Process:** Waste rubber tyres will be shredded into rubber powder and processed to form rubber bricks. WEEE will be dismantled/shredded and recovered for reusable components.

3.8.1 In this reporting quarter, waste rubber tyres were recycled.

3.9 Food Waste Management Group (FWMG) of EPD

- **Lot No.:** T7 (Phase 1)
- Lot Size: Approx. 4,000m²
- Activity: Temporary storage of wood chip and waste trees handling
- **Recycling Process:** Bulk reduction of waste tree by mechanical shearing and chipping.
- 3.9.1 In this reporting quarter, temporary storage of wood chip and waste trees handling were conducted.

3.10 E. Tech Management (HK) Limited

- **Lot No.:** P14 (Phase 2)
- **Lot Size:** Approx. 5,000m²
- **Activity:** Recycling of WEEE
- **Recycling Process:** CRT, computer/electronics, white goods and florescent lamps will be recycled. The recycling processes include testing and dismantling of components, repair of refurbished equipment, sorting for reusable components and shredding for scrap..
- 3.10.1 In this reporting quarter, WEEE was recycled.

3.11 Throughput Statistics

- 3.11.1 For the active recyclers, most of the incoming waste materials and outgoing products were delivered by land transportation, except for the metals from Chung Yue were delivered by both marine and land transportation.
- 3.11.2 The throughputs of WEEE.PARK and the eight active tenants are summarised in *Table 3.1* below. Please note that product output plus waste disposal does not necessarily equal the waste input, due to material losses during processing and material retained within the lot.

Material Type	Waste Input (tonne)	Product Output (4) (tonne)	Waste Disposed (4) (tonne)
Waste Organic Food	2,234	986	592
Waste Ferrous Metals	20,430	21,740	148
Waste Wood	369	341	-
Waste Electronics	4,216	3,439	487
Waste Plastics	349	311	-
Construction Waste	2,193	14.400	0
Waste Glass	607	14,499	8
Waste Rubber Tyres	n/a	n/a	-


Table 3.1 Throughput Statistics for the Reporting Quarter

Notes:

- 1) The throughput data presented above is the best available data and has been rounded off to the nearest whole tonne for presentation.
- 2) The total product output may not be the same as the waste input due to processing of materials that were received before the reporting quarter and were stored within the lots.
- 3) Waste disposal refers to the disposal of general refuse (i.e. packaging) and/or chemical waste.
- 4) Since the recycling of waste glass and construction waste is combined to produce concrete block at K.Wah, the product output and waste disposal from both processes are combined.
- 5) "-" in the column of waste disposal denotes zero quantity; while "n/a" a denotes unavailable information at the time of report preparation.
- 3.11.3 Detailed throughput figures of the reporting quarter are provided in *Appendix 3.1*. Updated throughput figures of the previous months based on the latest available data, and the updates to the throughput figures from the previous quarter are not significant. The throughput figures are provided in *Appendix 3.2*.

3.12 Process Review

- 3.12.1 Process Review, and possibly Design Audit (DA) where required, had been conducted for each recycling process to be operated within EcoPark to confirm its compliance with the findings and recommendations of the EIA report and the conditions of the EP.
- 3.12.2 Since 2008, twenty four process reviews and three DAs had been approved. Among those, sixteen process reviews and three DAs are related to the current recycling processes in EcoPark as of December 2020. In the reporting period, neither process review nor DA were approved in the reporting period. Full set of the completed PRCs and DAs are submitted separately to relevant authorities in EPD.



4 IMPLEMENTATION STATUS OF ENVIRONMENTAL PROTECTION MEASURES

- 4.1.1 Environmental mitigation measures applicable to the operation phase EM&A as stated in the implementation schedule are summarised in *Appendix 1*. Environmental requirements specified in tenancy agreements are summarised in *Appendix 2*. The implementation status of the environmental requirements for tenants are summarised in the site inspection checklist, in *Appendix 6*.
- 4.1.2 By December 2020, WEEE.PARK, Lot T7 (FWMG of EPD) and seven tenants (Champway, HK Biomass, HP Telford, K. Wah, E. Tech, Chung Yue and On Fat Lung) were under full operation.
- 4.1.3 Appropriate environmental protection measures are in place at all lots.

5 MONITORING RESULTS

5.1 Monitoring Date, Time, Frequency and Duration

5.1.1 As described in *Section 2.1*, operational LFG monitoring is conducted quarterly at five monitoring locations, three in Phase 1 and two in Phase 2. In this reporting quarter, monitoring was undertaken on 25th November 2020. Monitoring details are shown *Table 5.1* below.

Table 5.1 Sampling Schedule for the Quarterly LFG Monitoring

Station ID	Sampling Date	Time	Duration	Ambient Air Temp.	Weather
EP1-1		10:03 – 10:05	2 minutes	24°C	Sunny
EP1-2		10:16 – 10:18	2 minutes	24°C	Sunny
EP1-3	25 th November 2020	10:13 – 10:15	2 minutes	24°C	Sunny
EP2-1		10:08 – 10:10	2 minutes	24°C	Sunny
EP2-2		10:10 – 10:12	2 minutes	24°C	Sunny

5.2 Monitoring Methodology, Parameters and Equipment

5.2.1 The LFG monitoring requirement and methodology are stipulated in *Section 6* of the EM&A Manual. The LFG monitoring parameters and their measurement ranges are detailed in *Table 5.2* below.

Table 5.2 Parameters and Measurement Ranges for LFG Monitoring

Parameters	Measurement Ranges
Methane (CH ₄)	0 – 100% LEL & 0-100% v/v
Oxygen (O ₂)	0 - 25% v/v
Carbon Dioxide (CO ₂)	0 – 100% v/v
Barometric Pressure	mBar (absolute)

- 5.2.2 LFG monitoring shall be carried out using intrinsically-safe, portable multi-gas monitoring instruments. The gas monitoring equipment shall:
 - 1. Comply with BS 6020 and be approved by BASEEFA as intrinsically safe, suitable for use in a Zone 2 are to BS 5345;
 - 2. Be capable of continuous monitoring of methane, oxygen and carbon dioxide;
 - 3. Be capable of continuous barometric pressure and gas pressure measurements;
 - 4. Normally operate in diffusion mode unless required for spot sampling, when it should be capable of operating by means of an aspirator or pump;

- 5. Have low battery, fault and over range indication incorporated;
- 6. Store monitoring data, and shall be capable of being down-loaded directly to a PC; and
- 7. Measure in the following ranges:

- Methane 0 - 100% LEL & 0 - 100% v/v

Oxygen 0 - 25% v/v
 Carbon dioxide 0 - 100% v/v
 Barometric pressure mBar (absolute)

5.3 Results and Graphical Plots of Monitoring Parameters

- 5.3.1 RKI Instruments EAGLE 2 Gas Detector (serial number E2F694) was used for LFG measurements. The gas analyser is calibrated every year. *Appendix 4* presents the calibration records of the monitoring equipment.
- 5.3.2 LFG monitoring results are summarised in *Table 5.3* and compared with the Action and Limit Levels tabulated in *Table 2.2*. Graphical plots of the monitoring results are also provided in *Appendix 5*.

Table 5.3 Quarterly LFG Monitoring Results in the Reporting Quarter

		Monitoring Results				
Station ID	Sampling Date	Methane (% v/v)	Methane (% LEL)	Oxygen (% v/v)	Carbon Dioxide (% v/v)	Barometric Pressure (mBar)
EP1-1		0.0	0.0	20.9	< 0.1	1004
EP1-2	25^{th}	0.0	0.0	20.9	< 0.1	1004
EP1-3	November	0.0	0.0	20.9	< 0.1	1004
EP2-1	2020	0.0	0.0	20.9	< 0.1	1004
EP2-2		0.0	0.0	20.9	0.4	1004

5.3.3 No exceedance of Action and Limit Levels was recorded in the reporting quarter. The reading of Carbon Dioxide (% v/v) at EP2-2 was observed to be higher than the other monitoring stations, at 0.4% v/v. Although no exceedance of Action and Limit Levels were recorded, the status of EP2-2 will be reviewed in the next reporting period.

6 SUMMARY OF ENVIRONMENTAL AUDIT

6.1 General

- 6.1.1 In the reporting quarter, WEEE.PARK, Lot T7 (FWMG of EPD) and seven active tenants were under full operation.
- 6.1.2 Environmental audits based on the approved site inspection checklist were carried out by the Operator and the ET on 20th October, 25th November, 17th December 2020. IEC random site audits were also carried out on 20th October and 17th December 2020. A quarterly joint site inspection was carried out by the Operator, the IEC and the ET on 25th November 2020. The completed audit checklists for tenants are provided in *Appendix* 6.

6.2 Champway Technology Limited

6.2.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in *Table 6.1* below. The completed checklists for Champway are given in *Appendix 6.1*.

Table 6.1 Environmental Audit Findings for Champway

Date	Item	Comment	Status			
Observations From Previous Reporting Quarters						
23 Sept 2020	Oil sheen is still observed on the perimeter drain at the oil storage tank area opposite the biodiesel processing plant.	The tenant was requested to clear up the oil spillage and prevent oil from entering the public stromwater drainage.	As observed on 20 October 2020, oil sheen on the perimeter drain at the oil storage tank area opposite the biodiesel processing plant was cleared up.			
23 Sept 2020	A broken oil pipe was observed under the plant building near site office.	The tenant was requested to clear up the oil spillage and replace the broken oil pipe.	As observed on 20 October 2020, oil spillage under the plant building near site office was cleared up. The broken oil pipe under the plant building is no longer in use, and will be removed from underneath the plant building.			
23 Sept 2020	Oil spillage was observed in the perimeter drainage next to the new filter press facility.	The tenant was requested to clear up the spillage and prevent oil from entering the public stormwater drainage.	As observed on 20 October 2020, oil spillage in the perimeter drainage next to the new filter press facility was cleared up.			
23 Sept 2020	Oil spillage was observed in the stormwater manhole at the vehicular access.	The tenant was requested to clear up the spillage and prevent oil from entering the public stormwater drainage.	As observed on 20 October 2020, oil spillage in the stormwater manhole at the vehicular access was cleared up.			

EcoPark Operation

Date	Item	Comment	Status
23 Sept 2020	Oil spillage was observed at the stockpile area next to the processing plant.	The tenant was requested to clear up the spillage.	As observed on 20 October 2020, oil spillage at the stockpile area next to the processing plant was cleared up.
Observations I	From This Reporting	Quarter	
20 Oct 2020	Oily layer on sewage water was observed in the sewerage outside the site entrance.	The tenant was requested to clear up the oil and prevent oil from entering the sewerage system.	As observed on 25 November 2020, oily layer on sewage water in the sewerage outside the site entrance was cleared.
25 Nov 2020	Oil stain was observed near the bins in the refuse area at the front of the processing plant.	The tenant was requested to clear up the oil.	As observed on 17 December 2020, oil stain was still observed near the bins in the refuse area at the front of the processing plant. This item will be reviewed in the next inspection in January 2021.
25 Nov 2020	Oil stain was observed near the tanks in the stockpile area near the site office.	The tenant was requested to clear up the oil.	As observed on 17 December 2020, oil stain was still observed near the tanks in the stockpile area near the site office. This item will be reviewed in the next inspection in January 2021.
25 Nov 2020	The perimeter drainage was observed to have been blocked.	The tenant was requested to clear up the blockage and oil to avoid overflow and pollution.	As observed on 17 December 2020, the perimeter drainage was still observed to have been blocked. In addition, oil and oil sludge were also observed in the drainage. This item will be reviewed in the next inspection in January 2021.
17 Dec 2020	Activated carbon was observed to have been spilled all over the floor.	The tenant was requested to better monitor the condition of material storage.	This item will be reviewed in the next inspection in January 2021.

6.3 Hong Kong Biomass (Wood) Collect and Recycle Company Limited

6.3.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in *Table 6.2* below. The completed checklist for HK Biomass is given in *Appendix 6.2*.

Table 6.2 Environmental Audit Findings for HK Biomass

Date	Item	Comment	Status		
Observations From Previous Reporting Quarters					
None					

Date	Item	Comment	Status		
Observations I	Observations From This Reporting Quarter				
20 Oct 2020	No new critical issue was identified.				
25 Nov 2020	No new critical issue was identified.				
17 Dec 2020	No new critical issu	e was identified.			

6.4 HP Telford Envirotech Group Limited

6.4.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in Table 6.3 below. The completed checklists for HP Telford are given in Appendix 6.3.

Table 6.3 Environmental Audit Findings for HP Telford

Date	Item	Comment	Status			
Observations .	Observations From Previous Reporting Quarters					
None						
Observations .	From This Reporting (Quarter				
20 Oct 2020	Oct 2020 No new critical issue was identified.					
25 Nov 2020	No new critical issue was identified.					
17 Dec 2020	No new critical issue	was identified.				

6.5 **Chung Yue Steel Group Company Limited**

Audit observations from previous reporting quarters and this reporting quarter are 6.5.1 summarised in Table 6.4 below. The completed checklists for Chung Yue are given in Appendix 6.4.

Table 6.4 Environmental Audit Findings for Chung Yue

Date	Item	Comment	Status	
Observations I	From Previous Repor	ting Quarters		
23 Sept 2020	Loads levels of trucks were observed to exceed the levels of the sides and the tailboard during the inspection.	The tenant was requested to reduce the load levels of trucks.	As observed on 20 October 2020, loads levels of trucks were reduced.	
Observations I	From This Reporting	Quarter		
20 Oct 2020	No new critical issu	e was identified.		
25 Nov 2020	No new critical issue was identified.			
17 Dec 2020	Loads levels of trucks were observed to	The tenant was requested to reduce the load levels of trucks.	This item will be reviewed in the next	

AEC Issue 1

Date	Item	Comment	Status
	exceed the levels		inspection in January
	of the sides and		2021.
	the tailboard		
	during the		
	inspection.		

6.6 K.Wah Construction Products Limited

6.6.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in *Table 6.5* below. The completed checklists for K. Wah are given in *Appendix* 6.5.

Table 6.5 Environmental Audit Findings for K.Wah

Date	Item	Comment	Status				
Observations I	Observations From Previous Reporting Quarters						
None							
Observations I	From This Reporting Qu	arter					
20 Oct 2020	C&D materials were observed in the surface channel near the stockpile area.	The tenant was requested to clear up the C&D materials, and further reminded to implement sufficient mitigation measures to prevent materials from entering into drains.	As observed on 17 December 2020, C&D materials in the surface channel near the stockpile area were cleared. The tenant was reminded to cover the C&D materials to avoid future blockage.				
25 Nov 2020	No new critical issue was identified.						
17 Dec 2020	C&D materials were observed to have blocked the perimeter drain.	The tenant was requested to clear up the C&D materials to avoid overflow by covering them with tarpaulin.	This item will be reviewed in the next inspection in January 2021.				

6.7 E. Tech Management (HK) Limited.

6.7.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in *Table 6.6* below. The completed checklists for E. Tech are given in *Appendix* 6.6.

Table 6.6 Environmental Audit Findings for E. Tech

Date	Item	Comment	Status			
Observations .	Observations From Previous Reporting Quarters					
None						
Observations .	Observations From This Reporting Quarter					
20 Oct 2020	20 Oct 2020 No new critical issue was identified.					
25 Nov 2020	No new critical issue was identified.					

Date	Item	Comment	Status
17 Dec 2020	No new critical issue was identified.		

6.8 WEEE.PARK

6.8.1 Audit observations from this reporting quarter are summarised in *Table 6.7* below. The completed checklists for WEEE.PARK are given in *Appendix 6.7*.

Table 6.7 Environmental Audit Findings for WEEE.PARK

Date	Item	Comment	Status				
Observations I	Observations From Previous Reporting Quarters None						
- 1, 3, 2, 2	From This Reporting	Quarter					
20 Oct 2020	The sieve on the stormwater manhole opposite the chemical waste stores was found to be filled by plastics debris.	The tenant was requested to clear up the debris, and further reminded to better maintain drains to prevent any blockage.	As observed on 17 December 2020, the plastic waste in the sieve on the stormwater manhole opposite the chemical waste stores was cleared up. The tenant was reminded to take extra care to avoid future blockage.				
25 Nov 2020	No new critical issue was identified.						
17 Dec 2020	No new critical issue was identified.						

6.9 On Fat Lung Innovative Resources Limited

6.9.1 Audit observations from this reporting quarter are summarised in *Table 6.8* below. The completed checklists for On Fat Lung are given in *Appendix 6.8*.

Table 6.8 Environmental Audit Findings for On Fat Lung

Date	Item	Comment	Status		
Observations From Previous Reporting Quarters					
None	None				
Observations From This Reporting Quarter					
20 Oct 2020	20 Oct 2020 No new critical issue was identified.				
25 Nov 2020	Nov 2020 No new critical issue was identified.				
17 Dec 2020	c 2020 No new critical issue was identified.				

6.10 Lot T7 (FWMG of EPD)

6.10.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in *Table 6.9* below. The completed checklists of general site inspection for EcoPark are given in *Appendix 6.9*.

Table 6.9 Environmental Audit Findings for Lot T7

Date	Item	Comment		Status	
Observations From Previous Reporting Quarters					
None					
Observations From This Reporting Quarter					
20 Oct 2020	Oct 2020 No new critical issue was identified.				
25 Nov 2020	No new critical issue was identified.				
17 Dec 2020	No new critical issue wa	as identified.			

6.11 General Condition of EcoPark

6.11.1 Audit observations from previous reporting quarters and this reporting quarter are summarised in *Table 6.10* below. The completed checklists of general site inspection for EcoPark are given in *Appendix 6.10*.

Table 6.10 General EcoPark Audit Findings

Date	Item	Comment	Status			
Observations From Previous Reporting Quarters						
23 Sept 2020	Baguio Mud debris was observed to have been flushed into the stormwater gulley on the road outside the site entrance.	The tenant was immediately requested to avoid discharging untreated surface runoff into the public stormwater system and remove the mud debris from the gully. The tenant should implement sufficient measures on site to collect, treat and reuse wastewater generated from construction activity (such as wheelwashing activity) for better wastewater control. The tenant was requested to clean the mud debris before operation of the sit's drainage network to prevent runoff into the public drainage system.	As observed on 25 November 2020, the surface of Baguio's lot had been paved with concrete during the site inspection. It is noted the existing surface channel was temporarily blocked off from the public drainage network to facilitate the drainage work of the site. As observed on 17 December 2020, mud debris was still observed in the surface channel. This item will be reviewed in the next			

Date	Item	Comment	Status		
23 Sept 2020	Baguio Stockpile was observed to not be covered or watered.	The tenant was requested to cover the stockpiles with tarpaulin for dust suppression.	inspection in January 2021. As observed on 17 December 2020, the temporary stockpile of C&D materials was still observed to not be covered or watered. This item will be reviewed in the next inspection in January 2021.		
Observations From This Reporting Quarter					
20 Oct 2020	20 Oct 2020 No new critical issue was identified.				
25 Nov 2020	25 Nov 2020 No new critical issue was identified.				
17 Dec 2020 No new critical issue was identified.					

7 ENVIRONMENTAL COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTION

- 7.1 New Environmental Complaint, Notification of Summon and Successful Prosecution in the Reporting Period
- 7.1.1 By the end of December 2020, no complaint or notification of summon or successful prosecution related to recycling activities was received in this reporting quarter.

8 CONCLUSIONS

- 8.1.1 This is the fifty-fifth (55th) quarterly EM&A report prepared for the operation phase of EcoPark and covers the reporting quarter from October to December 2020. The recycling activities are audited on a monthly basis and the results are summarised in this report. In the reporting quarter, there were twelve tenants in EcoPark Phase 1 and Phase 2, one operator (FWMG of EPD) of Lot T7 in EcoPark Phase 1 and one operator (Alba IWS) in EcoPark Phase 2.
- 8.1.2 The ET has conducted monthly site inspections while the IEC has carried out full site inspection on quarterly basis and random site audits on monthly basis, and some general observations have been made. The approved checklist has been used in the monthly site inspections for various tenants.
- 8.1.3 The throughputs of WEEE.PARK and the seven active tenants in the reporting quarter are summarised in *Table 8.1*. Please note that product output plus waste disposal do not necessarily equal the waste input, due to material losses during processing and material retained within the lots.

Table 8.1 Throughput Statistics for the Reporting Quarter


Material Type	Waste Input (tonne)	Product Output (4) (tonne)	Waste Disposed ⁽⁴⁾ (tonne)	
Waste Organic Food	2,234	986	592	
Waste Ferrous Metals	20,430	21,740	148	
Waste Wood	369	341	1	
Waste Electronics	4,216	3,439	487	
Waste Plastics	349	311	-	
Construction Waste	2,193	14,499	8	
Waste Glass	607	14,499	0	
Waste Rubber Tyres	n/a	n/a	-	

Notes:

- 1) The throughput data presented above is the best available data and has been rounded off to the nearest whole tonne for presentation.
- 2) The total product output may not be the same as the waste input due to processing of materials that were received before the reporting quarter and were stored within the lots.
- 3) Waste disposal refers to the disposal of general refuse (i.e. packaging) and/or chemical waste.
- 4) Since the recycling of waste glass and construction waste is combined to produce concrete block at K.Wah, the product output and waste disposal from both processes are combined.
- 5) "-" in the column of waste disposal denotes zero quantity; while "n/a" denotes unavailable information at the time of report preparation.
- 8.1.4 LFG monitoring during the reporting quarter was undertaken on 25th November 2020 at five locations (three in Phase 1 and two in Phase 2). No exceedance of Action or Limit Level was recorded in the reporting quarter.
- 8.1.5 Numbers of complaints, summons and successful prosecutions in the reporting quarter are summarised below:
 - **Complaints:** Zero.

31

- **Summons:** Zero.
- Successful Prosecutions: Zero.
- 8.1.6 In the next reporting quarter, LFG monitoring in operation phase for Phase 1 and Phase 2 will be continued.



Appendix 1

Environmental Mitigation Measures (from the Implementation Schedule)

EIA Ref.	EM&A Ref.	Environmental Protection Measures Identified in the Implementation Schedule that are Applicable to the Operation Phase of EcoPark	Location / Duration of Measures / Timing of Completion of Measures	Implementation Agent	Relevant Legislation and Guidelines	Implementation Status (✓ - Implemented; X - Not Implemented; / - To Be Implemented)
General						
5.5.23 to 5.5.25, 10.2.24 & 10.2.37	4.2.5 to 4.2.8	The Operator shall develop and implement an Emergency Response Plan (ERP) that lists the procedures to be followed in case of fire, fuel or chemical spillage or other emergency within the EcoPark.	Throughout the duration of the operation.	Operator		✓
12.2	7.2	No process shall be allowed to operate within EcoPark without approval from WFBU. Approval will be based on the ten-step Process Review, which may include a Design Audit if deemed to be necessary.	Throughout the duration of the operation.	ET IEC Project Proponent		V
	8.1.2	All reports (including Process Review Checklists and any Design Audits) shall be prepared and certified by the ET, verified by the IEC and approved by the Project Proponent.	Throughout the duration of construction works until construction is substantially completed. Throughout the duration of the operation.	ET IEC Project Proponent		✓
12.3	7.3	The Operator shall prepare and implement an Environmental Management Plan (EMP) to define mechanisms for achieving the environmental requirements specified in the EIA, EP and in statutory regulations.	Throughout the duration of the operation.	Operator		✓

EIA Ref.	EM&A Ref.	Environmental Protection Measures Identified in the Implementation Schedule that are Applicable to the Operation Phase of EcoPark	Location / Duration of Measures / Timing of Completion of Measures	Implementation Agent	Relevant Legislation and Guidelines	Implementation Status (✓ - Implemented; X - Not Implemented; / - To Be Implemented)
13.2		The Operator shall ensure that EcoPark "base case" assumptions for air quality shown in Table 13.1 of the Final EIA Report are met by tenants, as a whole.	Throughout the duration of the operation.	Operator	Table 13.1 of the Final EIA Report	✓
Water Qua	ılity			ı		
5.4.11 & 5.6.7		To minimise the chance of accidental spillage during loading and unloading, and thereby reduce marine water quality impacts, well established cargo handling guidelines should be followed.	Adjacent to EcoPark marine frontage when loading or unloading goods.	Operator Operators of bulk carriers	Sections 5 & 6 of IMO Code of Practice for the Safe Loading/ Unloading of Bulk Carriers	/
5.5.19		Contaminated water collected in the surface drainage systems shall be treated at the WTF or other appropriate treatment facility.	Within EcoPark throughout the life of the facility.	Operator		✓
5.5.23 to 5.5.25	4.2.5 to 4.2.7	An Emergency Response Plan (ERP) will be formulated to address various accident scenarios. The ERP will be certified by the Environmental Team (ET) and verified by the Independent Environmental Checker (IEC) under the operation EM&A programme.	Within EcoPark throughout the life of the facility.	Operator		✓
5.6.4		For uncovered areas where recovery process identified as causing potentially high level of contamination are located, stop-logs will be installed in the perimeter drainage system to isolate contamination.	Within EcoPark throughout the life of the facility.	Operator		✓

Issue 1 AEC

EIA Ref.	EM&A Ref.	Environmental Protection Measures Identified in the Implementation Schedule that are Applicable to the Operation Phase of EcoPark	Location / Duration of Measures / Timing of Completion of Measures	Implementation Agent	Relevant Legislation and Guidelines	Implementation Status (✓ - Implemented; X - Not Implemented; / - To Be Implemented)
	4.2.2	The ET should develop an audit checklist, with the agreement of the IEC, to ensure that each mitigation measure is implemented when appropriate and operated correctly when implemented.	Within EcoPark throughout the life of the facility.	ET with IEC		✓
Waste Ma	nagement					
6.8.7	5.2.4	The Operator should register with EPD as a chemical waste producer.	Within EcoPark throughout the life of the facility.	Operator	Waste Disposal (Chemical Waste) (General) Regulation	✓
6.8.16		The dust collected by any air pollution control equipment installed by tenants must be tested to ensure compliance for landfill disposal.	Within EcoPark throughout the life of the facility.	Operator	Practice Note for disposal of dusty waste at landfills & Admission Ticket System	✓
6.8.18 & 6.8.22	5.2.4	Sludge will be disposed of at WENT landfill, or at any future dedicated sludge treatment facility. Sludge will be collected by a Licensed collector at regular intervals, as determined by the operation of the WTF.	Within EcoPark throughout the life of the facility.	Operator		✓
6.8.21	5.2.4	Chemical wastes shall be stored in appropriate containers in a covered area. "No Smoking" signs will be clearly displayed to prevent accidental ignition of flammable materials. Drip trays capable of storing 110% of the volume of the largest container will be used to	Within EcoPark throughout the life of the facility.	Operator	Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes	✓

Issue 1 AEC


EIA Ref.	EM&A Ref.	Environmental Protection Measures Identified in the Implementation Schedule that are Applicable to the Operation Phase of EcoPark	Location / Duration of Measures / Timing of Completion of Measures	Implementation Agent	Relevant Legislation and Guidelines	Implementation Status (✓ - Implemented; X - Not Implemented; / - To Be Implemented)
	5.2.3 & 5.2.5	mitigate possible leakage. The ET should develop an audit checklist, with the agreement of the IEC, to ensure that each mitigation measure is implemented when appropriate and operated correctly when implemented.	Within EcoPark throughout the life of the facility.	ET with IEC		✓
6.8.7	5.2.4	The Operator should register with EPD as a chemical waste producer.	Within EcoPark throughout the life of the facility.	Operator	Waste Disposal (Chemical Waste) (General) Regulation	✓
Prevention 7.3.1	5.3.2	Any spillages of contaminating material shall be cleaned up immediately through the use of an absorbent. Any such used material should then be considered chemical waste and disposed of appropriately.	Within EcoPark throughout the life of the facility.	Operator		/
7.3.3		Any areas within the lot to be used for recycling processes shall be concrete paved before recycling activities commence.	Within EcoPark throughout the life of the facility.	Operator		✓

EcoPark Operation

Quarterly Environmental Monitoring & Audit Report (October - December 2020)

	Identified in the Implementation Schedule that are Applicable to the Operation Phase of EcoPark	of Measures / Timing of Completion of Measures	Agent	Legislation and Guidelines	(✓ - Implemented; X -Not Implemented; / - ToBe Implemented)
7.3.5 5.3.2 Landfill Gas	 During operation, the greatest risk of land contamination will come from storage of chemical wastes, therefore the measures should be followed: All chemical storage areas shall be provided with locks and be sited on sealed areas. The storage areas shall be surrounded by bunds with a capacity equal to 110% of the storage capacity of the largest tank to prevent spilled oil and chemicals from contaminating the ground. Chemical wastes will be collected, stored and disposed of in accordance with the Regulation. Disposal of other construction waste will be undertaken by licensed contractors in accordance with applicable statutory requirements in the WDO. Chemical wastes shall be handled according to the relevant code of practice. Spent chemicals shall be stored and collected by an approved operator for disposal at a licensed facility in accordance with the relevant regulation. 	Within EcoPark throughout the life of the facility.	Operator		*

EIA Ref.	EM&A Ref.	Environmental Protection Measures Identified in the Implementation Schedule that are Applicable to the Operation Phase of EcoPark	Location / Duration of Measures / Timing of Completion of Measures	Implementation Agent	Relevant Legislation and Guidelines	Implementation Status (✓ - Implemented; X - Not Implemented; / - To Be Implemented)
8.7.10 & 8.7.11	6.1.2	 Alert workers and visitors of possible LFG hazards Prohibit smoking and open fires on site Conduct regular (quarterly) LFG monitoring at mobile offices, equipment stores, etc. 	Within EcoPark throughout the life of the facility.	Operator		✓
	6.4.3	Following construction, routine monthly monitoring may be required at service voids and utility boxes. The monitoring requirement and specific locations of monitoring points shall be established based on the findings of the monitoring carried out during construction (i.e. if no LFG is detected during construction then no routine monitoring is required). The need for continued monitoring shall, however, be reviewed through discussion with EPD.	Within EcoPark throughout the life of the facility.	Operator		✓
Hazard to	Life			•		
10.4.3		Building height limit within EcoPark shall be applied to structures within which people may work at elevated levels.	Within EcoPark throughout the life of the facility.	Operator	EIA Report Table 10.2	✓
Landscape	e and Visu	al				
9.4.4		It recommended that this commonality be promoted throughout EcoPark by the Operator and adopted by tenants, if practicable.	Within EcoPark throughout the life of the facility.	Operator		✓



Issue 1_____AEC

Compliance of Environmental Legislation

5. The Tenant shall comply with and observe all Ordinances, by-laws, regulations and rules for the time being in force in Hong Kong governing the control of any form of pollution, including air, noise, water and waste pollution, and for the protection of the environment.

Air Pollution

6. Save with an appropriate exemption under the Air Pollution Control Ordinance (Cap. 311) any regulations made thereunder and any amending legislation, the Tenant shall not install or permit or suffer to be installed upon the Premises or any part thereof or any building(s) or structure(s) or part of any building(s) or structure(s) erected or to be erected thereon any furnace, oven, chimney or flue or any other combustion equipment or use or permit or suffer to be used any fuel or any method or process of manufacture or treatment that might in any circumstance result in, cause or contribute to the discharge or emission of any pollutant or any noxious, harmful or corrosive matter, whether it be in the form of gas, smoke, liquid, solid or otherwise (including but not limited to air pollutant as defined in Section 2 of the Air Pollution Control Ordinance

(Cap. 311), which exists or which is imminent, without the prior written approval of the Director.

Water Pollution

- 7. (a) In the event that the Tenant produces, generates, permits, causes, allows or suffers any discharge which is subject to control under the Water Pollution Control Ordinance (Cap. 358) any regulations made thereunder and any amending legislation, the Tenant shall apply to the Director for a licence and comply with the terms and conditions stipulated in the licence at the Tenant's own cost(s). Otherwise, the Tenant is not allowed to discharge directly or indirectly or to produce, generate, permit, cause, allow or suffer any discharge into any public sewer, storm-water drain, channel, stream-course, sea or any area inside or outside the Premises any trade effluent or foul or contaminated water or cooling or hot water. Subject to the said licence from the Director, the Tenant shall at its own cost(s) separate, collect, and discharge all process or industrial wastewater which comply with the standard required for discharge into a sewer leading to the sewage treatment works at Pillar Point or other treatment works specified in the licence.
 - (b) Subject to obtaining advance written approval of the Director, the Tenant shall at its own cost(s) provide, install, operate and maintain its own waste water pretreatment plants within the Premises if such process or industrial wastewater could not meet the standard required for discharge into a sewer leading to the sewage treatment works at Pillar Point or other treatment works specified in the licence. The Tenant shall at its own cost(s) separate, collect, discharge and send all domestic wastewater (i.e. other than process or industrial wastewater) to the Pillar Point Sewage Treatment Works directly for treatment or other treatment works specified in the licence.
 - (c) In any event, the Tenant shall prevent any spilled materials from entering the surface water drainage system and prevent contamination of the sea at its own cost(s) by, inter alia, providing, installing, operating and maintaining stop-logs or interceptors in the surface water drainage system and at the marine frontage area, respectively, or as required by the licence. The Tenant shall at its own cost comply with relevant provisions of the Dumping at Sea Ordinance (Cap. 466) good practices and relevant provisions of the EIA Report and Final EM&A Manual.

Waste Management

- 8. (a) The Tenant shall at its own cost(s) comply with relevant provisions of the Waste Disposal Ordinance (Cap. 354).
 - (b) The Tenant shall not permit, allow or suffer any fuel or chemical and any sewage, waste water or effluent containing sand, cement, silt or any suspended or dissolved material to flow, escape or run from the Premises onto any adjoining land or allow any waste matter which does not form part of the recovery and/or recycling and/or reprocessing operation or is not part of the final product of such operation to be deposited, kept, held or stored anywhere within the Premises and other areas of EcoPark. The Tenant shall at its own cost(s) have all such matters and all materials arising from recycling activities, chemical materials arising from maintenance of plant and equipment, sewage sludge (from wastewater treatment facilities, if any) and general daily waste from the operation removed from the Premises or any building(s) or structure(s) or any part of any building(s) or structure(s) erected or to be erected thereon in a proper manner to the satisfaction of the Landlord and/or the Director.

Noise Pollution

- 9. (a) The Tenant shall take all necessary measures as may be required by and to the satisfaction of the Landlord and/or the Director to ensure that the operation of all plant and equipment, installed or used on the Premises or in any building(s) or structure(s) or any part of any building(s) or structure(s) erected or to be erected thereon, will not result, not cause and/or will not contribute any noise (which exists or which is imminent) which disturbs or annoys the residents or occupiers of any adjoining or neighbouring lot or lots or premises, or causes and/or contributes to disturbance to the general public under the Noise Control Ordinance (Cap. 400) any regulations made thereunder and any amending legislation.
 - (b) The decision of the Landlord or the Director as to whether any such plant and equipment are causing disturbance or annoyance as aforesaid shall be final and binding on the Tenant.

Landfill Gas Hazard

10. To mitigate landfill gas hazard, the Tenant shall at its own cost(s) comply with, inter alia, Condition 4.13 of the Environmental Permit No. EP-226/2005/A regarding raising clear of the ground all buildings and enclosed structures as specified in inter alia

Condition 3.7 (and comply with the conditions of any updated Permit, amended permit and further permit regarding measures to mitigate hazard to life impact).

EcoPark Being Within the 250m Consultation Zone of Siu Lang Shui Landfill

- 11. (a) The Tenant acknowledges that the EcoPark is within the 250m Consultation Zone of the Siu Lang Shui Landfill and that the Premises may be affected by problems associated with migrating landfill gas and undertakes to provide suitable precautionary or protection measures at his own expense to control these potential hazards.
 - (b) The Tenant shall ensure all personnel entering the Premises and all visitors to the Premises are aware of the potential hazards of the landfill gas by posting suitable warning notices of the potential hazards at his own expense.
 - (c) All buildings and enclosed structures, including temporary offices, temporary stores and the administration building, within the 250m Consultation Zone of the Siu Lang Shui Landfill shall be provided with the following measure(s):
 - (i) buildings shall be raised clear of the ground with a clear separation distance (as measured from the highest point on the ground surface to the underside of the lowest floor joist) of at least 500mm; or
 - (ii) a low-gas permeability membrane shall be applied to the surface of any wall or floor slab that rests on or is below ground. A gravel-fill vent system shall be provided such that passive venting is achieved around the perimeter of the structure. In addition, other building materials, such as dense well-compacted concrete or steel shuttering which provide a measure of resistance to gas permeation, shall be used to achieve gas protection.
 - (d) The Tenant shall ensure that the electrical equipment used on the Premises shall be intrinsically safe. Welding, flame-cutting or other hot works shall be confined to the open areas of the Premises and shall be at least 15m away from any ground-level confined space.
 - (e) No drilling, trenching and excavation shall be allowed on the Premises. During any construction work, the Tenant shall observe the guidelines recommended in Chapter 8 of the "Landfill Gas Hazard Assessment Guidance Note" published by the Department of Environmental Protection. In particular, no smoking, naked

flames and all other sources of ignition shall be allowed within 15m of any ground-level confined space.

Hazard to Life Impact

- 12. To mitigate hazard to life impact, the Tenant shall comply with, inter alia, Conditions 4.8 to 4.10 of the Environmental Permit No. EP-226/2005/A (and comply with the conditions of any updated Permit, amended permit and further permit regarding measures to mitigate hazard to life impact) and shall not:-
 - (a) bring, keep, store or transport chlorine within the Premises and other areas of EcoPark;
 - (b) bring, keep, store, locate or transport dangerous goods, substances and fuels supporting combustion including oxygen, acetylene, hydrogen peroxide, rubber tyres and diesel within 10 metres from the boundary of the site of EcoPark; and
 - (c) exceed the building height restrictions for buildings on the Premises which are on/near the western boundary of the site of EcoPark as mentioned in Annex B to the Environmental Permit No. EP-226/2005/A (including any updated Permit, amended permit and further permit).


Landscape and Visual Impacts


13. To mitigate landscape and visual impacts, the Tenant shall at its own cost(s) comply with, inter alia, Condition 4.14 of the Environmental Permit No. EP-226/2005/A regarding maintaining landscape, planting, treatment and mitigation measures as specified in inter alia Condition 3.8 and Figure 3 (and comply with the conditions of any updated Permit, amended permit and further permit regarding measures to mitigate landscape and visual impacts).

Environmental Permits Relating to EcoPark

14. The Tenant hereby declares, confirms and acknowledges that it is fully aware that, pursuant to the Environmental Impact Assessment Ordinance (Cap.499), the Director has the right to grant, amend or revoke environmental permit(s) or to grant further or amended environmental permit(s) relating to the lots comprising the EcoPark and any other lots but that such right may be challenged by third parties on justifiable grounds. The Tenant hereby undertakes to waive all its rights and remedies for any loss, damages, cost and expenses whatsoever which it may sustain and/or incur directly or

indirectly as a result of the grant, amendment or revocation of the environmental permit(s) or the consequential grant of further or amended environmental permit(s), including but not limited to any right to terminate this Lease and/or to make any claim against the Landlord and/or the Director for any compensation whatsoever.





Issue 1_____AEC

Table A3.1-1 Recycling of Waste Organic Food

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
October 2020	2,234 ^[5]	986 ^[5]	592 ^[5]
November 2020	n/a	n/a	n/a
December 2020	n/a	n/a	n/a

Table A3.1-2 Recycling of Waste Ferrous Metals

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
October 2020	9,628	7,235	72
November 2020	10,802	14,505	76
December 2020	n/a	n/a	n/a

Table A3.1-3 Recycling of Waste Wood

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
October 2020	182	182	-
November 2020	187	159	-
December 2020	n/a	n/a	n/a

Table A3.1-4 Recycling of Waste Electronics

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
October 2020	2,200	1,780	249
November 2020	2,016 ^[5]	1,659 ^[5]	238 ^[5]
December 2020	n/a	n/a	n/a

Table A3.1-5 Recycling of Waste Plastics

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
October 2020	156	107	-
November 2020	193	204	-
December 2020	n/a	n/a	n/a

Issue 1 AEC

Table A3.1-6 Recycling of Waste Glass and Construction Waste

	Waste Inp	out (tonne)	Product	Waste	
Date	Construction Waste	Glass	Output ⁽⁴⁾ (tonne)	Disposal ⁽⁴⁾ (tonne)	
October 2020	710	392	7,323	3	
November 2020	1,483	215	7,176	5	
December 2020	n/a	n/a	n/a	n/a	


Table A3.1-7 Recycling of Waste Rubber Tyres

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
October 2020	n/a	n/a	-
November 2020	n/a	n/a	-
December 2020	n/a	n/a	n/a

Notes:

- 1) The throughput data presented in Tables A3.1-1 to A3.1-7 has been rounded off to the nearest whole tonne for presentation.
- 2) The total product output may not be the same as the waste input due to processing of materials that were received before the reporting quarter and were stored within the lots.
- 3) Waste disposal refers to the disposal of general refuse (i.e. packaging) and/or chemical waste.
- 4) Since the recycling of waste glass and construction waste is combined to produce concrete block at K.Wah, the product output and waste disposal from both processes are combined.
- 5) The presented throughput is the best available data.
- 6) "-" in the column of waste disposal denotes zero quantity; while "n/a" denotes unavailable information at the time of report preparation.

Issue 1 AEC



Issue 1_____AEC

Table A3.2-1 Recycling of Waste Organic Food

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
August 2020	$1,047^{[5]}$	640 ^[5]	$249^{[5]}$
September 2020	1,558 ^[5]	640 ^[5]	395 ^[5]

Table A3.2-2 Recycling of Waste Ferrous Metals

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
September 2020	12,028	10,185	75

Table A3.2-3 Recycling of Waste Wood

Date Waste Input (tonne)		Product Output (tonne)	Waste Disposal (tonne)
September 2020	163	137	-

Table A3.2-4 Recycling of Waste Electronics

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
August 2020	2,096*	1,960*	262*
September 2020	2,237	1,982	263

Table A3.2-5 Recycling of Waste Plastics

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
September 2020	164	106	-

Table A3.2-6 Recycling of Waste Glass and Construction Waste

	Waste Inp	out (tonne)	Product	Waste
Date	Construction Waste	Glass	Output ⁽⁴⁾ (tonne)	Disposal ⁽⁴⁾ (tonne)
September 2020	2,263	569	8,474	11

Table A3.2-7 Recycling of Waste Rubber Tyres

Date	Waste Input (tonne)	Product Output (tonne)	Waste Disposal (tonne)
July 2020	149	60	-
August 2020	211	70	
September 2020	204	120	-

Issue 1 AEC


EcoPark Operation

Quarterly Environmental Monitoring & Audit Report (October - December 2020)

Notes:

- 1) The throughput data in Tables A3.2-1 to A3.2-6 supersede the same batch of the throughput data in previous Quarterly Environmental Monitoring & Audit Reports. The presented data has been rounded off to the nearest whole tonne for presentation.
- 2) The total product output may not be the same as the waste input due to processing of materials that were received before the reporting quarter and were stored within the lots.
- 3) Waste disposal refers to the disposal of general refuse (i.e. packaging) and/or chemical waste.
- 4) Since the recycling of waste glass and construction waste is combined to produce concrete block at K.Wah, the product output and waste disposal from both processes are combined.
- 5) "-" in the column of waste disposal denotes zero quantity; while "n/a" denotes unavailable information at the time of report preparation.
- 6) The throughput data marked with "*" have been revised with updated data since submission of previous quarterly EM&A report (Apri-Jun 2020).

Issue 1_____AEC



Draft 1_____AEC



東業德勤測試顧問有限公司 ETS-TESTCONSULT LTD.

8/F Block B, Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fo Tan, Hong Kong

T: +852 2695 8318 F: +852 2695 3944 E: etl@ets-testconsult.com W: www.ets-testconsult.com

Calibration Certificate

Information Provided by Customer

Customer

: ETS - TESTCONSULT LIMITED

Address

8/F, Block B, Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fo Tan, Hong Kong

Information of Unit-under test (UUT)

Description

Gas Detector

Equipment I.D. No

ET/EA/005/01

Manufacturer

RKI Instruments EAGLE 2

Serial No.

E2F694

Type of gas

CO₂, O₂, CH₄

Laboratory Information

Procedure

In-house method

Data of Receipt

11-Jun-2020

Data of Calibration

18-Jun-2020

Calibration Location

Environmental Laboratory

Data of issue

19-Jun-2020

Calibration Condition

Ambient Temperature :

(20 ± 3) ℃

Relative Humidity

(50 ± 20)%

Stabilizing Time

30 minutes

Warm-up Time

30 minutes

Reference Equipment

- Reference Gas Detector, ET/EA/005/02

Calibration Specification

- To perform the calibration of gas below:
- CO2 at 0, 3000 and 5000ppm
- O2 at 10, 20 & 30vol%
- CH4 at 0, 5 & 10%LEL

Calibration Result (CO2)

Calibration Range (ppm)	Reference Equipment Reading (ppm)	*Corrected Value (ppm)	UUT Reading (ppm)	Deviation (ppm)
0	0.0	0.0	0.0	0.0
3000	3134.3	3071,6	3089 0	17.4
5000	5289.4	5183.6	5184.1	0,5

Remark

Measurement Result (CO2)

Items	Results
Indication Error (%)	0
Repeatability (%)	0.8

^{2%} indicator error of reference equipment is applied



東業德勤測試顧問有限公司 ETS-TESTCONSULT LTD

8/F Block B, Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fo Tan, Hong Kong

T: +852 2695 8318 F: +852 2695 3944 E: etl@ets-testconsult.com W: www.ets-testconsult.com

Calibration Result (O2)

Calibration Range (%vol)	Reference Equipment Reading (%vol)	*Corrected Value (%vol)	UUT Reading (%vol)	Deviation (%vol)
10	10.8	10.7	10,8	0.1
20	20,8	20.6	20.8	0.2
30	31.4	31.0	31.2	0.2

Remark:

Measurement Result (O2)

Items	Results
Indication Error (%)	1
Repeatability (%)	0.5

Calibration Result (CH₄)

Calibration Range (%LEL)	Reference Equipment Reading (%LEL)	*Corrected Value (%LEL)	UUT Reading (%LEL)	Deviation (%LEL)
0	0	0.0	0	0,0
5	5	5.1	5	0.1
10	10	10.2	10	0.2

Remark:

Measurement Result (CH4)

measurement result (Oria)	
Items	Results
Indication Error (%)	a1
Repeatability (%)	2.5

Note

Remarks:

- The calibration results apply to the particular unit-under-test only.

Calibrated By:


(Technician)

Approved Signatory: Guy to

^{1.0%} indicator error of reference equipment is applied

 ^{-2%} indicator error of reference equipment is applied.

^(*) Corrected Value = Reference Equipment Reading x Indicator Error of Reference Equipment



Draft 1_____AEC

Quarterly Landfill Gas Monitoring Results

								Measurement Results				Action Level			Limit Level			
Monitoring Station ID	Monitoring Locations	Date	Weather Conditions	Temperature (°C)	Start Time	End Time	Met	hane	Oxygen	Carbon Dioxide	Barometric Pressure	Methane	Oxygen	Carbon Dioxide	Methane	Oxygen	Carbon Dioxide	Remarks
							% v/v	% LEL	% v/v	% v/v	mBar (absolute)	% LEL	% v/v	% v/v	% LEL	% v/v	% v/v	
	Inside the landscaping area of Administration Building	25 Nov 2020	Sunny	24	10:03	10:05	0.0	0	20.9	< 0.1	1004							Nil
EP1-2	PCCW below-ground chamber outside Lot T1	25 Nov 2020	Sunny	24	10:16	10:18	0.0	0	20.9	< 0.1	1004							Nil
EPI-3	HGC Broadband below-ground chamber outside Lot T3	25 Nov 2020	Sunny	24	10:13	10:15	0.0	0	20.9	< 0.1	1004	> 10	< 19	> 0.5	> 20	< 18	> 1.5	Nil
FP7-1	HGC Broadband below-ground chamber outside Lot P1	25 Nov 2020	Sunny	24	10:08	10:10	0.0	0	20.9	< 0.1	1004							Nil
EP7=7	HGC Broadband below-ground chamber outside Lot P3	25 Nov 2020	Sunny	24	10:10	10:12	0.0	0	20.9	0.4	1004							Nil

Notes:

- (1) Underlined figure indicates an exceedance of Action Level
- (2) Shaded area indicates an exceedance of Limit Level

EP1-1

Date	Methan	e (% LEI	٦)	Oxyge	n (% v/v)		Carbon Di	Barometric Pressure (mBar)		
Date	Measurement	Action Level	Limit Level	Measurement	Action Level	Limit Level	Measurement	Action Level	Limit Level	Measurement
19 Mar 2020	4	10	20	20.7	19	18	< 0.1	0.5	1.5	1018
26 Jun 2020	0	10	20	20.3	19	18	< 0.1	0.5	1.5	1010
25 Aug 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004
25 Nov 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004

EP1-2

Date	Methan	e (% LEI	۲)	Oxyge	n (% v/v))	Carbon Di	Barometric Pressure (mBar)			
Date	Measurement	Action Level	Limit Level	Measurement	Action Level	. Measure		Action Level	Limit Level	Measurement	
19 Mar 2020	4	10	20	20.7	19	18	< 0.1	0.5	1.5	1018	
26 Jun 2020	0	10	20	19.7	19	18	0.1	0.5	1.5	1010	
25 Aug 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004	
25 Nov 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004	

EP1-3

Date	Methan	e (% LEI	<u>(</u> .)	Oxyge	n (% v/v))	Carbon Di	Barometric Pressure (mBar)		
Date	Measurement	Action Level	Limit Level	Measurement	Action Level	Limit Level	Measurement	Action Level	Limit Level	Measurement
19 Mar 2020	4	10	20	20.7	19	18	< 0.1	0.5	1.5	1018
26 Jun 2020	0	10	20	19.9	19	18	< 0.1	0.5	1.5	1010
25 Aug 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004
25 Nov 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004

EP2-1

Date	Methan	e (% LEI	L)	Oxyge	n (% v/v)	١	Carbon Di	Barometric Pressure (mBar)		
Date	Measurement	Action Level	Limit Level	Measurement	Action Level	Limit Level	Measurement	Action Level	Limit Level	Measurement
19 Mar 2020	4	10	20	20.7	19	18	< 0.1	0.5	1.5	1018
26 Jun 2020	0	10	20	20.1	19	18	< 0.1	0.5	1.5	1010
25 Aug 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004
25 Nov 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004

EP2-2

Date	Methan	e (% LEI	L)	Oxyge	n (% v/v))	Carbon Di	Barometric Pressure (mBar)		
Date	Measurement	Action Level	Limit Level	Measurement Action Level		Limit Level	Measurement	Action Level	Limit Level	Measurement
19 Mar 2020	4	10	20	20.7	19	18	< 0.1	0.5	1.5	1018
26 Jun 2020	0	10	20	20.0	19	18	< 0.1	0.5	1.5	1010
25 Aug 2020	0	10	20	20.9	19	18	< 0.1	0.5	1.5	1004
25 Nov 2020	0	10	20	20.9	19	18	0.4	0.5	1.5	1004



東業德勤測試顧問有限公司

ETS-TESTCONSULT LTD.

T: +852 2695 8318 F: +852 2695 3944 E: eti@ets-testconsult.com W: www.ets-testconsult.com

8/F Block B.

Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fo Tan, Hong Kong



TEST REPORT

Test Report of Landfill Gas Monitoring

Report No.

: ENA08208

Date of Issue: 13 December 2020

Page No.

Information Provided by Customer

Customer Name

: Allied Enviornmental Consultants Ltd.

Customer Address

: 27/F, Overseas Trust Bank Building, 160 Gloucester Road, Wan Chai, Hong Kong

Sample Source

: Landfill Gas Monitoring at Eco Park, Tuen Mun

Sampling Location

: EP1-1 Inside the Landscaping area of Administration Building

EP1-2 PCCW underground chamber outside Lot T1

EP1-3 HGC Broadband underground chamber outside Lot T3 EP2-1 HGC Broadband underground chamber outside Lot P1

EP2-2 HGC Broadband underground chamber outside Lot P3

: 25 November 2020

Method

: To carry out landfill gas monitoring by gas detector

Equipment

Date of Test

Reference Number

ET/EA/005/01

Manufacturer

RKI Instruments EAGLE 2

Serial Number

: E2F694


Daguille


Sampling Location	Compling Time	Barometric Pressure,	Met	hane		0 % /	
Sampling Location	Sampling Time	mBar	%v/v	%LEL	Carbon Dioxide, %v/v	Oxygen, %v/v	
EP1-1	10:03	1004	0	0	<0.1	20.9	
EP1-2	10:16	1004	0	0	<0.1	20.9	
EP1-3	10:13	1004	Ō	0	<0.1	20.9	
EP2-1	10:08	1004	0	0	<0.1	20.9	
EP2-2	10:10	1004	0	0	0.35	20.9	


Approved Signatory:


LAU, Chi Leung


This report shall not be reproduced unless with prior written approval from this laboratory.














































Remark: All < 0.1% v/v for carbon dioxide is regarded as 0.0% v/v in graphical presentation















Draft 1_____AEC



Draft 1_____AEC



	Inspection Date: 2020/10/20 Time: 9:45 Lot Number: T5 Tenant: Champway	Inspected by: Chris LO, Charles YUEN
	Lot Number. 13 Tenant. Champway	
Weat	<u>her</u>	
	Condition: Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 24 °C Humidity: ✓ High	Moderate Low
	Wind: Calm Light Breeze Strong	
1. Gei	neral_	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	Sampling report (October 2020)
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	✓ via Grease Trap
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	Follow-up Observation (1, 3-4) / New observation (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	Petrol interceptor is provided
2.13	Drainage from maintenance area discharged via oil interceptor?	
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage durin	g	√			Not required
	loading and unloading adjacent to marine frontage?					
2.15	Bulk cargo and materials packed properly?		Ш		Щ	
2.16	Temporary stockpiles covered during rainstorms?			\sqsubseteq	Щ	No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?		✓	Ш		No sand/silt is generated from the recycling process
3. Air	<u>Quality</u>		N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?			~		Valid from Feb 2018 to Feb 2023
	a) SP Licence conditions / monitoring requirements comply?			<u> </u>		
3.2	Operate without generation of noticeable odour?					
	a) If odour is detected, can the source be identified?		✓			
	b) Odourous materials covered?		✓			
	c) If odour control system is installed, is it operating normally?			√		
3.3	Dusty materials dampened prior to loading/unloading?		✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?		✓			Not required
	a) Monitoring frequency met the licence requirement?		✓			
	b) Any exceedance?		√			
	c) If exceedance is recorded, follow-up action taken?		√			
3.5	Dust-suppression measures provided where main dust-generating activities take place enclosures or regular dampening)?	(i.e.	✓			No dust-generating activity is observed
3.6	Open burning prohibited?			√		
3.7	Emission from chimney or powered plant free of black smoke?			√		
3.8	Vehicles and equipment switched off while not in use?			✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming of 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	over	✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?		✓			Not required
3.11	Air pollution control system properly maintained and function normally?			√		Regular replacement of activated carbon filter
3.12	Dust collected by any air pollution control equipment installed by tenants tested to encompliance for landfill disposal?	sure	✓			
	a) Obtained approval for the use of controlled refrigerant?		✓			
	b) If yes, record of refrigeration equipment service available?		√			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?		✓			
3.14	Public road around site entrance kept clean and free from dust?			√		
3.15	Materials transported on trucks covered?		✓			Not observed
3.16	Truck loads to a level within the side and tail boards?		✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?		✓			No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Veh	icle/equi	ipment	movem	ent
	Loading/unloading of materials	✓ Oth	ers:	n/a		
4 Wa	ste / Chemical Management					
			N T/ 2	3 7	3.7	D. I
Gener			N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?			lacksquare		



4.2	Sufficient receptacles (e.g. rubbish bins) available?		√		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not observed
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		√		
4.9	Spillage cleaned up immediately through the use of absorbent?		✓		Follow-up Observation (2, 5)
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ing of Chemical Waste				
4.11	Provision of chemical waste label?		√		
	a) Label is securely attached and visible?		√		
	b) Label is bilingual and in proper dimension?		√		
	c) Information is accurate and sufficient?		√		
Storag	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		√		
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<50L$), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity $>50L$)?		√		
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		√		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		√		
4.18	Cover provided for outdoor storage area?		√		
4.19	Chemical waste collected by licensed collector?	\checkmark			Not observed
Liquio	d Chemical Storage				
4.20	Storage area provided with permeation-proof floor or surface?		√		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		√		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
<u>5. Lai</u>	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	✓			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		✓		
6. Otl	<u>ers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		√		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		✓		

SITE INSPECTION CHECKLIST




6.5	Areas within lot for recycling activities paved with concrete?	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?	
6.7	Valid calibration certificate for any monitoring equipment?	
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	
	a) Storage area in compliance with the approved plan?	Subject to tenant's information provision
	b) Storage area is securely locked?	
	c) Total storage capacity in compliance with relevant statutory requirement?	
	d) Proper labelling provided?	
	e) Dangerous goods properly packaged?	

Remarks:

Follow-up from Previous Audits

1) Oil sheen on the perimeter drain at the oil storage tank area opposite the biodiesel processing plant was cleared up.







(Observed on 20 October 2020)

2) The oil spillage under the plant building near site office was cleared up. The broken oil pipe under the plant building is no longer in use, and will be removed from underneath the plant building.



(Observed on 23 September 2020)



(Observed on 20 October 2020)

SITE INSPECTION CHECKLIST



3) Oil spillage in the perimeter drainage next to the new filter press facility was removed



(Observed on 23 September 2020)



(Observed on 20 October 2020)

4) Oil spillage in the stormwater manhole at the vehicular access was cleared up.



(Observed on 23 September 2020)



(Observed on 20 October 2020)

5) Oil spillage at the stockpile area next to the processing plant was cleared up.



(Observed on 23 September 2020)



(Observed on 20 October 2020)

New Observations

1) Oily layer on sewage water was observed in the sewerage outside the site entrance. The tenant was requested to clear up the oil and prevent oil from entering the sewerage system. This item will be reviewed in the next inspection.



(Observed on 20 October 2020)

Signatures:

ET Representative:

..../

Name: Chris LO

Date: 2020/10/20

Operator Representative:

Name: May Wu

Date:

30 OCT 2020

Terlant Representative:

Name: Kenji Wong

Date: 13 Nov 2020

IEC Representative:

Name: Drycen Ceny

Date: 28/10/2020



	Inspection Date: 2020/11/25 Time: 10:15 Lot Number: T5 Tenant: Champway	Inspected by: Chris LO, Timmy WONG
<u>Weatl</u>	Condition: Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Moderate Low
1. Gei	neral_	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	✓ Sampling report (October 2020)
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	✓ via Grease Trap
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	Follow-up Observation (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	Petrol interceptor is provided
2.13	Drainage from maintenance area discharged via oil interceptor?	✓
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓		Not required
	loading and unloading adjacent to marine frontage?			
2.15	Bulk cargo and materials packed properly?			
2.16	Temporary stockpiles covered during rainstorms?	<u> </u>		No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓		No sand/silt is generated from the recycling process
3. Air	<u>Quality</u>	N/A Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?			Valid from Feb 2018 to Feb 2023
	a) SP Licence conditions / monitoring requirements comply?			
3.2	Operate without generation of noticeable odour?			
	a) If odour is detected, can the source be identified?	✓		
	b) Odourous materials covered?	✓		
	c) If odour control system is installed, is it operating normally?			
3.3	Dusty materials dampened prior to loading/unloading?	✓		No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓		Not required
	a) Monitoring frequency met the licence requirement?	✓		
	b) Any exceedance?	✓		
	c) If exceedance is recorded, follow-up action taken?	✓		
3.5	Dust-suppression measures provided where main dust-generating activities take place (enclosures or regular dampening)?	e. 🗸		No dust-generating activity is observed
3.6	Open burning prohibited?	✓		
3.7	Emission from chimney or powered plant free of black smoke?			
3.8	Vehicles and equipment switched off while not in use?	✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	√		Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓		Not required
3.11	Air pollution control system properly maintained and function normally?			Regular replacement of activated carbon filter
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensucompliance for landfill disposal?	· V		
	a) Obtained approval for the use of controlled refrigerant?	✓		
	b) If yes, record of refrigeration equipment service available?	✓		_
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓		
3.14	Public road around site entrance kept clean and free from dust?			
3.15	Materials transported on trucks covered?	✓		Not observed
3.16	Truck loads to a level within the side and tail boards?	✓		Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	✓		No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equipmen	it movem	ent
	Loading/unloading of materials	✓ Others: n/a		
4. Wa	ste / Chemical Management			
Gener	al	N/A Yes	No	Remarks
	Registered as chemical waste producer?			



4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	√			Not observed
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		√		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?			✓	New Observation (1-3)
4.10	Obtained approval for the use of chemical waste container >450L?	√			
Labell	ing of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Storag	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<50L$), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity $>50L$)?		✓		
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?	✓			Not observed
Liquio	l Chemical Storage				
4.20	Storage area provided with permeation-proof floor or surface?		√		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
5. La	adfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	✓			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		✓		
6. Otl	ners_	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		✓	\Box	
6.3	Site lighting designed to avoid glare to surrounding receivers?			\equiv	
6.4	Materials and machinery stored in an orderly manner?	\Box	✓	\equiv	

SITE INSPECTION CHECKLIST



6.5	Areas within lot for recycling activities paved with concrete?		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		
6.7	Valid calibration certificate for any monitoring equipment?	✓	
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?		
	a) Storage area in compliance with the approved plan?		Subject to tenant's information provision
	b) Storage area is securely locked?		
	c) Total storage capacity in compliance with relevant statutory requirement?		
	d) Proper labelling provided?		
	e) Dangerous goods properly packaged?		

Remarks:

Follow-up from Previous Audits

1) Oily layer on sewage water in the sewerage outside the site entrance was cleared.



(Observed on 20 October 2020)



(Observed on 25 November 2020)

New Observations

1) Oil stain was observed near the bins in the refuse area at the front of the processing plant. The tenant was requested to clear up the oil. This item will be reviewed in the next inspection.



(Observed on 25 November 2020)

Oil stain was observed near the tanks in the stockpile area near the site office. The tenant was requested to clear up the oil.
 This item will be reviewed in the next inspection.



(Observed on 25 November 2020)

SITE INSPECTION CHECKLIST



The perimeter drainage was observed to have been blocked. The tenant was requested to clear up the blockage to avoid overflow. 3) This item will be reviewed in the next inspection.



(Observed on 25 November 2020)

Signatures:

ET Representative:

Operator Representative:

Tenant Representative:

IEC Representative:

Name: Chris LO

Date: 2020/11/25

Name: Date:

May Wu 3 Dec 2020 Name: Kenji Wong

Date: 4 Dec 2020

Name:

Date:

02/12/2020



	00004045	
	Inspection Date: 2020/12/17 Time: 9:50 Lot Number: T5 Tenant: Champway	Inspected by: Chris LO, Timmy WONG
Weatl	<u>ner</u>	
	Condition: ✓ Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 12 °C Humidity: \checkmark High	Moderate Low
	Wind: Calm Light Breeze Strong	
1. Gei	neral_	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2 Wo	ton Onelite	N/A Yes No Remarks
	ter Quality	
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	Sampling report (November 2020)
	b) Monitoring frequency met the licence requirement?c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	via Grease Trap
2.2	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	Petrol interceptor is provided
2.13	Drainage from maintenance area discharged via oil interceptor?	
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	[✓			Not required
2.15	loading and unloading adjacent to marine frontage?	Г				
	Bulk cargo and materials packed properly?	L				- <mark></mark>
	Temporary stockpiles covered during rainstorms?	L	<u> </u>			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	<u>.</u>	<u> </u>			No sand/silt is generated from the recycling process
<u>3. Air</u>	Quality		N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?			✓		Valid from Feb 2018 to Feb 2023
	a) SP Licence conditions / monitoring requirements comply?			✓		
3.2	Operate without generation of noticeable odour?			✓		
	a) If odour is detected, can the source be identified?		✓			·
	b) Odourous materials covered?		✓			·
	c) If odour control system is installed, is it operating normally?	[✓		
3.3	Dusty materials dampened prior to loading/unloading?	[✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?		✓			Not required
	a) Monitoring frequency met the licence requirement?		✓			
	b) Any exceedance?		✓			
	c) If exceedance is recorded, follow-up action taken?		✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (enclosures or regular dampening)?	i.e.	✓			No dust-generating activity is observed
3.6	Open burning prohibited?			✓		
3.7	Emission from chimney or powered plant free of black smoke?	[✓		
3.8	Vehicles and equipment switched off while not in use?	[✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming ov 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	er	✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	[✓			Not required
3.11	Air pollution control system properly maintained and function normally?	[✓		Regular replacement of activated carbon filter
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensu compliance for landfill disposal?	re	✓			
	a) Obtained approval for the use of controlled refrigerant?		✓			
	b) If yes, record of refrigeration equipment service available?	[✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	[✓			
3.14	Public road around site entrance kept clean and free from dust?	[✓		·
3.15	Materials transported on trucks covered?	[✓			Not observed
3.16	Truck loads to a level within the side and tail boards?		✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	[✓			No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehic	cle/equ	ipment	movem	eent
	Loading/unloading of materials	✓ Other	s:	n/a		
4. Wa	ste / Chemical Management					
Gener	<u>al</u>		N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	[√		



4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not observed
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		√		
4.9	Spillage cleaned up immediately through the use of absorbent?			✓	Follow-up observation (1-3) / New Observation (1)
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Labell	ing of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Storag	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<$ 50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity $>$ 50L)?		✓		
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?	✓			Not observed
Liquio	l Chemical Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
<u>5. Laı</u>	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	✓			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		✓		
6. Otl	ners_	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		√		

SITE INSPECTION CHECKLIST



6.5	Areas within lot for recycling activities paved with concrete?		✓	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		✓	
6.7	Valid calibration certificate for any monitoring equipment?	✓		
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?		✓	
	a) Storage area in compliance with the approved plan?	✓		Subject to tenant's information provision
	b) Storage area is securely locked?		✓	
	c) Total storage capacity in compliance with relevant statutory requirement?	✓		
	d) Proper labelling provided?		✓	
	e) Dangerous goods properly packaged?	✓		

Remarks:

Follow-up from Previous Audits

Oil stain was still observed near the bins in the refuse area at the front of the processing plant. The tenant was requested to clear up the oil. This item will be reviewed in the next inspection.



(Observed on 25 November 2020)



(Observed on 17 December 2020)

2) Oil stain was still observed near the tanks in the stockpile area near the site office. The tenant was requested to clear up the oil. This item will be reviewed in the next inspection.



(Observed on 25 November 2020)




(Observed on 17 December 2020)

SITE INSPECTION CHECKLIST



The perimeter drainage was still observed to have been blocked. In addition, oil and oil sludge were also observed in the drainage. 3) The tenant was requested to clear up the blockage and oil to avoid overflow and pollution. This item will be reviewed in the next inspection.







(Observed on 17 December 2020)

New Observations

Activated carbon was observed to have been spilled all over the floor. The tenant was requested to better monitor the condition of material storage. 1) This item will be reviewed in the next inspection.



(Observed on 17 December 2020)

Signatures:

ET Representative:

Name: Chris LO Date: 2020/12/17

Operator Representative:

Date:

May Wu


2 4 DEC 2020

Tenant Representative:

Name: Kenji Wong

Date: 29 Dec 2020

IEC Representative:



Draft 1_____AEC



	Inspection Date: 2020/10/20 Time: 10:25 Lot Number: T4 Tenant: Hong Kong Biomass (Wong Biomass)	Inspected by: Chris LO, Charles YUEN
	Lot Number. 14 Tenant. Hong Kong Diomass (W.	0001)
Weat	<u>her</u>	
	Condition:	Rain Storm Hazy Moderate Low
	Wind: Calm Light Breeze Strong	
1. Ge	nera <u>l</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	iter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is generated from the recycling process
	a) Sampling record available?	/
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	/
	d) If exceedance is recorded, any follow-up action taken?	/
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	/
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓ Not required



	loading and unloading adjacent to marine frontage?	
2.15	Bulk cargo and materials packed properly?	
2.16	Temporary stockpiles covered during rainstorms?	No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?	No sand/silt is generated from the recycling process
3. Air	Quality	N/A Yes No Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓ Not required
	a) SP Licence conditions / monitoring requirements comply?	
3.2	Operate without generation of noticeable odour?	
	a) If odour is detected, can the source be identified?	
	b) Odourous materials covered?	
	c) If odour control system is installed, is it operating normally?	
3.3	Dusty materials dampened prior to loading/unloading?	Dampening of waste wood affects the wood quality and is therefore unsuitable
3.4	Dust monitoring record available?	✓ Not required
	a) Monitoring frequency met the licence requirement?	
	b) Any exceedance?	
	c) If exceedance is recorded, follow-up action taken?	
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?	e.
3.6	Open burning prohibited?	
3.7	Emission from chimney or powered plant free of black smoke?	
3.8	Vehicles and equipment switched off while not in use?	
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	Not required
3.11	Air pollution control system properly maintained and function normally?	
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	
	a) Obtained approval for the use of controlled refrigerant?	
	b) If yes, record of refrigeration equipment service available?	/
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	/
3.14	Public road around site entrance kept clean and free from dust?	
3.15	Materials transported on trucks covered?	✓ Not observed
3.16	Truck loads to a level within the side and tail boards?	✓ Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	Dampening of waste wood affects the wood quality and is therefore unsuitable
3.18	Major dust source(s): Wind erosion	Vehicle/equipment movement
	Loading/unloading of materials	✓ Others: n/a

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gene	ral	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	\checkmark			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	iging of Chemical Waste				
4.7	Stored in suitable container?	✓			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	✓			
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	✓			
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	✓			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	✓			
4.18	Cover provided for outdoor storage area?	✓			
4.19	Chemical waste collected by licensed collector?	✓			
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	✓			
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	√			
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?		√		
5.2	Smoking and open fires prohibited?		✓		

Date: 2020/10/20

SITE INSPECTION CHECKLIST



6. Ot	<u>hers</u>			N/A	Yes	No	Remarks	
6.1	Works confined within lot bour	ndaries?			✓			
6.2	Damage to surrounding areas a	voided?			✓			
6.3	Site lighting designed to avoid	glare to surrounding receivers?		✓				
6.4	Materials and machinery stored	l in an orderly manner?			✓			
6.5	Areas within lot for recycling a	ctivities paved with concrete?			✓			
6.6	Potential stagnant pools cleared	d and mosquito breeding prevented?			✓			
6.7	Valid calibration certificate for	any monitoring equipment?		✓			No monitoring is required	
6.8	Valid licence(s) obtained for m	anufacture or storage of dangerous goo	ds?	✓			Not required	
	a) Storage area in compliance v	vith the approved plan?		✓				
	b) Storage area is securely lock	ed?		✓				
	c) Total storage capacity in con	npliance with relevant statutory require	ment?	✓				
	d) Proper labelling provided?			✓				
	e) Dangerous goods properly pa	ackaged?		✓				
Rema	nrks: Observations No major environmental deficie	ency was observed.						
Signa	itures:							
	epresentative:	Operator Representative:	Tenant Representati	ive:		I	EC Representative:	
6	ing le			0		_ <	Bagan	
Name:	Chris LO	Name: May Wu	Name: Eagle I	Lam		Name		
D-4-	2020/10/20	Date:	Date: 4/11/20	020		Date:	28/10/2020	

Date:

4/11/2020

Date:

3 0 OCT 2020



	Inspection Date: 2020/11/25 Time: 9:35 Lot Number: T4 Tenant: Hong Kong Biomass (V	Inspected by: Chris LO, Timmy WONG	
Weat	hou		
weat	Condition:	Rain Storm Haz	y
1. Ge	<u>neral</u>	N/A Yes No Remarks	
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required	I
1.2	Environmental Policy documented?	✓ UPML's Environmental Poli	icy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed	
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed	
1.5	All recycling processes in operation have been approved by WRG of EPD?		
1.6	Any record of complaint or prosecution?		
2 W	oton Quality	N/A Yes No Remarks	
	ater Quality	No wastewater is generated	from the
2.1	Valid Effluent Discharge Licence available?	recycling process	
	a) Sampling record available?		
	b) Monitoring frequency met the licence requirement?		
	c) Monitoring result comply with the licence requirement?		
	d) If exceedance is recorded, any follow-up action taken?		
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?		
	a) Adequate capacity?		
	b) Properly maintained and function normally?		
2.3	Surface run-off control measures in place and adequately maintained?		
2.4	Surface run-off discharging into drainage system?		
2.5	All manholes covered?		
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?		
2.7	Storage of materials and equipment located away from water bodies?		
2.8	Drainage system well maintained to prevent flooding or overflow?		. 1 . 6
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low recontamination Contamination	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for u needed.	ise by tenant if
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not	observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is of	oserved
2.13	Drainage from maintenance area discharged via oil interceptor?	Not required	
	a) Oil and grease removed regularly?		
	b) Collected by licensed collector?		
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓ Not required	



	loading and unloading adjacent to marine frontage?					
2.15	Bulk cargo and materials packed properly?			✓		
2.16	Temporary stockpiles covered during rainstorms?		/			No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?		/			No sand/silt is generated from the recycling process
3. Air	Quality	N	/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?		/			Not required
	a) SP Licence conditions / monitoring requirements comply?		/			
3.2	Operate without generation of noticeable odour?			✓		
	a) If odour is detected, can the source be identified?			✓		
	b) Odourous materials covered?					
	c) If odour control system is installed, is it operating normally?		/			
3.3	Dusty materials dampened prior to loading/unloading?	_	/			Dampening of waste wood affects the wood quality and is therefore unsuitable
3.4	Dust monitoring record available?	_	/			Not required
	a) Monitoring frequency met the licence requirement?		/			
	b) Any exceedance?	_	/			
	c) If exceedance is recorded, follow-up action taken?		/			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?	·		✓		
3.6	Open burning prohibited?			✓		
3.7	Emission from chimney or powered plant free of black smoke?			✓		
3.8	Vehicles and equipment switched off while not in use?			✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?					Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?		/			Not required
3.11	Air pollution control system properly maintained and function normally?			✓		·
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?		/			
	a) Obtained approval for the use of controlled refrigerant?		/			
	b) If yes, record of refrigeration equipment service available?	_	/			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?		/			
3.14	Public road around site entrance kept clean and free from dust?			✓		
3.15	Materials transported on trucks covered?	_	/			Not observed
3.16	Truck loads to a level within the side and tail boards?		/			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	_	/			Dampening of waste wood affects the wood quality and is therefore unsuitable
3.18	Major dust source(s): Wind erosion	Vehicle	/equ	ipment	movem	ent
	Loading/unloading of materials	✓ Others:		n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	a <u>l</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	✓			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?	✓			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	✓			
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Storag	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	✓			
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	√			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	✓			
4.18	Cover provided for outdoor storage area?	✓			
4.19	Chemical waste collected by licensed collector?	✓			
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	√			
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?		✓		
5.2	Smoking and open fires prohibited?		<u></u> ✓	\equiv	
	8				

SITE INSPECTION CHECKLIST



<u>6. Otl</u>	<u>ners</u>			N/A	Yes 1	No Remarks
6.1	Works confined within lot bo	undaries?			✓	
6.2	Damage to surrounding areas	avoided?			√	
6.3	Site lighting designed to avoi	d glare to surrounding receivers?		✓		
6.4	Materials and machinery stor	ed in an orderly manner?			✓	
6.5	Areas within lot for recycling	activities paved with concrete?			✓	
6.6	Potential stagnant pools clear	ed and mosquito breeding prevented?			✓	
6.7	Valid calibration certificate f	or any monitoring equipment?		✓		No monitoring is required
6.8	Valid licence(s) obtained for	manufacture or storage of dangerous goo	ods?	✓		Not required
	a) Storage area in compliance	with the approved plan?		✓		
	b) Storage area is securely lo	cked?		✓		
	c) Total storage capacity in c	ompliance with relevant statutory require	ement?	✓		
	d) Proper labelling provided?			✓		
	e) Dangerous goods properly	packaged?		✓		
Rema	orks: Observations No major environmental defi	ciency was observed.				
	,	•				
Signa	tures:					
ET R	epresentative:	Operator Representative:	Tenant Representative:			IEC Representative:
6	m Col	July		2		Buyun
Name:	Chris LO	Name: May Wu 3 Dec 2020	Name: Eagle Lan	n	V	Vame: Byen Yeary
Date:	2020/11/25	Date: 3 Dec 2020	Date: 10/12/2020)	I	Date: OL 1121 2000



	Inspection Date: 2020/12/17 Time: 10:30 Lot Number: T4 Tenant: Hong Kong Biomass (World Biomass)	Inspected by: Chris LO, Timmy WONG
Weat	her_	
	Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 12 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	neral_	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ter Quality	N/A Yes No Remarks No wastewater is generated from the
2.1	Valid Effluent Discharge Licence available?	recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓ Not required



	loading and unloading adjacent to marine frontage?					
2.15	Bulk cargo and materials packed properly?			√		
2.16	Temporary stockpiles covered during rainstorms?		✓			No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?		✓			No sand/silt is generated from the recycling process
2 4:	Quality		N/A	Vac	No	Remarks
5. AII	Quality	_	IN/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	L	✓			Not required
	a) SP Licence conditions / monitoring requirements comply?		✓			
3.2	Operate without generation of noticeable odour?		✓			No operation is observed during inspection
	a) If odour is detected, can the source be identified?		✓			
	b) Odourous materials covered?		✓			
	c) If odour control system is installed, is it operating normally?		✓			
3.3	Dusty materials dampened prior to loading/unloading?		✓			Dampening of waste wood affects the wood quality and is therefore unsuitable
3.4	Dust monitoring record available?		✓			Not required
	a) Monitoring frequency met the licence requirement?		✓			
	b) Any exceedance?		✓			
	c) If exceedance is recorded, follow-up action taken?		✓			<u> </u>
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?	е.		✓		
3.6	Open burning prohibited?			√		
3.7	Emission from chimney or powered plant free of black smoke?		✓			No operation is observed during inspection
3.8	Vehicles and equipment switched off while not in use?			✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	r [✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?		✓			Not required
3.11	Air pollution control system properly maintained and function normally?		✓			No operation is observed during inspection
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?		✓			
	a) Obtained approval for the use of controlled refrigerant?		✓			
	b) If yes, record of refrigeration equipment service available?		✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?		✓			
3.14	Public road around site entrance kept clean and free from dust?			✓		
3.15	Materials transported on trucks covered?		✓			Not observed
3.16	Truck loads to a level within the side and tail boards?	Γ	✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	Γ	✓			Dampening of waste wood affects the wood quality and is therefore unsuitable
	Major dust source(s): Wind erosion	Vehic	le/equ	ipment	movem	ent
	Loading/unloading of materials	✓ Others	s:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	a <u>l</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	✓			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?	✓			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	✓			
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Storag	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	✓			
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	√			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	✓			
4.18	Cover provided for outdoor storage area?	✓			
4.19	Chemical waste collected by licensed collector?	✓			
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	√			
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?		✓		
5.2	Smoking and open fires prohibited?		<u></u> ✓	\equiv	
	8				

Name: Chris LO

Date: 2020/12/17

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>ners</u>			N/A	Yes	No	Remarks
6.1	Works confined within lot bour	ndaries?			√		
6.2	Damage to surrounding areas a	voided?			✓		
6.3	Site lighting designed to avoid	glare to surrounding receivers?		✓			
6.4	Materials and machinery stored	l in an orderly manner?			✓		
6.5	Areas within lot for recycling a	ctivities paved with concrete?			✓		
6.6	Potential stagnant pools cleared	I and mosquito breeding prevented?			✓		
6.7	Valid calibration certificate for	any monitoring equipment?		✓			No monitoring is required
6.8	Valid licence(s) obtained for m	anufacture or storage of dangerous goods?		✓			Not required
	a) Storage area in compliance v	with the approved plan?		✓			
	b) Storage area is securely lock	ed?		✓			
	c) Total storage capacity in cor	npliance with relevant statutory requirement	?	✓			
	d) Proper labelling provided?			\checkmark			
	e) Dangerous goods properly p	ackaged?		✓			_
Rema	orks: Observations No major environmental defici	ency was observed.					
Signa	tures:						
ET R	epresentative:	Operator Representative:	Tenant Representative:				IEC Representative:
0				0		-	
Name:	Chris LO	Name: May Wu	Name: Eagle La	m]	Name:

Date:


29 Dec 2020

2 4 DEC 2020

Date:

Name:

Date:



Draft 1_____AEC



	Inspection Date: 2020/10/20 Time: 11:45 Lot Number: T1 Tenant: HP Telford	Inspected by: Chris LO, Charles YUEN	
West	hor		
Weat	Condition:	Rain Storm Hazy Moderate Low	
<u>1. Ge</u>	<u>neral</u>	N/A Yes No Remarks	
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required.	
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed	red
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed	
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed	
1.5	All recycling processes in operation have been approved by WRG of EPD?		
1.6	Any record of complaint or prosecution?		
2. Wa	nter Quality	N/A Yes No Remarks No wastewater is generated from recycling	ling
2.1	Valid Effluent Discharge Licence available?	process	
	a) Sampling record available?		
	b) Monitoring frequency met the licence requirement?		
	c) Monitoring result comply with the licence requirement?	<u> </u>	
	d) If exceedance is recorded, any follow-up action taken?		
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?		
	a) Adequate capacity?		
	b) Properly maintained and function normally?		
2.3	Surface run-off control measures in place and adequately maintained?		
2.4	Surface run-off discharging into drainage system?		
2.5	All manholes covered?		
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?		
2.7	Storage of materials and equipment located away from water bodies?		
2.8	Drainage system well maintained to prevent flooding or overflow?		
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.	t if
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed	
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed	



2.13	Drainage from maintenance area discharged via oil interceptor?	✓			Not required
	a) Oil and grease removed regularly?	√			
	b) Collected by licensed collector?	✓			
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓			Not required
2.15	loading and unloading adjacent to marine frontage?				
	Bulk cargo and materials packed properly?				
	Temporary stockpiles covered during rainstorms?	Ľ	Щ		No dusty stockpile is observed No sand/silt is generated from the recycling
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			process
3. Air	<u>Quality</u>	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	\checkmark			Not required
	a) SP Licence conditions / monitoring requirements comply?	\checkmark			-
3.2	Operate without generation of noticeable odour?	✓			No operation is observed during inspection
	a) If odour is detected, can the source be identified?	√			
	b) Odourous materials covered?	√			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	√			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	√			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?	✓			No operation is observed during inspection
3.6	Open burning prohibited?		√		
3.7	Emission from chimney or powered plant free of black smoke?	✓			No operation is observed during inspection
3.8	Vehicles and equipment switched off while not in use?		√		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	√			Not required
3.11	Air pollution control system properly maintained and function normally?	√			No operation is observed during inspection
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	✓			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			-
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not observed



3.16	Truck loads to a level within the side and tail boards?		✓			Not observed
3.17 \$	Stockpiles of dusty materials covered or regularly watered?		✓			No stockpile of dusty material is observed
3.18 N	Major dust source(s): Wind erosion	Vehi	cle/equ	ipment	movem	ent
	Loading/unloading of materials	✓ Othe	rs:	n/a		
4. Was	ste / Chemical Management					
Genera	<u>.1</u>		N/A	Yes	No	Remarks
4.1 I	Registered as chemical waste producer?		√			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?			✓		
4.3 I	Disposed of regularly and properly?			✓		- <u></u> -
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?			√		
4.5 I	Records of quantities of waste generated, recycled and disposed properly kept?			√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?		√			
Packag	ring of Chemical Waste					
4.7	Stored in suitable container?		√			
4.8	Container properly closed or sealed?		√			
4.9	Spillage cleaned up immediately through the use of absorbent?		✓			
4.10	Obtained approval for the use of chemical waste container >450L?		✓			
<u>Labellii</u>	ng of Chemical Waste					
4.11 I	Provision of chemical waste label?		✓			
г	a) Label is securely attached and visible?		✓			
ł	b) Label is bilingual and in proper dimension?		✓			
C	c) Information is accurate and sufficient?		✓			
Storage	e of Chemical Waste					
4.12 I	Proper "Chemical Waste" sign displayed?		√			
4.13 I	Incompatible wastes separated by impermeable partition?		√			
	Containers kept in cabinet or receptacle of suitable material (if quantity $<$ 50L), or provide with drip trays capable of storing 110% of the volume of the largest container (if quantity		✓			
	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		√			
4.16 I	Properly stored and locked in designated area with adequate ventilation?		√			
4.17	Storage area paved with concrete and kept clean and dry?		√			
4.18	Cover provided for outdoor storage area?		√			
4.19	Chemical waste collected by licensed collector?		✓			
Liquid	Waste Storage					
4.20 \$	Storage area provided with permeation-proof floor or surface?		√			
	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓			



4.22	Walls or partitions of stacked container storage area constructed of imperme	eable material?
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A Yes No Remarks
5.1	Alert workers and visitors of possible LFG hazards?	
5.2	Smoking and open fires prohibited?	
6. Ot	ners	N/A Yes No Remarks
6.1	Works confined within lot boundaries?	
6.2	Damage to surrounding areas avoided?	
6.3	Site lighting designed to avoid glare to surrounding receivers?	
6.4	Materials and machinery stored in an orderly manner?	
6.5	Areas within lot for recycling activities paved with concrete?	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?	
6.7	Valid calibration certificate for any monitoring equipment?	✓ Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓ Not required
	a) Storage area in compliance with the approved plan?	
	b) Storage area is securely locked?	
	c) Total storage capacity in compliance with relevant statutory requirement	?
	d) Proper labelling provided?	
	e) Dangerous goods properly packaged?	✓
Rema	rks:	
New	Observation	
	No major environmental deficiency was observed.	
Signa	tures:	
	epresentative: Operator Representative:	Tenant Representative: IEC Representative:
6	my la more	Ant.
Name:	Chris LO Name: May Wu	Name: MRS. LEG Name:
Date:	2020/10/20 Date: 3 0 OCT 2020	Date: 4/11/2020 Date:



	Inspection Date: 2020/11/25 Time: 12:15 Lot Number: T1 Tenant: HP Telford	Inspected by: Chris LO, Timmy WONG
Weat	Mer Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	nera <u>l</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	<u>iter Quality</u>	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is generated from recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed



2.13	Drainage from maintenance area discharged via oil interceptor?	✓			Not required
	a) Oil and grease removed regularly?	✓			
	b) Collected by licensed collector?	✓			
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?		✓		
2.16	Temporary stockpiles covered during rainstorms?	✓			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			No sand/silt is generated from the recycling process
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓			Not required
	a) SP Licence conditions / monitoring requirements comply?	✓			
3.2	Operate without generation of noticeable odour?	✓			No operation is observed during inspection
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	\checkmark			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?	✓			No operation is observed during inspection
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?	✓			No operation is observed during inspection
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	√			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	√			Not required
3.11	Air pollution control system properly maintained and function normally?	\checkmark			No operation is observed during inspection
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	✓			
	a) Obtained approval for the use of controlled refrigerant?	√			
	b) If yes, record of refrigeration equipment service available?	√			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not observed



3.16	5 Truck loads to a level within the side and tail boards?		✓	lШ		Not observed	
3.17	7 Stockpiles of dusty materials covered or regularly watered?		✓			No stockpile of dusty material is observed	
3.18	Major dust source(s): Wind erosion		Vehicle/eq	uipment	movem	ent	
	Loading/unloading of mat	erials	✓ Others:	n/a			
4. W:	Vaste / Chemical Management						
Gene	<u>eral</u>		N/A	Yes	No	Remarks	
4.1	Registered as chemical waste producer?		✓			No chemical waste is observed	
4.2	Sufficient receptacles (e.g. rubbish bins) available?			✓			
4.3	Disposed of regularly and properly?			✓			
4.4	Sorting of materials on-site for reuse or disposal to designate	ed outlet?		✓			
4.5	Records of quantities of waste generated, recycled and dispo	sed properly kept?		✓		Verified via quarterly report	
4.6	Collection of sludge by licensed collector at regular intervals	?	✓				
Packa	saging of Chemical Waste						
4.7	Stored in suitable container?		✓				
4.8	Container properly closed or sealed?		✓				
4.9	Spillage cleaned up immediately through the use of absorber	ıt?	✓				
4.10	Obtained approval for the use of chemical waste container >	450L?	✓				
<u>Label</u>	elling of Chemical Waste						
4.11	1 Provision of chemical waste label?		✓				
	a) Label is securely attached and visible?		✓				
	b) Label is bilingual and in proper dimension?		✓				
	c) Information is accurate and sufficient?		✓				
Stora	age of Chemical Waste						
4.12	2 Proper "Chemical Waste" sign displayed?		✓				
4.13	3 Incompatible wastes separated by impermeable partition?		✓				
4.14	4 Containers kept in cabinet or receptacle of suitable material with drip trays capable of storing 110% of the volume of the					l	
4.15	5 Enclosed on 3 sides with no less than 2m in height or height of containers?	of tallest container / stack	✓			·	
4.16	6 Properly stored and locked in designated area with adequate	ventilation?	✓				
4.17	7 Storage area paved with concrete and kept clean and dry?		✓				
4.18	8 Cover provided for outdoor storage area?		✓				
4.19	O Chemical waste collected by licensed collector?		✓				
<u>Liqui</u>	Liquid Waste Storage						
4.20	Storage area provided with permeation-proof floor or surface	e?	✓				
4.21	1 Capacity of retention structure sufficient to accommodate co- largest container or 20% volume of the material in storage?	ntents of the	✓			·	

SITE INSPECTION CHECKLIST



4.22	Walls or partitions of stacked container storage area constructed of impermea	able material?	
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A Yes No Remarks	
5.1	Alert workers and visitors of possible LFG hazards?		
5.2	Smoking and open fires prohibited?		
<u>6. Ot</u>	<u>hers</u>	N/A Yes No Remarks	
6.1	Works confined within lot boundaries?		
6.2	Damage to surrounding areas avoided?		
6.3	Site lighting designed to avoid glare to surrounding receivers?		
6.4	Materials and machinery stored in an orderly manner?		
6.5	Areas within lot for recycling activities paved with concrete?		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		
6.7	Valid calibration certificate for any monitoring equipment?	✓ Not required	
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓ Not required	
	a) Storage area in compliance with the approved plan?	<u> </u>	
	b) Storage area is securely locked?		
	c) Total storage capacity in compliance with relevant statutory requirement?		
	d) Proper labelling provided?		
	e) Dangerous goods properly packaged?		
Rema	<u>rks:</u>		
New	Observation		
	No major environmental deficiency was observed.		
Signa	tures:		
ET R	epresentative: Operator Representative:	Tenant Representative: IEC Representative:	
0	Chris LO Name: May Wu Na	Ben Burn Lee MING TAK Rame: Burn June	
	3 Dec 2020	nte: 3-12-2020 Date: 021 121 1000	



	Inspection Date: 2020/12/17 Time: 11:45 Lot Number: T1 Tenant: HP Telford	Inspected by: Chris LO, Timmy WONG
Weat	Mer Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 12 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	neral_	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is generated from recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed



2.13	Drainage from maintenance area discharged via oil interceptor?	\checkmark			Not required
	a) Oil and grease removed regularly?	\checkmark			
	b) Collected by licensed collector?	✓			
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?		✓		
2.16	Temporary stockpiles covered during rainstorms?	\checkmark			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			No sand/silt is generated from the recycling process
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	\checkmark			Not required
	a) SP Licence conditions / monitoring requirements comply?	\checkmark			
3.2	Operate without generation of noticeable odour?	✓			No operation is observed during inspection
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?	✓			No operation is observed during inspection
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?	\checkmark			No operation is observed during inspection
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			Not required
3.11	Air pollution control system properly maintained and function normally?	✓			No operation is observed during inspection
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	√			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not observed




3.16	5 Truck loads to a level within the side and tail boards?		✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?		✓			No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion		Vehicle/eq	uipment 1	movem	ent
	Loading/unloading of mater	rials	✓ Others:	n/a		
4. Wa	aste / Chemical Management					
Gene	<u>eral</u>		N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?			✓		
4.3	Disposed of regularly and properly?			✓		
4.4	Sorting of materials on-site for reuse or disposal to designated	outlet?		√		
4.5	Records of quantities of waste generated, recycled and dispose	ed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?		✓			
Packa	aging of Chemical Waste					
4.7	Stored in suitable container?		✓			
4.8	Container properly closed or sealed?		✓			
4.9	Spillage cleaned up immediately through the use of absorbent	?	✓			
4.10	Obtained approval for the use of chemical waste container >4.	50L?	✓			
Label	elling of Chemical Waste					
4.11	Provision of chemical waste label?		✓			
	a) Label is securely attached and visible?		✓			
	b) Label is bilingual and in proper dimension?		✓			
	c) Information is accurate and sufficient?		✓			
Stora	age of Chemical Waste					
4.12	2 Proper "Chemical Waste" sign displayed?		✓			
4.13	3 Incompatible wastes separated by impermeable partition?		✓			
4.14	Containers kept in cabinet or receptacle of suitable material (i with drip trays capable of storing 110% of the volume of the l					
4.15	Enclosed on 3 sides with no less than 2m in height or height or of containers?	f tallest container / stack	✓			
4.16	6 Properly stored and locked in designated area with adequate v	entilation?	✓			
4.17	7 Storage area paved with concrete and kept clean and dry?		✓			
4.18	3 Cover provided for outdoor storage area?		✓			
4.19	Chemical waste collected by licensed collector?		✓			
<u>Liqui</u>	id Waste Storage					
4.20	Storage area provided with permeation-proof floor or surface?	•	\checkmark			
4.21	Capacity of retention structure sufficient to accommodate con largest container or 20% volume of the material in storage?	tents of the	✓			

SITE INSPECTION CHECKLIST



4.22	Walls or partitions of stacked container storage area constructed of impermeab	ole material?
5. Lai	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A Yes No Remarks
5.1	Alert workers and visitors of possible LFG hazards?	
5.2	Smoking and open fires prohibited?	
6. Otl	<u>iers</u>	N/A Yes No Remarks
6.1	Works confined within lot boundaries?	
6.2	Damage to surrounding areas avoided?	
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓ □ □
6.4	Materials and machinery stored in an orderly manner?	
6.5	Areas within lot for recycling activities paved with concrete?	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?	
6.7	Valid calibration certificate for any monitoring equipment?	Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	Not required
	a) Storage area in compliance with the approved plan?	
	b) Storage area is securely locked?	
	c) Total storage capacity in compliance with relevant statutory requirement?	
	d) Proper labelling provided?	
	e) Dangerous goods properly packaged?	
Rema	rks:	
New 0	<u>Observation</u>	
	No major environmental deficiency was observed.	
Signa	tures:	
ET Re	presentative: Operator Representative: T	Tenant Representative: IEC Representative:
1	and a more	of /
Name:	Chris LO Name: May Wu	Name: LEZ HING TAK Name:
Date:	2020/12/17 Date: 2 4 DEC 2020	Date: 24-12-20 Date:



Draft 1_____AEC

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/10/20 Time: 11:15 Lot Number: P13 Tenant: Chung Yue	Inspected by: Chris LO, Charles YUEN
Weat	<u>her</u>	
	Condition:	Rain Storm Hazy Moderate Low
1. Ge	neral	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. W	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is discharged from recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	



2.15	Bulk cargo and materials packed properly?			✓		
2.16	Temporary stockpiles covered during rainstorms?		✓			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?		✓			No sand/silt is generated from the recycling process
			27/4	**		P. 1
3. Aii	· Quality		N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?		✓			Not required
	a) SP Licence conditions/monitoring requirements comply?		✓			
3.2	Operate without generation of noticeable odour?			✓		
	a) If odour is detected, can the source be identified?		\checkmark			
	b) Odourous materials covered?		✓			
	c) If odour control system is installed, is it operating normally?		✓			
3.3	Dusty materials dampened prior to loading/unloading?			✓		
3.4	Dust monitoring record available?		✓			Not required
	a) Monitoring frequency met the licence requirement?		✓			
	b) Any exceedance?		✓			
	c) If exceedance is recorded, follow-up action taken?		✓			
3.5	$Dust-suppression\ measures\ provided\ where\ main\ dust-generating\ activities\ take\ place\ (i.e.\ enclosures\ or\ regular\ dampening)?$			✓		
3.6	Open burning prohibited?			✓		
3.7	Emission from chimney or powered plant free of black smoke?			✓		
3.8	Vehicles and equipment switched off while not in use?			✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?		✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?		√			Not required
3.11	Air pollution control system properly maintained and function normally?		✓			Not required
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?		✓			
	a) Obtained approval for the use of controlled refrigerant?		\checkmark			
	b) If yes, record of refrigeration equipment service available?		\checkmark			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?		✓			
3.14	Public road around site entrance kept clean and free from dust?			✓		
3.15	Materials transported on trucks covered?		✓			Not applicable for trucks transporting scrap steel material as observed on site.
3.16	Truck loads to a level within the side and tail boards?			√		Follow-up Observation (1)
3.17	Stockpiles of dusty materials covered or regularly watered?		✓			No dusty material is observed
3.18	Major dust source(s): Wind erosion		Vehicle/equ	ipment	movem	ent
	Loading/unloading of materials	√	Others:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	r <u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	\checkmark			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		To be verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	\checkmark			Not required
Packa	iging of Chemical Waste				
4.7	Stored in suitable container?	\checkmark			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	\checkmark			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	✓			
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	√			
4.13	Incompatible wastes separated by impermeable partition?	\checkmark			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	✓			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	√			
4.18	Cover provided for outdoor storage area?	✓			
4.19	Chemical waste collected by licensed collector?	✓			
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	√			
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
<u>5. La</u>	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	✓			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		<u>√</u>		

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A Yes No Remarks
6.1	Works confined within lot boundaries?	
6.2	Damage to surrounding areas avoided?	
6.3	Site lighting designed to avoid glare to surrounding receivers?	
6.4	Materials and machinery stored in an orderly manner?	
6.5	Areas within lot for recycling activities paved with concrete?	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?	
6.7	Valid calibration certificate for any monitoring equipment?	✓ Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓ Not required
	a) Storage area in compliance with the approved plan?	
	b) Storage area is securely locked?	
	c) Total storage capacity in compliance with relevant statutory requirement?	
	d) Proper labelling provided?	
	e) Dangerous goods properly packaged?	✓ □ □

Remarks:

Follow-up from Previous Audit

1) Loads levels of trucks were reduced.



(Observed on 23 September 2020)



(Observed on 20 October 2020)

_						
•	10	n	١t	111	es	•
v	12	116	ıı	uı	·	٠.

ET Representative:

Name: Chris LO

Date: 2020/10/20

Operator Representative:

Name: May Wu

Date:

3 0 OCT 2020

Tenant Representative:

Name: 3, 3, 48

IEC Representative:

Name:

Date:



	Inspection Date: 2020/11/25 Time: 11:45 Lot Number: P13 Tenant: Chung Yue	Inspected by: Chris LO, Timmy WONG	
Weat	<u>her</u>		
	Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low	
<u>1. Ge</u>	<u>neral</u>	N/A Yes No Remarks	
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required	
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed	l
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed	
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed	
1.5	All recycling processes in operation have been approved by WRG of EPD?		
1.6	Any record of complaint or prosecution?		
2. Wa	nter Quality	N/A Yes No Remarks	
2.1	Valid Effluent Discharge Licence available?	No wastewater is discharged from recyclin process	ıg
2.1	a) Sampling record available?		
	b) Monitoring frequency met the licence requirement?		
	c) Monitoring result comply with the licence requirement?		_
	d) If exceedance is recorded, any follow-up action taken?		
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?		
2.2	a) Adequate capacity?		
	b) Properly maintained and function normally?		_
2.2			—
	Surface run-off control measures in place and adequately maintained?		
	Surface run-off discharging into drainage system?		
2.5	All manholes covered?		—
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?		_
2.7	Storage of materials and equipment located away from water bodies?		
2.8	Drainage system well maintained to prevent flooding or overflow?		
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed	
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed	
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed	
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required	
	a) Oil and grease removed regularly?		
	b) Collected by licensed collector?		
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?		



2.15	Bulk cargo and materials packed properly?	
2.16	Temporary stockpiles covered during rainstorms?	✓ No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	No sand/silt is generated from the recycling process
3. Air	Quality	N/A Yes No Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓ Not required
	a) SP Licence conditions/monitoring requirements comply?	✓
3.2	Operate without generation of noticeable odour?	
	a) If odour is detected, can the source be identified?	V
	b) Odourous materials covered?	
	c) If odour control system is installed, is it operating normally?	/
3.3	Dusty materials dampened prior to loading/unloading?	
3.4	Dust monitoring record available?	✓ Not required
	a) Monitoring frequency met the licence requirement?	
	b) Any exceedance?	-
	c) If exceedance is recorded, follow-up action taken?	
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?	·
3.6	Open burning prohibited?	
3.7	Emission from chimney or powered plant free of black smoke?	
3.8	Vehicles and equipment switched off while not in use?	
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	Not required
3.11	Air pollution control system properly maintained and function normally?	✓ Not required
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	
	a) Obtained approval for the use of controlled refrigerant?	
	b) If yes, record of refrigeration equipment service available?	
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	
3.14	Public road around site entrance kept clean and free from dust?	
3.15	Materials transported on trucks covered?	Not applicable for trucks transporting scrap steel material as observed on site.
3.16	Truck loads to a level within the side and tail boards?	
3.17	Stockpiles of dusty materials covered or regularly watered?	✓ No dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equipment movement
	Loading/unloading of materials	Others: n/a

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	<u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	\checkmark			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		√		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		To be verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	\checkmark			Not required
Packa	iging of Chemical Waste				
4.7	Stored in suitable container?	✓			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	\checkmark			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	\checkmark			
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	✓			
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<50L$), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity $>50L$)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	✓			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	\checkmark			
4.18	Cover provided for outdoor storage area?	✓			
4.19	Chemical waste collected by licensed collector?	√			
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	√			
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	✓			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		<u>√</u>		

ET Representative:

Name: Chris LO

Date: 2020/11/25

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		✓		
6.5	Areas within lot for recycling activities paved with concrete?		✓		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		✓		
6.7	Valid calibration certificate for any monitoring equipment?	\checkmark			Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	\checkmark			Not required
	a) Storage area in compliance with the approved plan?	\checkmark			_
	b) Storage area is securely locked?	\checkmark			
	c) Total storage capacity in compliance with relevant statutory requirement?	\checkmark			_
	d) Proper labelling provided?	\checkmark			
	e) Dangerous goods properly packaged?	✓			_
Rema	nrks:				
New	<u>Observation</u>				
•	No major environmental deficiency was observed.				
Signa	itures:				

Tenant Representative:

Date:

IEC Representative:

Name

Operator Representative:

May Wu 3 Dec 2020

Name:

Date:



	Inspection Date: 2020/12/17 Time: 11:15 Lot Number: P13 Tenant: Chung Yue	Inspected by: Chris LO, Timmy WONG
Weat	<u>her</u>	
	Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 12 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	neral	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is discharged from recycling process
2.1	a) Sampling record available?	[] [] process
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring regulately met the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
22	Provision of wastewater treatment facility (WTF) prior to discharge?	
2.2	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	<u> </u>
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	



2.15	Bulk cargo and materials packed properly?		✓		
2.16	Temporary stockpiles covered during rainstorms?	✓			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			No sand/silt is generated from the recycling process
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓			Not required
	a) SP Licence conditions / monitoring requirements comply?	✓			
3.2	Operate without generation of noticeable odour?		✓		
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?		✓		
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?		√		
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		_		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			Not required
3.11	Air pollution control system properly maintained and function normally?	✓			Not required
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	✓			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		W. F. H. C
3.15	Materials transported on trucks covered?	✓			Not applicable for trucks transporting scrap steel material as observed on site.
3.16	Truck loads to a level within the side and tail boards?			✓	New Observation (1)
3.17	Stockpiles of dusty materials covered or regularly watered?	✓			No dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/ed	quipment	movem	ent
	Loading/unloading of materials	✓ Others:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	<u>ral</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?	\checkmark			No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		To be verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	\checkmark			Not required
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?	✓			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	\checkmark			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	✓			
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	\checkmark			
4.13	Incompatible wastes separated by impermeable partition?	\checkmark			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	√			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	\checkmark			
4.18	Cover provided for outdoor storage area?	√			
4.19	Chemical waste collected by licensed collector?	\checkmark			
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	✓			
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	√			Outside LFG consultation zone
	Smoking and open fires prohibited?		✓		

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		√		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		√		
6.5	Areas within lot for recycling activities paved with concrete?		√		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		✓		
6.7	Valid calibration certificate for any monitoring equipment?	✓			Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓			Not required
	a) Storage area in compliance with the approved plan?	✓			
	b) Storage area is securely locked?	✓			
	c) Total storage capacity in compliance with relevant statutory requirement?	✓			
	d) Proper labelling provided?	✓			
	e) Dangerous goods properly packaged?	✓			

Remarks:

New Observation

1) Loads levels of trucks were observed to exceed the levels of the sides and the tailboard during the inspection. The tenant was requested to reduce the load levels of trucks. This item will be reviewed in the next inspection.



(Observed on 17 December 2020)

Signatures:	
ET Representa	a

Name: Chris LO

Date: 2020/12/17

Operator Representative:


Name:

May Wu 2 4 DEC 2020 Tenant Representative:

IEC Representative:

Name:

Date:



Draft 1_____AEC

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/10/20 Time: 11:00 Lot Number: P11 Tenant: K. Wah	Inspected by: Chris LO, Charles YUEN
Weat	<u>her</u>	
	Condition: Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 24 °C Humidity: ✓ High	Moderate Low
	Wind: Calm Light Breeze Strong	
1. Ge	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. W	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	✓ Wastewater is reused
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	Sedimentation pit is provided
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	New Observation (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	

SITE INSPECTION CHECKLIST



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	\checkmark			Not required
	loading and unloading adjacent to marine frontage?				
	Bulk cargo and materials packed properly?			Ш	
2.16	Temporary stockpiles covered during rainstorms?	<u> </u>		\sqsubseteq	No rainstorm during inspection Fall gradient is provided to direct runoff from
2.17	Measures to prevent the washing away of sand/silt to drains?		✓		works area to sedimentation pit
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?		✓		
	a) SP Licence conditions/monitoring requirements comply?		✓		Quarterly reporting on quantity of raw material and product (up to May - Jul 2020)
3.2	Operate without generation of noticeable odour?		✓		
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading was observed Measurement of 24-hr RSP required by SP
3.4	Dust monitoring record available?		✓		Licence (September 2020)
	a) Monitoring frequency met the licence requirement?		✓		
	b) Any exceedance?			✓	
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?		✓		Enclosures and sprinkler system are provided
3.6	Open burning prohibited?		√		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	~			
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			
3.11	Air pollution control system properly maintained and function normally?		✓		Maintenance record to be provided
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	✓			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not observed
3.16	Truck loads to a level within the side and tail boards?	✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?		√		
3.18	Major dust source(s): Wind erosion	Vehicle/equ	ipment :	moveme	ent
	Loading/unloading of materials	✓ Others:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	r <u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			
Packa	iging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?		✓		
4.10	Obtained approval for the use of chemical waste container >450L?	√			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		√		
4.13	Incompatible wastes separated by impermeable partition?	\checkmark			Not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?		√		
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		√		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		√		
4.19	Chemical waste collected by licensed collector?	✓			Not observed
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		√		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?		✓		
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?				Outside LFG consultation zone
5.2	Smoking and open fires prohibited?				- I S CONSTRUCTION
	Sincerning and open these promotion.		<u> </u>		

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		√		
6.2	Damage to surrounding areas avoided?		√		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		√		
6.5	Areas within lot for recycling activities paved with concrete?		√		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		√		
6.7	Valid calibration certificate for any monitoring equipment?	✓			Not provided
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓			Not required
	a) Storage area in compliance with the approved plan?	✓			
	b) Storage area is securely locked?	✓			
	c) Total storage capacity in compliance with relevant statutory requirement?	✓			
	d) Proper labelling provided?	✓			
	e) Dangerous goods properly packaged?	✓			
Rema	arks:				
New	<u>Observation</u>				
1)	C&D materials were observed in the surface channel near the stockpile area. The tenant was requested reminded to implement sufficient mitigation measures to prevent materials from entering into drains. This item will be reviewed in the next inspection.		up the	C&D n	naterials, and further



(Observed on 20 October 2020)

ET Representative:	

Signatures:

Name: Chris LO Date: 2020/10/20 Operator Representative:

May Wu Name: 30 OCT 2020 Date:

Tenant Representative:

IEC Representative:

Name:

Date:

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/11/25 Time: 11:30 Lot Number: P11 Tenant: K. Wah	Inspected by: Chris LO, Timmy WONG
Weat	<u>her</u>	
	Condition:	Rain Storm Hazy Moderate Low
<u>1. Ge</u>	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	✓ Wastewater is reused
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	✓ Sedimentation pit is provided
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	Follow-up item (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Stop-logs are available for use by tenant if
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	

SITE INSPECTION CHECKLIST



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓			Not required
2 1 5	loading and unloading adjacent to marine frontage?				
	Bulk cargo and materials packed properly?				
	Temporary stockpiles covered during rainstorms?				No rainstorm during inspection Fall gradient is provided to direct runoff from
2.17	Measures to prevent the washing away of sand/silt to drains?		✓	<u> </u>	works area to sedimentation pit
3. Aiı	<u>Quality</u>	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?		✓		
	a) SP Licence conditions / monitoring requirements comply?		✓		Quarterly reporting on quantity of raw material and product (up to Aug - Oct 2020)
3.2	Operate without generation of noticeable odour?		✓		
	a) If odour is detected, can the source be identified?	\checkmark			
	b) Odourous materials covered?	\checkmark			
	c) If odour control system is installed, is it operating normally?	\checkmark			
3.3	Dusty materials dampened prior to loading/unloading?	\checkmark			No loading/unloading was observed Measurement of 24-hr RSP required by SP
3.4	Dust monitoring record available?		✓		Licence (October 2020)
	a) Monitoring frequency met the licence requirement?		✓		
	b) Any exceedance?			✓	
	c) If exceedance is recorded, follow-up action taken?	\checkmark			
3.5	$Dust-suppression\ measures\ provided\ where\ main\ dust-generating\ activities\ take\ place\ (i.e.\ enclosures\ or\ regular\ dampening)?$		✓		Enclosures and sprinkler system are provided
3.6	Open burning prohibited?		✓		_
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	✓			
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			
3.11	Air pollution control system properly maintained and function normally?		✓		Maintenance record to be provided
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	✓			
	a) Obtained approval for the use of controlled refrigerant?	\checkmark			_
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	\checkmark			_
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	\checkmark			Not observed
3.16	Truck loads to a level within the side and tail boards?	\checkmark			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?		✓		
3.18	Major dust source(s): Wind erosion	Vehicle/equi	ipment ı	noveme	ent
	Loading/unloading of materials	✓ Others:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	r <u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		√		
4.9	Spillage cleaned up immediately through the use of absorbent?		✓		
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		_
	c) Information is accurate and sufficient?		✓		
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	✓			Not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?		✓		
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		√		
4.19	Chemical waste collected by licensed collector?	✓			Not observed
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?		✓		
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards? Smoking and open fires prohibited?				Outside LFG consultation zone
5.2	Smoking and open fires prohibited?				-

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		✓		
6.5	Areas within lot for recycling activities paved with concrete?		✓		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		✓		
6.7	Valid calibration certificate for any monitoring equipment?	✓			Not provided
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓			Not required
	a) Storage area in compliance with the approved plan?	✓			
	b) Storage area is securely locked?	✓			
	c) Total storage capacity in compliance with relevant statutory requirement?	✓			
	d) Proper labelling provided?	✓			
	e) Dangerous goods properly packaged?	✓			

Remarks:

Follow-up from Previous Audit

C&D materials were still observed in the surface channel near the stockpile area. The tenant was requested to clear up the C&D materials, and further reminded to implement sufficient mitigation measures to prevent materials from entering into drains. This item will be reviewed in the next inspection.



(Observed on 20 October 2020)



(Observed on 25 November 2020)

Signatures:

ET Representative:

Operator Representative:

Tenant Representative:

IEC Representative:

Name: Chris LO

Date: 2020/11/25

Name:

3 Dec 2020 Date:

May Wu

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/12/17 Time: 11:00 Lot Number: P11 Tenant: K. Wah	Inspected by: Chris LO, Timmy WONG
Weat	he <u>r</u>	
	Condition: ✓ Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 12 °C Humidity: ✓ High	Moderate Low
	Wind: Calm Light Breeze Strong	
1. Ge	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	nter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	✓ Wastewater is reused
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	Sedimentation pit is provided
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	Follow-up item (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	/
	b) Collected by licensed collector?	

SITE INSPECTION CHECKLIST



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓			Not required
	loading and unloading adjacent to marine frontage?				
2.15	Bulk cargo and materials packed properly?		\checkmark		
2.16	Temporary stockpiles covered during rainstorms?	✓			No rainstorm during inspection Fall gradient is provided to direct runoff from
2.17	Measures to prevent the washing away of sand/silt to drains?		✓		works area to sedimentation pit
3. Aiı	<u> Quality</u>	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?		✓		
	a) SP Licence conditions / monitoring requirements comply?		✓		Quarterly reporting on quantity of raw material and product (up to Aug - Oct 2020)
3.2	Operate without generation of noticeable odour?		✓		-
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			-
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading was observed
3.4	Dust monitoring record available?		✓		Measurement of 24-hr RSP required by SP Licence (October 2020)
	a) Monitoring frequency met the licence requirement?		✓		,
	b) Any exceedance?			✓	
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?		✓		Enclosures and sprinkler system are provided
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	✓			
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			
3.11	Air pollution control system properly maintained and function normally?		✓		Maintenance record to be provided
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	✓			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			-
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not observed
3.16	Truck loads to a level within the side and tail boards?	✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?		✓		
3.18	Major dust source(s): Wind erosion	Vehicle/equ	ipment :	moveme	ent
	Loading/unloading of materials	✓ Others:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

					Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?		✓		
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Storaș	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	✓			Not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?		✓		
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?	✓			Not observed
Liquio	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?		√		
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	√			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		✓		

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		✓		
6.5	Areas within lot for recycling activities paved with concrete?		✓		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		√		
6.7	Valid calibration certificate for any monitoring equipment?	✓			Not provided
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓			Not required
	a) Storage area in compliance with the approved plan?	✓			
	b) Storage area is securely locked?	✓			
	c) Total storage capacity in compliance with relevant statutory requirement?	✓			
	d) Proper labelling provided?	✓			
	e) Dangerous goods properly packaged?	√			

Remarks:

Follow-up from Previous Audit

1) C&D materials in the surface channel near the stockpile area was observed to have been cleared. The tenant was reminded to cover the C&D materials to avoid future blockage.



(Observed on 25 November 2020)



(Observed on 17 December 2020)

SITE INSPECTION CHECKLIST



New Observation

1) C&D materials were observed to have blocked the parameter drain. The tenant was requested to clear up the C&D materials to avoid overflow. by covering them with tarpaulin. This item will be reviewed in the next inspection.



(Observed on 17 December 2020)

ET Representative:

Mel

Name: Chris LO

Date: 2020/12/17

Operator Representative:

Name:

Date:

2 4 DEC 2020

May Wu

Tenant Representative:


lame: , Vi

Date:

IEC Representative:

Name:

Date:



Draft 1_____AEC



	Inspection Date: 2020/10/20 Time: 11:25 Lot Number: P14 Tenant: E.Tech	Inspected by: Chris LO, Charles YUEN
Weat	<u>her</u>	
	Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	neral	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	OTALS ENT. IS TOURS
1.6	Any record of complaint or prosecution?	
2. W	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Stop-logs are available for use by tenant if
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?	✓			
2.16	Temporary stockpiles covered during rainstorms?	✓			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			No sand/silt is generated from the recycling process
3. Aiı	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓			Not required
	a) SP Licence conditions/monitoring requirements comply?	\checkmark			
3.2	Operate without generation of noticeable odour?		√		
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			
	c) If odour control system is installed, is it operating normally?	✓			N. I. F. / I. F. Cl. / C
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?		√		Shredder is enclosed and connected with dust collector with filter
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	· ✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			Not required
3.11	Air pollution control system properly maintained and function normally?		✓		Dust filter was checked and maintained.
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	√			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not Observed
3.16	Truck loads to a level within the side and tail boards?	✓			Not Observed
3.17	Stockpiles of dusty materials covered or regularly watered?	✓			No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equ	ipment	moveme	ent
	Loading/unloading of materials	✓ Others:	n/a		

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	<u>ral</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		√		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		To be verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		√		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?	\checkmark			No spillage is observed
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	\checkmark			Incompatible wastes are not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?		✓		
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			No storage of liquid waste
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	✓			No storage of liquid waste
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			No storage of liquid waste
<u>5. La</u>	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	✓			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		√		

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	<u>hers</u>	N/A Yes No Remarks	
6.1	Works confined within lot boundaries?		
6.2	Damage to surrounding areas avoided?		
6.3	Site lighting designed to avoid glare to surrounding receivers?		
6.4	Materials and machinery stored in an orderly manner?		
6.5	Areas within lot for recycling activities paved with concrete?		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		
6.7	Valid calibration certificate for any monitoring equipment?	✓ Not required	
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓ Not required	
	a) Storage area in compliance with the approved plan?		
	b) Storage area is securely locked?		
	c) Total storage capacity in compliance with relevant statutory requirement?		
	d) Proper labelling provided?		
	e) Dangerous goods properly packaged?		
Rema	nrks:		
New	Observation		
•	No major environmental deficiency was observed.		

a	
Signatur	06.
Dignatui	Co.

ET Representative:

Operator Representative:

Name: Chris LO Name:

Date: 2020/10/20

May Wu

Date:

30 OCT 2020

Tenant Representative:

Duinel Sill 2/11/2020.

Date:

Name:

IEC Representative:

Date:



	Inspection Date: 2020/11/25 Time: 11:55	Inspected by: Chris LO, Timmy WONG
	Lot Number: P14 Tenant: E.Tech	Chris Lo, Thinny World
Weat	<u></u>	
	Condition: Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 24 °C Humidity: ✓ High	Moderate Low
	Wind: Calm Light Breeze Strong	
1. Ge	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
		WA W N D I
<u>2. W</u>	<u>ater Quality</u>	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	<u> </u>
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	✓
	d) If exceedance is recorded, any follow-up action taken?	✓
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from	
2.7	entering nearby drains or sewer? Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Stop-logs are available for use by tenant if
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	✓
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?	✓			
2.16	Temporary stockpiles covered during rainstorms?	✓			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			No sand/silt is generated from the recycling process
3. Aiı	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	√			Not required
	a) SP Licence conditions / monitoring requirements comply?				
3.2	Operate without generation of noticeable odour?		$\overline{}$		
	a) If odour is detected, can the source be identified?				
	b) Odourous materials covered?			$\overline{\Box}$	
	c) If odour control system is installed, is it operating normally?	<u> </u>	$\overline{\Box}$		
3.3	Dusty materials dampened prior to loading/unloading?		一	$\overline{\Box}$	No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?		√		Shredder is enclosed and connected with dust collector with filter
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	·			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			Not required
3.11	Air pollution control system properly maintained and function normally?		✓		Dust filter was checked and maintained.
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	· 🗸			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	\checkmark			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not Observed
3.16	Truck loads to a level within the side and tail boards?	✓			Not Observed
3.17	Stockpiles of dusty materials covered or regularly watered?	✓			No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equ	ipment i	novem	ent
	Loading/unloading of materials	✓ Others:	n/a		
_					

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	r <u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		To be verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	iging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?	\checkmark			No spillage is observed
4.10	Obtained approval for the use of chemical waste container >450L?	\checkmark			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		√		
	c) Information is accurate and sufficient?		✓		
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		√		
4.13	Incompatible wastes separated by impermeable partition?	✓			Incompatible wastes are not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		√		
4.19	Chemical waste collected by licensed collector?		✓		
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			No storage of liquid waste
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	✓			No storage of liquid waste
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			No storage of liquid waste
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	\checkmark			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		✓		

SITE INSPECTION CHECKLIST



6. Ot	<u>hers</u>	N/A Yes No Remarks
6.1	Works confined within lot boundaries?	
6.2	Damage to surrounding areas avoided?	
6.3	Site lighting designed to avoid glare to surrounding receivers?	
6.4	Materials and machinery stored in an orderly manner?	
6.5	Areas within lot for recycling activities paved with concrete?	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?	
6.7	Valid calibration certificate for any monitoring equipment?	Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	Not required
	a) Storage area in compliance with the approved plan?	
	b) Storage area is securely locked?	
	c) Total storage capacity in compliance with relevant statutory requirement?	
	d) Proper labelling provided?	
	e) Dangerous goods properly packaged?	
Rema	nrks:	
New	<u>Observation</u>	

No major environmental deficiency was observed.

Signatures: ET Representative: Operator Representative: Tenant Representative: IEC Representative: May Wu Name: Name: Name: Chris LO 3 Dec 2020 Date: Date: Date: 2020/11/25



	Inspection Date: 2020/12/17 Time: 11:25 Lot Number: P14 Tenant: E.Tech	Inspected by: Chris LO, Timmy WONG
Weat	<u>her</u>	
	Condition: ✓ Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 12 °C Humidity: ✓ High	Moderate Low
	Wind: Calm Light Breeze Strong	
1. Ge	neral	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	nter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
2.1	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from maintenance area discharged via oil interceptor?	Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	



2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?	✓			
2.16	Temporary stockpiles covered during rainstorms?	✓			No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓			No sand/silt is generated from the recycling process
3. Aiı	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	√			Not required
	a) SP Licence conditions / monitoring requirements comply?				
3.2	Operate without generation of noticeable odour?		$\overline{}$		
	a) If odour is detected, can the source be identified?				
	b) Odourous materials covered?			$\overline{\Box}$	
	c) If odour control system is installed, is it operating normally?		$\overline{\Box}$		
3.3	Dusty materials dampened prior to loading/unloading?		一	$\overline{\Box}$	No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e enclosures or regular dampening)?		√		Shredder is enclosed and connected with dust collector with filter
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	·			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	✓			Not required
3.11	Air pollution control system properly maintained and function normally?		✓		Dust filter was checked and maintained.
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	· 🗸			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	\checkmark			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	✓			Not Observed
3.16	Truck loads to a level within the side and tail boards?	✓			Not Observed
3.17	Stockpiles of dusty materials covered or regularly watered?	✓			No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equ	ipment i	novem	ent
	Loading/unloading of materials	✓ Others:	n/a		
_					

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Gener	r <u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		To be verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	iging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?	\checkmark			No spillage is observed
4.10	Obtained approval for the use of chemical waste container >450L?	\checkmark			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		√		
	c) Information is accurate and sufficient?		✓		
Stora	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		√		
4.13	Incompatible wastes separated by impermeable partition?	✓			Incompatible wastes are not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	✓			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		√		
4.19	Chemical waste collected by licensed collector?		✓		
Liqui	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	\checkmark			No storage of liquid waste
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	✓			No storage of liquid waste
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?	✓			No storage of liquid waste
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?	\checkmark			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?		✓		

SITE INSPECTION CHECKLIST



<u>6. Ot</u>	her <u>s</u>	N/A Y	Yes N	lo Remarks
6.1	Works confined within lot boundaries?		√	
6.2	Damage to surrounding areas avoided?		√	
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓		
6.4	Materials and machinery stored in an orderly manner?		√	
6.5	Areas within lot for recycling activities paved with concrete?		✓]
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		√]
6.7	Valid calibration certificate for any monitoring equipment?	✓		Not required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?	✓		Not required
	a) Storage area in compliance with the approved plan?	✓		□
	b) Storage area is securely locked?	✓		
	c) Total storage capacity in compliance with relevant statutory requirement?	✓		□
	d) Proper labelling provided?	✓		□
	e) Dangerous goods properly packaged?	✓		
Rema	nrks:			
New	<u>Observation</u>			
•	No major environmental deficiency was observed.			

Signatures:

ET Representative: Operator Representative: Tenant Representative: IEC Representative:

Name: Chris LO

Name: May Wu

Name: Fell Fell

Name: Na


Date:

Date:

Date:

Date: 2020/12/17

2 4 DEC 2020



Draft 1_____AEC

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/10/20 Time: 12:00 Lot Number: P2, P3 & P4 Tenant: WEEE.PARK	Inspected by: Chris LO, Charles YUEN
Weat	han	
weat	Condition:	Orizzle Rain Storm Hazy Hazy Low trong
1. Ge	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	
1.3	Environmental Management Plan (EMP) kept up-to-date?	
1.4	Emergency Response Plan (ERP) documented?	✓ In-house Emergency Procedure Plan was applied
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	nter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	Self-monitoring when required
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	✓ via petrol interceptor
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	New observation (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where rec process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance	area? Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treat facility or other appropriate treatment facility?	ment No contaminated water is observed
2.13	Drainage from fuel dispensing area discharged via oil interceptor?	
	a) Oil and grease removed regularly?	Not observed
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage duri	ng Not required

SITE INSPECTION CHECKLIST



	loading and unloading adjacent to marine frontage?		
2.15	Bulk cargo and materials packed properly?		_
2.16	Temporary stockpiles covered during rainstorms?	No dusty stockpile is observed	_
2.17	Measures to prevent the washing away of sand/silt to drains?	No sand/silt is generated from the recycling process	<u>;</u>
3. Air	Quality_	N/A Yes No Remarks	_
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓ Not required	
	a) SP Licence conditions/monitoring requirements comply?		_
3.2	Operate without generation of noticeable odour?		
	a) If odour is detected, can the source be identified?		
	b) Odourous materials covered?		_
	c) If odour control system is installed, is it operating normally?		_
3.3	Dusty materials dampened prior to loading/unloading?	Dusty material is not observed	_
3.4	Air monitoring record available?		_
	a) Monitoring frequency met the licence requirement?	Requirements stipulated in Compliance Audit Repo	rt
	b) Any exceedance?	☐ Against AQO/USEPA	_
	c) If exceedance is recorded, follow-up action taken?		_
3.5	Suppression measures provided where main pollutant-generating activities take place (i.e. enclosures or regular dampening)?	Use of localised hood and extraction system with HEPA filter for CRT Recovery	_
3.6	Open burning prohibited?		
3.7	Emission from chimney or powered plant free of black smoke?		_
3.8	Vehicles and equipment switched off while not in use?		_
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?		_
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?		
3.11	Air pollution control system properly maintained and function normally?	Dust filter was checked and maintained.	
3.12	Filtered dust/ fluorescent powder from any air pollution control equipment installed by tenants disposed of as chemical waste?		
	a) Obtained approval for the use of controlled refrigerant?		
	b) If yes, record of refrigeration equipment service available?		
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?		_
3.14	Public road around site entrance kept clean and free from dust?		_
3.15	Materials transported on trucks covered?	✓ Not observed	
3.16	Truck loads to a level within the side and tail boards?	✓ Not observed	_
3.17	Stockpiles of dusty materials covered or regularly watered?	No stockpile of dusty material is observed	_
3.18	Major dust source(s): Wind erosion	Vehicle/equipment movement	
	Loading/unloading of materials	Others: n/a	_
3.19	Shredding, crushing and sorting processes including CRT dismantling are carried out in		_
	enclosed structure(s)?		_

SITE INSPECTION CHECKLIST



4. Waste/Chemical Management

Genera	<u>ıl</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		√		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Labell	ing of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		√		
	c) Information is accurate and sufficient?		√		
Storag	e of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	✓			Not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50L)?	√			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		√		
4.16	Properly stored and locked in designated area with adequate ventilation?		✓		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?		√		
Liquid	Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		√		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?		√		
	ACH Con (LEC) (within LEC Complete or Torn)	N T/A	V	NT.	Damada
5. Lar	dfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?		✓		
5.2	Smoking and open fires prohibited?		✓		

SITE INSPECTION CHECKLIST



<u>. Oti</u>	<u>iers</u>	1 N / P A	1 68	INO	Remarks
6.1	Works confined within lot boundaries?		√		
6.2	Damage to surrounding areas avoided?		√		
6.3	Site lighting designed to avoid glare to surrounding receivers?	\checkmark			
6.4	Materials and machinery stored in an orderly manner?		√		
6.5	Areas within lot for recycling activities paved with concrete?		√		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		√		
6.7	Valid calibration certificate for any monitoring equipment?	\checkmark			Not provided
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?		√		
	a) Storage area in compliance with the approved plan?	\checkmark			
	b) Storage area is securely locked?		√		
	c) Total storage capacity in compliance with relevant statutory requirement?	\checkmark			
	d) Proper labelling provided?		√		
	e) Dangerous goods properly packaged?	\checkmark			

Remarks:

New Observation

1) The sieve on the stormwater manhole opposite the chemical waste stores was found to be filled by plastics debris.

The tenant was requested to clear up the debris, and further reminded to better maintain drains to prevent any blockage.

This item will be reviewed in the next inspection.



(Observed on 20 October 2020)

Signatures:	

ET Representative:

Name: Chris LO

Date: 2020/10/20

Operator Representative:

Name:

Date:

3 0 OCT 2020

May Wu

Tenant Representative:

amo: Linus

IEC Representative:

Name:

Date:

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/11/25 Time: 12:30 Lot Number: P2, P3 & P4 Tenant: WEEE.PARK	Inspected by: Chris LO, Timmy WONG
Weat	<u>ner</u>	
	Condition:	Rain Storm Hazy Moderate Low
1. Ger	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required
1.2	Environmental Policy documented?	
1.3	Environmental Management Plan (EMP) kept up-to-date?	
1.4	Emergency Response Plan (ERP) documented?	✓ In-house Emergency Procedure Plan was applied
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	ter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	Self-monitoring when required
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	✓ via petrol interceptor
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	Follow-up Observation (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from fuel dispensing area discharged via oil interceptor?	
	a) Oil and grease removed regularly?	✓ Not observed
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓ Not required

SITE INSPECTION CHECKLIST



	loading and unloading adjacent to marine frontage?	
2.15	Bulk cargo and materials packed properly?	
2.16	Temporary stockpiles covered during rainstorms?	No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	No sand/silt is generated from the recycling process
3. Air	Quality_	N/A Yes No Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓ Not required
	a) SP Licence conditions / monitoring requirements comply?	/
3.2	Operate without generation of noticeable odour?	
	a) If odour is detected, can the source be identified?	/
	b) Odourous materials covered?	
	c) If odour control system is installed, is it operating normally?	✓ □ □ □
3.3	Dusty materials dampened prior to loading/unloading?	Dusty material is not observed
3.4	Air monitoring record available?	
	a) Monitoring frequency met the licence requirement?	Requirements stipulated in Compliance Audit Report
	b) Any exceedance?	✓ Against AQO/USEPA
	c) If exceedance is recorded, follow-up action taken?	/
3.5	Suppression measures provided where main pollutant-generating activities take place (i.e. enclosures or regular dampening)?	Use of localised hood and extraction system with HEPA filter for CRT Recovery
3.6	Open burning prohibited?	
3.7	Emission from chimney or powered plant free of black smoke?	
3.8	Vehicles and equipment switched off while not in use?	
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	<u> </u>
3.11	Air pollution control system properly maintained and function normally?	Dust filter was checked and maintained.
3.12	Filtered dust/ fluorescent powder from any air pollution control equipment installed by tenants disposed of as chemical waste?	
	a) Obtained approval for the use of controlled refrigerant?	/
	b) If yes, record of refrigeration equipment service available?	/
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	
3.14	Public road around site entrance kept clean and free from dust?	
3.15	Materials transported on trucks covered?	✓ Not observed
3.16	Truck loads to a level within the side and tail boards?	Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equipment movement
	Loading/unloading of materials	Others: n/a
3.19	Shredding, crushing and sorting processes including CRT dismantling are carried out in	
	enclosed structure(s)?	

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Genera	<u>d</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packag	ging of Chemical Waste				
4.7	Stored in suitable container?		✓		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Labell	ing of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Storag	e of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		✓		
4.13	Incompatible wastes separated by impermeable partition?	✓			Not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<50L$), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity $>50L$)?	√			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		√		
4.16	Properly stored and locked in designated area with adequate ventilation?		√		
4.17	Storage area paved with concrete and kept clean and dry?		✓		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?		√		
Liquid	Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?		✓		;
5. Lan	dfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
	Alert workers and visitors of possible LFG hazards?		✓		
5.2	Smoking and open fires prohibited?	\vdash		\Box	
J. _	σ	ш			

SITE INSPECTION CHECKLIST



<u>6. Oth</u>	<u>iers</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		√		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		✓		
6.5	Areas within lot for recycling activities paved with concrete?		✓		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		✓		
6.7	Valid calibration certificate for any monitoring equipment?	✓			Not provided
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?		✓		
	a) Storage area in compliance with the approved plan?	√			
	b) Storage area is securely locked?		✓		
	c) Total storage capacity in compliance with relevant statutory requirement?	✓			
	d) Proper labelling provided?		✓		
	e) Dangerous goods properly packaged?	✓			

Remarks:

Follow-up from Previous Audits

The sieve on the stormwater manhole opposite the chemical waste stores was still found to be filled by plastics debris. The tenant was requested to clear up the debris, and further reminded to better maintain drains to prevent any blockage. This item will be reviewed in the next inspection.



(Observed on 20 October 2020)



(Observed on 25 November 2020)

Signatures:

ET Representative:

Name: Chris LO

2020/11/25 Date:

Operator Representative:

Name: Date:

May Wu 3 Dec 2020 Tenant Representative:

Name: Clement Pang

7 Dec 2020

IEC Representative:

Name:

Date: 021121200

SITE INSPECTION CHECKLIST



	Inspection Date: 2020/12/17 Time: 12:00	Instructed by
	Inspection Date: 2020/12/17 Time: 12:00 Lot Number: P2, P3 & P4 Tenant: WEEE.PARK	Inspected by: Chris LO, Timmy WONG
	2011 miles. 12,10 00 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Weatl	<u>er</u>	
	Condition: Sunny Fine Overcast Drizzle	Rain Storm Hazy
	Temperature: 12 °C Humidity: ✓ High	Moderate Low
	Wind: Calm ✓ Light Breeze Strong	
1. Ger	<u>ieral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required
1.2	Environmental Policy documented?	
1.3	Environmental Management Plan (EMP) kept up-to-date?	
1.4	Emergency Response Plan (ERP) documented?	In-house Emergency Procedure Plan was applied
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
		NA V N D I
<u>2. Wa</u>	ter Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	Self-monitoring when required
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	via petrol interceptor
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	Follow-up Observation (1)
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed
2.13	Drainage from fuel dispensing area discharged via oil interceptor?	
	a) Oil and grease removed regularly?	✓ Not observed
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during	✓ Not required

SITE INSPECTION CHECKLIST



	loading and unloading adjacent to marine frontage?			
2.15	Bulk cargo and materials packed properly?			
2.16	Temporary stockpiles covered during rainstorms?	✓		No dusty stockpile is observed
2.17	Measures to prevent the washing away of sand/silt to drains?	✓		No sand/silt is generated from the recycling process
3. Air	<u>Quality</u>	N/A Ye	s No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓		Not required
	a) SP Licence conditions / monitoring requirements comply?	✓		
3.2	Operate without generation of noticeable odour?	✓		No operation was observed in lunch hour
	a) If odour is detected, can the source be identified?	✓		
	b) Odourous materials covered?	✓		
	c) If odour control system is installed, is it operating normally?	✓		
3.3	Dusty materials dampened prior to loading/unloading?	✓		Dusty material is not observed
3.4	Air monitoring record available?			
	a) Monitoring frequency met the licence requirement?			Requirements stipulated in Compliance Audit Report
	b) Any exceedance?		✓	Against AQO/USEPA
	c) If exceedance is recorded, follow-up action taken?	✓		
3.5	Suppression measures provided where main pollutant-generating activities take place (i.e enclosures or regular dampening)?			Use of localised hood and extraction system with HEPA filter for CRT Recovery
3.6	Open burning prohibited?			
3.7	Emission from chimney or powered plant free of black smoke?	✓		No operation was observed in lunch hour
3.8	Vehicles and equipment switched off while not in use?			
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?			
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	V		
3.11	Air pollution control system properly maintained and function normally?	✓		Dust filter was checked and maintained.
3.12	Filtered dust/ fluorescent powder from any air pollution control equipment installed by tenants disposed of as chemical waste?			
	a) Obtained approval for the use of controlled refrigerant?	✓		
	b) If yes, record of refrigeration equipment service available?	✓		
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓		
3.14	Public road around site entrance kept clean and free from dust?			
3.15	Materials transported on trucks covered?	✓		Not observed
3.16	Truck loads to a level within the side and tail boards?	_		Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	V		No stockpile of dusty material is observed
3.18	Major dust source(s): Wind erosion	Vehicle/equipme	nt movem	ent
	Loading/unloading of materials	✓ Others: n/a		
3.19	Shredding, crushing and sorting processes including CRT dismantling are carried out in			
	enclosed structure(s)?			

SITE INSPECTION CHECKLIST



4. Waste / Chemical Management

Genera	<u>ıl</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		√		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			Not required
Packa	ging of Chemical Waste				
4.7	Stored in suitable container?		√		
4.8	Container properly closed or sealed?		✓		
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Labell	ing of Chemical Waste				
4.11	Provision of chemical waste label?		✓		
	a) Label is securely attached and visible?		✓		
	b) Label is bilingual and in proper dimension?		✓		
	c) Information is accurate and sufficient?		✓		
Storag	e of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?		√		
4.13	Incompatible wastes separated by impermeable partition?	✓			Not observed
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<50L$), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity $>50L$)?	√			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?		✓		
4.16	Properly stored and locked in designated area with adequate ventilation?		√		
4.17	Storage area paved with concrete and kept clean and dry?		√		
4.18	Cover provided for outdoor storage area?		✓		
4.19	Chemical waste collected by licensed collector?		✓		
Liquid	Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?		✓		
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?		✓		
4.22	Walls or partitions of stacked container storage area constructed of impermeable material?		✓		
5. Lar	dfill Gas (LFG) (within LFG Consultation Zone)	N/A	Yes	No	Remarks
5.1	Alert workers and visitors of possible LFG hazards?		✓		
5.2	Smoking and open fires prohibited?		√		

SITE INSPECTION CHECKLIST




6. Otl	<u>ners</u>	N/A	Yes	No	Remarks
6.1	Works confined within lot boundaries?		✓		
6.2	Damage to surrounding areas avoided?		✓		
6.3	Site lighting designed to avoid glare to surrounding receivers?	✓			
6.4	Materials and machinery stored in an orderly manner?		✓		
6.5	Areas within lot for recycling activities paved with concrete?		✓		
6.6	Potential stagnant pools cleared and mosquito breeding prevented?		✓		
6.7	Valid calibration certificate for any monitoring equipment?	✓			Not provided
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?		✓		
	a) Storage area in compliance with the approved plan?	✓			
	b) Storage area is securely locked?		✓		
	c) Total storage capacity in compliance with relevant statutory requirement?	✓			
	d) Proper labelling provided?		✓		
	e) Dangerous goods properly packaged?	✓			
Rema	rks:				
	w-up from Previous Audits				

Plastics debris in the sieve on the stormwater manhole opposite the chemical waste stores was observed to have been cleared. The tenant was reminded to take extra care to avoid future blockage.





(Observed on 25 Novem	aber 2020)	(Observed on 17 December 2020)					
Signatures:							
ET Representative:	Operator Representative:	Tenant Representative:	IEC Representative:				
MI		Loc					
Name: Chris LO	Name: May Wu	Name: [was lex Date: 31-12-2020	Name:				
Date: 2020/12/17	Date:	Date: 3 - 1 L - L - L	Date:				



Draft 1_____AEC



	Inspection Date: 2020/10/20 Time: 10:40 Lot Number: P8 Tenant: On Fat Lung	Inspected by: Chris LO, Charles YUEN
Weat	her Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	nera <u>l</u>	N/A Yes No Remarks
1.1 1.2 1.3 1.4 1.5	Environmental Permit (EP) for Tenant displayed at entrances/exits? Environmental Policy documented? Environmental Management Plan (EMP) kept up-to-date? Emergency Response Plan (ERP) documented? All recycling processes in operation have been approved by WRG of EPD?	EP for tenant is not required. UPML's Environmental Policy is followed UPML's EMP is followed UPML's ERP is followed
1.6	Any record of complaint or prosecution? Atter Quality	N/A Yes No Remarks
	Valid Effluent Discharge Licence available? a) Sampling record available? b) Monitoring frequency met the licence requirement? c) Monitoring result comply with the licence requirement? d) If exceedance is recorded, any follow-up action taken?	No wastewater is generated from recycling process No wastewater is generated from recycling process No wastewater is generated from recycling
2.2	Provision of wastewater treatment facility (WTF) prior to discharge? a) Adequate capacity? b) Properly maintained and function normally? Surface run-off control measures in place and adequately maintained?	process V
2.4	Surface run-off discharging into drainage system?	
2.52.6	All manholes covered? Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	Stop-logs are available for use by tenant if
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water was observed



2.13	Drainage from maintenance area discharged via oil interceptor?	✓			Not required
	a) Oil and grease removed regularly?	✓			Not required
	b) Collected by licensed collector?	✓			Not required
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	√			Not required
2.15	Bulk cargo and materials packed properly?		✓		
2.16	Temporary stockpiles covered during rainstorms?	✓			No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?		✓		
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓			Not required
	a) SP Licence conditions/monitoring requirements comply?	✓			
3.2	Operate without generation of noticeable odour?		√		
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	✓			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	✓			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	√			
	c) If exceedance is recorded, follow-up action taken?	✓			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?		√		
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		√		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	✓			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	√			Not required
3.11	Air pollution control system properly maintained and function normally?		✓		Via enclosure
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	√			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		✓		
3.15	Materials transported on trucks covered?	√			Not observed



3.16	Truck loads to a level within the side and tail boards?	✓			Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?		✓		
3.18	Major dust source(s): Wind erosion	Vehicle/eq	uipment	movem	ent
	Loading/unloading of materials	Others:	n/a		
4. Wa	aste/Chemical Management				
Gener	r <u>al</u>	N/A	Yes	No	Remarks
4.1	Registered as chemical waste producer?		✓		
4.2	Sufficient receptacles (e.g. rubbish bins) available?		✓		
4.3	Disposed of regularly and properly?		✓		
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?		✓		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?		✓		Verified via quarterly report
4.6	Collection of sludge by licensed collector at regular intervals?	✓			
Packa	nging of Chemical Waste				
4.7	Stored in suitable container?	✓			
4.8	Container properly closed or sealed?	✓			
4.9	Spillage cleaned up immediately through the use of absorbent?	✓			-
4.10	Obtained approval for the use of chemical waste container >450L?	✓			
Label	ling of Chemical Waste				
4.11	Provision of chemical waste label?	✓			-
	a) Label is securely attached and visible?	✓			
	b) Label is bilingual and in proper dimension?	✓			
	c) Information is accurate and sufficient?	✓			
Storag	ge of Chemical Waste				
4.12	Proper "Chemical Waste" sign displayed?	✓			
4.13	Incompatible wastes separated by impermeable partition?	✓			
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provided with drip trays capable of storing 110% of the volume of the largest container (if quantity >50l)	oL)?			
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	✓			
4.16	Properly stored and locked in designated area with adequate ventilation?	✓			
4.17	Storage area paved with concrete and kept clean and dry?	✓			
4.18	Cover provided for outdoor storage area?	✓			
4.19	Chemical waste collected by licensed collector?	✓			
Liquio	d Waste Storage				
4.20	Storage area provided with permeation-proof floor or surface?	✓			
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	√			

SITE INSPECTION CHECKLIST



4.22	Walls or partitions of stacked cont	ainer storage area constructed of impermeable ma	terial?		
<u>5. La</u>	ndfill Gas (LFG) (within LFG Co.	nsultation Zone)	N/A Y	Yes No	Remarks
5.1	Alert workers and visitors of possi	ble LFG hazards?		✓	
5.2	Smoking and open fires prohibited	??		√	
6. Ot	<u>hers</u>		N/A Y	Yes No	Remarks
6.1	Works confined within lot bounda	ries?		√	
6.2	Damage to surrounding areas avoi	ded?		√	
6.3	Site lighting designed to avoid glas	re to surrounding receivers?	✓		
6.4	Materials and machinery stored in	an orderly manner?		√	
6.5	Areas within lot for recycling activ	vities paved with concrete?		√	
6.6	Potential stagnant pools cleared an	d mosquito breeding prevented?		✓ <u> </u>	
6.7	Valid calibration certificate for an	y monitoring equipment?	✓		Not required
6.8	Valid licence(s) obtained for manu	facture or storage of dangerous goods?	✓		Not required
	a) Storage area in compliance with	the approved plan?	✓		
	b) Storage area is securely locked?		✓		
	c) Total storage capacity in compli	ance with relevant statutory requirement?	✓		
	d) Proper labelling provided?		✓		
	e) Dangerous goods properly pack	aged?	✓		
Rema	nrks:				
New	Observation				
•	No major environmental deficienc	y was observed.			
Signa	itures:				
	epresentative:	Operator Representative:	Tenant Representative	e:	IEC Representative:
6	in the		-07		
Name:	Chris LO	Name: May Wu	Name: My . KN	mling (Name:
Date:	2020/10/20	Date: 3 0 OCT 2020	Date: 4-11	- 202	Date:



	Inspection Date: 2020/11/25 Time: 11:10 Lot Number: P8 Tenant: On Fat Lung	Inspected by: Chris LO, Timmy WONG
Weat	her Condition: ✓ Sunny Fine Overcast Drizzle Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	Rain Storm Hazy Moderate Low
1. Ge	neral	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
	,	
2. Wa	ater Quality	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is generated from recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	No wastewater is generated from recycling process
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water was observed



2.13	Drainage from maintenance area discharged via oil interceptor?	✓			Not required
	a) Oil and grease removed regularly?	✓			Not required
	b) Collected by licensed collector?	✓			Not required
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?		✓		
2.16	Temporary stockpiles covered during rainstorms?	✓			No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?		✓		
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓			Not required
	a) SP Licence conditions / monitoring requirements comply?	✓			
3.2	Operate without generation of noticeable odour?		✓		
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	√			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	√			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	√			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?		√		
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	√			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	√			Not required
3.11	Air pollution control system properly maintained and function normally?		✓		Via enclosure
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	√			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		√		
3.15	Materials transported on trucks covered?	✓			Not observed
		<u></u>			



3.16	3.16 Truck loads to a level within the side and tail boards?				┨┖	Not observed			
3.17	3.17 Stockpiles of dusty materials covered or regularly watered?			✓					
3.18	Major dust source(s):	Wind erosion	Vehicle	Vehicle/equipment movement					
		Loading/unloading of materials	✓ Others:	: <u>n/a</u>					
4. Wa	. Waste / Chemical Management								
Gener	<u>ral</u>		N	N/A Yes	No	Remarks			
4.1	Registered as chemical wa	aste producer?		✓		l			
4.2	Sufficient receptacles (e.g.	. rubbish bins) available?		✓					
4.3	Disposed of regularly and	properly?		✓		l			
4.4	Sorting of materials on-site	e for reuse or disposal to designated outlet?		✓					
4.5	Records of quantities of w	raste generated, recycled and disposed properly kept?		✓		Verified via quarterly report			
4.6	Collection of sludge by lic	ensed collector at regular intervals?		√					
Packa	aging of Chemical Waste								
4.7	Stored in suitable containe	er?		√					
4.8	Container properly closed	or sealed?		√					
4.9	Spillage cleaned up immed	diately through the use of absorbent?		√					
4.10	Obtained approval for the	use of chemical waste container >450L?		✓					
Label	lling of Chemical Waste								
4.11	Provision of chemical was	ste label?		√					
	a) Label is securely attached	ed and visible?		√					
	b) Label is bilingual and in	n proper dimension?		✓					
	c) Information is accurate	and sufficient?		✓					
Stora	ge of Chemical Waste								
4.12	Proper "Chemical Waste"	sign displayed?		√					
4.13	Incompatible wastes separ	rated by impermeable partition?		✓					
4.14	-	or receptacle of suitable material (if quantity <50L), or prostoring 110% of the volume of the largest container (if quantity)		√		l			
4.15	Enclosed on 3 sides with n of containers?	no less than 2m in height or height of tallest container / stac	k	√		l			
4.16	Properly stored and locked	d in designated area with adequate ventilation?		√					
4.17	Storage area paved with co	oncrete and kept clean and dry?		√					
4.18	Cover provided for outdoo	or storage area?		√					
4.19	Chemical waste collected l	by licensed collector?		√		l			
Liqui	d Waste Storage								
4.20	Storage area provided with	h permeation-proof floor or surface?		√		l			
4.21		cture sufficient to accommodate contents of the volume of the material in storage?		√		l			



4.22	Walls or partitions of stacked con	tainer storage area constructed of impermeable mater	ial?	
5. La	ndfill Gas (LFG) (within LFG Co	onsultation Zone)	N/A Yes No	Remarks
5.1	Alert workers and visitors of poss	ible LFG hazards?		
5.2	Smoking and open fires prohibited	d?		
6. Ot	<u>hers</u>		N/A Yes No	Remarks
6.1	Works confined within lot bounda	aries?		
6.2	Damage to surrounding areas avoi			
6.3	Site lighting designed to avoid gla			
6.4	Materials and machinery stored in			
6.5	Areas within lot for recycling acti	vities paved with concrete?		
6.6	Potential stagnant pools cleared a	nd mosquito breeding prevented?		
6.7	Valid calibration certificate for ar	y monitoring equipment?		Not required
6.8	Valid licence(s) obtained for man	ufacture or storage of dangerous goods?		Not required
	a) Storage area in compliance with	h the approved plan?		
	b) Storage area is securely locked	?	V	
	c) Total storage capacity in compl	iance with relevant statutory requirement?	/	
	d) Proper labelling provided?		V	
	e) Dangerous goods properly pack	taged?		
Rema	arks:			
New	Observation			
	No major environmental deficience	ov was observed		
	No major environmental deficient	y was observed.		
	atures:			
ET R	epresentative:	Operator Representative:	Tenant Representative:	IEC Representative:
	m Col			
1/		\	- /	2
U	(***			- Luis
Name:	Chris LO	Name: May Wu	Name: / KLAN NING ON	Name: Bu Jang
Date:	2020/11/25	Date: 3 Dec 2020	Date: 3-12-2020	Date: 02/12/200



	Inspection Date: 2020/12/17 Time: 10:40 Lot Number: P8 Tenant: On Fat Lung	Inspected by: Chris LO, Timmy WONG
Weat		
	Condition:	Rain Storm Hazy Moderate Low
<u>1. Ge</u>	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	✓ EP for tenant is not required.
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	<u>iter Quality</u>	N/A Yes No Remarks
2.1	Valid Effluent Discharge Licence available?	No wastewater is generated from recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	No wastewater is generated from recycling process
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	
2.9	Processes or activities with high risk of contamination located under covered area?	
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water was observed



2.13	Drainage from maintenance area discharged via oil interceptor?	✓			Not required
	a) Oil and grease removed regularly?	✓			Not required
	b) Collected by licensed collector?	✓			Not required
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	✓			Not required
2.15	Bulk cargo and materials packed properly?		✓		
2.16	Temporary stockpiles covered during rainstorms?	✓			No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?		✓		
3. Air	Quality	N/A	Yes	No	Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓			Not required
	a) SP Licence conditions / monitoring requirements comply?	✓			
3.2	Operate without generation of noticeable odour?		✓		
	a) If odour is detected, can the source be identified?	✓			
	b) Odourous materials covered?	√			
	c) If odour control system is installed, is it operating normally?	✓			
3.3	Dusty materials dampened prior to loading/unloading?	✓			No loading/unloading of dusty materials is observed
3.4	Dust monitoring record available?	√			Not required
	a) Monitoring frequency met the licence requirement?	✓			
	b) Any exceedance?	✓			
	c) If exceedance is recorded, follow-up action taken?	√			
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?		√		
3.6	Open burning prohibited?		✓		
3.7	Emission from chimney or powered plant free of black smoke?		✓		
3.8	Vehicles and equipment switched off while not in use?		✓		
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	√			Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	√			Not required
3.11	Air pollution control system properly maintained and function normally?		✓		Via enclosure
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	√			
	a) Obtained approval for the use of controlled refrigerant?	✓			
	b) If yes, record of refrigeration equipment service available?	✓			
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	✓			
3.14	Public road around site entrance kept clean and free from dust?		√		
3.15	Materials transported on trucks covered?	✓			Not observed
		<u></u>			



3.16	3.16 Truck loads to a level within the side and tail boards?				┨┖	Not observed			
3.17	3.17 Stockpiles of dusty materials covered or regularly watered?			✓					
3.18	Major dust source(s):	Wind erosion	Vehicle	Vehicle/equipment movement					
		Loading/unloading of materials	✓ Others:	: <u>n/a</u>					
4. Wa	. Waste / Chemical Management								
Gener	<u>ral</u>		N	N/A Yes	No	Remarks			
4.1	Registered as chemical wa	aste producer?		✓		l			
4.2	Sufficient receptacles (e.g.	. rubbish bins) available?		✓					
4.3	Disposed of regularly and	properly?		✓		l			
4.4	Sorting of materials on-site	e for reuse or disposal to designated outlet?		✓					
4.5	Records of quantities of w	raste generated, recycled and disposed properly kept?		✓		Verified via quarterly report			
4.6	Collection of sludge by lic	ensed collector at regular intervals?		√					
Packa	aging of Chemical Waste								
4.7	Stored in suitable containe	er?		√					
4.8	Container properly closed	or sealed?		√					
4.9	Spillage cleaned up immed	diately through the use of absorbent?		√					
4.10	Obtained approval for the	use of chemical waste container >450L?		✓					
Label	lling of Chemical Waste								
4.11	Provision of chemical was	ste label?		√					
	a) Label is securely attached	ed and visible?		√					
	b) Label is bilingual and in	n proper dimension?		✓					
	c) Information is accurate	and sufficient?		✓					
Stora	ge of Chemical Waste								
4.12	Proper "Chemical Waste"	sign displayed?		√					
4.13	Incompatible wastes separ	rated by impermeable partition?		✓					
4.14	-	or receptacle of suitable material (if quantity <50L), or prostoring 110% of the volume of the largest container (if quantity)		√		l			
4.15	Enclosed on 3 sides with n of containers?	no less than 2m in height or height of tallest container / stac	k	√		l			
4.16	Properly stored and locked	d in designated area with adequate ventilation?		√					
4.17	Storage area paved with co	oncrete and kept clean and dry?		√					
4.18	Cover provided for outdoo	or storage area?		√					
4.19	Chemical waste collected l	by licensed collector?		√		l			
Liqui	d Waste Storage								
4.20	Storage area provided with	h permeation-proof floor or surface?		√		l			
4.21		cture sufficient to accommodate contents of the volume of the material in storage?		√		l			

SITE INSPECTION CHECKLIST




4.22	Walls or partitions of stacked con	tainer storage area constructed of impermeable m	aterial?	
5. La	ndfill Gas (LFG) (within LFG Co	nsultation Zone)	N/A Yes No	Remarks
5.1	Alert workers and visitors of poss	ible LFG hazards?		
5.2	Smoking and open fires prohibite	1?		
6. Ot	her <u>s</u>		N/A Yes No	Remarks
6.1	Works confined within lot bounda	uries?		
6.2	Damage to surrounding areas avo	ded?		
6.3	Site lighting designed to avoid gla	re to surrounding receivers?	V	
6.4	Materials and machinery stored in	an orderly manner?		
6.5	Areas within lot for recycling acti	vities paved with concrete?		
6.6	Potential stagnant pools cleared as	nd mosquito breeding prevented?		
6.7	Valid calibration certificate for ar	y monitoring equipment?	/	Not required
6.8	Valid licence(s) obtained for man	ufacture or storage of dangerous goods?	V	Not required
	a) Storage area in compliance with	n the approved plan?	/	
	b) Storage area is securely locked	?	V	
	c) Total storage capacity in compl	iance with relevant statutory requirement?	/	
	d) Proper labelling provided?		V	
	e) Dangerous goods properly pack	aged?	V	
Rema	nrks:			
New	Observation			
•	No major environmental deficienc	ey was observed.		
Signa	itures:			
ET R	epresentative:	Operator Representative:	Tenant Representative:	IEC Representative:
6	y ld	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	B B B B B B B B B B B B B B B B B B B	
Name:	Chris LO	Name: May Wu	Name: Kenny Kwan	Name:
Date:	2020/12/17	Date: 2 4 DEC 2020	Date: 24-12-2020	Date:

24-12-2020

Date:

Date: 2020/12/17



Draft 1_____AEC



	Inspection Date: 2020/10/2	Time:	10:20	Inspected by:	Chris LO, Charles YUEN
	Lot Number: T7	Tenant:	FWMG (Wood)		25, 534115 1 521
Weat	the <u>r</u>				
	Condition: Sunny	Fine Ove	ercast Drizzle	Rain	Storm Hazy
	Temperature: 24 °C	— Н	umidity: High	Moderate	Low
	Wind: Calm	✓ Light Bre	eeze Strong		
1. Ge	<u>eneral</u>			N/A Yes	No Remarks
1.1	Environmental Permit (EP) for Tenant	displayed at entrances/exits?		V	EP for tenant is not required
1.2	Environmental Policy documented?			✓	UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EM	P) kept up-to-date?		✓	UPML's EMP is followed
1.4	Emergency Response Plan (ERP) docu	imented?		✓	UPML's ERP is followed
1.5	All recycling processes in operation ha	we been approved by WRG of	EPD?	✓	
1.6	Any record of complaint or prosecution	n?			✓
2. Wa	ater Quality			N/A Yes	No Remarks No wastewater is generated from the
2.1	Valid Effluent Discharge Licence avai	lable?		√	recycling process
	a) Sampling record available?			✓	
	b) Monitoring frequency met the licen-	ce requirement?		✓	
	c) Monitoring result comply with the l	icence requirement?		✓	
	d) If exceedance is recorded, any follo	w-up action taken?		✓	
2.2	Provision of wastewater treatment fac-	ility (WTF) prior to discharge?		√	
	a) Adequate capacity?			✓	
	b) Properly maintained and function n	ormally?		✓	
2.3	Surface run-off control measures in pl	ace and adequately maintained	?		
2.4	Surface run-off discharging into drain	age system?			
2.5	All manholes covered?				
2.6	Foam, oil, grease, debris, rubbish and entering nearby drains or sewer?	other objectionable matters pre	evented from		
2.7	Storage of materials and equipment lo	cated away from water bodies?			
2.8	Drainage system well maintained to pr	event flooding or overflow?			
2.9	Processes or activities with high risk of	f contamination located under	covered area?	✓	Recycling process has low risk of contamination
2.10	Installation of stop-logs in perimeter d process with potentially high level of o		areas where recovery	✓	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replaces	ments performed only in bunde	d maintenance area?	✓	Replacement activity is not observed
2.12	Contaminated water collected in the su facility or other appropriate treatment		ed at water treatment	✓	No contaminated water is observed



2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	Not required
2.15	Bulk cargo and materials packed properly?	
2.16	Temporary stockpiles covered during rainstorms?	No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?	No sand/silt is generated from the recycling process No sand/silt is generated from the recycling process
3. Air	Quality	N/A Yes No Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	Not required
	a) SP Licence conditions / monitoring requirements comply?	
3.2	Operate without generation of noticeable odour?	
	a) If odour is detected, can the source be identified?	
	b) Odourous materials covered?	
	c) If odour control system is installed, is it operating normally?	
3.3	Dusty materials dampened prior to loading/unloading?	Dampening of waste wood affects the wood quality and is therefore not applicable
3.4	Dust monitoring record available?	✓ Not required
	a) Monitoring frequency met the licence requirement?	
	b) Any exceedance?	
	c) If exceedance is recorded, follow-up action taken?	
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?	
3.6	Open burning prohibited?	
3.7	Emission from chimney or powered plant free of black smoke?	
3.8	Vehicles and equipment switched off while not in use?	
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	Not required
3.11	Air pollution control system properly maintained and function normally?	
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	
	a) Obtained approval for the use of controlled refrigerant?	
	b) If yes, record of refrigeration equipment service available?	
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	
3.14	Public road around site entrance kept clean and free from dust?	
3.15	Materials transported on trucks covered?	✓ Not observed



3.16	Truck loads to a level within the side and tail boards?	✓				Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	✓				Dampening of waste wood affects the wood quality and is therefore not applicable
3.18	Major dust source(s): Wind erosion	Vehicle/	equipn	ent 1	novem	ent
	Loading/unloading of materials	✓ Others:	n/a	a		
4. Wa	aste/Chemical Management					
Gener	ra <u>l</u>	N/	A Y	es	No	Remarks
4.1	Registered as chemical waste producer?	_				No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?	_				
4.3	Disposed of regularly and properly?	_				
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?			/		
4.5	Records of quantities of waste generated, recycled and disposed properly kept?	~				
4.6	Collection of sludge by licensed collector at regular intervals?	~				Not required
Packa	aging of Chemical Waste					
4.7	Stored in suitable container?	_				
4.8	Container properly closed or sealed?	_				
4.9	Spillage cleaned up immediately through the use of absorbent?	_				
4.10	Obtained approval for the use of chemical waste container >450L?	_				
Label	ling of Chemical Waste					
4.11	Provision of chemical waste label?	_				
	a) Label is securely attached and visible?	_				
	b) Label is bilingual and in proper dimension?	_				
	c) Information is accurate and sufficient?	~				
Stora	ge of Chemical Waste					
4.12	Proper "Chemical Waste" sign displayed?	~				
4.13	Incompatible wastes separated by impermeable partition?	✓				
4.14	Containers kept in cabinet or receptacle of suitable material (if quantity $<$ 50L), or provide with drip trays capable of storing 110% of the volume of the largest container (if quantity					
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	V				
4.16	Properly stored and locked in designated area with adequate ventilation?	✓				
4.17	Storage area paved with concrete and kept clean and dry?	_				
4.18	Cover provided for outdoor storage area?	_				
4.19	Chemical waste collected by licensed collector?	_				
<u>Liqui</u>	d Waste Storage					
4.20	Storage area provided with permeation-proof floor or surface?	~				
4.21	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	_				

SITE INSPECTION CHECKLIST



4.22	Walls or partitions of stacked container storage area constructed of imperm	eable material?	/	
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)		N/A Yes N	No Remarks
5.1	Alert workers and visitors of possible LFG hazards?			Outside LFG consultation zone
5.2	Smoking and open fires prohibited?			
6. Ot	<u>hers</u>		N/A Yes N	No Remarks
6.1	Works confined within lot boundaries?		✓	
6.2	Damage to surrounding areas avoided?			
6.3	Site lighting designed to avoid glare to surrounding receivers?		✓	<u> </u>
6.4	Materials and machinery stored in an orderly manner?			
6.5	Areas within lot for recycling activities paved with concrete?			
6.6	Potential stagnant pools cleared and mosquito breeding prevented?			□
6.7	Valid calibration certificate for any monitoring equipment?		✓	No monitoring is required
6.8	Valid licence(s) obtained for manufacture or storage of dangerous goods?		✓ <u> </u>	Not required
	a) Storage area in compliance with the approved plan?		✓	
	b) Storage area is securely locked?		✓	
	c) Total storage capacity in compliance with relevant statutory requirement	?	✓	
	d) Proper labelling provided?		✓	
	e) Dangerous goods properly packaged?		✓ <u> </u>]
Rema	nrks:			
New	<u>Observation</u>			
•	No major environmental deficiency was observed.			
Signa	itures:			
ET R	epresentative: Operator Representative:	Tenant Representative	:	IEC Representative:
6	med wo	~		Baga
Name:	Chris LO Name: May Wu	Name: Eagle La	m Nan	no: Brycen Cury.
Date:	2020/10/20 Date: 3 0 0 CT 2020	Date: 4/11/202	O Date	28/10/2020



	Inspection Date: 2020/11/25 Time: 9:30 Lot Number: T7 Tenant: FWMG (Wood)	Inspected by: Chris LO, Timmy WONG
Weat	<u>her</u>	
	Condition: Sunny Fine Overcast Drizzle	
	Temperature: 24 °C Humidity: ✓ High Wind: Calm ✓ Light Breeze Strong	ModerateLow
1. Ge	<u>neral</u>	N/A Yes No Remarks
1.1	Environmental Permit (EP) for Tenant displayed at entrances/exits?	EP for tenant is not required
1.2	Environmental Policy documented?	✓ UPML's Environmental Policy is followed
1.3	Environmental Management Plan (EMP) kept up-to-date?	✓ UPML's EMP is followed
1.4	Emergency Response Plan (ERP) documented?	✓ UPML's ERP is followed
1.5	All recycling processes in operation have been approved by WRG of EPD?	
1.6	Any record of complaint or prosecution?	
2. Wa	nter Qualit <u>y</u>	N/A Yes No Remarks No wastewater is generated from the
2.1	Valid Effluent Discharge Licence available?	recycling process
	a) Sampling record available?	
	b) Monitoring frequency met the licence requirement?	
	c) Monitoring result comply with the licence requirement?	
	d) If exceedance is recorded, any follow-up action taken?	
2.2	Provision of wastewater treatment facility (WTF) prior to discharge?	
	a) Adequate capacity?	
	b) Properly maintained and function normally?	
2.3	Surface run-off control measures in place and adequately maintained?	
2.4	Surface run-off discharging into drainage system?	
2.5	All manholes covered?	
2.6	Foam, oil, grease, debris, rubbish and other objectionable matters prevented from entering nearby drains or sewer?	
2.7	Storage of materials and equipment located away from water bodies?	
2.8	Drainage system well maintained to prevent flooding or overflow?	Recycling process has low risk of
2.9	Processes or activities with high risk of contamination located under covered area?	contamination Stop-logs are available for use by tenant if
2.10	Installation of stop-logs in perimeter drainage system for uncovered areas where recovery process with potentially high level of contamination is carried out?	Stop-logs are available for use by tenant if needed.
2.11	Equipment oil and lubrication replacements performed only in bunded maintenance area?	Replacement activity is not observed
2.12	Contaminated water collected in the surface drainage system is treated at water treatment facility or other appropriate treatment facility?	No contaminated water is observed




2.13	Drainage from maintenance area discharged via oil interceptor?	✓ Not required
	a) Oil and grease removed regularly?	
	b) Collected by licensed collector?	
2.14	Follow Cargo Handling Guideline to minimise the chance of accidental spillage during loading and unloading adjacent to marine frontage?	Not required
2.15	Bulk cargo and materials packed properly?	✓ □ □ □
2.16	Temporary stockpiles covered during rainstorms?	✓ No rainstorm during inspection
2.17	Measures to prevent the washing away of sand/silt to drains?	No sand/silt is generated from the recycling process
3. Air	Quality	N/A Yes No Remarks
3.1	Valid Specified Process (SP) Licence available for all specified process?	✓ Not required
	a) SP Licence conditions / monitoring requirements comply?	/
3.2	Operate without generation of noticeable odour?	
	a) If odour is detected, can the source be identified?	
	b) Odourous materials covered?	
	c) If odour control system is installed, is it operating normally?	<u> </u>
3.3	Dusty materials dampened prior to loading/unloading?	Dampening of waste wood affects the wood quality and is therefore not applicable
3.4	Dust monitoring record available?	✓ Not required
	a) Monitoring frequency met the licence requirement?	
	b) Any exceedance?	
	c) If exceedance is recorded, follow-up action taken?	/
3.5	Dust-suppression measures provided where main dust-generating activities take place (i.e. enclosures or regular dampening)?	
3.6	Open burning prohibited?	
3.7	Emission from chimney or powered plant free of black smoke?	
3.8	Vehicles and equipment switched off while not in use?	
3.9	Obtained approval for installation/alteration of furnace, oven or chimney consuming over 25L liquid fuel/hour, or 35kg solid fuel/hour, or 1150MJ gaseous fuel/hour?	Not required
3.10	Obtained approval for the use of liquid fuel with a viscosity point of ignition >30 centistokes or an equivalent viscosity?	Not required
3.11	Air pollution control system properly maintained and function normally?	
3.12	Dust collected by any air pollution control equipment installed by tenants tested to ensure compliance for landfill disposal?	
	a) Obtained approval for the use of controlled refrigerant?	✓ □ □
	b) If yes, record of refrigeration equipment service available?	
3.13	Only ultra-low sulphur diesel is used for activities requiring liquid fuel?	
3.14	Public road around site entrance kept clean and free from dust?	
3.15	Materials transported on trucks covered?	✓ Not observed



3.16	Truck loads to a level within the side and tail boards?	Not observed
3.17	Stockpiles of dusty materials covered or regularly watered?	Dampening of waste wood affects the wood quality and is therefore not applicable
3.18	Major dust source(s): Wind erosion	Vehicle/equipment movement
	Loading/unloading of materials	✓ Others: n/a
4. Wa	ste/Chemical Management	
Gener	<u>al</u>	N/A Yes No Remarks
4.1	Registered as chemical waste producer?	No chemical waste is observed
4.2	Sufficient receptacles (e.g. rubbish bins) available?	✓
4.3	Disposed of regularly and properly?	
4.4	Sorting of materials on-site for reuse or disposal to designated outlet?	
4.5	Records of quantities of waste generated, recycled and disposed properly kept?	
4.6	Collection of sludge by licensed collector at regular intervals?	Not required
Packa	iging of Chemical Waste	
4.7	Stored in suitable container?	
4.8	Container properly closed or sealed?	
4.9	Spillage cleaned up immediately through the use of absorbent?	
4.10	Obtained approval for the use of chemical waste container >450L?	
Label	ling of Chemical Waste	
4.11	Provision of chemical waste label?	
	a) Label is securely attached and visible?	
	b) Label is bilingual and in proper dimension?	
	c) Information is accurate and sufficient?	
Storas	ge of Chemical Waste	
4.12	Proper "Chemical Waste" sign displayed?	
	Incompatible wastes separated by impermeable partition?	
	Containers kept in cabinet or receptacle of suitable material (if quantity <50L), or provide with drip trays capable of storing 110% of the volume of the largest container (if quantity capable of storing 110%).	
4.15	Enclosed on 3 sides with no less than 2m in height or height of tallest container / stack of containers?	
4.16	Properly stored and locked in designated area with adequate ventilation?	
4.17	Storage area paved with concrete and kept clean and dry?	
4.18	Cover provided for outdoor storage area?	
	Chemical waste collected by licensed collector?	
	d Waste Storage	<u> </u>
	Storage area provided with permeation-proof floor or surface?	
	Capacity of retention structure sufficient to accommodate contents of the largest container or 20% volume of the material in storage?	



4.22	Walls or partitions of stacked container storage area constructed of imperm	neable material?
5. La	ndfill Gas (LFG) (within LFG Consultation Zone)	N/A Yes No Remarks
5.1	Alert workers and visitors of possible LFG hazards?	Outside LFG consultation zone
5.2	Smoking and open fires prohibited?	
6. Ot	ner <u>s</u>	N/A Yes No Remarks
6.1	Works confined within lot boundaries?	
6.2	Damage to surrounding areas avoided?	
6.3	Site lighting designed to avoid glare to surrounding receivers?	
6.4	Materials and machinery stored in an orderly manner?	
6.5	Areas within lot for recycling activities paved with concrete?	
6.6	Potential stagnant pools cleared and mosquito breeding prevented?	
6.7	Valid calibration certificate for any monitoring equipment?	✓ No monitoring is required
6.8	$Valid\ licence(s)\ obtained\ for\ manufacture\ or\ storage\ of\ dangerous\ goods?$	✓ Not required
	a) Storage area in compliance with the approved plan?	
	b) Storage area is securely locked?	
	c) Total storage capacity in compliance with relevant statutory requiremen	t?
	d) Proper labelling provided?	
	e) Dangerous goods properly packaged?	
Rema	rks:	
New	<u>Observation</u>	
	No major environmental deficiency was observed.	
Signa	tures:	
ET R	epresentative: Operator Representative:	Tenant Representative: IEC Representative:
6	and and	Day
Name:	Chris LO Name: May Wu	Name: Eagle Lam Name: By Yer)
Date:	2020/11/25 Date: 3 Dec 2020	Date: 10/12/2020 Date: 02 / 12 / 200



Draft 1_____AEC

SITE INSPECTION CHECKLIST




Inspection Date: Lot Number:	2020/10/20 n/a	Time: Tenant:	9:40 - 12:40 n/a	Inspected by:	Chris LO, Charles YUEN
Weather Condition: Temperature: Wind:	Sunny 24 °C Calm	Fine	Overcast Drizzle Humidity: High Breeze Strong	Rain Moderate	Storm Hazy Low

Follow-up from Previous Audit

Baguio

1) Mud debris was still observed being flushed into the stormwater gulley on the road outside the site entrance. The tenant should implement sufficient measures on site to collect, treat and reuse wastewater generated from construction activity (such as wheel-washing activity) for better










(Observed on 23 September 2020)









SITE INSPECTION CHECKLIST



Temporary stockpile of C&D materials was still observed to not be covered or watered. The tenant was requested to cover the stockpiles with tarpaulin 2) for dust suppression. This item will be reviewed in the next inspection.





(Observed on 20 October 2020)

(Observed on 23 September 2020)

New Observation

HKBRC

No major environmental deficiency was observed.

Baguio

No major environmental deficiency was observed.

3R

No major environmental deficiency was observed.

South China

No major environmental deficiency was observed.

Other Areas

No major environmental deficiency was observed.

Signatures:

ET Representative:

Name: Chris LO

Date: 2020/10/20

Operator Representative:

May Wu

Date:

30 OCT 2020

Tenant Representative:

Name:

Date:

IEC Representative:

Name:

Date:

SITE INSPECTION CHECKLIST



Inspection Date: Lot Number:	2020/11/25 n/a	Time: Tenant:	9:40 - 13:10 n/a	Inspected by:	Chris LO, Timmy WONG
Weather Condition: Temperature: Wind:	✓ Sunny 24 °C Calm	Fine Light	Overcast Drizzle Humidity: High Breeze Strong	Rain Moderate	Storm Hazy Low

Follow-up from Previous Audit

Baguio

1) The surface of Baguio's lot was observed to have been paved with concrete during the site inspection. It is noted the existing surface channel was temporarily blocked off from the public drainage network to facilitate the drainage works of the site. However, mud debris was still observed in the surface channel. The contractor was requested to clean the mud debris before operation of the site's drainage network to prevent runoff into the public drainage system. This item will be reviewed in the next inspection.








(Observed on 20 October 2020)









SITE INSPECTION CHECKLIST



Temporary stockpile of C&D materials was still observed to not be covered or watered. The tenant was requested to cover the stockpiles 2) with tarpaulin for dust suppression. This item will be reviewed in the next inspection.



(Observed on 20 October 2020)



(Observed on 25 November 2020)

New Observation

HKBRC

No major environmental deficiency was observed.

Baguio

No major environmental deficiency was observed.

<u>3R</u>

No major environmental deficiency was observed.

South China

No major environmental deficiency was observed.

Other Areas

No major environmental deficiency was observed.

Signatures:

ET Representative:

Name: Chris LO

Date: 2020/11/25

Operator Representative:

Name:

May Wu

Date:

3 Dec 2020

Tenant Representative:

Name:

Date:

IEC Representative:

Date:

SITE INSPECTION CHECKLIST



Inspection Date: Lot Number:	2020/12/17 n/a	Time:	9:40 - 12:40 t: n/a	Inspected by:	Chris LO, Timmy WONG	
Weather Condition: Temperature: Wind:	Sunny 12 °C Calm	Fine Light	Overcast Drizzle Humidity: High Breeze Strong	Rain Moderate	Storm Hazy Low	

Follow-up from Previous Audit

Baguio

 It is noticed the existing surface channel was still blocked. Mud debris was still observed in the surface channel. The contractor was requested clean the mud debris before operation of the site's drainage network to prevent runoff into the public drainage system.
 This item will be reviewed in the next inspection.







(Observed on 25 November 2020)







(Observed on 17 December 2020)

SITE INSPECTION CHECKLIST



2) Temporary stockpile of C&D materials was still observed to not be covered or watered. The tenant was requested to cover the stockpiles with tarpaulin for dust suppression. This item will be reviewed in the next inspection.



(Observed on 25 November 2020)



(Observed on 17 December 2020)

New Observation

HKBRC

· No major environmental deficiency was observed.

Baguio

· No major environmental deficiency was observed.

<u>3R</u>

· No major environmental deficiency was observed.

South China

· No major environmental deficiency was observed.

FWMG

· No major environmental deficiency was observed.

Other Areas

· No major environmental deficiency was observed.

Signatures:

ET Representative:

Name: Chris LO

Date: 2020/12/17

Operator Representative:

Name: May Wu

Date: 24 DEC 2020

Tenant Representative:

Name:

Date:

IEC Representative:

Name:

Date: