

APPENDIX 14.1. PHOTO RECORDS OF SITE VISITS

<p>Plate 1 Reprofilling of ponds at Fung Kong</p> 	<p>Plate 2 Fisheries apparatus at Fung Kong</p> 
<p>Plate 3 Aquaculture ponds at Long Valley</p> 	<p>Plate 4 Wildlife ponds at Long Valley</p> 
<p>Plate 5 Re-instated Fish Pond at Lo Wu Correctional Institution; this pond subsequently developed into marsh and is classified as such in the Ecological Impact Assessment</p>	<p>Plate 6 Abandoned pond to the west of Ng Tung River</p>
	

Plate 7 Abandoned Pond at Nam Wa Po; this is a typical example of isolated abandoned ponds in the assessment area, this pond has been adversely affected by dumping of construction waste



Plate 8 Mitigation Meander along Ng Tung River (note: recreational angler present)

