



Highways Department

Contract No. HY/2007/13

**Environmental Team for Deep Bay Link
(Operational Phase)**

**Monthly EM&A Report No. 3
(for the month of December 2007)**

01/2008

	Name	Signature
Prepared & Checked:	Y T Tang	
Reviewed & Approved:	Alan Kwok	

Version:	0	Date: 14 January 2008
<p>The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and Maunsell Consultants Asia Ltd. accepts no responsibility for its use by others.</p> <p>This report is copyright and may not be reproduced in whole or in part without prior written permission.</p>		

Maunsell Consultants Asia Ltd.

8/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2605 6262 Fax: (852) 2891 0305 www.maunsell.aecom.com

**CH2MHILL**

西圖香港有限公司
CH2M HILL Hong Kong Limited
Suite 1801, Harcourt House
39 Gloucester Road
Wanchai, Hong Kong
Tel (852) 2507-2203
Fax (852) 2507-2293

Our Ref.: HYDDBLWCEM00/2/10943

Date: 15 January 2008

Highways Department
Major Works Project Management Office
6th Floor, Ho Man Tin Government Offices,
88 Chung Hau Street, Homantin, Kwoloon

By Fax (2761 4864) & Post

Attention: Mr. Robert Chan / Mr. Stephen Chan

Dear Sirs,

**Re: Contract No. HY/2007/13
Deep Bay Link (Operational Phase)
Monthly EM&A Report for Operational Phase – December 2007**

Reference is made to ET's e-mail correspondences enclosed with a copy of the Operational Phase Monthly EM&A Report for December 2007 and revised pages for the captioned project. We are pleased to inform that we have no further comment on the captioned report.

We are pleased to inform you that the captioned report, which had been certified by the Environmental Team Leader, is verified by IEC in compliance with Condition 1.9 of the Environmental Permit No.EP-163/2003/G of the project.

Thank you very much for your kind attention and please do not hesitate to contact the undersigned or our Mr. Simon Lam if you have any queries.

Yours sincerely,

K.S. Lee
Independent Environmental Checker

c.c. Mr. Alan Kwok
Mr. Eric Chan

MCAL (ETL)
Arup (HY2002/21)

By Fax: 2891 0305
By Fax: 2268 3955

TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY	I
Environmental Monitoring Works	I
Reporting Change	I
Environmental Complaints and Prosecution	I
Future Key Issues	II
1. INTRODUCTION	1
Background	1
Project Organization	1
Summary of the EM&A Requirements	1
2. OPERATIONAL NOISE MONITORING	2
Monitoring Requirements	2
Monitoring Parameters, Frequency and Duration	2
Monitoring Locations	2
Results and Observations	2
3. WATER QUALITY	3
Monitoring Requirements	3
Monitoring Equipment	3
Monitoring Parameters, Frequency and Duration	3
Monitoring Locations	4
Monitoring Methodology	4
QA/QC Procedure and Detection Limits	5
Results and Observations	5
4. ECOLOGY	10
Monitoring Requirements	10
Monitoring Parameters, Frequency and Duration	10
Hydrology	10
Fauna	11
Vegetation	16
5. licencing and implementation status of ENVIRONMENTAL mitigation measures	20
Status of Environmental Licensing and Permitting	20
Implementation Status of Environmental Mitigation Measures	20
Summary of Exceedances of Environmental Quality Performance Limit	20
Implementation Status of Environmental Complaint Handling Procedures	20
6. FUTURE KEY ISSUES	21
Key Issues for the Coming Month	21
Environmental Monitoring Programme for the Next Month	21
7. CONCLUSIONS AND RECOMMENDATIONS	22
Conclusion	22
Recommendations	22

List of Tables

Table 3.1	Road Surface Runoff from Carriageway Monitoring Equipment	3
Table 3.2	Locations of Road Surface Runoff Monitoring in the Reporting Month.....	4
Table 3.3	Detection Limit for Monitoring Parameters.....	5
Graph 3.1	Graphical Presentation of Total Suspended Solids Concentration	6
Graph 3.2	Graphical Presentation of Nitrite and Nitrate Concentration	6
Graph 3.3	Graphical Presentation of Total Kjeldahl Nitrogen Concentration	6
Graph 3.4	Graphical Presentation of Total Phosphorus Concentration	7
Graph 3.5	Graphical Presentation of Total Organic Carbon Concentration	7
Graph 3.6	Graphical Presentation of Chemical Oxygen Demand Concentration	7
Graph 3.7	Graphical Presentation of Copper Concentration	8
Graph 3.8	Graphical Presentation of Lead Concentration	8
Graph 3.9	Graphical Presentation of Zinc Concentration	8
Table 4.1	Water Levels at Pond 15X, 15ABD, 15Y and 15C1	11
Table 4.2	Water Quality at Pond 15X, 15ABD, 15Y and 15C1	11
Table 4.3	Summary of Abundance and Richness of Bird Species at Pond 15 Complex.....	12
Table 4.4	Abundance and Richness of Bird Species Recorded at Pond 15X, 15ABD, 15Y and 15C1 over the 2-Consecutive-Days Survey	13
Table 4.5	Summary of Benthos Recorded at Pond 15X, 15ABD, 15Y and 15C1.....	14
Graph 4.1	Number of Benthos Individuals Recorded at Pond 15X, 15ABD, 15Y and 15C1	14
Graph 4.2	Species Richness and Dry Biomass of Each Benthos Species Recorded at Pond 15X, 15ABD, 15Y and 15C1	15
Graph 4.3	Composition of Benthos Species and Dry Biomass at Pond 15X, 15ABD, 15Y and 15C1	15
Table 4.6	Summary of Pelagic Fauna Monitoring Results at Pond 15 Complex	16
Figure 4.4	Abundance and Biomass of Pelagic Fauna at Pond 15X, 15ABD, 15Y and 15C1	16
Table 4.7	Summary of Flora Species Recorded in Pond 15X, 15ABD, 15Y and 15C1	17
Figure 4.5	Average Floral Composition in the Fixed Transects at Pond 15X, 15ABD, 15Y and 15C1	18
Table 5.1	Summary of Environmental Notification, Licensing and Permit Status	20

List of Figures

Figure 1.1	Project Organization
Figure 1.2	Site Layout
Figure 3.1	Road Surface Runoff from Carriageway Monitoring Locations
Figure 4.1	Locations of Fixed Sampling Points for Bird Monitoring
Figure 4.2	Locations of Sampling Points for Benthos Monitoring
Figure 4.3	Locations of Fixed Flora Transect
Figure 4.4A	Photos of Quadrats for Flora Monitoring (Page 1 of 4)
Figure 4.4B	Photos of Quadrats for Flora Monitoring (Page 2 of 4)
Figure 4.4C	Photos of Quadrats for Flora Monitoring (Page 3 of 4)
Figure 4.4D	Photos of Quadrats for Flora Monitoring (Page 4 of 4)

List of Appendices

Appendix A	Contact of Key Environmental Personnel
Appendix B	Action / Limit Levels and Event Action Plans
Appendix C	Environmental Monitoring Schedules
Appendix D	Summary of Environmental Mitigation Implementation Schedule
Appendix E	Environmental Complaint Handling Procedure
Appendix F	Results of Road Surface Runoff from Carriageway Monitoring
Appendix G	Interim Notifications of Environmental Exceedances
Appendix H	QA / QC Results
Appendix I	Results of Ecological Monitoring at Pond 15 Complex