



VP3 – Existing conditions



VP3 – Photomontage at Day 1 of operation with no mitigation / enhancement

Figure 11.10a

DATE: 25/09//2017

Photomontage from VP3 – View from Lo Kei Wan, Lantau Island
(Sheet 1 of 2)



VP3 – Photomontage at Day 1 of operation with mitigation / enhancement



VP3 – Photomontage at Year 10 of operation with mitigation / enhancement

Figure 11.10b

Photomontage from VP3 – View from Lo Kei Wan, Lantau Island
(Sheet 2 of 2)

DATE: 25/09//2017

Environmental
Resources
Management

