


VP4 – Existing conditions



VP4 – Photomontage at Day 1 of operation with no mitigation / enhancement


Figure 11.11a

Photomontage from VP4 – View from Cheung Sha Beach, S. Lantau  
(Sheet 1 of 2)


DATE: 25/09//2017

Environmental  
Resources  
Management





VP4 – Photomontage at Day 1 of operation with mitigation / enhancement



VP4 – Photomontage at Year 10 of operation with mitigation / enhancement

Figure 11.11b

Photomontage from VP4 – View from Cheung Sha Beach, S. Lantau  
(Sheet 2 of 2)

DATE: 25/09//2017

Environmental  
Resources  
Management

