



VP9 – Existing conditions



VP9 – Photomontage at Day 1 of operation with no mitigation / enhancement

Figure 11.16a

Photomontage from VP9 – View from Lamma Island near Lo So Shing  
(Sheet 1 of 2)

DATE: 25/09/2017

Environmental  
Resources  
Management





VP9 – Photomontage at Day 1 of operation with mitigation / enhancement



VP9 – Photomontage at Year 1 of operation with mitigation / enhancement

Figure 11.16b

Photomontage from VP9 – View from Lamma Island near Lo So Shing  
(Sheet 2 of 2)

DATE: 25/09/2017

Environmental  
Resources  
Management

