





VP12 – Existing conditions



VP12 – Photomontage at Day 1 of operation with no mitigation / enhancement



VP12 – Photomontage at Day 1 of operation with mitigation / enhancement



VP12 – Photomontage at Year 10 of operation with mitigation / enhancement

Figure 11.19b

Photomontage from VP12 – View from South Lantau Country Trail
(Sheet 2 of 2)

DATE: 25/09/2017

Environmental
Resources
Management

