




VP1 – Existing conditions



VP1 – Photomontage at Day 1 of operation with no mitigation / enhancement

Figure 11.8a

Photomontage from VP1 – View from Siu A Chau
(Sheet 1 of 2)


DATE: 25/09//2017

Environmental
Resources
Management





VP1 – Photomontage at Day 1 of operation with mitigation / enhancement



VP1 – Photomontage at Year 10 of operation with mitigation / enhancement

Figure 11.8b

Photomontage from VP1 – View from Siu A Chau
(Sheet 2 of 2)

DATE: 25/09//2017

Environmental
Resources
Management

