


(a) Flat featureless seabed in Segment E, indicative of much of the Assessment Area



(b) Rocky seabed in Segment C

Figure 12.12

Seabed Condition of the Assessment Area

DATE: 10/08/2017

Environmental
Resources
Management

