



Contract No. HY/99/19

**Middle Section
Castle Peak Road Improvement between
Ting Kau and Sham Tseng, Tsuen Wan**

**Annual EM&A Review Report No. 3
(July 2004 - June 2005)**

[August 2005]


Reviewed by (PM):


Checked by:


Approved by:

Report Version: <u>Rev. 0</u>	Date of Submission: <u>10 August 2005</u>
-------------------------------	---

The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD

11/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305 Email: mem@maunsell.aecom.com

TABLE OF CONTENTS

EXECUTIVE SUMMARY

1. INTRODUCTION

BACKGROUND
SUMMARY OF CONSTRUCTION WORKS

2. ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS

MONITORING PARAMETERS
MONITORING METHODOLOGY AND CALIBRATION DETAILS
ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)
ENVIRONMENTAL MITIGATION MEASURES

3. MONITORING RESULTS

AIR QUALITY
NOISE LEVEL
WATER QUALITY

4. INSPECTION RESULTS

IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES
STATUS OF ENVIRONMENTAL LICENSING AND PERMITTING

5. NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVEL)

SUMMARY OF EXCEEDANCES
REVIEW OF THE REASONS FOR AND THE IMPLICATIONS OF NON-COMPLIANCE
SUMMARY OF ACTIONS TAKEN

6. ENVIRONMENTAL COMPLAINTS

COMPLAINT LOG
COMPLAINT HANDLING PROCEDURE

7. NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS

8. ANNUAL SUMMARY

REVIEW OF EM&A PROGRAM
COMPARISON OF THE EM&A DATA WITH THE EIA PREDICTIONS
REVIEW OF THE MONITORING METHODOLOGY
REVIEW OF THE MONITORING RESULTS

9. COMMENTS, CONCLUSIONS AND RECOMMENDATIONS

List of Tables

Table 1.1	Contact Information of Key Personnel
Table 1.2	Summary of Works Undertaken in the Reporting Year
Table 3.1	Summary of Air Quality Exceedances for the Reporting Year
Table 3.2	Comparison of Baseline and Impact Monitoring Results of 1-hr TSP Concentration in the Reporting Year
Table 3.3	Comparison of Baseline and Impact Monitoring Results of 24-hr TSP Concentration in the Reporting Year
Table 3.4	Comparison of Baseline and Impact Monitoring Results of Noise (Day-time) Monitoring in the Reporting Year
Table 3.5	Comparison of Baseline and Impact Monitoring Results of Noise (Evening Time) Monitoring in the Reporting Year
Table 3.6	Total Number of Water Quality Exceedances in the Reporting Year
Table 4.1	Summary of Waste Disposal for the Reporting Year (No. of Truckloads)
Table 5.1	Number of Exceedances in the Reporting Year

List of Figures

Figure 1.1	Project Site Location
Figure 2.1	Air Quality and Noise Environmental Monitoring Stations (1 of 3)
Figure 2.2	Air Quality and Noise Environmental Monitoring Stations (2 of 3)
Figure 2.3	Air Quality and Noise Environmental Monitoring Stations (3 of 3)
Figure 2.4	Water Quality Monitoring Stations (1 of 2)
Figure 2.5	Water Quality Monitoring Stations (2 of 2)
Figure 6.1	Complaint Response Procedures

Appendices

Appendix A	Project Organisation Chart and Contact Details of the Project Organisation
Appendix B	Construction Programme
Appendix C	Details of Monitoring Requirements
Appendix D	Environmental Quality Performance (Action/Limit) Levels
Appendix E	Implementation Status of Environmental Mitigation Measures (EMIS)
Appendix F	Graphical Presentation of Air Quality Monitoring Results
Appendix G	Graphical Presentation of Noise Monitoring Results
Appendix H	Graphical Presentation of Water Monitoring Results
Appendix I	Summary Status of Environmental Licences and Permits
Appendix J	Summary of Environmental Complaints