



Highways Department

**Contract No.: HY/2002/05
Route 9 – Advance Works
Contract No.: HY/2002/06
Route 9 – Re-provisioning of Waterworks**

**Quarterly EM&A Summary Report No. 1
(From November 2002 to January 2003)
(Rev.0)**

February 2003

Prepared By	 (Resident Site Staff)
Certified By	 (Environmental Team Leader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

MEMCL accepts no responsibility for changes made to this report by third parties.

**MAUNSELL ENVIRONMENTAL
MANAGEMENT CONSULTANTS LTD**
Room 1213-1219, Grand Central Plaza, Tower 2
138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305
Email: mem@maunsell.com.hk

Maunsell

CONTENTS

EXECUTIVE SUMMARY

1. INTRODUCTION
BACKGROUND
SUMMARY OF CONSTRUCTION WORKS
2. ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS
MONITORING PARAMETERS
MONITORING METHODOLOGY AND CALIBRATION DETAILS
ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)
ENVIRONMENTAL MITIGATION MEASURES
3. MONITORING RESULTS
AIR QUALITY
NOISE
4. INSPECTION RESULTS
IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES
STATUS OF ENVIRONMENTAL LICENSING AND PERMITTING
ADVICE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS
5. NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)
SUMMARY OF EXCEEDANCES
REVIEW OF THE REASONS FOR AND THE IMPLICATIONS OF NON-COMPLIANCE
SUMMARY OF ACTIONS TAKEN
6. ENVIRONMENTAL COMPLAINTS
COMPLAINT LOG
7. NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS
8. COMMENTS, CONCLUSIONS AND RECOMMENDATIONS

LIST OF TABLES, FIGURES, AND APPENDICES

TABLES:

TABLE 1.1	CONTACT INFORMATION OF KEY PERSONNEL
TABLE 1.2	SUMMARY OF WORKS UNDERTAKEN IN THE REPORTING QUARTER
TABLE 3.1	COMPARISON OF BASELINE AND AVERAGED IMPACT MONITORING RESULTS OF 1-HR TSP CONCENTRATION
TABLE 3.2	COMPARISON OF BASELINE AND AVERAGED IMPACT MONITORING RESULTS OF 24-HR TSP CONCENTRATION
TABLE 3.3	COMPARISON OF BASELINE AND IMPACT MONITORING RESULTS OF NOISE (07:00 – 19:00 ON ALL WEEKDAYS) MONITORING
TABLE 3.4	COMPARISON OF BASELINE AND IMPACT MONITORING RESULTS OF NOISE (19:00 – 23:00 ON ALL WEEKDAYS) MONITORING
TABLE 4.1	ESTIMATED WASTE DISPOSAL IN THE REPORTING QUARTER

FIGURES:

Figure 1.1	Project Site Location
Figure 2.1	Air Quality Environmental Monitoring Stations
Figure 2.2	Noise Environmental Monitoring Stations

APPENDICES:

Appendix A	Project Organisation Chart
Appendix B	Construction Programme
Appendix C	Details of Monitoring Requirements
Appendix D	Copy of Equipment Calibration Certificates
Appendix E	Environmental Quality Performance (Action/Limit) Levels
Appendix F	Implementation Status of Environmental Mitigation Measures (EMIS)
Appendix G	Air Quality Monitoring Results and Graphical Presentation
Appendix H	Noise Monitoring Results and Graphical Presentation
Appendix I	Summary Status of Environmental Licences and Permits
Appendix J	Interim Notification of Environmental Quality Limit Exceedance