

Territory Development Department
NT EAST Development Office

Sha Tin New Town, Stage II

**Route 9 between Cheung Sha Wan and
Sha Tin – Entrusted Portion**

**Environmental Monitoring and Audit
Quarterly Report (Version 1)**

November 2002 to January 2003

Certified By



(Environmental Team/Leader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties.

CINOTECH CONSULTANTS LTD

Room 1601-1610, Delta House,
3 On Yiu Street,

Shatin, NT, Hong Kong

Tel: (852) 2151 2083 Fax: (852) 3107 1388

Email: info@cinotech.com.hk

TABLE OF CONTENTS

EXECUTIVE SUMMARY

Environmental Monitoring Works
Environmental Complaint and Prosecution
Environmental Licensing and Permitting
Future Key Issues

1. INTRODUCTION

2. PROJECT CHARACTERISTICS

Project Organization and Contacts of Key Management
Construction Programme and Synopsis of Work

3. ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS

Monitoring Parameters and Monitoring Locations
Monitoring Methodology and Calibration Details
Environmental Quality Performance Limits (Action and Limit Levels)
Environmental Mitigation Measures

4. MONITORING RESULTS

Weather Conditions
Air Quality
Noise

5. AUDIT RESULTS

Implementation Status of Environmental Mitigation Measures
Site Audit Summary
Status of Environmental Licensing and Permitting
Advice on Solid Waste Management Status

6. NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)

Summary of Exceedances
Review of the Reasons for and the Implications of Non-compliance
Summary of Actions Taken

7. ENVIRONMENTAL COMPLAINTS

Complaints Log

8. NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS

9. COMMENTS, CONCLUSIONS AND RECOMMENDATIONS

LIST OF TABLES, FIGURES, AND APPENDICES

LIST OF TABLE

Table 2.1 Summary of Works Undertaken in the Reporting Months

LIST OF FIGURES

Figure 1 Site Layout Plan
Figure 2a Location of Monitoring Stations
Figure 2b Location of Monitoring Stations
Figure 3 Project Organization Chart

LIST OF APPENDICES

Appendix A Contact Details of the Project Organisation
Appendix B Construction Programme File1| File 2 | File 3 | File 4 | File 5 | File 6 | File 7 | File 8
Appendix C Monitoring Requirements
Appendix D Environmental Quality Performance (Action/Limit) Levels
Appendix E Graphical Presentation of Air Quality Monitoring Results
Appendix F Graphical Presentation of Noise Monitoring Results
Appendix G Implementation Status of Environmental Mitigation Measures (EMIS)
Appendix H Summary Status of Environmental Licences and Permits
Appendix I Complaint Log
Appendix J Summary of Exceedances for November 2002 to January 2003