



Environmental Management Division

**CALIBRATION REPORT**

Client : Maeda Corporation  
Address : Tai Po Site Office,  
Ting Kok Road,  
Tai Po

Report No. : CR 000075  
Page No. : 1 of 2  
Issue Date : 23/08/2006

Received Date : 19/08/2006  
Approved Signatory : Grace Ting  
Remarks :

Completion Date : 22/08/2006

**Calibration Results:**

Item : Gas Analyser model GA 2000, Geotechnical Instruments  
Serial No. : GA 08277  
Calibration Method : In house method (calibrated and checked with certified gas standards)  
Date of Calibration : 22/08/2006  
Results: :

**Oxygen**

Expected, %	Reading, %
0.0	0.0
7.7	7.1
20.0	19.8

**Methane**

Expected, %	Reading, %
0.0	0.0
16.6	15.6
31.6	30.4
44.8	45.3
60.0	60.3



Environmental Management Division

## CALIBRATION REPORT

Client : Maeda Corporation  
Address : Tai Po Site Office,  
Ting Kok Road,  
Tai Po

Report No. : CR 000075  
Page No. : 2 of 2  
Issue Date : 23/08/2006

Received Date : 19/08/2006  
Approved Signatory : Grace Ting  
Remarks :

Completion Date : 22/08/2006

### Calibration Results:

Item : Gas Analyser model GA 2000, Geotechnical Instruments  
Serial No. : GA 08277  
Calibration Method : In house method (calibrated and checked with certified gas standards)  
Date of Calibration : 22/08/2006  
Results :

#### Carbon Dioxide

Expected, %	Reading, %
0.0	0.0
11.1	10.6
21.3	21.1
30.1	31.2
40.0	39.9