CONTRACT NO: HK/2011/07

WANCHAI DEVELOPMENT PHASE II AND CENTRAL WANCHAI BYPASS SAMPLING, FIELD MEASUREMENT AND TESTING WORK (STAGE 2)

ENVIRONMENTAL PERMIT NO. EP-376/2009, FURTHER ENVIRONMENTAL PERMIT NO. FEP-01/376/2009

MONTHLY ENVIRONMENTAL MONITORING & AUDIT REPORT

- NOVEMBER 2015 -

CLIENTS:

Civil Engineering and Development Department

PREPARED BY:

Lam Geotechnics Limited

11/F Centre Point 181-185 Gloucester Road, Wanchai, H.K.

Telephone: (852) 2882-3939 Facsimile: (852) 2882-3331 E-mail: info@lamenviro.com

Website: http://www.lamenviro.com

CERTIFIED BY:

Raymond Dai

Environmental Team Leader

DATE:

10 December 2015



Ref.: AACWBIECEM00_0_7519L.15

14 December 2015

By Post and Fax (2691 2649)

AECOM Asia Company Limited 11/F Tower 2 Grand Central Plaza 138 Shatin Rural Committee Road Shatin New Territories Hong Kong

Attention: Mr. Conrad Ng

Dear Mr. Ng,

Re: Contract No. HK/2011/07 Wan Chai Development Phase II - Central-Wan Chai Bypass Sampling, Field Measurement and Testing Works (Stage 2)

Monthly Environmental Monitoring and Audit Report (November 2015) for EP-376/2009 and FEP-01/376/2009

Reference is made to the Environmental Team's submission of the captioned Monthly Environmental Monitoring and Audit (EM&A) Report for November 2015 received by e-mail on 10 December 2015 for our review and comment.

Please be informed that we have no adverse comment on the captioned submission. We write to verify the captioned submission in accordance with Condition 3.4 in the captioned Environmental Permit.

Thank you very much for your attention and please do not hesitate to contact the undersigned should you have any queries.

Yours sincerely,

David Yeung

Independent Environmental Checker

C.C.

CEDD

Attn: Mr. Stephen Lo

by fax: 2577 5040

Lam

Attn: Mr. Raymond Dai

by fax: 2882 3331

AECOM

Attn: Mr. Francis Leong/ Stephen Lai by fax: 2691 2649

Q:\Projects\AACWBIECEM00\Corr\AACWBIECEM00_0_7519L.15.docx



TABLE OF CONTENTS

| EXE | JUIIVE | SUMMARY | 3 |
|-----|--------------------------|--|----------|
| 1 | INTRO | DUCTION | 5 |
| | 1.1 1.2 | Scope of the Report | |
| 2 | PROJ | ECT BACKGROUND | 7 |
| | 2.1 2.2 2.3 | Background | 7 |
| 3 | STAT | JS OF REGULATORY COMPLIANCE | 10 |
| | 3.1 | Status of Environmental Licensing and Permitting under the Project | 10 |
| 4 | MONIT | TORING REQUIREMENTS | 12 |
| | 4.1 4.2 | Noise MonitoringAir Quality Monitoring | |
| 5 | MONIT | TORING RESULTS | 15 |
| | 5.1 5.2 5.3 | Noise Monitoring Results Air Quality Monitoring Results Waste Monitoring Results | 15 |
| 6 | COMP | LIANCE AUDIT | 18 |
| | 6.1 6.2 6.3 6.4 | Noise Monitoring | 18 18 |
| 7 | CUMU | LATIVE CONSTRUCTION IMPACTS DUE TO THE CONCURRENT PROJECTS | 19 |
| 8 | ENVIR | ONMENTAL SITE AUDIT | 20 |
| 9 | COMP | LAINTS, NOTIFICATION OF SUMMONS AND PROSECUTION | 21 |
| 10 | CONC | LUSION | 22 |



LIST OF TABLES

| Table 2.1 | Schedule 2 Designated Projects under this Project |
|------------------|--|
| <u>Table 2.2</u> | Contact Details of Key Personnel |
| Table 3.1 | Summary of the current status on licences and/or permits on environmental |
| | protection pertinent to the Project |
| Table 3.2 | Cumulative Summary of Valid Licences and Permits under Contract no. HK/2012/08 |
| Table 3.3 | Summary of submission status under FEP-01/376/2009 Condition |
| Table 4.1 | Noise Monitoring Stations |
| Table 4.2 | Air Quality Monitoring Stations |
| <u>Table 5.1</u> | Noise Monitoring Stations for Contract no. HK/2012/08 |
| Table 5.2 | Air Quality Monitoring Station for Contract no. HK/2012/08 |
| <u>Table 5.3</u> | Details of Waste Disposal for Contract no. HK/2012/08 |
| Table 8.1 | Summary of Environmental Inspections for Contract no. HK/2012/08 |
| Table 9.1 | Cumulative Statistics on Complaints |
| Table 9.2 | Cumulative Statistics on Successful Prosecutions |
| Table 10.1 | Summary of Key Construction Activities of Individual Contract(s) to be |
| | commenced in Coming Reporting Month |

LIST OF FIGURES

| Figure 2.1 | Project Layout |
|------------|--|
| Figure 2.2 | Project Organization Chart |
| Figure 4.1 | Locations of Environmental Monitoring Stations |

LIST OF APPENDICES

| Appendix 3.1 | Environmental Mitigation Implementation Schedule |
|---------------|--|
| Appendix 4.1 | _Action and Limit Level |
| Appendix 4.2 | Copies of Calibration Certificates |
| Appendix 5.1 | Monitoring Schedule for Reporting Month and Coming month |
| Appendix 5.2 | Noise Monitoring Results and Graphical Presentations |
| Appendix 5.3 | Air Quality Monitoring Results and Graphical Presentations |
| Appendix 6.1 | Event Action Plans |
| Appendix 6.2 | Notification of Exceedance |
| Appendix 9.1 | Complaint Log |
| Appendix 10.1 | Construction Programme of Individual Contracts |



EXECUTIVE SUMMARY

- i. This is the Environmental Monitoring and Audit (EM&A) Monthly Report November 2015 specific for Environmental Permit no. EP-376/2009 and Further Environmental Permit no. FEP-01/376/2009. The EM&A report is prepared by the Environmental Team (ET) employed under Contract No. HK/2011/07 Wan Chai Development Phase II and Central Wanchai Bypass Sampling, Field Measurement and Testing Works (Stage 2). This report presents the environmental monitoring findings and information recorded during the period October 2015 to November 2015. The cut-off date of reporting is at 27th of each reporting month.
- ii. In the reporting month, the principal work activities of the contract are included as follows:
 Contract no. HK/2012/08 Wan Chai Development Phase II Central- Wan Chai Bypass at Wan Chai West
 - Utilities
 - Drainage

Noise Monitoring

- iii. Noise monitoring was conducted at M1a Harbour Road Sports Centre.
- iv. One limit level exceedance was recorded at M1a Harbour Road Sports Centre on 24 November 2015 in the reporting month. After the investigation, the exceedance was concluded as non-project related.

Air Quality Monitoring


- v. 1-hour and 24-hour Total Suspended Particulates (TSP) monitoring were conducted on every six days basis at CMA5b and CMA6a Contractor HK/2012/08 Site Office.
- vi. Due to interruption of electricity supplies, the 24hr TSP monitoring of monitoring station CMA5b was rescheduled from 20 November 2015 to 21 November 2015.
- vii. No exceedances were recorded in the reporting month.

Complaints, Notifications of Summons and Successful Prosecutions

viii. No environmental complaint was received in this reporting month.

Site Inspections and Audit

ix. The Environmental Team (ET) conducted weekly site inspection for Contract no. HK/2012/08 in this reporting period. The Contractors rectified major observations and recommendations made during the audit sessions. No non-conformance was identified during the site inspections.





Future Key Issues

x. In the coming reporting month, the principal work activities of the contract is anticipated as follows:

<u>Contract no. HK/2012/08 – Wan Chai Development Phase II – Central- Wan Chai Bypass at Wan Chai West</u>

- Utilities
- Drainage

1 INTRODUCTION

1.1 Scope of the Report

- 1.1.1. Lam Geotechnics Limited (LGL) has been appointed take up the role as the Environmental Team (ET) under Environmental Permit no. EP-376/2009 and Further Environmental Permit no. FEP-01/376/2009 to implement the Environmental Monitoring and Audit (EM&A) programme as stipulated in the EM&A Manual of the approved Environmental Impact Assessment (EIA) Report for Wan Chai Development Phase II and Central-Wan Chai Bypass (Register No.: AEIAR-458/2008).
- 1.1.2. This report documents the finding of EM&A works for Environmental Permit (EP) no. EP-376/2009 and Further Environmental Permit no. FEP-01/376/2009, during the period October 2015 to November 2015. The cut-off date of reporting is the 27th of each reporting month.

1.2 Structure of the Report

- **Section 1** *Introduction* details the scope and structure of the report.
- **Section 2** *Project Background* summarizes background and scope of the project, site description, project organization and contact details of key personnel during the reporting period.
- Section 3 Status of Regulatory Compliance summarizes the status of valid Environmental Permits / Licenses during the reporting period.
- **Section 4** *Monitoring Requirements* summarizes all monitoring parameters, monitoring methodology and equipment, monitoring locations, monitoring frequency, criteria and respective event and action plan and monitoring programmes.
- **Section 5** *Monitoring Results* summarizes the monitoring results obtained in the reporting period.
- **Section 6 Compliance Audit** summarizes the auditing of monitoring results, all exceedances environmental parameters.
- Section 7 Cumulative Construction Impact due to the Concurrent Projects summarizes the relevant cumulative construction impact due to the concurrent activities of the concurrent Projects.



Section 8 Environmental Site Audit – summarizes the findings of weekly site inspections undertaken within the reporting period, with a review of any relevant follow-up actions within the reporting period.

Section 9 Complaints, Notification of summons and Prosecution – summarizes the cumulative statistics on complaints, notification of summons and prosecution

Section 10 Conclusion

2 **PROJECT BACKGROUND**

2.1 Background

2.1.1 Wan Chai Development phase II and Central-Wan Chai Bypass (hereafter called "the Project") are Designated Project (DP) under the Environmental Impact Assessment Ordinance (Cap. 499) (EIAO). The Environmental Impact Assessment (EIA) Report for Wan Chai Development phase II and Central-Wan Chai Bypass (Register No.: AEIAR-125/2008) has been approved on 11 December 2008.

2.2 Scope of the Project and Site Description

- 2.2.1. The design and construction of Wan Chai Development Phase II and Central Wanchai Bypass involves the construction and operation of primary and district distributor roads that is shown at Figure 2.1.
- 2.2.2. The key purpose of the study area encompasses the Wan Chai harbourfront area. The area starts at the boundary of Central Reclamation Phase III (CRIII) at the west and connects to the existing Hung Hing Road at the east. The scope of the project includes:
 - A dual 2-lane primary distributor road, Road P2, approximately 0.6km in length; and
 - Other new primary and district distributor roads connecting to the slip roads of the Central-Wan Chai Bypass with a total length of approximately 0.7km.
- 2.2.3. The project also contains various Schedule 2 DP that, under the EIAO, require Environmental Permits (EPs) to be granted by the DEP before they may be either constructed or operated. Table 2.1 summarises the DP under this Project. Figure 2.1 shows the locations of these Schedule 2 DP.

Table 2.1 Schedule 2 Designated Project under this Project

| Item | Designated Project | EIAO Reference |
|------|---|-------------------------|
| DP2 | Road P2 and other roads which are classified as | Schedule 2, Part I, A.1 |
| | primary/district distributor roads | |

2.2.4. The designated project work II (DP2) was awarded to China State-Leader Joint Venture HK/2012/08 (Contract Title: Wan Chai Development Phase II Central – Wan Chai Bypass at Wan Chai West) as part of the Project works by the Civil Engineering and Development Department (CEDD). The construction work under Contract no. HK/2012/08 was commenced on 13 May 2015.

2.3 **Project Organization and Contact Personnel**

Civil Engineering and Development Department and Highway Department are the overall 2.3.1 project controllers for the Wan Chai Development Phase II and Central-Wan Chai Bypass

7



respectively. For the construction phase of the Project, Project Engineer, Contractor(s), Environmental Team and Independent Environmental Checker are appointed to manage and control environmental issues.

2.3.2 The proposed project organization and lines of communication with respect to environmental protection works are shown in <u>Figure 2.2.</u> Key personnel and contact particulars are summarized in *Table 2.2*:

Table 2.2 Contact Details of Key Personnel

| Party | Role | Post | Name | Contact No. | Contact Fax |
|--|---|---|--------------------|----------------|----------------|
| AECOM | Engineer's Representative for WDII | Principal Resident Engineer | Mr. Frankie Fan | 2587 1778 | 2587 1877 |
| | Engineer's Representative for CWB | Principal Resident Engineer | Mr. Peter Poon | 3922 3388 | 3912 3010 |
| China State- Leader JV | Contractor under Contract | Project Director | C. N. LAI | 9106 5806 | 2877 1522 |
| | no. HK/2012/08 | Project Manager | Mr. Eddie Chung | 9189 8118 | |
| | | Site Agent | Mr. Keith Tse | 9037 1839 | |
| | | Environmental Officer | Mr. James Ma | 9130 9549 | |
| | | Environmental Supervisor | Mr. Y. L. HO | 9856 5669 | |
| Ramboll Environ Hong Kong Limited | Independent Environmental Checker (IEC) | Independent Environmental Checker (IEC) | Mr. David Yeung | 3465 2888 | 3465 2899 |
| Lam Geotechnics Limited | Environmental Team (ET) | Environmental Team Leader (ETL) | Mr. Raymond Dai | 2882 3939 | 2882 3331 |

- 2.3.3 In this reporting month, the principal work activities of the contract is included as follows:
 <u>Contract no. HK/2012/08 Wan Chai Development Phase II Central- Wan Chai Bypass at</u>
 Wan Chai West
 - Utilities
 - Drainage
- 2.3.4 In coming reporting month, the principal work activities of the contract is anticipated as



follows:

<u>Contract no. HK/2012/08 – Wan Chai Development Phase II – Central- Wan Chai Bypass at Wan Chai West</u>

- Utilities
- Drainage



3 STATUS OF REGULATORY COMPLIANCE

3.1 Status of Environmental Licensing and Permitting under the Project

3.1.1. A summary of the current status on licences and/or permits on environmental protection pertinent to the Project is shown in *Table 3.1*.

Table 3.1 Summary of the current status on licences and/or permits on environmental protection pertinent to the Project

| Permits and/or Licences | Reference No. | Issued Date | Status |
|------------------------------|-----------------|-------------|--------|
| Environmental Permit | EP-376/2009 | 13 Nov 2009 | Valid |
| Further Environmental Permit | FEP-01/376/2009 | 31 Mar 2015 | Valid |

3.1.2. The current status on licences and/or permits on environmental protection pertinent for contract no. HK/2012/08 under FEP-01/376/2009 showed in *Table 3.2.* and *Table 3.3*

Table 3.2 Cumulative Summary of Valid Licences and Permits under Contract no. HK/2012/08

| Permits and/or Licences | Reference No. | Issued Date | Valid Period/ Expiry Date | Status |
|--|-------------------|-------------|------------------------------|--------|
| Further Environmental Permit | FEP-01/376/2009 | 31 Mar 2015 | N/A | Valid |
| Notification of Works Under APCO | 355439 | 4 Feb 2013 | N/A | Valid |
| Registration as a Chemical Waste Producer | 5213-134-C3790-01 | 8 Mar 2013 | N/A | Valid |
| Billing Account under Waste Disposal Ordinance | 7016883 | 18 Feb 2013 | 18 Jul 2017 | Valid |
| Water Discharge Licence | WT00018470-2014 | 6 Mar 2014 | 31 Mar 2019 | Valid |
| Construction Noise Permit | GW-RS0921-15 | 26 Aug 2015 | 9 Sep 2015 to 8 Mar 2016 | Valid |



Table 3.3 Summary of submission status under FEP-01/376/2009 Condition

| EP Condition | Submission | Date of Submission |
|----------------|--------------------------------|--|
| Condition 2.9 | Noise Management Plan (Rev. 2) | Generally in order as commented by EPD on 27 Oct 2015 |
| Condition 2.10 | Landscape Plan (Rev. 0) | Generally in order as commented by EPD on 5 Aug 2015 |

3.1.3. Implementation status of the recommended mitigation measures during this reporting month is presented in *Appendix 3.1*.



4 MONITORING REQUIREMENTS

4.1 Noise Monitoring

NOISE MONITORING STATION

4.1.1. The noise monitoring station for the Project is listed and shown in *Table 4.1* and *Figure 4.1*. *Appendix 4.1* shows the established Action/Limit Levels for the monitoring works.

Table 4.1 Noise Monitoring Station

| District | Station | Description |
|----------|---------|----------------------------|
| Wan Chai | M1a | Harbour Road Sports Centre |

NOISE MONITORING PARAMETERS, FREQUENCY AND DURATION

- 4.1.2. The construction noise level shall be measured in terms of the A-weighted equivalent continuous sound pressure level (Leq). Leq (30 minutes) shall be used as the monitoring parameter for the time period between 0700 and 1900 hours on normal weekdays. For all other time periods, Leq (5 minutes) shall be employed for comparison with the Noise Control Ordinance (NCO) criteria. Supplementary information for data auditing, statistical results such as L10 and L90 shall also be obtained for reference.
- 4.1.3. Noise monitoring shall be carried out at all the designated monitoring stations. The monitoring frequency shall depend on the scale of the construction activities. The following is an initial guide on the regular monitoring frequency for each station on a weekly basis when noise generating activities are underway:
 - One set of measurements between 0700 and 1900 hours on normal weekdays.

MONITORING EQUIPMENT

- 4.1.4. As referred to in the Technical Memorandum ™ issued under the NCO, sound level meters in compliance with the International Electrotechnical Commission Publications 651: 1979 (Type 1) and 804: 1985 (Type 1) specifications shall be used for carrying out the noise monitoring. Immediately prior to and following each noise measurement the accuracy of the sound level meter shall be checked using an acoustic calibrator generating a known sound pressure level at a known frequency. Measurements may be accepted as valid only if the calibration level from before and after the noise measurement agrees to within 1.0 dB.
- 4.1.5. Noise measurements shall not be made in fog, rain, wind with a steady speed exceeding 5 m/s or wind with gusts exceeding 10 m/s. The wind speed shall be checked with a portable wind speed meter capable of measuring the wind speed in m/s.



4.2 Air Quality Monitoring

AIR QUALITY MONITORING STATIONS

4.2.1. The air quality monitoring stations for the Project are listed and shown in *Table 4.2* and *Figure*4.1. Appendix 4.1 shows the established Action/Limit Levels for the monitoring works.

Table 4.2 Air Quality Monitoring Stations


| Station ID | Description |
|------------|----------------------|
| CMA5b | Pedestrian Plaza |
| CMA6a | WDII PRE Site Office |

AIR QUALITY MONITORING PARAMETERS, FREQUENCY AND DURATION

- 4.2.2. One-hour and 24-hour TSP levels should be measured to indicate the impacts of construction dust on air quality. The 24-hour TSP levels shall be measured by following the standard high volume sampling method as set out in the Title 40 of the Code of Federal Regulations, Chapter 1 (Part 50), Appendix B.
- 4.2.3. All relevant data including temperature, pressure, weather conditions, elapsed-time meter reading for the start and stop of the sampler, identification and weight of the filter paper, and any other local atmospheric factors affecting or affected by site conditions, etc., shall be recorded down in detail.
- 4.2.4. For regular impact monitoring, the sampling frequency of at least once in every six-days, shall be strictly observed at all the monitoring stations for 24-hour TSP monitoring. For 1-hour TSP monitoring, the sampling frequency of at least three times in every six-days should be undertaken when the highest dust impact occurs.

SAMPLING PROCEDURE AND MONITORING EQUIPMENT

- 4.2.5. High volume samplers (HVSs) in compliance with the following specifications shall be used for carrying out the 1-hour and 24-hour TSP monitoring:
 - 0.6 1.7 m³ per minute adjustable flow range;
 - Equipped with a timing / control device with +/- 5 minutes accuracy for 24 hours operation;
 - Installed with elapsed-time meter with +/- 2 minutes accuracy for 24 hours operation;
 - Capable of providing a minimum exposed area of 406 cm2;
 - Flow control accuracy: +/- 2.5% deviation over 24-hour sampling period;
 - Equipped with a shelter to protect the filter and sampler;
 - Incorporated with an electronic mass flow rate controller or other equivalent devices;
 - Equipped with a flow recorder for continuous monitoring;





- Provided with a peaked roof inlet;
- Incorporated with a manometer;
- Able to hold and seal the filter paper to the sampler housing at horizontal position;
- · Easily changeable filter; and
- Capable of operating continuously for a 24-hour period.
- 4.2.6. Initial calibration of dust monitoring equipment shall be conducted upon installation and thereafter at bi-monthly intervals. The transfer standard shall be traceable to the internationally recognized primary standard and be calibrated annually. The concern parties such as IEC shall properly document the calibration data for future reference. All the data should be converted into standard temperature and pressure condition.

LABORATORY MEASUREMENT / ANALYSIS

- 4.2.7. A clean laboratory with constant temperature and humidity control, and equipped with necessary measuring and conditioning instruments to handle the dust samples collected, shall be available for sample analysis, and equipment calibration and maintenance. The laboratory should be HOKLAS accredited.
- 4.2.8. Filter paper of size 8" x 10" shall be labelled before sampling. It shall be a clean filter paper with no pinholes, and shall be conditioned in a humidity-controlled chamber for over 24-hours and be pre-weighed before use for the sampling.
- 4.2.9. After sampling, the filter paper loaded with dust shall be kept in a clean and tightly sealed plastic bag. The filter paper shall then be returned to the laboratory for reconditioning in the humidity controlled chamber followed by accurate weighing by an electronic balance with readout down to 0.1 mg. The balance shall be regularly calibrated against a traceable standard.
- 4.2.10. All the collected samples shall be kept in a good condition for 6 months before disposal.
- 4.2.11. Current calibration certificates of equipment are presented in *Appendix 4.2*.



5 MONITORING RESULTS

- 5.0.1. The environmental monitoring will be implemented based on the division of works areas of the designated project managed under the contract with FEP applied by individual contractors. Overall layout showing work areas of various contracts, latest status of work commencement and monitoring stations is shown in Figure 2.1 and Figure 4.1. The monitoring results are presented in according to the Individual Contract(s).
- 5.0.2. In the reporting month, the concurrent contract is:
 - Contract no. HK/2012/08 Wan Chai Development Phase II Central Wan Chai Bypass at Wan Chai West.
- 5.0.3. The environment monitoring schedules for reporting month and coming month are presented in *Appendix 5.1*.

5.1 Noise Monitoring Results

5.1.1 The proposed division of noise monitoring station is summarized in *Table 5.1* below.

Table 5.1 Noise Monitoring Station for Contract no. HK/2012/08

| Location ID | District | Description |
|-------------|----------|----------------------------|
| M1a | Wan Chai | Harbour Road Sports Centre |

- 5.1.2 One limit level exceedance was recorded at M1a Harbour Road Sports Centre on 24 November 2015 in the reporting month.
- 5.1.3 After the investigation, no construction works for EP-376/2009 was conducted by Contract HK/2012/08 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDIICWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
- 5.1.4 The noise monitoring results measured in this reporting period are reviewed and summarized.
 Details of the noise monitoring results and graphical presentation can be referred to <u>Appendix</u>
 5.2.

5.2 Air Quality Monitoring Results

5.2.1 The proposed division of air quality monitoring stations are summarized in *Table 5.2* below.

Table 5.2 Air Quality Monitoring Station for Contract no. HK/2012/08

| Station | Description |
|---------|-------------|
| | |

Contract No. HK/2011/07 Wan Chai Development Phase II and Central Wanchai Bypass - Sampling, Field Measurement and Testing Works (Stage 2) Monthly EM&A Report (November 2015)

| CMA5b | Pedestrian Plaza |
|-------|----------------------|
| CMA6a | WDII PRE Site Office |

- 5.2.2 No exceedances were recorded in the reporting month.
- 5.2.3 The air quality monitoring results measured in this reporting period are reviewed and summarized. Details of air quality monitoring results and graphical presentation can be referred in *Appendix* 5.3.

5.3 WASTE MONITORING RESULTS

5.3.1 Inert and non-inert C&D wastes were disposed in this reporting month. Details of the waste flow table are summarized in *Table 5.3*.

Table 5.3 Details of Waste Disposal for Contract no. HK/2012/08

| Waste Type | Quantity this month | Cumulative Quantity- to-Date | Disposal / Dumping Grounds |
|--|---------------------|---------------------------------|-------------------------------|
| Inert C&D materials disposed, m3 | NIL | NIL | NIL |
| Inert C&D materials recycled, m3 | NIL | NIL | NIL |
| Non-inert C&D materials disposed, m3 | NIL | NIL | NIL |
| Non-inert C&D materials recycled, m3 | NIL | NIL | NIL |
| Chemical waste disposed, kg | NIL | NIL | NIL |



6 COMPLIANCE AUDIT

6.0.1. The Event Action Plan for construction noise and air quality are presented in Appendix 6.1.

6.1 Noise Monitoring

6.1.1. One limit level exceedance was recorded at M1a – Harbour Road Sports Centre on 24 November 2015 in the reporting month. After the investigation, the exceedance was concluded as non-project related.

6.2 Air Quality Monitoring

6.2.1. No exceedances were recorded in the reporting month.

6.3 Review of the Reasons for and the Implications of Non-compliance

- 6.3.1 There was no non-compliance from the site audits in the reporting period. The observations and recommendations made in each individual site audit session were presented in Section 8.
- 6.4 Summary of action taken in the event of and follow-up on non-compliance
- 6.4.1 There was no particular action taken since no non-compliance was recorded from the site audits in the reporting period.

18



7 CUMULATIVE CONSTRUCTION IMPACT DUE TO THE CONCURRENT PROJECTS

- 7.0.1. According to the Condition 3.4 of the EP-376/2009, this section addresses the relevant cumulative construction impact due to the concurrent activities of the current projects including the Central Reclamation Phase III (CRIII), Wan Chai Development Phase II (WDII), Central-WanChai Bypass (CWB), Island Eastern Corridor Link projects (IECL) and Wan Chai Development Phase II Central Wan Chai Bypass at Wan Chai East (CWB Tunnel).
- 7.0.2. According to the Final EM&A report of Central Reclamation Phase III (CRIII) for Contract HK 12/02, the major construction activities were completed by end of January 2014 and no construction activities were undertaken thereafter and the water quality monitoring was completed in October 2011. As such, it is considered that there were no cumulative construction impact due to the concurrent activities of the current projects with the Central Reclamation Phase III (CRIII) undertaken by contractor HK12/02 in the reporting month.
- 7.0.3. According to the construction programme of Central-Wanchai Bypass at Wanchai West at the Central Reclamation Phase III area, include caisson seawall installation, ELS works, road works and drainage works and Road P1 pedestrian road reinstatement were performed in November 2015 reporting month. As no project related exceedance were recorded during the reporting period, cumulative construction impact due to the concurrent activities of the current projects with the Central Reclamation Phase III (CRIII) was considered as insignificant.
- 7.0.4. According to the construction programme of Wan Chai Development Phase II, Central-Wan Chai Bypass and Island Eastern Corridor Link projects, the major construction activities under Wan Chai Development Phase II were tunnel works, ELS works and road works at Wan Chai East and caisson installation, D-wall construction and ELS works at Wan Chai West. The major construction activities under Central-Wan Chai Bypass and Island Eastern Corridor Link Projects were bridge construction and road works at Central Interchange, ELS works at Ex-PCWAW, ELS works and retaining wall construction at Victoria Park; D- wall construction, ELS works and tunnel works at TS3; IEC demolition and tunnel works at North Point area in the reporting month. In addition, other non-Wan Chai Development Phase II, Central-Wan Chai Bypass and Island Eastern Corridor Link projects were observed undertaken at Wan Chai North area.
- 7.0.5. No significant air impact from construction activities was anticipated in the reporting month. Besides, no project related exceedance was recorded during the water, air and noise environmental monitoring events in the reporting month. Thus, it is evaluated that the cumulative construction impact from the concurrent projects including Central Reclamation Phase III (CRIII), Wan Chai Development Phase II (WDII), Central-WanChai Bypass (CWB), Island Eastern Corridor Link projects (IECL) was insignificant.

8 ENVIRONMENTAL SITE AUDIT

8.0.1. Four site inspections for Contract no. HK/2012/08 were carried out on 3, 10, 17 and 24 November 2015 in this reporting period. The results of inspection and outcome are summarized in *Table 8.1.*

Table 8.1 Summary of Environmental Inspections for Contract no. HK/2012/08

| Item | Date | Observations | Action taken by Contractor | Outcome |
|-----------|-----------|---|---|--|
| 151110_01 | 10-Nov-15 | Chemical wastes at Zone C(E) shall be properly placed and handled. | chemical wastes has cleared and disposed. | Completion as observed on 17 November 2015 |
| 151117_01 | 17-Nov-15 | Drip tray shall be provided for oil containers near MVB area. | Oil containers were removed near MVB area. | Completion as observed on 24 November 2015. |
| 151117_02 | 17-Nov-15 | Silt curtain shall be properly deployed and maintain and ensure it is fully extended to seabed level such that the marine work area at Zone A2 is fully enclosed. | Silt curtain has properly deployed and maintained at Zone A2. | Completion as observed on 24 November 2015 |
| 151117_03 | 17-Nov-15 | Muddy effluent at site entrance "Gate 6" shall be properly collected and treated to avoid muddy discharge into public stormwater drainage. | Sand bag was placed around the stormwater drain to avoid any effluent discharge. | Completion as observed on 24 November 2015 |
| 151117_04 | 17-Nov-15 | Muddy effluent at Expo Drive West shall be properly cleaned and ensure the cleaning procedure is properly | The cleaning procedure was implemented orderly on site and at the gate exit that no muddy effluent was observed on public road. | Completion as observed on 1 December 2015. |
| 151117_05 | 17-Nov-15 | Construction effluent from tunnel excavation work zone shall be properly | The pump has stopped and removed such that no discharge was further observed. | Completion as observed on 24 November 2015 |

COMPLAINTS, NOTIFICATION OF SUMMONS AND PROSECUTION 9

- No environmental complaint was received in the reporting period.
- 9.0.2. The details of cumulative complaint log and updated summary of complaints are presented in Appendix 9.1
- 9.0.3. Cumulative statistic on complaints and successful prosecutions are summarized in Table 9.1 and Table 9.2 respectively.

Table 9.1 Cumulative Statistics on Complaints

| Reporting Period | No. of Complaints |
|---|-------------------|
| Commencement works (May 2015) to last reporting month | 0 |
| November 2015 | 0 |
| Total | 0 |

Table 9.2 Cumulative Statistics on Successful Prosecutions

| Environmental Parameters | Cumulative No. Brought Forward | No. of Successful Prosecutions this month (Offence Date) | Cumulative No. Project-to-Date |
|-----------------------------|-----------------------------------|--|--------------------------------|
| Air | 0 | 0 | 0 |
| Noise | 0 | 0 | 0 |
| Water | 0 | 0 | 0 |
| Waste | 0 | 0 | 0 |
| Total | 0 | 0 | 0 |

10 CONCLUSION


- 10.0.1. The EM&A programme was carried out in accordance with the EM&A Manual requirements, minor alterations to the programme proposed were made in response to changing circumstances.
- 10.0.2. The scheduled construction activities and the recommended mitigation measures for the coming month are listed in *Table 10.1*. The construction programmes of individual contracts are provided in *Appendix 10.1*.

Table 10.1 Summary of Key Construction Activities of Individual Contract(s) to be commenced in Coming Reporting Month

| Contract No. | Key Construction Works | Recommended Mitigation Measures |
|-----------------|--|---|
| HK/2012/08 | UtilitiesDrainage | Dust control during dust generating works; Implementation of proper noise pollution control; and Provision of protection to ensure no runoff out of site area or direct discharge into public drainage system |

Figure 2.1

Project Layout





Project Title : Road P2 and other roads which are classified as primary/district distributor roads (referred to as "DP2" in the WDII&CWB EIA Report)

工程項目名稱: P2 路及其他分類爲主要幹路或地區幹路的道路(WDII&CWB 環評報告內稱 "DP2")

Environmental Permit No.: EP-376/2009 環境許可證編號 : EP-376/2009 Figure 1: Location of the Project

圖 1: 工程項目位置圖

(This figure was prepared based on Figure 1.2b of the WDII&CWB EIA report (Register No.: AEIAR-125/2008)) (本圖是根據 WDII&CWB 環評報告(登記冊編號 AEIAR-125/2008)圖 1.2b 編制)

Figure 2.2

Project Organization Chart

Project Organization Chart






Figure 4.1

Locations of Monitoring Stations





Noise Monitoring Station

Location of Impact Noise Monitoring Stations

Appendix 3.1

Environmental Mitigation Implementation Schedule

Appendix A

Table A13.1 Implementation Schedule for Air Quality Control

Table A13.2 Implementation Schedule for Noise Control

Table A13.3 Implementation Schedule for Water Quality Control

Table A13.4 Implementation Schedule for Waste Management

Table A13.7 Implementation Schedule for Landscape and Visual

IMPLEMENTATION SCHEDULE OF THE PROPOSED MITIGATION MEASURES

Table A13.1 Implementation Schedule for Air Quality Control

| EIA Ref | Environmental Protection Measures / Mitigation Measures | Location / Timing | Implementation Agent | Implementation stage | | | | Relevant Legislation |
|-------------|--|---------------------------------|-------------------------|----------------------|----------|---|-----|----------------------|
| | | | | Des | C | О | Dec | and Guidelines |
| Constructio | n Phase | | | | | | | |
| For the Who | ole Project | | | | | | | |
| S3.6.5 | Four times a day watering of the work site with active operations. | Work site / during construction | Contractor | | 1 | | | EIAO-TM |
| S3.8.1 | Implementation of dust suppression measures stipulated in Air Pollution Control (Construction Dust) Regulation. The following mitigation measures, good site practices and a comprehensive dust monitoring and audit programme are recommended to minimise cumulative dust impacts. Strictly limit the truck speed on site to below 10 km per hour and water spraying to keep the haul roads in wet condition; Watering during excavation and material handling; Provision of vehicle wheel and body washing facilities at the exit points of the site, combined with cleaning of public roads where necessary; and Tarpaulin covering of all dusty vehicle loads transported to, from and between site locations. | Work site / during construction | Contractor | | V | | | |

Des - Design, C - Construction, O - Operation, and Dec - Decommissioning

Table A13.2 Implementation Schedule for Noise Control

| EIA Ref | Environmental Protection Measures / Mitigation Measures | Location / Timing | Implementation Agent | Implementation stage | | | | Relevant Legislation |
|--------------------|--|---------------------------------|-------------------------|----------------------|----------|----------|-----|----------------------|
| | | | | Des | C | О | Dec | and Guidelines |
| Constructio | n Phase | | L | | | <u> </u> | | |
| For the Who | ole Project | | | | | | | |
| S4.9.4 | Good Site Practice: Only well-maintained plant shall be operated on-site and plant shall be serviced regularly during the construction program. Silencers or mufflers on construction equipment shall be utilized and shall be properly maintained during the construction program. Mobile plant, if any, shall be sited as far away from NSRs as possible. Machines and plant (such as trucks) that may be in intermittent use shall be shut down between works periods or shall be throttled down to a minimum. Plant known to emit noise strongly in one direction shall, wherever possible, be orientated so that the noise is directed away from the nearby NSRs. Material stockpiles and other structures shall be effectively utilized, wherever practicable, in screening noise from onsite construction activities. | Work site / during construction | Contractor | | V | | | EIAO-TM, NCO |
| S4.8.3 – S4.8.4 | Use of quiet powered mechanical equipment, movable noise barrier and temporary noise barrier for the | Work site / during construction | Contractor | | V | | | EIAO-TM, NCO |
| | following tasks: Temporary road diversion Resurfacing At-grade roadwork | | | | | | | |

[•] Des - Design, C - Construction, O - Operation, and Dec - Decommissioning

Table A13.3 Implementation Schedule for Water Quality Control

| | installed in order to minimise the sediment loading of the effluent prior to discharge; All temporary and permanent drainage pipes and culverts provided to facilitate runoff discharge shall be adequately designed for the controlled release of storm flows. All sediment control measures shall be regularly inspected and maintained to ensure proper and efficient operation at all times and particularly following rain storms. The temporarily diverted drainage shall be reinstated to its original condition when the construction work is finished or the temporary diversion is no longer required. All fuel tanks and store areas shall be provided with locks and be sited on sealed areas, within bunds of a capacity equal to 110% of the storage capacity. Minimum distances of 100 m shall be maintained between the storm water discharges and the existing or planned WSD flushing water intakes during construction phase. | | | | |
|------|--|---------------------------------|------------|---|-----------------------------------|
| S5.8 | Sewage from Construction Work Force Construction work force sewage discharges on site shall be connected to the existing trunk sewer or sewage treatment facilities. The construction sewage shall be handled by portable chemical toilets prior to the commission of the on-site sewer system. Appropriate numbers of portable toilets shall be provided by a licensed contractor to serve the large number of construction workers over the construction site. The Contractor shall also be responsible for waste disposal and maintenance practices. | Work site / during construction | Contractor | V | ProPECC PN 1/94; WPCO (TM-DSS) |

<u>EP-376/2009</u> EM&A Manual

| S5.8 | Floating Debris and Refuse | Work site and | Contractor | | | WPCO |
|------|---|----------------------|------------|------|--|------|
| | Collection and removal of floating refuse shall | adjacent water / | | | | |
| | be performed at regular intervals on a daily | During the | | | | |
| | basis. The contractor shall be responsible for | construction period. | | | | |
| | keeping the water within the site boundary and | | | | | |
| | the neighbouring water free from rubbish. | | | | | |
| S5.8 | Storm Water Discharges | Work site and | Contractor | | | WPCO |
| | Minimum distances of 100 m shall be | adjacent water | | | | |
| | maintained between the existing or planned | / During the design | | | | |
| | stormwater discharges and the existing or | and construction | | | | |
| | planned WSD flushing water intakes. | period. | | | | |

• Des - Design, C - Construction, O – Operation, and Dec – Decommissioning

Table A13.4 Implementation Schedule for Waste Management

| EIA Ref | Environmental Protection Measures / | Location / Timing | Implementation | Imp | lemen | tation | stage | Relevant Legislation |
|--------------|---|---|----------------|-----|-------|--------|-------|----------------------|
| | Mitigation Measures | | Agent | Des | C | О | Dec | and Guidelines |
| Construction | on Phase | | <u>l</u> | 1 | | | | <u> </u> |
| For the Who | ole Project | | | | | | | |
| S6.7.7 | Good Site Practices Recommendations for good site practices during the construction activities include: nomination of an approved person, such as a site manager, to be responsible for good site practices, arrangements for collection and effective disposal to an appropriate facility, of all wastes generated at the site; training of site personnel in proper waste management and chemical waste handling procedures; provision of sufficient waste disposal points and regular collection for disposal; appropriate measures to minimise windblown litter and dust during transportation of waste by either covering trucks or by transporting wastes in enclosed containers; regular cleaning and maintenance programme for drainage systems, sumps and oil interceptors; and a recording system for the amount of wastes generated, recycled and disposed of (including the disposal sites). | Work site / During planning and design stage, and construction stage | Contractor | | | | | |
| S.6.7.8 | Waste Reduction Measures Recommendations to achieve waste reduction include: • Sort C&D waste from demolition of the existing waterfront structures to recover | Work site / During planning and design stage, and construction stage | Contractor | V | V | | | |

| | recyclable portions such as metals. Segregation and storage of different types of waste in different containers, skips or stockpiles to enhance reuse or recycling of materials and their proper disposal. Encourage collection of aluminium cans, PET bottles and paper by providing separate labelled bins to enable these wastes to be segregated from other general refuse generated by the work force. Any unused chemicals or those with remaining functional capacity shall be recycled. Use of reusable non-timber formwork, such as in casting the tunnel box sections, to reduce the amount of C&D material. Proper storage and site practices to minimise the potential for damage or contamination of construction materials. Plan and stock construction materials carefully to minimise amount of waste generated and avoid unnecessary generation of waste. | | | | | |
|---------|--|--|------------|----------|---|--|
| S6.7.10 | General Refuse General refuse shall be stored in enclosed bins or compaction units separate from C&D material. A licensed waste collector shall be employed by the contractor to remove general refuse from the site, separately from C&D material. A collection area shall be provided where wastes can be stored and loaded prior to removal from site. An enclosed and covered area is recommended to reduce the occurrence of 'wind | Work site / During the construction period | Contractor | V | Public Health and Municipal Services Ordinance (Cap. 13 | |

| S6.7.11 | Chemical Wastes After use, chemical wastes (for example, cleaning fluids, solvents, lubrication oil and fuel) shall be handled according to the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes. Spent chemicals shall be collected by a licensed collector for disposal at the CWTF or other licensed facility in accordance with the Waste Disposal (Chemical Waste) (General) Regulation. | Work site / During the construction period | Contractor | V | Waste Disposal (Chemical Waste) (General) Regulation Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes |
|----------------------|---|--|---|----------|--|
| S6.7.12 – S6.7.13 | Construction and Demolition Material C&D material shall be sorted on-site into inert C&D material (that is, public fill) and C&D waste. All the suitable inert C&D material shall be broken down to 250 mm in size for reuse as public fill in the WDII reclamation. C&D waste, such as wood, glass, plastic, steel and other metals shall be reused or recycled and, as a last resort, disposed of to landfill. A suitable area shall be designated to facilitate the sorting process and a temporary stockpiling area will be required for the separated materials. | Work site / During the construction period | Contractor and Independent Environmental Checker | V | DEVB TCW No.6/2010; ETWB TCW No. 33/2002; ETWB TCW No. 19/2005 |
| | In order to monitor the disposal of public fill and C&D waste at public fill reception facilities and landfills, respectively, and to control fly tipping, a trip-ticket system shall be included as one of the contractual requirements and implemented by the Environmental Team undertaking the environmental monitoring and audit work. An Independent Environment Checker shall be responsible for auditing the results of the system. | | | | |
| S6.7.14 | Bentonite Slurry The disposal of residual used bentonite slurry shall follow the good practice guidelines stated | Work site / During the construction period | Contractor | V | ProPECC PN 1/94 |

EP-376/2009 EM&A Manual in ProPECC PN 1/94 "Construction Site Drainage" and listed as follows: If the disposal of a certain residual quantity cannot be avoided, the used slurry may be disposed of at the marine spoil grounds subject to obtaining a marine dumping licence from EPD on a case-by-case basis. If the used bentonite slurry is intended to be disposed of through the public drainage system, it shall be treated to the respective effluent standards applicable to foul sewers, storm drains or the receiving waters as set out in the Technical Memorandum of Standards for Effluents Discharged into Drainage and Sewerage Systems, Inland and Coastal Waters. If the used bentonite slurry is intended to be disposed to public fill reception facilities, it will be mixed with dry soil on site before disposal.

• Des - Design, C - Construction, O – Operation, and Dec – Decommissioning

Table A13.7 Implementation Schedule for Landscape and Visual

| EIA Ref | Environmental Protection Measures / | Location / Timing | Implementation | Imp | lemen | tation | stage | Relevant Legislation |
|--------------|--|--|----------------|-----|----------|--------|-------|----------------------|
| | Mitigation Measures | | Agent | Des | C | 0 | Dec | and Guidelines |
| Construction | n Phase | | 1 | | 1 | | | |
| For the Who | le Project | | | | | | | |
| Table 10.5 | CM1 Topsoil, where identified, shall be stripped and stored for re-use in the construction of the soft landscape works, where practical. | Work site / During Construction Phase | Contractor | V | 1 | | | EIAO TM |
| Table 10.5 | CM2 Existing trees to be retained on site shall be carefully protected during construction. | Work site / During Construction Phase | Contractor | V | V | | | EIAO TM |
| Table 10.5 | CM3 Trees unavoidably affected by the works shall be transplanted where practical. | Work site / During Construction Phase | Contractor | 1 | 1 | | | EIAO TM |
| Table 10.5 | CM4 Compensatory tree planting shall be provided to compensate for felled trees. | Work site / During Construction Phase | Contractor | 1 | 1 | | | EIAO TM |
| Table 10.5 | CM5 Control of night-time lighting. | Work site / During Construction Phase | Contractor | | √ | | | EIAO TM |
| Table 10.5 | CM6 Erection of decorative screen hoarding compatible with the surrounding setting. | Work site / During Construction Phase | Contractor | | 1 | | | EIAO TM |
| For DP2 - V | VDII Major Roads (Road P2) | | | | | | | |
| Table 10.5 | CM1 Topsoil, where identified, shall be stripped and stored for re-use in the construction of the soft landscape works, where practical. | Work site / During Construction Phase | Contractor | √ | 1 | | | EIAO TM |
| Table 10.5 | CM2 Existing trees to be retained on site shall be carefully protected during construction. | Work site / During Construction Phase | Contractor | V | V | | | EIAO TM |
| Table 10.5 | CM3 Trees unavoidably affected by the works shall be transplanted where practical. | Work site / During Construction Phase | Contractor | 1 | √ | | | EIAO TM |
| Table 10.5 | CM4 Compensatory tree planting shall be provided to compensate for felled trees. | Work site / During Construction Phase | Contractor | 1 | √ | | | EIAO TM |
| Table 10.5 | CM5 Control of night-time lighting. | Work site / During Construction Phase | Contractor | | √ | | | EIAO TM |
| Table 10.5 | CM6 Erection of decorative screen hoarding compatible with the surrounding setting. | Work site / During Construction Phase | Contractor | | 1 | | | EIAO TM |

| Operation Pl | Operation Phase | | | | | | | | | |
|--------------------------------------|---|--|----------|---|---|--|-----------------|--|--|--|
| For DP2 – WDII Major Roads (Road P2) | | | | | | | | | | |
| Table 10.6, Figure | OM1 Aesthetic design of buildings and road- related structures, | Work site / During Design Stage and | CEDD/HyD | V | 1 | | ETWB TCW 2/2004 | | | |
| 10.5.1- | including viaducts, vent buildings, subways, | Operation Phases | | | | | | | | |
| 10.5.5 | footbridges | | | | | | | | | |
| Table 10.6, | and noise barriers and enclosure. OM3 Buffer Tree and Shrub Planting to screen | Work site / During | CEDD/HyD | V | 1 | | ETWB TCW 2/2004 | | | |
| Figure | proposed roads | Design Stage and | | ' | ' | | | | | |
| 10.5.1- | and associated structures. | Operation Phases | | | | | | | | |
| 10.5.5 Table 10.6. | OM5 Aesthetic streetscape design. | Work site / During | CEDD/HyD | V | 1 | | ETWB TCW 2/2004 | | | |
| Figure | | Design Stage and | | | ' | | | | | |
| 10.5.1- 10.5.5 | | Operation Phases | | | | | | | | |
| Table 10.6, | OM6 Aesthetic design of roadside amenity areas | Work site / During | CEDD/HyD | V | 1 | | ETWB TCW 2/2004 | | | |
| Figure | 22.20 22.20.000 | Design Stage and | | | ' | | | | | |
| 10.5.1- | | Operation Phases | | | | | | | | |
| 10.5.5 | | | | | | | | | | |

[•] Des - Design, C - Construction, O – Operation, and Dec – Decommissioning

Appendix 4.1

Action and Limit Level

Action and Limit Level

Action and Limit Level for Noise Monitoring

| Time Period | Action Level | Limit Level |
|--|--|-------------|
| 07:00 - 19:00 hours on normal weekdays | When one documented complaint is received. | 75 dB(A) |

Notes: If works are to be carried out during restricted hours, the conditions stipulated in the Construction Noise Permit (CNP) issued by the Noise Control Authority have to be followed. *The Limit level shall be 70 dB(A) and 65 dB(A) for educational institute during normal teaching periods and school examination periods, respectively.

Action and Limit Level for Air Monitoring

| Monitoring Locations | 1-hour TSP Level inµg/m3 | | 24-hour TSP Level inµg/m | | |
|-------------------------------|--------------------------|-------------|--------------------------|-------------|--|
| | Action Level | Limit Level | Action Level | Limit Level | |
| CMA5b Pedestrian Plaza | 339.7 | 500 | 209.9 | 260 | |
| CMA6a WDII PRE Site Office | 333.0 | 500 | 207.1 | 260 | |

Appendix 4.2

Copies of Calibration Certificates



G/F, 9/F, 12/F, 13/F, & 20/F, Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. 香港黃竹坑道37號利達中心地下,9樓,12樓,13樓及20樓 E-mail: smec@cigismec.com Website: www.cigismec.com



CERTIFICATE OF CALIBRATION

Certificate No.:

15CA0312 02-02

Page:

of

2

Item tested

Description:

Acoustical Calibrator (Class 1) B & K

Manufacturer: Type/Model No.:

4230 1411076

Serial/Equipment No.: Adaptors used:

Yes

Item submitted by

Curstomer:

Lam Geotechnics Limited

Address of Customer:

Request No.:

Date of receipt:

12-Mar-2015

Date of test:

13-Mar-2015

Reference equipment used in the calibration

| Model: | Serial No. | Expiry Date: | Traceable to: |
|----------|---|--|--|
| B&K 4180 | 2412857 | 13-May-2015 | SCL |
| B&K 2673 | 2239857 | 10-Apr-2015 | CEPREI |
| B&K 2610 | 2346941 | 08-Apr-2015 | CEPREI |
| DS 360 | 61227 | 09-Apr-2015 | CEPREI |
| 34401A | US36087050 | 01-Dec-2015 | CEPREI |
| 8903B | GB41300350 | 07-Apr-2015 | CEPREI |
| 53132A | MY40003662 | 11-Apr-2015 | CEPREI |
| | B&K 4180 B&K 2673 B&K 2610 DS 360 34401A 8903B | B&K 4180 2412857 B&K 2673 2239857 B&K 2610 2346941 DS 360 61227 34401A US36087050 8903B GB41300350 | B&K 4180 2412857 13-May-2015 B&K 2673 2239857 10-Apr-2015 B&K 2610 2346941 08-Apr-2015 DS 360 61227 09-Apr-2015 34401A US36087050 01-Dec-2015 8903B GB41300350 07-Apr-2015 |

Ambient conditions

Temperature: Relative humidity:

Air pressure:

21 ± 1 °C 60 ± 10 % 1010 ± 5 hPa

Test specifications

- The Sound Calibrator has been calibrated in accordance with the requirements as specified in IEC 60942 1997 Annex B
 and the lab calibration procedure SMTP004-CA-156.
- 2, The calibrator was tested with its axis vertical facing downwards at the specific frequency using insert voltage technique.
- The results are rounded to the nearest 0.01 dB and 0.1 Hz and have not been corrected for variations from a reference
 pressure of 1013.25 hectoPascals as the maker's information indicates that the instrument is insensitive to pressure
 changes.

Test results

This is to certify that the sound calibrator conforms to the requirements of annex B of IEC 60942: 1997 for the conditions under which the test was performed. This does not imply that the sound calibrator meets IEC 60942 under any other conditions.

Details of the performed measurements are presented on page 2 of this certificate

Approved Signatory:

Date: Huang Jian Min/Feng Jun Qi

13-Mar-2015

Company Chop:

SENGINEGO COMPAND TO THE STREET OF THE STRE

Comments: The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

© Soils & Materials Engineering Co., Ltd.

Form No CARP156-1/Issue 1/Rev D/01/03/2007



G/F., 9/F., 12/F., 13/F. & 20/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. 香港黃竹坑道37號利達中心地下,9樓,12樓,13樓及20樓 E-mail: smec@cigismec.com Website: www.cigismec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



CERTIFICATE OF CALIBRATION

(Continuation Page)

Certificate No.:

15CA0312 02-02

Page:

2

2

1, Measured Sound Pressure Level

The output Sound Pressure Level in the calibrator head was measured at the setting and frequency shown using a calibrated laboratory standard microphone and insert voltage technique. The results are given in below with the estimated uncertainties.

| Frequency | Output Sound Pressure | Measured Output | Estimated Expanded Uncertainty dB |
|-----------|-----------------------|----------------------|-----------------------------------|
| Shown | Level Setting | Sound Pressure Level | |
| Hz | dB | dB | |
| 1000 | 94.00 | 94.22 | 0.10 |

2, Sound Pressure Level Stability - Short Term Fluctuations

The Short Term Fluctuations was determined by measuring the maximum and minimum of the fast weighted DC output of the B&K 2610 measuring amplifier over a 20 second time interval as required in the standard. The Short Term Fluctuation was found to be:

At 1000 Hz

STF = 0.002 dB

Estimated expanded uncertainty

0.005 dB

3, **Actual Output Frequency**

The determination of actual output frequency was made using a B&K 4180 microphone together with a B&K 2673 preamplifier connected to a B&K 2610 measuring amplifier. The AC output of the B&K 2610 was taken to an universal counter which was used to determine the frequency averaged over 20 second of operation as required by the standard. The actual output frequency at 1 KHz was:

At 1000 Hz

Actual Frequency = 965.3 Hz

Estimated expanded uncertainty

0.1 Hz

Coverage factor k = 2.2

Total Noise and Distortion 4,

For the Total Noise and Distortion measurement, the unfiltered AC output of the B&K 2610 measuring amplifier was connected to an Agilent Type 8903 B distortion analyser. The TND result at 1 KHz was:

At 1000 Hz

TND = 0.7 %

Estimated expanded uncertainty

0.7 %

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

Calibrated by:

End

Fung Chi Yip

Checked by:

Lam Tze Wai

Date:

13-Mar-2015

Date:

13-Mar-2015

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd

Form No CARP156-2/Issue 1/Rev C/01/05/2005



G/F, 9/F, 12/F, 13/F, & 20/F, Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. 香港 黃竹坑 道 3 7 號 利達中心地下,9 樓,1 2 樓,1 3 樓及 2 0 樓 E-mail: smec@cigismec.com Website: www.cigismec.com

Tel : (852) 2873 6860 Fax: (852) 2555 7533



CERTIFICATE OF CALIBRATION

Certificate No.:

14CA1213 01

Page

of

Item tested

Description:

Sound Level Meter (Type 1)

Microphone **B&K**

Manufacturer: Type/Model No.: B&K 2236

Serial/Equipment No.:

2100736

4188 2288941

Adaptors used:

Item submitted by

Customer Name:

Lam Geotechnics Limited

Address of Customer: Request No.:

13-Dec-2014

Date of receipt:

Date of test:

13-Dec-2014

Reference equipment used in the calibration

Model:

Serial No.

Expiry Date:

Traceable to:

Multi function sound calibrator

B&K 4226

2288444

20-Jun-2015

CIGISMEC

Signal generator Signal generator

DS 360 DS 360

33873 61227

09-Apr-2015 09-Apr-2015

CEPREI CEPREI

Ambient conditions

Temperature:

21 ± 1 °C

Relative humidity: Air pressure:

60 ± 5 % 1010 ± 5 hPa

Test specifications

The Sound Level Meter has been calibrated in accordance with the requirements as specified in BS 7580; Part 1: 1997 and the lab calibration procedure SMTP004-CA-152.

2. The electrical tests were performed using an electrical signal substituted for the microphone which was removed and replaced by an equivalent capacitance within a tolerance of ±20%.

The acoustic calibration was performed using an B&K 4226 sound calibrator and corrections was applied for the difference 3, between the free-field and pressure responsess of the Sound Level Meter.

Test results

This is to certify that the Sound Level Meter conforms to BS 7580: Part 1: 1997 for the conditions under which the test was performed.

Details of the performed measurements are presented on page 2 of this certificate.

Actual Measurement data are documented on worksheets.

Approved Signatory:

Date:

15-Dec-2014

Company Chop:

Huang Jian Min/∮eng Jun Qi

Comments: The results reported in his certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

© Soils & Materials Engineering Co., Ltd.

Form No CARP152-1/Issue 1/Rev C/01/02/2007



G/F, 9/F, 12/F, 13/F. & 20/F, Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. 香港黃竹坑道37號利達中心地下,9樓,12樓,13樓及20樓 E-mail: smec@cigismec.com Website: www.cigismec.com

Tel (852) 2873 6860 Fax: (852) 2555 7533



CERTIFICATE OF CALIBRATION

(Continuation Page)

Certificate No.:

14CA1213 01

Page

2

2

1, Electrical Tests

The electrical tests were performed using an equivalent capacitance substituted for the microphone. The results are given in below with test status and the estimated uncertainties. The "Pass" means the result of the test is inside the tolerances stated in the test specifications. The "-" means the result of test is outside these tolerances.

| Test: | Subtest: | Status: | Expanded Uncertanity (dB) | Coverage Factor |
|-------------------------|--|---------|------------------------------|--------------------|
| Self-generated noise | A | Pass | 0.3 | |
| | C | Pass | 1.0 | 2.1 |
| | Lin | Pass | 2.0 | 2.2 |
| Linearity range for Leq | At reference range, Step 5 dB at 4 kHz | Pass | 0.3 | |
| | Reference SPL on all other ranges | Pass | 0.3 | |
| | 2 dB below upper limit of each range | Pass | 0.3 | |
| | 2 dB above lower limit of each range | Pass | 0.3 | |
| Linearity range for SPL | At reference range, Step 5 dB at 4 kHz | Pass | 0.3 | |
| Frequency weightings | Α | Pass | 0.3 | |
| | C | Pass | 0.3 | |
| | Lin | Pass | 0.3 | |
| Time weightings | Single Burst Fast | Pass | 0.3 | |
| | Single Burst Slow | Pass | 0.3 | |
| Peak response | Single 100µs rectangular pulse | Pass | 0.3 | |
| R.M.S. accuracy | Crest factor of 3 | Pass | 0.3 | |
| Time weighting I | Single burst 5 ms at 2000 Hz | Pass | 0.3 | |
| | Repeated at frequency of 100 Hz | Pass | 0.3 | |
| Time averaging | 1 ms burst duty factor 1/103 at 4kHz | Pass | 0.3 | |
| | 1 ms burst duty factor 1/104 at 4kHz | Pass | 0.3 | |
| Pulse range | Single burst 10 ms at 4 kHz | Pass | 0.4 | |
| Sound exposure level | Single burst 10 ms at 4 kHz | Pass | 0.4 | |
| Overload indication | SPL | Pass | 0.3 | |
| | Leq | Pass | 0.4 | |
| | | | | |

2, Acoustic tests

The complete sound level meter was calibrated on the reference range using a B&K 4226 acoustic calibrator with 1000Hz and SPL 94 dB. The sensitivity of the sound level meter was adjusted. The test result at 125 Hz and 8000 Hz are given in below with test status and the estimated uncertainties.

| Test: | Subtest | Status | Expanded Uncertanity (dB) | Coverage Factor |
|-------------------|------------------------|--------|------------------------------|--------------------|
| Acoustic response | Weighting A at 125 Hz | Pass | 0.3 | |
| | Weighting A at 8000 Hz | Pass | 0.5 | |
| | | | 1000 | |

3, Response to associated sound calibrator

N/A

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

Calibrated by:

Date:

Fung Chi Yip 13-Dec-2014 End

Checked by:

Date:

fam Tze Wai 15-Dec-2014

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP152-2/Issue 1/Rev.C/01/02/2007



TISCH ENVIRONMENTAL, INC. 145 SOUTH MIAMI AVE VILLAGE OF CLEVES, OH 45002 513.467.9000 877.263.7610 TOLL FREE 513.467.9009 FAX

ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

| Date - Ji Operator | | 5 Rootsmeter Orifice I.I | | 438320 0005 | Ta (K) - Pa (mm) - | 749.3 |
|-----------------------|----------------------------|-----------------------------|------------------------------|--|----------------------------------|--------------------------------------|
| ======= | ======= | ========= | ======== | | METER | ORFICE |
| PLATE OR Run # | VOLUME START (m3) | VOLUME STOP (m3) | DIFF VOLUME (m3) | DIFF TIME (min) | DIFF Hg (mm) | DIFF H2O (in.) |
| 1 2 3 4 5 | NA NA NA NA NA | NA NA NA NA NA | 1.00 1.00 1.00 1.00 | 1.3930 0.9800 0.8790 0.8350 0.6900 | 3.2 6.4 7.9 8.7 12.7 | 2.00 4.00 5.00 5.50 8.00 |
| | | | | | | |

DATA TABULATION

| Vstd | (x axis) Qstd | (y axis) | | Va | (x axis) Qa | (y axis) |
|--|--|--|-------|--|--|--|
| 0.9883 0.9841 0.9820 0.9810 0.9757 | 0.7095 1.0042 1.1172 1.1749 1.4141 | 1.4090 1.9926 2.2278 2.3365 2.8179 | | 0.9957 0.9915 0.9894 0.9884 0.9830 | 0.7148 1.0117 1.1256 1.1837 1.4247 | 0.8889 1.2570 1.4054 1.4740 1.7777 |
| Qstd slop intercept coefficie | (b) = | 2.00072 -0.01209 0.99995 | n e n | Qa slope intercept coefficie | t(b) = | 1.25282 -0.00763 0.99995 |
| y axis = | SQRT[H2O(B | Pa/760)(298/5 | Га)] | y axis = | SQRT [H20 (7 | [a/Pa]] |

CALCULATIONS

Vstd = Diff. Vol[(Pa-Diff. Hg)/760](298/Ta)
Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]
Qa = Va/Time

For subsequent flow rate calculations:

Qstd = $1/m\{[SQRT(H2O(Pa/760)(298/Ta))] - b\}$ Qa = $1/m\{[SQRT H2O(Ta/Pa)] - b\}$



Calibration Data for High Volume Sampler (TSP Sampler)

| Location : | | CMA5b | | | Calbratio | on Date | : 2-Oct-15 |
|-----------------------------|-------------|------------|-----------------|------------------------------------|----------------------------|-----------------|---|
| Equipment no. | | EL222 | | | Calbratio | on Due Date | : 2-Dec-15 |
| | | | | | | | |
| | | | | | | | |
| CALIBRATION OF CON | ITINUOUS | S FLOW R | ECORDER | | | | |
| | l | | | Ambient Condition | | | |
| Temperature, T _a | | 301 | | Kelvin Pressure, P | a | 1 | 012 mmHg |
| | T | | Orifice T | ransfer Standard Infor | mation | | |
| Equipment No. | | EL086 | | Slope, m _c 2.000 | | Intercept, bc | -0.01209 |
| Last Calibration Date | | 30-Jun-1 | 5 | (H) | $\langle P_a / 10 \rangle$ | 13.3 x 298 / | $(T_a)^{1/2}$ |
| Next Calibration Date | | 30-Jun-1 | 6 | = | m _c x | $Q_{std} + b_c$ | |
| | | | | Calibration of TSP | | | |
| Calibration | Mar | nometer R | eading | Q _{std} | Contin | uous Flow | IC |
| Point | Н (| inches of | water) | (m ³ / min.) | Reco | order, W | (W(P _a /1013.3x298/T _a) ^{1/2} /35.31) |
| | (up) | (down) | (difference) | X-axis | (0 | CFM) | Y-axis |
| 1 | 5.8 | 5.8 | 11.6 | 1.6988 | | 60 | 59.6619 |
| 2 | 4.6 | 4.6 | 9.2 | 1.5135 | | 55 | 54.6901 |
| 3 | 3.6 | 3.6 | 7.2 | 1.3396 | | 50 | 49.7183 |
| 4 | 2.4 | 2.4 | 4.8 | 1.0949 | | 42 | 41.7634 |
| 5 | 1.5 | 1.5 | 3.0 | 0.8669 | | 34 | 33.8084 |
| By Linear Regression of | Y on X | | | | | | |
| | Slope, m | = | 31.1 | 467 Int | ercept, b = | 7.3 | 3520 |
| Correlation Co | oefficient* | = | 0.99 | 986 | | | |
| Calibration | Accepted | = | Yes/ | \lo ** | | | |
| | | | | | | | |
| * if Correlation Coefficier | nt < 0.990, | check and | l recalibratior | n again. | | | |
| | | | | | | | |
| ** Delete as appropriate. | | | | | | | |
| Remarks : | | | | | | | |
| | | IZ:4 A · · | | | Charles | l by | Demolel - |
| Calibrated by | | Kit Au | | | Checked | i by | Derek Lo |
| Date : | | 2-Oct-15 | | | Date | | : 2-Oct-15 |



Calibration Data for High Volume Sampler (TSP Sampler)

| Location : | | CMA6a | | Calbration Date : 2-Oct-15 | | | | | | |
|-----------------------------|-------------|-------------|---------------------|----------------------------|------------------|----------------------|-----------------|-----------------------|--|--|
| Equipment no. | | EL448 | | | | Calbratio | on Due Date | : | 2-Dec-15 | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| CALIBRATION OF CON | ITINUOUS | FLOW RI | ECORDER | | | | | | | |
| | | . = • | | Ambient 0 | Condition | | | | | |
| Temperature, T _a | | 301 | | | Pressure, P | a | 1 | 012 | mmHg | |
| | | | Orifice Tr | ansfer Sta | ındard Inforr | mation | | | | |
| Equipment No. | | EL086 | | Slope, m _c | 2.0007 | 72 | Intercept, bc | Т | -0.01209 | |
| Last Calibration Date | | 30-Jun-1 | 5 | | (H x | P _a / 101 | /3.3 x 298 / | $T_a)^{1/2}$ | ? | |
| Next Calibration Date | | 30-Jun-1 | 6 | | = | | $Q_{std} + b_c$ | | | |
| | | | | Calibratio | n of TSP | | | | | |
| Calibration | Man | ometer R | eading | C |) _{std} | Continu | uous Flow | | IC | |
| Point | H (i | nches of | water) | (m ³ | / min.) | Reco | order, W | (W(P _a /10 | 13.3x298/T _a) ^{1/2} /35.31) | |
| | (up) | (down) | (difference) | X- | axis | (C | CFM) | | Y-axis | |
| 1 | 6.5 | 6.5 | 13.0 | 1. | 7980 | | 56 | | 55.6845 | |
| 2 | 5.3 | 5.3 | 10.6 | 1.0 | 6242 | | 50 | | 49.7183 | |
| 3 | 4.0 | 4.0 | 8.0 | 1.4 | 4118 | | 43 | | 42.7577 | |
| 4 | 2.6 | 2.6 | 5.2 | 1. | 1394 | | 38 | | 37.7859 | |
| 5 | 1.6 | 1.6 | 3.2 | 0.8 | 8951 | | 30 | | 29.8310 | |
| By Linear Regression of | Y on X | | • | | | | | | | |
| | Slope, m | = | 27.6 | 043 | Inte | ercept, b = | 5.2 | 2357 | | |
| Correlation Co | pefficient* | = | 0.99 | 149 | | | | | | |
| Calibration | Accepted | = | Yes/ | 10 ** | | | | | | |
| | | | | | | | | | | |
| * if Completion Coefficien | 0 000 | معد بامدهام | l va a a lib vatia: | | | | | | | |
| * if Correlation Coefficier | ii < 0.990, | check and | recalibration | ı ayaırı. | | | | | | |
| ** Delete as appropriate. | | | | | | | | | | |
| Remarks : | | | | | | | | | | |
| | | | | | | | | | | |
| Calibrated by | | Kit Au | | | | Checked | i by | : | Derek Lo | |
| | 2 | 2-Oct-15 | | | | Date | | : | 2-Oct-15 | |

Appendix 5.1

Monitoring Schedules for Reporting Month and Coming Reporting Month

Contract No. HK/2011/07 Wan Chai Development Phase II and Central-Wan Chai Bypass Sampling, Field Measurement and Testing Works (Stage 2)

Environmental Monitoring Schedule November 2015

| Sunday | Monday | Tuesday | Wednesday | Thursday | Friday | Saturday |
|--------|-----------------|-----------------|-----------|----------|---------|------------------|
| | | | 28-Oct | 29-Oct | 30-Oct | 31-Oct |
| | | | 24hr TSP | | | |
| | | | | 1hr TSP | | |
| | | | | | | |
| 1-Nov | 2-Nov | 3-Nov | 4-Nov | 5-Nov | 6-Nov | 7-Nov |
| | | | | | | |
| | | 24hr TSP | 1hr TSP | | | |
| | Noise (daytime) | | 101 | | | |
| | | | | | | |
| 8-Nov | 9-Nov | 10-Nov | 11-Nov | 12-Nov | 13-Nov | 14-Nov |
| | | | | | | |
| | 24hr TSP | 1hr TSP | | | | 24hr TSP |
| | | Noise (daytime) | | | | |
| | | | | | | |
| 15-Nov | 16-Nov | 17-Nov | 18-Nov | 19-Nov | 20-Nov | 21-Nov |
| | | | | | | |
| | | | | | | 24hr TSP (CMA5b) |
| | 1hr TSP | Noise (daytime) | | | | 1hr TSP |
| | | | | | | |
| 22-Nov | 23-Nov | 24-Nov | 25-Nov | 26-Nov | 27-Nov | |
| | | | | | | |
| | | | | 24hr TSP | | |
| | | Noise (daytime) | | | 1hr TSP | |
| | | | | | | |
| | | | | | | |

Contract No. HK/2011/07 Wan Chai Development Phase II and Central-Wan Chai Bypass Sampling, Field Measurement and Testing Works (Stage 2)

Tentative Environmental Monitoring Schedule December 2015

| Sunday | Monday | Tuesday | Wednesday | Thursday | Friday | Saturday |
|--------|-----------------------------|--------------------------------|--------------------|----------|----------|----------|
| | | | | | | 28-Nov |
| 29-Nov | 30-Nov | 1-Dec | 2-Dec | 3-Dec | 4-Dec | 5-Dec |
| | Noise (daytime) | Noise (daytime) | 24hr TSP | 1hr TSP | | |
| 6-Dec | 7-Dec | 8-Dec 24hr TSP Noise (daytime) | 9-Dec | 10-Dec | 11-Dec | 12-Dec |
| 13-Dec | 14-Dec | 15-Dec | 16-Dec | 17-Dec | 18-Dec | 19-Dec |
| | 24hr TSP Noise (daytime) | 1hr TSP Noise (daytime) | | | 24hr TSP | 1hr TSP |
| 20-Dec | 21-Dec | 22-Dec | 23-Dec 24hr TSP | 24-Dec | 25-Dec | 26-Dec |
| | Noise (daytime) | Noise (daytime) | | 1hr TSP | | |
| 27-Dec | | | | | | |

Appendix 5.2

Noise Monitoring Results and Graphical Presentations



Noise Monitoring Result for EP-376/2009

Day Time (0700 - 1900hrs on normal weekdays)


Location: M1a - Harbour Road Sports Centre

| | | | Measur | ement Noi | se Level | Baseline Level | Construction Noise Level | Limit Level |
|----------|-------|---------|-------------|-----------|----------|----------------|--------------------------|-------------|
| Date | Time | Weather | Leq L10 L90 | | | Leq | Leq | Leq |
| | | | | | | Unit: dl | B(A), (30-min) | |
| 02/11/15 | 14:45 | Fine | 74.9 | 77.0 | 71.0 | 73 | 71 | 75 |
| 10/11/15 | 11:27 | Fine | 73.5 | 75.3 | 71.5 | 73 | 66 | 75 |
| 17/11/15 | 11:28 | Fine | 73.2 | 74.5 | 71.0 73 | | 64 | 75 |
| 24/11/15 | 10:25 | Fine | 87.4 | 90.5 | 80.5 | 73 | 87 | 75 |



Graphic Presentation of Noise Monitoring Result

Day Time (0700 - 1900hrs on normal weekdays)



Appendix 5.3

Air Quality Monitoring Results and Graphical Presentations



Location: CMA5b - Pedestrian Plaza

Report on 24-hour TSP monitoring for EP-376/2009 Action Level - 209.9 μ g/m³ Limit Level - 260 μ g/m³

| Date | Sampling | Weather | Filter paper | Filter Weigh | Filter Weight, g | | Elapse Time, hr | | Flo | Flow Rate, m ³ /min | | | TSP Level, |
|-----------|----------|-----------|--------------|--------------|------------------|---------|-----------------|----------|--------------------------|--------------------------------|---------|------------------------|------------|
| | Time | Condition | no. | Initial | Final | Initial | Final | Time, hr | Initial, Q _{si} | Final, Q _{sf} | Average | Volume, m ³ | μg/m³ |
| 28-Oct-15 | 8:00 | Cloudy | 013597 | 2.7880 | 2.9269 | 5602.89 | 5626.89 | 24.00 | 0.93 | 0.94 | 0.94 | 1347 | 103.1 |
| 3-Nov-15 | 8:00 | Cloudy | 013516 | 2.7946 | 3.0272 | 5629.89 | 5653.89 | 24.00 | 1.00 | 1.00 | 1.00 | 1443 | 161.2 |
| 9-Nov-15 | 8:00 | Cloudy | 013773 | 2.8027 | 3.0017 | 5656.91 | 5680.91 | 24.00 | 1.00 | 1.00 | 1.00 | 1436 | 138.5 |
| 14-Nov-15 | 8:00 | Cloudy | 013748 | 2.8008 | 2.9481 | 5683.91 | 5707.91 | 24.00 | 0.94 | 0.94 | 0.94 | 1352 | 109.0 |
| 21-Nov-15 | 12:15 | Cloudy | 014045 | 2.8689 | 2.9850 | 5723.80 | 5747.80 | 24.00 | 0.94 | 0.94 | 0.94 | 1351 | 86.0 |
| 26-Nov-15 | 8:00 | Fine | 014019 | 2.8937 | 2.9111 | 5747.81 | 5771.81 | 24.00 | 0.95 | 0.95 | 0.95 | 1373 | 12.7 |

Remark: Due to interruption of electricity, the 24hr TSP monitoring was rescheduled from 20 November 2015 to 21 November 2015.

Report on 1-hour TSP monitoring for EP-376/2009 Action Level - 339.7 μ g/m3 Limit Level - 500 μ g/m3

| Date | Sampling | Weather | Filter paper | Filter Weigh | nt, g | Elapse Time | e, hr | Sampling | Flo | w Rate, m ³ /ı | min | Total | TSP Level, |
|-----------|----------|-----------|--------------|--------------|--------|-------------|---------|----------|--------------------------|---------------------------|---------|------------------------|------------|
| | Time | Condition | no. | Initial | Final | Initial | Final | Time, hr | Initial, Q _{si} | Final, Q _{sf} | Average | Volume, m ³ | μg/m³ |
| 29-Oct-15 | 8:35 | Cloudy | 013568 | 2.8161 | 2.8277 | 5626.89 | 5627.89 | 1.00 | 1.06 | 1.06 | 1.06 | 64 | 182.4 |
| 29-Oct-15 | 10:04 | Cloudy | 013596 | 2.7989 | 2.8073 | 5627.89 | 5628.89 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 149.5 |
| 29-Oct-15 | 13:00 | Cloudy | 013528 | 2.8239 | 2.8297 | 5628.89 | 5629.89 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 103.2 |
| 4-Nov-15 | 8:40 | Cloudy | 013792 | 2.8162 | 2.8237 | 5653.89 | 5654.89 | 1.00 | 1.00 | 1.06 | 1.03 | 62 | 121.2 |
| 4-Nov-15 | 9:57 | Cloudy | 013662 | 2.8133 | 2.8203 | 5654.89 | 5655.89 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 124.3 |
| 4-Nov-15 | 11:00 | Cloudy | 013780 | 2.7842 | 2.7954 | 5655.90 | 5656.90 | 1.00 | 1.06 | 1.06 | 1.06 | 64 | 175.7 |
| 10-Nov-15 | 8:40 | Cloudy | 013766 | 2.8137 | 2.8257 | 5680.91 | 5681.91 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 213.2 |
| 10-Nov-15 | 10:24 | Cloudy | 013632 | 2.8054 | 2.8172 | 5681.91 | 5682.91 | 1.00 | 1.06 | 1.06 | 1.06 | 64 | 185.3 |
| 10-Nov-15 | 13:00 | Cloudy | 013627 | 2.8013 | 2.8107 | 5682.91 | 5683.91 | 1.00 | 1.06 | 1.06 | 1.06 | 64 | 147.6 |
| 16-Nov-15 | 13:00 | Cloudy | 013730 | 2.7709 | 2.7816 | 5707.91 | 5708.91 | 1.00 | 1.00 | 1.00 | 1.00 | 60 | 178.7 |
| 16-Nov-15 | 14:05 | Cloudy | 013712 | 2.8226 | 2.8360 | 5708.91 | 5709.91 | 1.00 | 1.00 | 1.00 | 1.00 | 60 | 223.8 |
| 16-Nov-15 | 15:10 | Cloudy | 013756 | 2.7884 | 2.7997 | 5709.91 | 5710.91 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 201.2 |
| 21-Nov-15 | 8:20 | Cloudy | 013896 | 2.8051 | 2.8084 | 5720.80 | 5721.80 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 58.6 |
| 21-Nov-15 | 9:24 | Cloudy | 014037 | 2.8986 | 2.9033 | 5721.80 | 5722.80 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 83.5 |
| 21-Nov-15 | 10:30 | Cloudy | 014041 | 2.8980 | 2.9077 | 5722.80 | 5723.80 | 1.00 | 0.94 | 0.94 | 0.94 | 56 | 172.4 |
| 27-Nov-15 | 8:05 | Fine | 014011 | 2.8316 | 2.8382 | 5771.82 | 5772.82 | 1.00 | 0.95 | 0.95 | 0.95 | 57 | 115.3 |
| 27-Nov-15 | 9:58 | Fine | 014054 | 2.8566 | 2.8623 | 5772.82 | 5773.82 | 1.00 | 0.95 | 0.95 | 0.95 | 57 | 99.6 |
| 27-Nov-15 | 13:00 | Fine | 013879 | 2.7888 | 2.7976 | 5773.82 | 5774.82 | 1.00 | 0.95 | 0.95 | 0.95 | 57 | 153.8 |



Location: CMA6a - WDII PRE Office

Report on 24-hour TSP monitoring for EP-376/2009

Action Level - 207.1 μ g/m3 Limit Level - 260 μ g/m3


| Date | Sampling | Weather | Filter | Filter Weigh | Filter Weight, g | | Elapse Time, hr | | Flow Rate, m ³ /min | | | Total | TSP Level, |
|-----------|----------|-----------|-----------|--------------|------------------|----------|-----------------|----------|--------------------------------|------------------------|---------|------------------------|------------|
| | Time | Condition | paper no. | Initial | Final | Initial | Final | Time, hr | Initial, Q _{si} | Final, Q _{sf} | Average | Volume, m ³ | μg/m³ |
| 28-Oct-15 | 8:00 | Cloudy | 013599 | 2.7906 | 3.0273 | 20675.21 | 20699.21 | 24.00 | 1.27 | 1.27 | 1.27 | 1831 | 129.3 |
| 3-Nov-15 | 8:00 | Cloudy | 012944 | 2.8269 | 3.0186 | 20702.21 | 20726.21 | 24.00 | 1.28 | 1.28 | 1.28 | 1839 | 104.2 |
| 9-Nov-15 | 8:00 | Cloudy | 013775 | 2.8086 | 3.0407 | 20729.21 | 20753.21 | 24.00 | 1.27 | 1.27 | 1.27 | 1831 | 126.7 |
| 14-Nov-15 | 8:00 | Cloudy | 013757 | 2.7874 | 2.9665 | 20756.21 | 20780.21 | 24.00 | 1.28 | 1.28 | 1.28 | 1836 | 97.5 |
| 20-Nov-15 | 8:00 | Cloudy | 013709 | 2.8371 | 3.0699 | 20783.21 | 20807.21 | 24.00 | 1.27 | 1.27 | 1.27 | 1835 | 126.9 |
| 26-Nov-15 | 8:00 | Fine | 014018 | 2.8870 | 3.0865 | 20810.22 | 20834.22 | 24.00 | 1.29 | 1.29 | 1.29 | 1863 | 107.1 |

Report on 1-hour TSP monitoring for EP-376/2009


Action Level - 333 μ g/m3 Limit Level - 500 μ g/m3

| Date | Sampling | Weather | Filter | Filter Weigh | nt, g | Elapse Tim | e, hr | Sampling | Flo | w Rate, m ³ /ı | min | Total | TSP Level, |
|-----------|----------|-----------|-----------|--------------|--------|------------|----------|----------|--------------------------|---------------------------|---------|------------------------|------------|
| | Time | Condition | paper no. | Initial | Final | Initial | Final | Time, hr | Initial, Q _{si} | Final, Q_{sf} | Average | Volume, m ³ | μg/m³ |
| 29-Oct-15 | 8:30 | Cloudy | 013590 | 2.8010 | 2.8137 | 20699.21 | 20700.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 166.3 |
| 29-Oct-15 | 9:49 | Cloudy | 013593 | 2.7742 | 2.7865 | 20700.21 | 20701.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 161.1 |
| 29-Oct-15 | 10:55 | Cloudy | 013529 | 2.8087 | 2.8213 | 20701.21 | 20702.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 165.0 |
| 4-Nov-15 | 9:00 | Cloudy | 013666 | 2.8147 | 2.8240 | 20726.21 | 20727.21 | 1.00 | 1.28 | 1.28 | 1.28 | 77 | 121.6 |
| 4-Nov-15 | 10:09 | Cloudy | 013661 | 2.8159 | 2.8282 | 20727.21 | 20728.21 | 1.00 | 1.28 | 1.28 | 1.28 | 77 | 160.8 |
| 4-Nov-15 | 13:00 | Cloudy | 013788 | 2.8122 | 2.8258 | 20728.21 | 20729.21 | 1.00 | 1.28 | 1.28 | 1.28 | 77 | 177.8 |
| 10-Nov-15 | 8:43 | Cloudy | 013617 | 2.8008 | 2.8104 | 20753.21 | 20754.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 125.5 |
| 10-Nov-15 | 10:35 | Cloudy | 013763 | 2.7938 | 2.8047 | 20754.21 | 20755.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 142.5 |
| 10-Nov-15 | 13:00 | Cloudy | 013760 | 2.7695 | 2.7802 | 20755.21 | 20756.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 139.9 |
| 16-Nov-15 | 13:00 | Cloudy | 013732 | 2.7933 | 2.8072 | 20780.21 | 20781.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 182.1 |
| 16-Nov-15 | 14:03 | Cloudy | 013711 | 2.8298 | 2.8437 | 20781.21 | 20782.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 182.1 |
| 16-Nov-15 | 15:30 | Cloudy | 013754 | 2.8013 | 2.8143 | 20782.21 | 20783.21 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 170.3 |
| 21-Nov-15 | 8:30 | Cloudy | 014028 | 2.8536 | 2.8662 | 20807.22 | 20808.22 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 164.8 |
| 21-Nov-15 | 9:35 | Cloudy | 014025 | 2.8587 | 2.8701 | 20808.22 | 20809.22 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 149.1 |
| 21-Nov-15 | 10:40 | Cloudy | 014022 | 2.8837 | 2.8963 | 20809.22 | 20810.22 | 1.00 | 1.27 | 1.27 | 1.27 | 76 | 164.8 |
| 27-Nov-15 | 8:35 | Fine | 014050 | 2.8704 | 2.8801 | 20834.23 | 20835.23 | 1.00 | 1.29 | 1.29 | 1.29 | 78 | 124.9 |
| 27-Nov-15 | 10:15 | Fine | 014008 | 2.8198 | 2.8300 | 20835.23 | 20836.23 | 1.00 | 1.29 | 1.29 | 1.29 | 78 | 131.4 |
| 27-Nov-15 | 13:00 | Fine | 014005 | 2.8243 | 2.8340 | 20836.23 | 20837.23 | 1.00 | 1.29 | 1.29 | 1.29 | 78 | 124.9 |







Graphic Presentation of 24 hour TSP Result for EP-376/2009






Graphic Presentation of 1 hour TSP Result for EP-376/2009







Appendix 6.1

Event Action Plans

Event/Action Plan for Construction Noise

| EVENT | | AC | CTION | | | | | | |
|-----------------------------|--|---|--|---|--|--|--|--|--|
| | ET | IEC | ER | CONTRACTOR | | | | | |
| Action Level being exceeded | Notify ER, IEC and Contractor; Carry out investigation; Report the results of investigation to the IEC, ER and Contractor; Discuss with the IEC and Contractor on remedial measures required; Increase monitoring frequency to check mitigation effectiveness. (The above actions should be taken within 2 working days after the exceedance is identified) | 1. Review the investigation results submitted by the ET; 2. Review the proposed remedial measures by the Contractor and advise the ER accordingly; 3. Advise the ER on the effectiveness of the proposed remedial measures. (The above actions should be taken within 2 working days after the exceedance is identified) | Confirm receipt of notification of failure in writing; Notify Contractor; In consolidation with the IEC, agree with the Contractor on the remedial measures to be implemented; Supervise the implementation of remedial measures. (The above actions should be taken within 2 working days after the exceedance is identified) | Submit noise mitigation proposals to IEC and ER; Implement noise mitigation proposals. (The above actions should be taken within 2 working days after the exceedance is identified) | | | | | |

| am | Lam Geotechnics Limit |
|----|-----------------------|
| | |

| EVENT | | A | CTION | |
|----------------------------|--|--|--|--|
| | ET | IEC | ER | CONTRACTOR |
| Limit Level being exceeded | Inform IEC, ER, Contractor and EPD; Repeat measurements to confirm findings; Increase monitoring frequency; 4. Identify source and investigate the cause of exceedance; 5. Carry out analysis of Contractor's working procedures; 6. Discuss with the IEC, Contractor and ER on remedial measures required; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; If exceedance stops, cease additional monitoring. (The above actions should be taken within 2 working days after the exceedance is identified) | Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly. (The above actions should be taken within 2 working days after the exceedance is identified) | Confirm receipt of notification of failure in writing; Notify Contractor; In consolidation with the IEC, agree with the Contractor on the remedial measures to be implemented; Supervise the implementation of remedial measures; If exceedance continues, consider stopping the Contractor to continue working on that portion of work which causes the exceedance until the exceedance is abated. The above actions should be taken within 2 working days after the exceedance is identified) | Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC and ER within 3 working days of notification; Implement the agreed proposals; Submit further proposal if problem still not under control; Stop the relevant portion of works as instructed by the ER until the exceedance is abated. (The above actions should be taken within 2 working days after the exceedance is identified) |

| EVENT | | ACTION | | |
|--|--|---|---|---|
| | 1. Identify source, investigate the causes of exceedance and propose remedial measures; 2. Inform IEC and ER; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily; 7. If exceedance is identified) 7. If exceedance continues, arrange meeting with IEC and ER; 8. If exceedance stops, cease additional monitoring. (The above actions should be taken within 2 working days after the exceedance is identified) 7. If exceedance continues, arrange meeting with IEC and ER; 8. If exceedance stops, cease additional monitoring. (The above actions should be taken within 2 working days after the exceedance is identified) 8. If exceedance stops, cease additional monitoring. (The above actions should be taken within 2 working days after the exceedance is identified) 9. Inform ER, Contractor and EPD; 2. Inform ER, Contractor and EPD; 2. Identify source; (The above actions should be taken within 2 working days after the exceedance is identified) 1. Identify source, investigate the causes of exceedance and propose remedial measures; 2. Inform ER, Contractor and EPD; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily; 5. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results. (The above actions should be taken within 2 working days after the exceedance is identified) 1. Identify source; investigate the causes of exceedance and propose remedial measures; 4. Advise the ER on the eff proposed remedial measures; 6. Increase monitoring frequency to daily; 7. Increase monitoring frequency to daily; 8. Increase monitoring frequency to daily; 9. Increase monitoring frequ | IEC | ER | CONTRACTOR |
| ACTION LEVEL | | | | |
| Exceedance for one sample | exceedance and propose remedial measures; 2. Inform IEC and ER; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily. (The above actions should be taken within 2 working days | | Notify Contractor. (The above actions should be taken within 2 working days after the exceedance is identified) | Rectify any unacceptable practice; Amend working methods if appropriat (The above actions should be taken within 2 working days after the exceedance is identified) |
| 2. Exceedance for two or more consecutive samples | 2. Inform IEC and ER; 3. Advise the ER on the effectiveness of the proposed remedial measures; 4. Repeat measurements to confirm findings; 5. Increase monitoring frequency to daily; 6. Discuss with IEC and Contractor on remedial actions required; 7. If exceedance continues, arrange meeting with IEC and ER; 8. If exceedance stops, cease additional monitoring. (The above actions should be taken within 2 working days) | Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ET on the effectiveness of the proposed remedial measures; Supervise Implementation of remedial | Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented. (The above actions should be taken within 2 working days after the exceedance is identified) | Submit proposals for remedial to ER within 3 working days of notification; Implement the agreed proposals; Amend proposal if appropriate. (The above actions should be taken within 2 working days after the exceedance is identified) |
| LIMIT LEVEL | | | | |
| Exceedance for one sample | exceedance and propose remedial measures; 2. Inform ER, Contractor and EPD; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily; 5. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results. (The above actions should be taken within 2 working days after the exceedance is identified) | Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ER on the effectiveness of the proposed remedial measures; Supervise implementation of remedial measures. (The above actions should be taken within 2 working days after the exceedance is identified) | Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented. (The above actions should be taken within 2 working days after the exceedance is identified) | Take immediate action to avoid furthe exceedance; Submit proposals for remedial actions IEC within 3 working days of notificati 3. Implement the agreed proposals; Amend proposal if appropriate. (The above actions should be taken within 2 working days after the exceedance is identified) |
| Exceedance for two or more consecutive samples | Identify source; Repeat measurement to confirm findings; Increase monitoring frequency to daily; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Arrange meeting with IEC and ER to discuss the remedial actions to be taken; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the | potential remedial actions; 2. Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; 3. Supervise the implementation of remedial | Confirm receipt of notification of failure in writing; Notify Contractor; In consolidation with the IEC, agree with the Contractor on the remedial measures to be implemented; Ensure remedial measures properly implemented; If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated. (The above actions should be taken within 2 working days after the exceedance is identified) | Take immediate action to avoid further exceedance; Submit proposals for remedial actions IEC within 3 working days of notifications. Implement the agreed proposals; Resubmit proposals if problem still not under control; Stop the relevant portion of works as determined by the ER until the exceedance is abated. (The above actions should be taken within 2 working days after the exceedance is identified. |



Event and Action Plan for Marine Water Quality

| EVENT | ACTION | | | | | | | | | | | | | |
|--|--|--|---|--|--|--|--|--|--|--|--|--|--|--|
| | ET | IEC | ER | CONTRACTOR | | | | | | | | | | |
| Action level being exceeded by one sampling day | Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform IEC and Contractor; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC and Contractor; (The above actions should be taken within 1 working day after the exceedance is identified) Repeat measurement on next day of exceedance. | Discuss with ET and Contractor on the mitigation measures; Review proposals on mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | Discuss with IEC on the proposed mitigation measures; Make agreement on the mitigation measures to be implemented. (The above actions should be taken within 1 working day after the exceedance is identified) | Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with ET and IEC and propose mitigation measures to IEC and ER; Implement the agree mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | | | | | | | | | | |
| Action level being exceeded by more than one consecutive sampling days | Identify source(s) of impact; Inform IEC and Contractor; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC and Contractor; Ensure mitigation measures are implemented; Prepare to increase the monitoring frequency to daily; (The above actions should be taken within 1 working day after the exceedance is identified) Repeat measurement on next working day of exceedance. | Discuss with ET and Contractor on the mitigation measures; Review proposals on mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | Discuss with IEC on the proposed mitigation measures; Make agreement on the mitigation measures to be implemented; Assess the effectiveness of the implemented mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | Inform the Engineer and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with ET and IEC and propose mitigation measures to IEC and ER within 3 working days; Implement the agreed mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | | | | | | | | | | |

| EVENT | | ACTION | | | | | | | | | | | | | |
|---|---|--|--|---|--|--|--|--|--|--|--|--|--|--|--|
| | ET | IEC | ER | CONTRACTOR | | | | | | | | | | | |
| Limit level being exceeded by one sampling day | Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, contractor and EPD; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit level. (The above actions should be taken within 1 working day after the exceedance is identified) | Discuss with ET and Contractor on the mitigation measures; Review proposals on mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | Discuss with IEC, ET and Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Make agreement on the mitigation measures to be implemented; Assess the effectiveness of the implemented mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | Inform the Engineer and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with ET, IEC and ER and propose mitigation measures to IEC and ER within 3 working days; Implement the agreed mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | | | | | | | | | | | |
| Limit level being exceeded by more than one consecutive sampling days | Identify source(s) of impact; Inform IEC, contractor and EPD; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit level for two consecutive days. (The above actions should be taken within 1 working day after the exceedance is identified) | Discuss with ET and Contractor on the mitigation measures; Review proposals on mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. (The above actions should be taken within 1 working day after the exceedance is identified) | Discuss with IEC, ET and Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Make agreement on the mitigation measures to be implemented; Assess the effectiveness of the implemented mitigation measures; Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the marine work until no exceedance of Limit level. (The above actions should be taken within 1 working day after the exceedance is identified) | Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with ET, IEC and ER and propose mitigation measures to IEC and ER within 3working days; Implement the agreed mitigation measures; As directed by the Engineer, to slow down or to stop all or part of the marine work or construction activities. (The above actions should be taken within 1 working day after the exceedance is identified) | | | | | | | | | | | |

Event and Action Plan for Odour Patrol

| Event | | ACTION |
|-------------------------------|---|---|
| | Person-in-charge of Odour Monitoring | Implementation Agent Identified by CEDD |
| Action Level | | |
| Exceedance of Action Level | Identify source/reason of exceedance; Repeat odour patrol to confirm finding. | Carry out investigation to identify the source/reason of exceedance; Rectify any unacceptable practice Implement more mitigation measures if necessary; Inform EPD or MD if exceedance is considered to be caused by expedient connections or floating debris. |
| Limit Level | | |
| Exceedance of Limit Level | 1. Identify source / reason of exceedance; 2. Repeat odour patrol to confirm findings; 3. Increase odour patrol frequency; 4. If exceedance stops, cease additional odour patrol. | Carry out investigation to identify the source/reason of exceedance. Investigation shall be completed within 2 weeks; Rectify any unacceptable practice; Formulate remedial actions; Ensure remedial actions properly implemented; If exceedance continues, consider what more/enhanced mitigation measures shall be implemented; Inform EPD or MD if exceedance is considered to be caused by expedient connections or floating debris. |

Appendix 6.2

Summary for Notification of Exceedance



| Ref. No. | Date | Time | Location | Construction Noise Level | Unit | Action Level | Limit Level | Follow-up action | |
|----------|-----------|-------|----------------------------------|--------------------------|-------------|--|-------------|----------------------|--|
| X_10N185 | 24-Nov-15 | 10:25 | M1a-Habour Road Sports Centre | 87 | Leq(30-min) | when one documented complaint was received. | 75 | | Breaking works at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor. |
| | | | | | | | | Remarks / Other Obs: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. No construction works for EP-376/2009 was conducted by Contract HK/2012/08 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related. |

Appendix 9.1

Complaint Log

Environmental Complaints Log

| Complaint Log No. | Date of Complaint | Received From and Received By | Location of Complainant | Nature of Complaint | Outcome | Status |
|----------------------|-------------------|-------------------------------|-------------------------|---------------------|---------|--------|
| | - | - | | • | | |

Appendix 10.1


Construction Programme of Individual Contracts



中國建築-利達聯營 CHINA STATE - LEADER JOINT VENTURE

CEDD Contract No. HK/2012/08 Wan Chai Development Phase II Central - Wan Chai Bypass at Wan Chai West

Page: 1/2





中國建築-利達聯營 CHINA STATE - LEADER JOINT VENTURE

CEDD Contract No. HK/2012/08 Wan Chai Development Phase II Central - Wan Chai Bypass at Wan Chai West

Page : 2 / 2

| vity ID | Activity Name | Orig Dur | Early Start | Early Finish | Road & | | | | | | 2015 | | | | | | | | | | | 20 | 016 | | | | | | | | | 2 | 017 | Jun Jul Aug Ser cable duct and drawpit Telecom cable duct and draw Utilities - lay & compact sub- & Utilities - construct road ke brk & Utilities - flexible pavem dwork & Utilities - footpath pa tilities - construct surface char V - Roadwork & Utilities - Ro | |
|---------|--|----------|-------------|--------------|--------|-----|-----|-----|-----|-----|-------|------|-------|-------|-------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|---------------|--------------|-----------|----------------|-------------|--|---------------|
| | | | | | Drain | Feb | Mai | Apr | May | Jun | ı Jul | l Au | g Sep | p Oct | t Nov | Dec | Jan | Feb | Mar | Apr | May | Jun | Jul | Aug | Sep | Oct | Nov | Dec | Jan | Feb | Mar | Apr Ma | / Jun | Jul | Aug Sr |
| SV10100 | Sec V - Roadwork & Utilities - Gas Main | 90 | 13-Sep-16 | 31-Dec-16 | Road | | | | | | | | | | | | | | | | | | | | - | | | | Sec | V - Roadwo | rk & Util | ities - Gas I | 1ain | | |
| SV10120 | Sec V - Roadwork & Utilities - HEC cable duct and drawpit | 90 | 28-Sep-16 | 16-Jan-17 | Road | | | | | | | | | | | | | | | | | | | | | | | | $\overline{}$ | Sec V - Road | lwork & | Utilities - H | EC cable o | uct and dra | awpit |
| SV10140 | Sec V - Roadwork & Utilities - Telecom cable duct and drawpit | 90 | 14-Oct-16 | 04-Feb-17 | Road | | | | | | | | | | | | | | | | | | | | | _ | | | | Sec V - | Roadwo | ork & Utilitie | s - Teleco | m cable du | ıct and dra |
| SV10160 | Sec V - Roadwork & Utilities - lay & compact sub-base | 110 | 28-Oct-16 | 14-Mar-17 | Road | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SV10180 | Sec V - Roadwork & Utilities - construct road kerb | 110 | 05-Nov-16 | 22-Mar-17 | Road | | | | | | | | | | | | | | | | | | | | | | _ | | | | | | | | |
| SV10200 | Sec V - Roadwork & Utilities - flexible pavement | 110 | 14-Nov-16 | 30-Mar-17 | Road | - | | | | | | | | | | | |] | | | | | | | | | - | | | | S | ec V - Roa | lwork & U | tilities - flex | xible paven |
| SV10220 | Sec V - Roadwork & Utilities - footpath paving block | 110 | 24-Nov-16 | 11-Apr-17 | Road | | | | | | | | | | | | | | | | | | | | | | | _ | | | | Sec V - F | oadwork | Utilities - | footpath p |
| SV10240 | Sec V - Roadwork & Utilities - concrete footpath | 72 | 02-Dec-16 | 04-Mar-17 | Road | | | | | | | | | | | | | | | | | | | | | | | | | | Sec V - | Roadwork | k Utilities | concrete f | ootpath |
| SV10260 | Sec V - Roadwork & Utilities - construct surface channel | 72 | 02-Dec-16 | 04-Mar-17 | Road | | | | | | | | | | | | | | | | | | | | | | | | | | Sec V - | Roadwork | k Utilities | construct | surface cha |
| SV10280 | Sec V - Roadwork & Utilities - Road Lighting, TCSS Ducts &Traffic Signs | 72 | 11-Feb-17 | 12-May-17 | Road | | | | | | | | | | | | | | | | | | | | | | | | | | | | Sec V - Ro | adwork & | Utilities - R |
| SV10300 | Achievement of Section V of the Works | 0 | | 12-May-17 | Road | | 1 | | | | | | | | | | | 7 | | | | | | | 7 | | 1 | | | | | • | | | |