Drainage Services Department

Contract No. CM 4/2017 Independent Environmental Checker for Construction of Dry Weather Flow Interceptor at Cherry Street Box Culvert

Monthly Environmental Audit Report No.39 (March 2021)

First version | March 2021

This report takes into account the particular instructions and requirements of our client. It is not intended for and should not be relied upon by any third party and no responsibility is undertaken to any third party.

Job number 258952

Ove Arup & Partners Hong Kong Ltd Level 5 Festival Walk 80 Tat Chee Avenue Kowloon Tong Kowloon Hong Kong www.arup.com



Contents

			Page
1	INTR	ODUCTION	1
	1.1	Background	1
	1.2	Scope of the Assignment	2
2	Proje	ct Organization	3
	2.1	Project Organization and Management Structure	3
	2.2	Construction Activities in the Reporting Period	3
3	Conci	se Overview of Assignment Progress	3
4	Status	s on Implementation of Environmental Mitigation Measure	s 3
5	Majo	r Accomplishment	7
	5.1	Deliverables	7
	5.2	Meetings	7
	5.3	Summary of Work Done	7
	5.4	IEC Site Audit	8

Figures

Figure 1 Project Location

Appendices

Appendix A Project Organization and Contacts of Key Personnel

Appendix B IEC Site Audit Checklist

1 INTRODUCTION

1.1 Background

The existing Cherry Street Box Culvert (CSBC) is a reinforced concrete 8-cell stormwater box culvert; each cell is 4.8 m wide and 3.5 m high. The CSBC collects run-off from three upstream box culverts underneath Palm Street, Cheung Wong Road and a section of West Kowloon Corridor West and ultimately discharges into the New Yau Ma Tei Typhoon Shelter (NYMTTS).

At present, the water quality at NYMTTS and the odour associated with it remains unsatisfactory. It is believed that polluted flow, including those from the expedient connections, cross-connections between the foul water sewerage and the stormwater drainage system in the area found their way into the CSBC and in turn discharges into NYMTTS. Measures have to be taken to improve the present conditions at the CSBC.

In 2010, Environmental Protection Department (EPD) completed a West Kowloon and Tsuen Wan Sewerage Master Plans Study Review and recommended to construct a dry weather flow interceptor (DWFI) at the outfall of the CSBC. Upon commissioning of the DWFI system, the intercepted flow would be discharged to the existing sewerage system via proposed discharge sewerage.

The proposed DWFI system will comprise construction of a DWFI at the CSBC to intercept the dry weather flow (DWF) inside the box culvert and construction of a sewage pumping station to pump the intercepted DWF to the existing sewerage network via proposed twin rising mains.

The Project titled "Construction of dry weather flow interceptor at Cherry Street box culvert" mainly comprises the construction of (i) an underground DWFI with automatic penstocks at CSBC; (ii) a pumping station; (iii) an underground stormwater bypass box culvert; and (iv) about 270 metres of underground twin rising main from the pumping station in (ii) above to an existing sewer at Lin Cheung Road. The Project will be implemented under PWP Item No. 4380DS. The Project location is shown in **Figure 1**.

The Project is classified as a designated project under item F.3(b) (i), Part 1 of the Schedule 2 of the Environmental Impact Assessment Ordinance (Cap. 499) (EIAO), since the proposed sewage pumping station has an installed capacity (average dry weather flow) of more than 2,000m³ per day and its boundary is less than 150 m from an existing residential area.

A project profile (Register No. PP-527/2015) ("Project Profile") entitled "Proposed Sewage Pumping Station and Dry Weather Flow Interceptor at Cherry Street Box Culvert" was submitted to Environmental Protection Department (EPD) under Application No. DIR241/2015. Permission to apply directly for environmental permit was granted by EPD in September 2015. An Environmental Permit (EP-

523/2016) ("EP") to construct and operate the Designated Project was issued to Drainage Services Department (DSD) on 23 December 2016.

According to the EP, DSD shall employ an Independent Environmental Checker ("IEC") to audit the implementation of all mitigation measures recommended in the Project Profile and required under the EP, and certify in writing in the monthly audit report full implementation of the mitigation measures during the construction phase of the Project

Arup was commissioned by DSD as the IEC in accordance with the conditions stipulated in the EP (EP-523/2016) for a period of 64 months from 8 January 2018.

1.2 Scope of the Assignment

Scope of work of this Assignment includes:

- (i) Provide the continual services of an IEC as stipulated in the Project Profile and the EP and reporting the findings to the Employer and the Engineer. The role of the IEC shall be independent from the Contractors;
- (ii) Conduct monthly site audits on the implementation of all mitigation measures recommended in the Project Profile and the EP and reporting the findings to the Employer and the Engineer;
- (iii) Advise the Engineer and the Employer on environmental issues related to the implementation of environmental mitigation measures under Contract No. DC/2017/01;
- (iv) Provide comments on the environmental aspects of the works programme, method statements and other relevant submissions by the Contractors;
- (v) Attend the monthly Site Safety and Environmental Management Committee (SSEMC) meetings;
- (vi) Report the findings of the site inspection and other environmental performance reviews to the Engineer and the Employer; and
- (vii) Submit monthly audit reports to EPD and confirming in writing in the report full implementation of the mitigation measures as recommended in the Project Profile and EP during and upon completion of the construction works under Contract No. DC/2017/01.

2 Project Organization

2.1 Project Organization and Management Structure

The project organization and contacts of key personnel of the Project are shown in **Appendix A**.

3 Concise Overview of Assignment Period

3.1 Construction Activities in the Reporting Period

The construction activities carried out by the Contractor during the reporting period included the following:

- Installation of DfMA segments of superstructure of sewage pumping station was completed.
- Installation of E&M equipment in sewage pumping station and Maintenance Corridor was in progress.
- Construction of civil requirement works in Cell 3 of DWFI was in progress.
- Construction of thrust block and grouting of the rising main in the pipe jacking tunnel between Ch. 0 and Ch. 22.5 was completed. Pressure testing of rising main was also completed.
- Installation of stoplog frame at Cell 5 outside Olympian City 2 was in progress.
- Installation of multi-part covers at expanded desilting access of Cell 3, 4 and 8 outside Olympian City 2 was in progress.
- Desilting by diver team in Cell 8 outside Olympian City 2 using air-lifting method was in progress.

The environmental performance was considered acceptable during the assignment period from 1 March 2021 to 31 March 2021.

4 Status on Implementation of Environmental Mitigation Measures

The potential environmental impacts and proposed mitigation measures to be incorporated into the design and construction of the Project are summarised in **Table 4.1** below.

Table 4.1 Summary of potential environmental impacts and proposed

environmental mitigation measures

environmental mitigation measures					
Mitigation Measures	Implementation Agent	Status			
Dust nuisance					
1. Adopt dust control and suppression measures as stipulated in the Air Pollution Control (Construction Dust) Regulation.		Implemented			
2. Water spraying on exposed area and during excavation.		Implemented			
3. Provide wheel-washing facilities.		Implemented			
4. Cover stockpile of dusty materials by impervious sheets.		Implemented			
5. Provide hoarding of not less than 2.4m high from ground level along the site boundary adjoining Hoi Fai Road.	Contractor (Construction Phase)	Implemented			
6. Cover dusty load on trucks before they leave the construction site.		Implemented			
7. Avoid concurrent excavation activities for construction of underground DWFI, underground emergency stormwater bypass culvert and CSBCSPS.		Implemented			
8. Minimize area involving dusty construction activities by arrangement of construction activities and methods.		Implemented			
Odour					
1. Locate the inlet chamber, screen chamber, valve chamber and wet well of the sewage pumping station underground and enclose them by a reinforced concrete structure.	Contractor (Construction Phase)	Implemented			
2. Install and properly maintain a deodorizer with a forced ventilation system and an odour removal efficiency of at least 99.5%.	DSD (Operational Phase)	N/A for the reporting month and shall be implemented in the later months			
Water Quality					
1. Control construction surface run-off according to ProPECC PN1/94, EPD's Practice Note for Professional Persons, Construction Site Drainage.	Contractor (Construction Phase)	Implemented			

Mitigation Measures	Implementation Agent	Status
2. All chemical tanks and storage areas will be provided with locks and placed on sealed areas, within bunds of a capacity equal to 110% of the storage capacity of the largest tank.		Implemented
3. Install and properly maintain a standby pump and dual power supply.	Contractor (Construction	Implemented
4. Provide a telemetry system to transmit signals showing irregularity or operational problem of the sewage pumping station and the dry weather flow interceptor to the Stonecutters Island Sewage Treatment Works.	Phase) DSD (Operational Phase)	N/A for the reporting month and shall be implemented in the later months
Noise		<u> </u>
Adoption of standard control measures such as adopting quiet mechanical equipment, temporary noise barriers and good site practices etc.		Implemented
Construction Noise Permit is required for construction work during restricted hours as defined under the Noise Control Ordinance.	Contractor (Construction	Implemented
3. Locate the pumps and screening facilities of the sewage pumping station underground and enclose them by a reinforced concrete structure.	Phase)	Implemented
4. Install all outlets of the extraction fans with acoustic louvers.		Implemented
Waste Management		

Mitigation Measures	Implementation Agent	Status
Standard waste management measures and good site practices in waste handling, disposal and transportation will be implemented.		Implemented
2. The Contractor will be required to sort all C&D materials and general refuse into different categories for reuse on site, recycling and disposal at designated public fill reception facilities or landfills. Disposal of C&D materials will be managed through the trip-ticket system as stipulated in DEVB TC(W) No. 6/2010.	Contractor (Construction	Implemented
3. All chemical wastes due to maintenance of equipment will be handled, stored and disposed of in accordance with the requirements of the Waste Disposal (Chemical Waste) (Chemical) Regulation.	Phase)	Implemented
4. General refuse will be stored and disposed of separately from general construction waste and chemical waste. The storage bins for general refuse will be provided with lids, which should be kept closed to avoid odour nuisance and windblown litter. General refuse will be removed regularly and disposed of to landfills.		Implemented
Landscape and Visual		
Erect site hoarding with decorative features that are compatible with the surrounding environment;		Implemented
2. Maintain site cleanliness and tidiness;	Contractor	Implemented
3. Properly manage construction waste in the works area;	(Construction Phase)	Implemented
Reinstate all temporary works areas to its original conditions upon completion of works.	DSD (Operational Phase)	N/A for the reporting month and shall be implemented in the later months

Mitigation Measures	Implementation Agent	Status
5. Implement and properly maintain the landscape and visual mitigation measures (e.g. rooftop greening, grasscrete, paving lock, vertical greening, permanent shrub planter, removable shrub planter, bench with shelter, and removable planter with trees) as shown in Figure 2 of the EP.		N/A for the reporting month and shall be implemented in the later months

5 Major Accomplishment

5.1 Deliverables

Deliverables completed in the reporting period are summarised in **Table 5.1**.

Table 5.1 Completed deliverables

Description	Submitted by IEC
Monthly Environmental Audit Report No. 38	8 March 2021
(February 2021)	

Planned deliverables to be completed in the coming reporting period is summarised in **Table 5.2**.

Table 5.2 Planned deliverables

Description	Planned Submission Date	Status
Monthly Environmental Audit Report No. 39 (March 2021)	7 April 2021	On schedule

5.2 Meetings

No meeting was held in the reporting month.

5.3 Summary of Work Done

Upon commencement of the Assignment, accumulated numbers of IEC monthly environmental audit report submission and various kinds of meetings are summarized in **Table 5.3**.

Table 5.3 Summary of work done


Work	Number
Reports	
IEC Monthly Environmental Audit Report	39
Meeting	
IEC monthly site inspection with DSD, Engineer Representative and Contractor	34
Project related meeting with DSD and EPD	1

5.4 IEC Site Audit

IEC site audit was conducted on 26 March 2021 with the presence of DSD, Resident Site Engineer, Contractor and IEC. No major site defect was observed in the reporting month. The IEC site audit checklist is given in Appendix B.

Figure 1

Project Location





Environmental Permit No.: EP-523/2016

環境許可證編號: EP-523/2016

Project Location Plan 工程項目位置圖 Figure 1 圖 1


- 櫻桃街箱形雨水渠擬建污水泵房及旱流截取設施

Street Box Culvert

工程項目名稱

Appendix A

Project Organization and Contacts of Key Personnel



———Contractual Relationship

Appendix B

IEC Site Audit Checklist

Construction of Dry Weather Flow Interceptor at Cherry Street Box Culvert Independent Environmental Checker Environmental Site Inspection Checklist



	Ref. No. Project Contract No. Inspected By	at Cherry S CM 4/2017 IEC's Rep. : Cilent's Rep Engineer's F Contractor's	Hilton Rep.: S.	n Tam and Cha K Kow	an	IEC Client Contractor Engineer Inspection Dat Time Period	Drai Chir Top Blac	k & Veat	vices orgical Constant oh HK	Group Cruction E	ent Corpor	ration - ering Limited JV
	Condition	Weather	∏ ipe	☐ Overcast	□ \$torm	Rain	Drizzle	г	Hazy			
	Humidity Wind	☐High ☑Calm	☐ Inderate	□ ow □ Breeze	☐ s trong	Gan		perature			Ċ	23.℃
No.	Part II	Water Quality	and Draina	ige			N/A	N/O Ye	Rdr	Obs N	V/C	Photos / Remarks
1	Is drainage sy	stem adequat	te?									7
2		stem well mai										
3		stem adequat							, \Box			
4		es to surround						,0 🗹				
5		meter channe										-
G		itside the site control measu									_	
6 7		porary ditches	and the same of			054 • 11 00 00 0 C - 200 0 1 1 2 1 2 0 0 0 0						V
	watercourse?	porary ditorics	i loi Tulloli	discriarge into	о арргорнас							
8		porary ditches	s with silt re	etention and r	emoval facil	ities?	☑.					
9a	Do permanen	t drainage cha	nnels have	e: sedime	entation basin	?	/				_	
9b				traps a	ind baffles?		V					
10	1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970 - 1970	rohitated from										_00s I
11		er from tunnels		runoff collec	ted and disc	harged						
40		tion traps/tank				10	_	/	_		_	
12 13a		imentation tan entation tanks			and the state of t							
13b	Are the sedim	entation tanks		equate capacit		i cells?						
13c				n silt and sedi								
14	Are there neu	tralisation tanl				narge?	<u> </u>				5	
15		ge diverted to					/				5	
16	Is the discharg	ge from neutra	alisation tar	nks routed to	silt trap or se	edimentation	∇					
	tanks before of	disposal?					,					
17	Are there oil in											
18		ease removed			T. C. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10		\square					
19 20	1073	ypass for oil to and plant clear	58	177		neavy rain?					_	
20	leaving the sit		ieu oi earti	i, iliuu aliu u	edits before							Y
21		shing bay prov	vided at ev	erv site exit?								
22a		ashing bay w		uate design?						74-27 (77	_	
22b			adeq	uate settling &	removal of sa	and/silt?						
22c			pave	d access road	leading to exi	t?						
22d				ss road sufficie	ently backfill to	oward						
22e	110000000000000000000000000000000000000	31. 34. 1. 1P. 34.		I wash bay?	1.0		_	/				
23	Is exposed ea					2012					_	
24 25		slope surfaces kpiles covere	A STATE OF THE PARTY OF THE PAR	and the same of th	ii otilei illeai	15)!						
26	and the second of the second decision of the second	covered and	and the state of the state of	<i>,</i>							_	×
27		roads protect		ned stones or	gravels?				, [_	
28		nected to fou										
29		d rubbish on s		95		ly?						
30	Is wastewater	discharge lice	ence availa	ble for insped	ction?							

Construction of Dry Weather Flow Interceptor at Cherry Street Box Culvert Independent Environmental Checker Environmental Site Inspection Checklist



No. 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	Part III Air Quality Are vehicles in the site travelling within speed limit of 10 km/h? Are site vehicle movement confined to designated haul roads? Is the public road around the site entrance kept clean and free from dust? Are areas of site with regular traffic movement have hard surface? Are the haul roads watered regularly to avoid dust disturbance? Are unpaved areas watered regularly to avoid dust disturbance? Does the water spraying truck work effectively? Is working area of excavation or earth moving operation sprayed with water to maintain the entire surface wet? Are the dusty materials sprayed with water during transfer operation? Do the site vehicles use the wheel wash at the site exits? Does the wheel wash work effectively? Are hoarding not less than 2.4m tall provided beside roads or areas with public access? Are incombustible screens not less than 1.8m tall provided in the public area affected by exhaust fumes or smoke emission? Is dark smoke emission avoided? Are dusty materials properly covered? Are the bags of cement (more than 20) covered entirely? Are the excavated materials dropped at minimum practical height? Are conveyor belts fitted with windboards, transfer points and hoppers enclosed? Are bulk fine grained materials stored in closed silos fitted with high level alarm indicator? Are weigh hoppers vented to suitable filters? Are weigh hoppers vented to suitable filters? Are completed earthworks sealed and hydroseeded and planted as soon as practicable? Is open burning avoided?	N/A N/O Yes Rdr Obs N/C Photos//	Remarks
25 26 27 28 29 30	Are vehicles and equipment switched off while not in use? Are all trucks loaded to a level within the side and tail boards? Are materials transported by dump trucks with mechanical cover? Do the truck covers work effectively? Does ULSD used in the construction activities? Observable dust sources	Sylvehicle/equipment movements Sylvehicle/equipment movements Sylvehicle/equipment movements	70n
No. 1a 1b 2a 2b 3 4 5	Part IV Construction Noise Impact Are the construction works scheduled to minimize airborne noise nuisance? groundborne noise nuisance? Are the works or equipment sited to minimize airborne noise nuisance? groundbrone noise nuisance? Are all plant and equipment well maintained and in good operating condition? Are idling equipment throttled down or turned off? Are powered mechanical equipment covered or shielded by appropriate acoustic materials? Are silenced equipment used where practicable? Are noise enclosure, noise barrier, or portable noise barrier used	N/A N/O Yes Rdr Obs N/C Photos / F	Remarks
8 9 10 11 12 13	where necessary? Do hand-held breakers (larger than or equal to 10kg) have valid noise labels? Do Quality Powered Mechanical Equipments (QPME) have valid noise labels? Do air compressors have valid noise labels? Do compressors operate with doors closed? Are Construction Noise Permits available for inspection? Major noise source(s)	Construction activities inside of site	

Construction of Dry Weather Flow Interceptor at Cherry Street Box Culvert Independent Environmental Checker Environmental Site Inspection Checklist



No.	Part V Waste Management and Contamination	N/A N/O Yes Rdr Obs N/C Photos / Remarks
1a	General refuse: Is accumulation avoided?	
1b	Is receptacles (e.g. rubbish bins) available?	
1c	Is there regular and proper disposal?	
2a	Construction waste: Is there avoidance or minimization of construction	
	waste generation (e.g. use of steel formwork)?	/
2b	Is there on site segregation as far as practicable	
	for reuse and recycle?	,
2c	Is construction waste reused where practicable?	
2d	Is construction waste disposed at public dumping	
	area or public landfill?	tion
2e	Are trip tickets available for inspection?	
За	Chemical waste/waste oil: Is there designated storage area?	
3b	Is chemical waste/waste oil stored properly?	Ø.
3c	Is there proper disposal?	
3d	Are trip tickets available for inspection?	Ø.0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
3e	Is chemical waste license available for	
	inspection?	
4a	Excavated material: Does excavated material appear uncontaminated	
	(colour, odour)?	·
4b	If contamination is suspected, is appropriate procedure	
	followed?	
4c	Are trip tickets available for inspection?	g, o o o o o
5a	Chemical/fuel: Is chemical/fuel stored in bunded area?	
5b	Is bund capacity adequate (>110% of the largest tank)?	
5c	Are storage areas provided with locks and located on	
00	sealed area?	W
6	Are relevant license/permit for disposal of construction waste or excavated	
J	materials available for inspection?	
7	Is foam, oil, grease or other objectionable matters in water of nearby drains	
	or sewer avoided?	
	of sover avoided.	
20000		
No.	Part VI Landscape & Visual Impact and Ecology	N/A N/O Yes Rdr Obs N/C
1	Is stripped top soil stored for re-use?	
2	Are retained trees protected from damage?	
3	Are compensatory trees planted and properly maintained?	
4	For trees identified for transplant in EP:	_/
4a	sufficient buffer zone allowed prior to transplant?	
4b	properly maintained following transplant?	
5	Is night-time lighting controlled to minimise glare to sensitive receivers?	ø, o o o o o
6	Is the screen hoarding compatible with the surrounding setting?	0,0000
7	Do the site clearance and tree felling works at the existing ardeid night roost	
	only be carried out at wintering season (November to March inclusive)?	
No.	Part VII Others	N/A N/O Yes, Rdr Obs N/C
1	Is a copy of the relevant permits/licences/registrations displayed	
	on the Project site at all vehicular site entrances/exits or at	
	a convenient location for public information all times?	

Part VIII Follow-up for the Pervious Site Audit

Construction of Dry Weather Flow Interceptor at Cherry Street Box Culvert Independent Environmental Checke **Environmental Site Inspection Checklist**



Part IX

Remarks

Obs I: Following previous inspection, silt cortain has some below sea level which result in contamination water leakage from sete into open sea. Contractor should vectory the issue immediately.

D	·V
Pai	T A

Signatures

IEC's Representative

Engineer's Representative

(Name: Bernard Chan

Contractor's Representative