

Quarterly EM&A Report (February 2022-April 2022)

0185/21/ED/0415 3

Sai O Trunk Sewer Sewage Pumping Station





Ref.: SHKSOSPSEM00_0_0046L.22

25 November 2022

By Fax (2827 0485)

Sun Hung Kai Properties Ltd. 42/F., Sun Hung Kai Centre 30 Harbour Road, Wan Chai, Hong Kong

Attention: Mr. Sunny Cheung

Dear Sir,

Re: Sai O Trunk Sewer Sewage Pumping Station Environmental Permit No. EP-597/2021 Quarterly EM&A Report (February 2022 to April 2022)

Reference is made to the Environmental Team's submission of the Monthly EM&A Report for February 2022 to April 2022 (ET's ref.:0185/21/ED/0415 03) certified by the ET Leader and provided to us via e-mail on 22 November 2022.

We are pleased to inform you that we have no further comments on the captioned submission. We write to verify the captioned submission in accordance with Condition 3.4 of EP-597/2021 and Section 12.1.1.2 of EM&A Manual for the captioned project.

Thank you very much for your attention and please feel free to contact the undersigned should you require further information.

Yours sincerely, For and on behalf of Ramboll Hong Kong Ltd.

Y H Hui Independent Environmental Checker

c.c. AECOM	Ms. Janice Tam / Mr. CK Man	(By Fax: 3894 5801)
Fugro	Mr. Calvin Leung	(By Fax: 2450 6138)
SGJV	Mr. Eddie Tse	(By Fax: 3894 5801)

Q:\Projects\SHKSOSPSEM00\02 Proj_Mgt\02 Corr\SHKSOSPSEM00_0_0046L.22.docx

Ramboll Hong Kong Limited 英環香港有限公司

21/F, BEA Harbour View Centre, 56 Gloucester Road, Wan Chai, Hong Kong Tel: 852.3465 2888 Fax: 852.3465 2899 www.ramboll.com

Document Control

Document Information

Project Title	Sai O Truck Sewer Sewage Pumping Station
Document Title	Quarterly EM&A Report (February 2022- April 2022)
Fugro Project No.	0185/21
Fugro Document No.	0185/21/ED/0415
Issue Number	3
Issue Status	For Verification

Client Information

Client	Light Time Investments Limited
Client Address	42/F, Sun Hung Kei Centre, 30 Harbour, Wan Chai, Hong Kong
Client Contact	Mr. Sunny Cheung

Environmental Team

Initials	Name	Role	Signature
МР	Calvin M.P. Leung	Environmental Team Leader	Cabin Leng
СҮ	Cyrus C.Y. Lai	Senior Environmental Consultant	
wc	Roy W.C. Cheung	Assistant Environmental Consultant	By
MS	Michelle T. Shum	Assistant Environmental Consultant	51.

Executive Summary

- i. This Quarterly Environmental Monitoring and Audit (EM&A) Report is prepared for Sai O Trunk Sewer Sewage Pumping Station. Light Time Investments Limited has appointed Fugro Technical Services Limited (FTS) to undertake the Environmental Team services for the project and implement the EM&A works.
- ii. This is the 1st Quarterly EM&A Report presents the environmental monitoring and audit works for the period between 1st February 2022 and 30th April 2022. The major activities in the reporting period informed by the Contractor are summarized in **Table I**.

	February	March	April
Sai O Pumping Station	 No construction activities were undertaken in the reporting month 	 No construction activities were undertaken in the reporting month 	 No construction activities were undertaken in the reporting month

Table I: Major construction activities undertaken in the reporting period

Breaches of Action and Limit Levels

- iii. No Action Level exceedance was recorded for 1-hr of impact air quality at the site area in the reporting quarter.
- iv. One Limit Level exceedance was recorded for 1-hr TSP at CA_M1(a) on 11 March 2022. The investigation was conducted on 14 March according to the Event-Action Plans. The Limit Level exceedance was considered as non-project related. No exceedance was recorded in the following monitoring conducted on 17 March 2022.
- v. No Action/ Limit Level exceedance was recorded for impact noise monitoring at the site area in the reporting quarter.

Complaint, Notification of Summons and Successful Prosecution

vi. Referring to the Contractor's information, no environmental complaint, notification of summons and successful prosecution was received in the reporting quarter.

Contents

cutive Summary	i
INTRODUCTION	1
SUMMARY OF EM&A REQUIREMENT AND MONITORING RESULTS	4
SITE INSPECTION AND AUDIT	8
NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMONS AND SUCCESSFUL PROSECUTIONS	10
IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURE	11
CONCLUSIONS AND RECOMMENDATIONS	12
	SUMMARY OF EM&A REQUIREMENT AND MONITORING RESULTS SITE INSPECTION AND AUDIT NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMONS AND SUCCESSFUL PROSECUTIONS IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURE

Appendices

Appendix A	Construction Programme
Appendix B	Graphical Presentation of Monitoring Data
Appendix C	Event_and Action Plan
Appendix D	Environmental Mitagation Implementation Schedule
Appendix E	Waste Flow Table
Appendix F	Cumulative Statistics on Environmental Complaints, Notifications of Summons and Successful Prosecutions

List of Figures

Figure 1	Location of the proposed Sai O Trunk Sewer SPS
Figure 2	Air Quality Monitoring Location
Figure 3	Noise Monitoring Location

List of Tables

i
2
2
3
4
4
5
5
6
6
6
6
7
8

1. INTRODUCTION

1.1 Background

- 1.1.1 The proposed Sai O Trunk Sewer Sewage Pumping Station (Sai O Trunk Sewer SPS) is a part of Public Works Programme Item 4125DS - Tolo Harbour Sewerage of Unsewered Areas, Stage II, is a core component of the proposed trunk sewerage system in Ma On Shan along Sai Sha Road. It is required to receive all sewage flows along Sai Sha Road from Kei Ling Ha Lo Wai to Cheung Muk Tau and the adjacent residential development, health care institution and education institutions, and then convey the sewage to Sha Tin Sewage Treatment Works.
- 1.1.2 Based on the latest design, the installed capacity per day of the proposed Sai O Trunk Sewer SPS is about 20,600m³ for coping with the sewerage needs of both existing and future developments. Location of the proposed Sai O Trunk Sewer SPS is shown in **Figure 1**.
- 1.1.3 The proposed Sai O Trunk Sewer SPS include the following main components:
 - Loading/unloading bay
 - Inlet chamber
 - Coarse screen channel
 - Distribution chamber
 - Wet wells
 - Valve chamber
 - Emergency storage tank
 - Deodorizing unit
 - Switch room
 - Transformer room
- 1.1.4 The Project is a designated project under Schedule 2 of the Environmental Impact Assessment Ordinance (EIAO) (Cap. 499) for which Environmental Impact Assessment (EIA) report and Environmental Monitoring and Audit (EM&A) Manual was approved by EPD (Register No.: AEIAR-230/2021) on 4 June 2021. The Environmental Permit (EP) (EP No. EP-597/2021) was issued by EPD on 28 September 2021.
- 1.1.5 Fugro Technical Services Limited (FTS) has been appointed as the Environmental Team (ET) by Light Time Investments Limited to undertake the Environmental Team services for the Project and implement the EM&A works under Sai O Trunk Sewer Sewage Pumping Station (hereinafter referred as "the Project").



1.1.6 This is the First Quarterly EM&A Report prepared by FTS. This report presents a summary of the environmental monitoring and audit works, list of activities and mitigation measures proposed by the ET for the Project in 1st February 2022 to 30th April 2022.

1.2 **Project Organization**

1.2.1 The key personnel contact information for the Project are summarized in **Table 1.1**.

Party	Position	Name	Telephone
Project Proponent (PP) (Light Time Investments Ltd.)	Senior Project Manager	Mr. Sunny Cheung	3894 5934
Engineer's Representative (ER) (AECOM Asia Co. Ltd.)	Senior Resident Engineer	Mr. C.K. Man	3894 5919
Independent Environmental Checker (IEC) (Ramboll Hong Kong Ltd.)	Independent Environmental Checker	Mr. Y.H. Hui	3465 2888
Contractor (Sanfield-Gammon Construction JV Company Ltd.)	Environmental Officer	MS. Carrie Kwan	3894 5816
Environmental Team (ET) (Fugro Technical Services Ltd.)	Environmental Team Leader (ETL)	Mr. Calvin Leung	3565 4441

Table 1.1: Contact Information of Key Personnel

1.3 Construction Programme and Activities

1.3.1 The construction programme of this project is shown in **Appendix A**.

Table 1.2: Major construction activities undertaken in the reporting period table

	February 2022	March 2022	April 2022
Sai O Pumping Station	 No construction activities were undertaken in the reporting month 	 No construction activities were undertaken in the reporting month 	 No construction activities were undertaken in the reporting month

UGRO

1.4 Status of Environmental Licenses, Notifications and Permits

1.4.1 A summary of the relevant environmental licenses, permits and/or notifications on environmental protection for this Contract is presented in **Table 1.3**.

Environmental License / Permit / Notification	Reference Number	Valid From	Valid Till
Environmental Permit	EP-597/2021	28-Sep-2021	NA
Notification of Construction Works under APCO	432718	18-Apr-2018	31-May-2023
Billing Account under Construction Waste Disposal Charging Scheme	7031695	28-Aug-2018	NA
	WT00040139-2021	11-Mar-2022	31-Mar-2027
Effluent Discharge License under WPCO	Application Ref. 477918	Being processed by EPD	NA
Chemical Waste Producer Registration	8334-741-S4115-01	14-Aug-2018	31-Aug-2023

Table 1.3: Relevant Environmental Licenses, Permits and/or Notifications

Notes:

NA=Not Applicable



2. SUMMARY OF EM&A REQUIREMENT AND MONITORING RESULTS

2.1 Monitoring Requirement

- 2.1.1 In accordance with the EM&A Manual, 1-hour Total Suspended Particulates (TSP) levels should be measured at the designated air quality monitoring station to ensure that any deteriorating air quality could be readily detected and timely action shall be undertaken to rectify such situation. Impact 1-hour TSP monitoring was conducted for at least three times every 6 days when the highest dust impact occurs.
- 2.1.2 In accordance with the EM&A Manual, Leq (30min) monitoring is conducted at least once a week when there are Project-related construction activities being undertaken within a radius of 300 m from the monitoring stations. The monitoring is conducted during the construction phase between 0700 and 1900 on normal weekdays at the designated monitoring locations.

2.2 Monitoring Locations

- 2.2.1 In accordance with the approved EM&A Manual, air quality monitoring should be carried out at a designated monitoring location.
- 2.2.2 As limitation of stable electricity supply & safety concern could not be obtained from the designated dust monitoring location, an alternative monitoring location (CA_M1(a)) was proposed to measure 1-hour TSP levels in accordance with EP Condition 3.1 & Section 2.2.1.20 of the EM&A manual. The alternative monitoring location (CA_M1(a)) was approved by EPD on 15 December 2021.
- 2.2.3 The air quality monitoring location is summarized in **Table 2.1** and shown in **Figure 2**.

Monitoring Location ID	Location
CA_M1(a)	Construction Site Boundary near Hong Kong Baptist Theological Seminary (HKBTS) Staff & Students Quarters

- Table 2.1: Summary of Impact Air Quality Monitoring Stations
- 2.2.4 In accordance with the EM&A Manual, noise monitoring should be carried out at 2 designated monitoring locations.
- 2.2.5 The noise monitoring locations are summarized in **Table 2.2** and shown in **Figure 3**.

Monitoring Location IDLocationType of
Measurement*CN_M1In front of the HKBTS Staff & Students QuartersFree FieldCN_M2In front of the HKBTS Administration and Education BlockFaçade

 Table 2.2: Summary of Impact Noise Monitoring Stations

Note: Correction of +3 dB(A) shall be made to the free field measurements.





2.3 Results and Observations

2.3.1 The Action and Limit Levels of air quality monitoring are summarized in **Table 2.3**.

Table 2.5. Action and Emit Lever for impact Air Quarty Monitoring								
Monitoring Station	Limit Level (µg/ m³)							
1-hour TSP								
CA_M1(a)	339	500						

Table 2.3: Action and Limit Level for Impact Air Quality Monitoring

2.3.2 The results of impact 1-hr TSP monitoring in this reporting quarter are summarized in Table2.4. Graphical presentation of the monitoring result in the reporting quarter is given in Appendix B.

Table 2.4: Summary of Impact Air Quality Monitoring Results

Reporting Month	Monitoring Station	Average (μg/m³)	Range (μg/ m³)	Action Level (μg/ m³)	Limit Level (µg/ m³)	
February 2022		158.4	112.3 – 235.6			
March 2022	CA_M1(a)	188.2	93.5 – 965.2	339	500	
April 2022		170.2				

- 2.3.3 The Event and Action Plan for Air Quality is given in **Appendix C**
- 2.3.4 Summary of impact air quality exceedances recorded in the reporting quarter at each impact monitoring station is given in **Table 2.5**. One Limit Level exceedance was recorded for 1-hr TSP at CA_M1(a) on 11 March 2022.

Table 2.5:	Summary	of Impact	Air Quality	Exceedances
------------	---------	-----------	-------------	-------------

Monitoring Station	Exceedance Level	No. of Exceedances
	Action	0
CA_M1(a)	Limit	1
Total	Action	0
Total	Limit	1

2.3.5 Due to the construction site has not officially started, no construction activities were observed next to the monitoring location CA_M1(a). Also, dust generated from vehicles movement was observed along Ning Ming Road. Road traffic emissions at Nin Ming Road and dusty road between Nin Ming Road & Cheung Muk Tak Kite-flying Site was observed. Vehicles had been passing by the air quality monitoring stations and may also generate dust impact. Thus, it is considered that this exceedance was not project related. No exceedance was recorded in the following monitoring conducted on 17 March 2022. Contractor was reminded to take mitigation measures of air quality while construction work is in progress as recommended in approved EIA Report.



2.3.6 The Action and Limit Levels of impact noise monitoring are summarized in **Table 2.6**.

Table 2.6: Action and Limit Levels for Impact Noise Monitoring

Parameter	Frequency
LAeq (30 min) (L10 and L90 will be recorded for reference)	At each station at 0700-1900 hours on normal weekdays at a frequency of once a week when construction activities are underway

2.3.7 The results of impact noise monitoring in this reporting quarter are summarized in **Table 2.7**. Graphical presentation of the monitoring result is given in **Appendix B.**

2.3.8 The Event and Action Plan for Construction Noise is given in **Appendix C**.

Reporting Month	Monitoring Station	Average (μg/m³)	Range (μg/ m³)	Action Level (μg/ m ³)	Limit Level (µg/ m³)
February 2022	CN_M1	68.9 – 69.3	69.1		
February 2022	CN_M2	61.2 – 62.0	61.6	_	70dB(A) during normal
March 2022	CN_M1	54.7 – 61.8	58.2	When one documented	teaching period
March 2022	CN_M2	49.5 – 56.2	52.6	complaint is received	and 65 dB(A) during
A - 1 2022	CN_M1	56.1 – 62.3	60.5	received	examination periods
April 2022	CN_M2	49.8 – 55.8	53.6		P

Table 2.7: Summary of Impact Noise Monitoring Results

2.3.9 Summary of impact noise exceedances recorded in the reporting quarter at each impact monitoring station are presented in **Table 2.8**. No exceedance was recorded during the reporting period.

Table 2.8: Summary of Impact Noise Exceedances

Monitoring Station	Exceedance Level	No. of Exceedance
CN M1	Action	0
CN_M1	Limit	0
	Action	0
CN_M2	Limit	0

2.3.10 Road traffic noise along Ning Ming Road was observed at CN_M1 & CN_M2 during the monitoring month. No effect that arose from the other special phenomena was noted during the current monitoring month.



2.3.11 The noise monitoring data was compared with the EIA predictions as summarized in **Table 2.9.**

Reporting Month	Monitoring Station	EIA ID	Maximum Predicted Mitigated Construction Noise Level L _{eq} (30min) dB(A)	Maximum Construction Noise Level in the Reporting Month
Falaman 2022	CN_M1	N1b	72	69.3
February 2022	CN_M2	N2	66	62.0
March 2022	CN_M1	N1b	72	61.8
March 2022	CN_M2	N2	66	56.2
A	CN_M1	N1b	72	62.3
April 2022	CN_M2	N2	66	55.8

Table 2.9: Comparison of Noise Monitoring Data with EIA Predictions

2.3.12 The construction noise monitoring result at CN_M1 and CN_M2 were below the Maximum Predicted Mitigated Construction Noise Level in the approved Environmental Impact Assessment (EIA) Report (Register No.: AEIAR-230/2021).

3. SITE INSPECTION AND AUDIT

3.1 Site Inspection

- 3.1.1 Site audits were carried out weekly to ensure that appropriate environmental protection and pollution control mitigation measures are properly implemented for the construction works activities associated with the Project.
- 3.1.2 A summary of the mitigation measures implementation schedule is provided in **Appendix D**.
- 3.1.3 In the reporting quarter, weekly site inspections were carried out. No outstanding issues were reported during the reporting quarter.
- 3.1.4 Details of observations recorded during the site inspections are presented in **Table 3.1**.

Parameters	Date	Observations and Recommendations
Air Quality	Not Applicable	No particular observation
Noise	Not Applicable	No particular observation
Water Quality	Not Applicable	No particular observation
Chemical and Waste Management	Not Applicable	No particular observation
Landscape and Visual Impact	Not Applicable	No particular observation
Permit / Licenses	Not Applicable	No particular observation
Others	Not Applicable	No particular observation

Table 3.1: Observations and Recommendations of Site Audit



3.2 Advice on the Solid and Liquid Waste Management Status

- 3.2.1 The Contractor registered as a chemical waste producer for the Contract. Sufficient numbers of receptacles were available for general refuse collection and sorting.
- 3.2.2 The quarterly summary of waste flow table is detailed in **Appendix E**.
- 3.2.3 If off-site disposal is required, the excavated marine mud from the land-based works shall be disposed of at the designated disposal site within Hong Kong as allocated by the Marine Fill Committee or other locations as agreed by the Director. The Contractor shall ensure no spilling and overflowing of materials during loading / unloading / transportation is allowed.
- 3.2.4 The Contractor was reminded that chemical waste should be properly treated and stored temporarily in designated chemical waste storage area on site in accordance with the Code of Practice on the Packing, Labelling and Storage of Chemical Waste.



UGRO

4. NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMONS AND SUCCESSFUL PROSECUTIONS

4.1 Non-compliance (Exceedances of Action & Limit levels)

- 4.1.1 No Action Levels exceedance was recorded for 1-hr TSP at CA_M1(a) in the reporting month.
- 4.1.2 One Limit Level exceedance was recorded for 1-hr TSP at CA_M1(a) on 11 March 2022.
- 4.1.3 The investigation was conducted on 14 March 2022 according to the Event-Action Plans presented in Appendix C. The Limit Level exceedance was considered as non-project related. No exceedance was recorded in the following monitoring conducted on 17 March 2022.
- 4.1.4 No Action / Limit Level exceedance was recorded for construction noise at CN_M1 & CN_M2 in the reporting month.

4.2 Complaints, Notification of Summons and Prosecution

- 4.2.1 No environmental complaint, notification of summons and successful prosecution were received in the reporting quarter.
- 4.2.2 Cumulative complaint log, summaries of complaints, notification of summons and successful prosecutions are presented in **Appendix F**.
- 4.2.3 No corrective actions were required.



5. IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURE

5.1 Implementation Status

5.1.1 The Contractor had implemented environmental mitigation measures and requirements as stated in the EIA Report, the EP and EM&A Manual. **Appendix F** summarized the Implementation Status of Environmental Mitigation Measures.

UGRO

6. CONCLUSIONS AND RECOMMENDATIONS

6.1 Conclusions

- 6.1.1 Air quality impact monitoring were carried out in the reporting quarter. One Limit Level exceedance was recorded. However, investigation indicated the exceedance were not related to the Project works.
- 6.1.2 Noise impact monitoring were carried out in the reporting quarter. No exceedance was recorded.
- 6.1.3 Ten weekly site inspection were carried out in February 2022, March 2022 and April 2022. Recommendations on mitigation measures for Permit/ Licenses were given to the Contractor for remediating the deficiencies identified during the site inspections.
- 6.1.4 Five landscape and visual site audits were carried out in the reporting period.Recommendations on mitigation measures for Permit / Licenses were given to the Contractor for remediating the deficiencies identified during the site inspections.
- 6.1.5 Referring to the Contractor's information, no environmental complaint, notification of summons and successful prosecution was received in the reporting month.

6.2 Comment and Recommendations

- 6.2.1 The recommended environmental mitigation measures, as proposed in the EA report and EM&A Manual shall be effectively implemented to minimize the potential environment impacts from the Project. The EM&A programme would effectively monitor the environmental impacts generated from the construction activities and ensure the proper implementation of mitigation measures.
- 6.2.2 According to the environmental audit performed in the reporting quarter, the following recommendations were made:

Air Quality Impact

• No specific observation was identified in the reporting quarter.

Construction Noise Impact

• No specific observation was identified in the reporting quarter.

Water Quality Impact

• No specific observation was identified in the reporting quarter.

Chemical and Waste Management

• The Contractor is reminded to provide drip tray for the chemical containers.

Landscape and Visual Impact

• No specific observation was identified in the reporting quarter.

Permit / Licenses


• No specific observation was identified in the reporting quarter.

Figure 1

Location of the proposed Sai O Trunk

Sewer SPS







PROJECT

TOLO HARBOUR SEWERAGE OF UNSEWERED AREAS STAGE 2 -INVESTIGATION, DESIGN AND CONSTRUCTION CLIENT




算法 新聞 Drainage Services De

CONSULTANT 工程期間公司

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 分列工和期間公司

ISSUE/REVISION



STATUS

SCALE 比例

DIMENSION UNIT

A1 1 : 1500

METRES

KEY PLAN



60547289

SHEET TITLE

LOCATION OF THE PROPOSED SAI O TRUNK SEWER SEWAGE PUMPING STATION

SHEET NUMBER


60547289/EM&A/FIGURE 1.1

CONTRACT NO.

Figure 2

Air Quality Monitoring Location





SITE BOUNDARY 500m ASSESSMENT AREA South ASSESSMENT AREA
 REPRESENTATIVE AIR
 SENSITIVE RECEIVER
 CA_MIT(a) PROPOSED AIR QUALITY MONITORING
 POINT DURING CONSTRUCTION PHASE



PROJECT

TOLO HARBOUR SEWERAGE OF UNSEWERED AREAS STAGE 2 -INVESTIGATION, DESIGN AND CONSTRUCTION CLIENT




築務署 Drainage Services Department

CONSULTANT

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 分判工程範囲公司

ISSUE/REVISION



STATUS

SCALE

DIMENSION UNIT

A11:2000

METRES

KEY PLAN

PROJECT NO.

CONTRACT NO.

60547289

SHEET TITLE

LOCATIONS OF PROPOSED DUST MOINTORING POINT


SHEET NUMBER

60547289/EM&A/FIGURE 2.1

Figure 3

Noise Monitoring Location

fugro





PROJECT

TOLO HARBOUR SEWERAGE OF UNSEWERED AREAS STAGE 2 -INVESTIGATION, DESIGN AND CONSTRUCTION CLIENT




算法 新考 Drainage Services De

CONSULTANT 工程期間公司

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 分列工程期間公司

ISSUE/REVISION



STATUS

SCALE 比例

DIMENSION UNIT

CONTRACT NO.

A1 1 : 1500

METRE

KEY PLAN #헤르

PROJECT NO.

60547289

SHEET TITLE

LOCATIONS OF PROPOSED NOISE MOINTORING POINT

SHEET NUMBER

60547289/EM&A/FIGURE 3.1

Appendix A

Construction Programme



	Activity	Days	Start	Finish									2022								
					30	06	February 13	20	27	06	March 13	20	27	03	Apri 10	 17	24	01	08	May 15	22
RM1095	Construct Shaft 3A	84	30-Aug-21 A	02-Apr-22	30	00	13	20		00	13	20	21	03	10	17	24	01	00	15	22
	L5m) - Shaft 6 to Shaft 7											+									+
RM1152	Lay twin DN630 pipes	132	02-Dec-21 A	16-Jul-22					; - <mark></mark>			· · · · · · · · · · · · · · · · · · · ·	}		·	¦			÷		<u>+</u>
RM1155	Grouting and testing for twin pipes	33		01-Jun-22													········		······	·	i
	17m) - Shaft 5 to Shaft 4																				
RM1320	Set Up in Shaft 5	24	23-Aug-21 A	28-Feb-22																	
RM1340	Dismantle Jacking Setup	24	-	11-Feb-22 A								+									
RM1350	Lay twin DN630 pipes	33	12-Feb-22 A									· • · · · · · · · · · · · · · · · · · ·	·								
RM1360	Grouting and testing for twin pipes	26		24-May-22					-												÷
	12m) - Shaft 6 to Shaft 5		•	,																	
RM1420	Pipe jacking Shaft 6 to Shaft 5 (1.5m/d)	208	13-Oct-21 A	21-Mar-22					i												
RM1430	Dismantle Jacking Setup	24											;								+
RM1440	Lay twin DN630 pipes, pressure test and grouting	83		-													·······				<u>.</u>
	20m) - Shaft 7 to Ma On Shan (Gravity Sewer by Trench Method)			0																	
RM1290	Gravity sewer M4.01 to M4.15 (363m)	490	25-Oct-21 A	27-May-23					· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·	·				·········				<u>.</u>
	Dutside Green Area with 4 WF (Refer to Detailed Prog)			,																	
WW1110	Waterworks - Work Front 1 (659m)	972	02-Dec-19 A	30-May-23								·i	·								
WW1120	Waterworks - Work Front 2 (960m)		31-Jul-20 A	-					; <mark>-</mark>												
WW1130	Waterworks - Work Front 3 (1240m, 70%)		31-Mar-20 A						j			· · · · · · · · · · · · · · · · · · ·									<u>i</u>
WW1140	Waterworks - Work Front 4 (1600m)		02-Jan-20 A																		
	g Station (Section 4)					1				 		1		1	1	 	1		1	1	+
	ent and Preparation Works																				
SOPS1110	Environmental Permit, Excavation Permit, Tree Fell Permit etc.	0	28-Feb-22*						•												
SOPS1140	Issue Construction Drawings for Structural, ABWF and E&M Works	0		28-Feb-22*					•			+									+
SOPS1155	Order king post and clutch pipe pile materials	68	25-Oct-21 A		· · · · · · · · · · · · · · · · · · ·					, ,											
SOPS1160	Subletting for ELS Works	32	25-Oct-21 A		· · · · · · · · · · · · · · · · · · ·																
SOPS1170	Latest Start Date	0		01-Mar-22*					•			+									+
Main Structure		Ū		of mar fil																	
ELS	-											+									+
SOPS1210	Site Clearance	12	28-Feb-22	12-Mar-22																	+
SOPS1220	Tree Felling	26	28-Feb-22	29-Mar-22								·i									
SOPS1225	Pre-grouting along existing retaining wall of pigging station	12	14-Mar-22																		
		74											·								
	Clutch pipe pile (140 nrs with 2 rigs)	/4	24-IVIdI-22																		

SAI SHA ROAD WIDENING

P. 5 Date 05-Mar-22 SSR - RMCP 67W

THREE MONTHLY ROLLING PROGRAMME AS OF 28/02/2022

Revision	Checked	Appr

C	Activity	Days	Start	Finish	2022																		
						00	March	00	07		Apr	il 17	04	01	00	May	00			-	June 12	10	' <u>ل</u>
RM1350	Lay twin DN630 pipes	33	12-Feb-22 A	10-May-22	27	06	13	20	21	03	10	17	24	01	08	15	22	29	0	5	12	19	26
RM1360	Grouting and testing for twin pipes	26		28-May-22					· · · · · · · · · · ·	++								····					
	.2m) - Shaft 6 to Shaft 5	20	27 Apr 22	20 1010 22					• • • • • • • • • • • • • • • • • • • •														
RM1420	Pipe jacking Shaft 6 to Shaft 5 (1.5m/d)	208	13-Oct-21 A	10 Mar 22 A																			
												<u>.</u>	<u></u>										
RM1430	Dismantle Jacking Setup		21-Mar-22 A	27-Apr-22																			<u></u>
RM1440	Lay twin DN630 pipes, pressure test and grouting	83	10-May-22	17-Aug-22																			
-	0m) - Shaft 7 to Ma On Shan (Gravity Sewer by Trench Method)											. <u>.</u>	<u> </u>				<u></u>				<u></u>	<u></u>	<u> </u>
RM1290	Gravity sewer M4.01 to M4.15 (363m)	490	25-Oct-21 A	12-May-23																			
Waterworks C	Dutside Green Area with 4 WF (Refer to Detailed Prog)																						
WW1110	Waterworks - Work Front 1 (659m)	972	02-Dec-19 A	31-Mar-23																			
WW1120	Waterworks - Work Front 2 (960m)	779	31-Jul-20 A	16-Jul-22			1					ļ	ļ										
WW1130	Waterworks - Work Front 3 (1240m, 70%)	730	31-Mar-20 A	20-Dec-22																			
WW1140	Waterworks - Work Front 4 (1600m)	850	02-Jan-20 A	27-Oct-22								1	1		1				-				
Sai O Pumpin	g Station (Section 4)																						
Commenceme	ent and Preparation Works											[]										
SOPS1110	Environmental Permit, Excavation Permit, Tree Fell Permit etc.	0	19-Apr-22*									•											
SOPS1140	Issue Construction Drawings for Structural, ABWF and E&M Works	0		21-Mar-22 A				•]				
SOPS1155	Order king post and clutch pipe pile materials	68	25-Oct-21 A	20-Apr-22																			
SOPS1160	Subletting for ELS Works	32	25-Oct-21 A	08-Apr-22			· •				1	;											
SOPS1170	Latest Start Date	0		19-Apr-22*						1		•											
Main Structur	e]												-									
ELS							+																
SOPS1210	Site Clearance	12	31-Mar-22	14-Apr-22	11				•	+													
SOPS1220	Tree Felling	26	19-Apr-22	19-May-22	††					+						····							
SOPS1225	Pre-grouting along existing retaining wall of pigging station	12	19-Apr-22	03-May-22						++													
SOPS1220	Clutch pipe pile (140 nrs with 2 rigs)	74	26-Apr-22	25-Jul-22	<u> </u>				· · · · · · · · · · · · ·	+													
JOF 31230	Cidici 1 pipe pire (140 111 3 WICH 2 1183)	/4	20-Api -22	2J-Jul-22			1		:			:	:										<u> </u>

P. 5

Date 02-Apr-22

THREE MONTHLY ROLLING PROGRAMME AS OF 31/03/2022

Revision	Checked	Appr

	Activity	Days	Start	Finish	17	03 1	Apri	17	24	01	08	May 15	22	2022		05	June 12	19
SSR8060	Installation of Noise Barrier Panels at NB17/18	30	13-May-22*	18-Jun-22	-/ 						E	10						
Vest Bound SSR8521	Cubmit DA14 for Diling and DA9 for Lagging M/oll	30	01 Feb 22 A	04 May 22														
SR8522	Submit BA14 for Piling and BA8 for Lagging Wall Excavation	66	01-Feb-22 A 31-May-22	04-May-22 17-Aug-22														
SR8523	Construct wall structure, 174m	116	14-Jul-22	29-Nov-22						-								
ilities Connec	tion																	
/aterworks																		
	Completion of Waterworks (Green Area) except Area 7 to Tin Liu Road	0		29-Jul-22							+							
	is Road to Tin Liu Village er Pile Wall SPW3 Zone 1			-														
LR2210	Construct Soidier Pile at Zone 1 (51 nos)	174	13-Sep-21 A	27-Apr-22 A	۰										·····			
LR2215	Prepare Document for BA14 Submission	24	30-Apr-22	28-May-22										•				
R2220	Submit BA14 for Soldier Pile and BA8 for Excavation	36	31-May-22	13-Jul-22]							
R2230	Construct mass concrete fill	24	23-Jul-22	19-Aug-22														
ge 3 - Roady		60	42.84- 22	22 1 1 22											<u> </u>			
	Utility diversion to vacate area for mass concrete fill	60	12-May-22	22-Jul-22														
	(Section 2 of the Works) Tau Road (R400: Ch100-250)										1							
t Bound																		
R1020	Drainage (carrier), 10m	13	20-Apr-22 A	29-Apr-22 A	4	1				1	j							
1030	Site formation work	24	29-Apr-22 A									•						
.060	Roadworks	24	30-Apr-22	28-May-22										•				
620	Implement TTM	0		30-May-22						.				•				
ies Works R1070	CATV-150m,CMHK-150m,HGC-150m,HKBN-100m,HKT-150m,SMT-75m,TGT-30m,VTL-30n	39	30-Apr-22	16-Jun-22							<u> </u>							
bound	CALA-T2011/CANILK-T2011/LIGC-T2011/LIKEIA-T0011/LIKE-T2011/2011/2011/2011/101-2011/01-2011	39	50-Api-22	10-Juli-22											·····			
455	Pile testing	26	02-Jun-22	05-Jul-22														
520	RW 6B1-6B15, 2WF	106	14-Jul-22	18-Nov-22							+							
3 - Outsta	anding Works at Tseng Tau Road																	
	ks for Watermain lead-in, Drainage and Rising Mains																	
0	Obtain TTM Approval for Waterwork & New Drainage Pipes	0	45.4	30-Mar-22											<u> </u>			<u></u>
30 Tau Pumr	Drainage & Waterworks near Site C	90	15-Apr-22 A	11-Aug-22														
ining Stru	ing Station																	
	Underground drainage, rising main connection	87	22-Nov-21 A	23-Apr-22 A	۰						+							
L090	Construct super structure of pumping room	47	30-Apr-22	25-Jun-22														
.091	Construct super structure of deodorization room	42	27-Jun-22	15-Aug-22														
093	Construct transformer room	57	20-Jun-22	25-Aug-22							ļ							
	Green Area (Section 3 of the Works)				.													
	for DN1800 Rising Main m) - Shaft 3 to Shaft 4																	
1093	Lay twin DN630 pipes, pressure test and grouting to Shaft 4 (454m)	126	15-Mar-22 A	15-Jul-22							. <u></u>		·	······		i		
1095	Construct Shaft 3A	84	30-Aug-21 A															
ion 2 (615r	n) - Shaft 6 to Shaft 7																	
1152	Lay twin DN630 pipes	132	02-Dec-21 A	-														
1155	Grouting and testing for twin pipes	33	30-Apr-22	09-Jun-22														
on 3 (147r 1320	n) - Shaft 5 to Shaft 4 Set Up in Shaft 5	24	22 Aug 21 A	20 Apr 22											·····			
L320 L350	Lay twin DN630 pipes	33	23-Aug-21 A 12-Feb-22 A															
1360	Grouting and testing for twin pipes	26	30-Apr-22	31-May-22														
on 4 (312r	n) - Shaft 6 to Shaft 5	1																
1430	Dismantle Jacking Setup	24	21-Mar-22 A	26-Apr-22 A	4						<u> </u>							
1440	Lay twin DN630 pipes, pressure test and grouting	83	01-Jun-22	08-Sep-22							ļ							
	n) - Shaft 7 to Ma On Shan (Gravity Sewer by Trench Method)	400									<u> </u>							
11290	Gravity sewer M4.01 to M4.15 (363m)	490	25-Oct-21 A	26-Apr-23														
/1110	tside Green Area with 4 WF (Refer to Detailed Prog) Waterworks - Work Front 1 (659m)	972	02-Dec-19 A	12-Apr-23						-								¦
/1120	Waterworks - Work Front 2 (960m)	779	31-Jul-20 A	11-Aug-22														
/1130	Waterworks - Work Front 3 (1240m, 70%)	730	31-Mar-20 A	-										- <u>+</u>				
1140	Waterworks - Work Front 4 (1600m)	850	02-Jan-20 A			· · · · · · · · · · · · · · · · · · ·			1		1	1						1
	Station (Section 4)																	
mencemen	t and Preparation Works																	
				S	ΔI	SHA ROAD W		NING								P. 4	Dat	
				0	7 11												05-May-	-22
					_				–		-							+
		THF	REE MOI	NTHLY	R	OLLING PROG	iRA	MME A	S OF 3	80/04/202	22							\longrightarrow
														S	SR - I	RMCP 69V	/	
																	1	

19	26		03	Jul 10	у	17		4	3
13	20		00	10		. /			5
									ļ
									ļ
								•	-
									-
									ļ
						<u></u>			
									-
									-
									-
									-
									-
				, 					
									-
									[]
									-
									[]
									į.,
									ļ.
			Devicie				 	A	
			Revision		-+	Chec	ked	Appr.	•
		_							_

ID	Activity	Days	Start	Finish	sh 2022																	
						April					May				June				Jul	/	ľ	
					27	03	10	17	24	01	08	15	22	29	05	12	19	26	03	10	17	24 31
SOPS1110	Environmental Permit, Excavation Permit, Tree Fell Permit etc.	0	03-May-22*							•												
SOPS1155	Order king post and clutch pipe pile materials	68	25-Oct-21 A	31-Mar-22 A			-															
SOPS1160	Subletting for ELS Works	32	25-Oct-21 A	31-Mar-22 A																		
SOPS1170	Latest Start Date	0		03-May-22*						•												
Main Structu	re]															
ELS							}				}											
SOPS1210	Site Clearance	12	03-May-22	16-May-22							1	-										
SOPS1220	Tree Felling	26	03-May-22	01-Jun-22							;											
SOPS1225	Pre-grouting along existing retaining wall of pigging station	12	17-May-22	30-May-22										-								
SOPS1230	Clutch pipe pile (140 nrs with 2 rigs)	74	17-May-22	12-Aug-22			}]											
					· · · · · · · · ·							•	·				·					

SAI SHA ROAD WIDENING P. 5	Date	
SAI SHA ROAD WIDENING	05-May-22	
THREE MONTHLY ROLLING PROGRAMME AS OF 30/04/2022		
SSR - RMCP 69W		

Revision	Checked	Appr


Appendix B

Graphical Presentation of

UGRO

Monitoring Data

Air Quality Monitoring Results





1-hr TSP Monitoring Graph



Noise Monitoring Results

Noise Monitoring Graph







Appendix C

Event and Action Plan



Event and Action Plan for Air Quality (Construction Dust)

		ACTIO	N	
EVENT	ET	IEC	ER	Contractor
vo being exceeded by one sampling	 Identify source, investigate the causes of complaint and propose remedial measures; Inform Contractor, IEC and ER; Repeat measurement to confirm finding; and Increase monitoring frequency to daily. 	 Check monitoring data submitted by ET; Check Contractor's working method; and Review and advise the ET and ER on the effectiveness of the proposed remedial measures. 	1. Notify Contractor.	 Identify source(s), investigate the causes of exceedance and propose remedial measures; Implement remedial measures; and Amend working methods agreed with the ER as appropriate.
Action level being exceeded by two or more consecutive sampling	 Identify source; Inform Contractor, IEC and ER; Advise the Contractor and ER on the effectiveness of the proposed remedial measures; Repeat measurements to confirm findings; Increase monitoring frequency to daily; Discuss with IEC and Contractor on remedial actions required; If exceedance continues, arrange meeting with Contractor, IEC and ER; and If exceedance stops, cease additional monitoring. 	 Check monitoring data submitted by ET; Check Contractor's working method; Discuss with ET, ER and Contractor on possible remedial measures; Advise the ET and ER on the effectiveness of the proposed remedial measures; and Supervise Implementation of remedial measures. 	 Confirm receipt of notification of exceedance in writing; Notify Contractor; Ensure remedial measures properly implemented. 	 Identify source and investigate the causes of exceedance; Submit proposals for remedial measures to the ER with a copy to ET and IEC within three working days of notification; Implement the agreed proposals; and Amend proposal as appropriate.
Limit level being exceeded by one sampling	 Identify source, investigate the causes of exceedance and propose remedial measures; Inform Contractor, IEC, ER, and EPD; Repeat measurement to confirm finding; Increase monitoring frequency to daily; and Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results. 	 Check monitoring data submitted by ET; Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ER on the effectiveness of the proposed remedial measures; and Supervise implementation of remedial measures. 	 Confirm receipt of notification of exceedance in writing; Notify Contractor; Ensure remedial measures properly implemented. 	 Identify source(s) and investigate the causes of exceedance; Take immediate action to avoid further exceedance; Submit proposals for remedial measures to ER with a copy to ET and IEC within three working days of notification; Implement the agreed proposals; and Amend proposal if appropriate.
Limit level being exceeded by two or more consecutive sampling	 Notify IEC, ER, Contractor and EPD; Identify source; Repeat measurement to confirm findings; Increase monitoring frequency to daily; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Arrange meeting with IEC and ER to discuss the remedial actions to be taken; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; and If exceedance stops, cease additional monitoring. 	 Check monitoring data submitted by the ET; Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; and Supervise the implementation of remedial measures. 	 Confirm receipt of notification of exceedance in writing; In consultation with the ET and IEC, agree with the Contractor on the remedial measures to be implemented; Supervise the implementation of remedial measures; and If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated. 	 Identify source(s) and investigate the causes of exceedance; Take immediate action to avoid further exceedance; Submit proposals for remedial measures to the ER with a copy to the IEC and ET within three working days of notification; Implement the agreed proposals; Revise and resubmit proposals if problem still not under control; and Stop the relevant portion of works as determined by the ER until the exceedance is abated.



Event and Action Plan for Noise (Construction Noise)

EVENT		ACTION								
EVENT	ET	IEC	ER	Contractor						
Action Level	 Notify IEC and Contractor; Carry out investigation; Report the results of investigation to the IEC, ER and Contractor; Discuss with the Contractor and formulate remedial measures; and Increase monitoring frequency to check mitigation effectiveness. 	 Review the analyzed results submitted by the ET; Review the proposed remedial measures by the Contractor and advise the ER accordingly; and Supervise the implementation of remedial measures. 	 Confirm receipt of notification of failure in writing; Notify Contractor; Require Contractor to propose remedial measures for the analyzed noise problem; and Ensure remedial measures are properly implemented. 	 Submit noise mitigation proposals to IEC; and Implement noise mitigation proposals. 						
Limit Level	 Identify source; Inform IEC, ER, EPD and Contractor; Repeat measurements to confirm findings; Increase monitoring frequency; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Inform IEC, ER and EPD the causes and actions taken for the exceedances; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; and If exceedance stops, cease additional monitoring. 	 Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractors remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; and Supervise the implementation of remedial measures. 	 Confirm receipt of notification of failure in writing; Notify Contractor; Require Contractor to propose remedial measures for the analyzed noise problem; Ensure remedial measures properly implemented; and If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated. 	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Resubmit proposals if problem still not under control; and Stop the relevant portion of works as determined by the ER until the exceedance is abated. 						

-fugro

Appendix D

Environmental Mitigation

Implementation Schedule



Implementation Status of Environmental Mitigation Measures (Construction Phase)

EIA	Environmental Protection Measures (Construction Phase) ⁽¹⁾	Location &	Implementation
Ref. (No.)	A) Air Quality	(Implementation Agent)	Status
3.7.1.1 (A1)	Sufficient dust suppression measures as stipulated under the Air Pollution Control (Construction Dust) Regulation (Cap. 311R), as well as good site practices and good housekeeping of the site should be properly implemented in order to minimise the construction dust generated. These measures include the followings::		
(A1)	a) Use of regular watering to reduce dust emissions from exposed site surfaces and unpaved roads, particularly during dry weather;		N/A
	 b) Use of frequent watering for particularly dusty construction areas and areas close to ASRs; 		N/A
	c) Use of frequent watering or water sprinklers for major haul roads, material stockpiling areas and other dusty activities within the construction site;		N/A
	d) Side enclosure and covering of any aggregate or dusty material storage piles to reduce emissions. Where this is not practicable owing to frequent usage, watering should be applied to aggregate fines;	All construction sites / construction phase / upon	N/A
	e) Provide hoarding of not less than 2.4 m high from ground level along the site boundary except for site entrance or exit;	completion of all	N/A
	f) Open temporary stockpiles should be avoided or covered. Prevent placing dusty material storage piles near ASRs;	construction activities	N/A
	g) Tarpaulin covering of all dusty vehicle loads transported to, from and between site locations;	(Contractor)	N/A
	h) Establishment and use of vehicle wheel and body washing facilities at the exit points of the site;		N/A
	i) Imposition of speed controls for vehicles on unpaved site roads, 8 km/hr is the recommended limit;		N/A
	j) Routing of vehicles and position of construction plant should be at the maximum possible distance from ASRs;		N/A
	k) Avoid position of material stockpiling areas, major haul roads and dusty works within the construction site close to concerned ASRs; and		N/A
	1) Avoid unnecessary exposed earth.		N/A
3.7.1.2 (A2)	Guidelines stipulated in EPD's <i>Recommended Pollution Control Clauses for Construction Contracts</i> should be incorporated in the contract documents to abate dust impacts. The clauses include:	<i>l</i> All construction sites /	
	a) The contractor shall observe and comply with the Air Pollution Control Ordinance and its subsidiary regulations, particularly the Air Pollution Control (Construction Dust) Regulation.		N/A
	b) The contractor shall undertake at all times to prevent dust nuisance as a result of the construction activities.	construction phase / upon	N/A
	c) The contractor shall ensure that there will be adequate water supply / storage for dust suppression.	completion of all construction activities	N/A
	d) The contractor shall devise, arrange methods of working and carrying out the works in such a manner so as to minimise dust impacts on the surrounding environment, and shall provide experienced personnel with suitable training to ensure that these methods are implemented.	construction activities (Contractor)	N/A
	e) Before the commencement of any work, the contractor may require to submit the methods of working, plant, equipment and air pollution control system to be used on the site for the engineer inspection and approval.		N/A
3.4.1.4	Control on fuel combustion from the use of PMEs	All construction sites /	
(A3)	a) Legal control on the types of fuel allowed for use and their sulphur contents in commercial and industrial processes should be observed.	construction phase / upon	N/A
	b) Only approved or exempted non-road mobile machinery should be allowed to be used in construction sites.	completion of all	N/A
	c) All construction plants are required to use ultra-low-sulphur diesel (ULSD) (defined as diesel fuel containing not more than 0.005% sulphur by weight).	construction activities (Contractor)	N/A

Note:

(1) Detailed EIA report and EM&A Manual reference refer to the Appendix B of approved EM&A Manual.

N/A: Not Available, N/O: Not Observed.

Tugro

EIA Ref. (No.)	Environmental Protection Measures (Construction Phase) ⁽¹⁾ B) Noise	Location & (Implementation Agent)	Implementation Status
4.8.1.2 (B1)	Good Site Practice The site practices listed below should be followed during construction works: a) Only well-maintained PME to be operated on site and should be serviced regularly during construction; b) Silencers or mufflers on construction equipment should be utilised (if appropriate) and should be properly maintained during the construction; c) Mobile plant, if any, should be sited as far away from NSRs as possible; d) Machines and plant (such as trucks) that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum; e) Plant known to emit noise strongly in one direction should, wherever possible, be orientated to direct noise away from the nearby NSRs; and f) Material stockpiles and other structures should be effectively utilised, wherever practicable, in screening noise from on-site construction activities	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A N/A N/A N/A N/A N/A
4.8.1.3 – 4.8.1.4 & Table 7 (B2)	Use of Quiet PME The Contractors may adopt alternative quiet PME as long as it can be demonstrated that they would not result in construction noise impacts worse than those predicted in this EIA Report. Use of quiet plant should be made reference to the Powered Mechanical Equipment (PME) listed in the Technical Memorandum or the Quality Powered Mechanical Equipment (QPME) / other commonly used PME listed in Environmental Protection Department (EPD) web pages as far as possible which includes the Sound Power Level (SWLs) for specific quiet PME.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
4.8.1.5 (B3)	Use of Movable Noise Barriers/Acoustic Mats Movable noise barriers that can be placed close to the construction equipment and moved along with the PME are effective for screening noise from NSRs. A typical design which has been used locally is a wooden framed barrier with a cantilevered upper portion of superficial density no less than 10 kg/m ² on a skid footing with internal sound absorptive lining. This measure is particularly effective for low level zone of NSRs. A longer cantilevered top cover would be required to achieve screening benefits at upper floors of NSRs. The Contractor shall be responsible for the design and actual position of the movable noise barriers with due consideration given to the position and size of the PME, and the requirement of intercepting the line-of-sight from the NSRs to the PME, as well as ensuring that the barriers should have no opening and gap. It is anticipated that properly designed noise barriers would achieve a 5 dB(A) reduction for mobile PME and a 10 dB(A) reduction for static PME. Acoustic mat with surface mass of not less than 7kg/m2 would be used for plant items such as piling, oscillator and a 10 dB(A) noise reduction is anticipated.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
4.8.1.7	Scheduling of Noisy Activities to outside Examination Period of HKBTS	All construction sites /	
(B4)	To minimise the construction noise impact on HKBTS, the use of piling (oscillator) in ELS and concurrent use of concrete lorry mixer with other PMEs in steel fixing and concreting of structure should be avoided during the examination period of HKBTS.	construction phase / upon completion of all	N/A
	Contractor should keep close communication with the operator of HKBTS to obtain the updated schedule of examination at the time conducting of the relevant construction works.	construction activities (Contractor)	N/A

fugro

Implementation Status of Environmental Mitigation Measures (Construction Phase)

Note:

(1) Detailed EIA report and EM&A Manual reference refer to the Appendix B of approved EM&A Manual.

N/A: Not Available, N/O: Not Observed.

Implementation Status of Environmental Mitigation Measures (Construction Phase)

EIA Ref.	Environmental Protection Measures (Construction Phase) ⁽¹⁾	Location & (Implementation	Implementation Status
(No.)	C) Water Quality	Agent)	Status
5.8.1.1 (C1)	Construction Site Runoff Proper site management measures should be implemented to control site runoff and drainage, and thereby prevent high sediment loadings from entering nearby watercourses. The contractor should follow the practices, and be responsible for the design, construction, operation and maintenance of all the mitigation measures as specified in ProPECC PN 1/94 " <i>Construction Site Drainage</i> ". The design of the mitigation measures should be submitted by the contractor to the engineer for approval.		
	These mitigation measures should include the following practices:		
	a) At the start of site establishment, perimeter cut-off drains to direct off-site water around the site should be constructed with internal drainage works and erosion and sedimentation control facilities implemented. Channels (both temporary and permanent drainage pipes and culverts), earth bunds or sand bag barriers should be provided on site to direct storm water to silt removal facilities.		N/A
	b) Sand / silt removal facilities such as sand / silt traps and sediment basins should be provided to remove sand / silt particles from runoff to meet the requirements of the TM standard under the WPCO. The design of efficient silt removal facilities should be based on the guidelines in Appendix A1 of ProPECC PN 1/94, which states that the retention time for silt / sand traps should be 5 minutes under maximum flow conditions.	All construction sites /	N/A
	 c) All drainage facilities and erosion and sediment control structures should always be regularly inspected and maintained to ensure proper and efficient operation and particularly during rainstorms. Deposited silt and grit should be regularly removed, at the onset of and after each rainstorm to ensure that these facilities are functioning properly at all times. 	construction phase / upon completion of all construction activities	N/A
	 d) Measures should be taken to minimise the ingress of site drainage into excavations. Water pumped out from foundation excavations should be discharged into storm drains via silt removal facilities. 	(Contractor)	N/A
	e) If surface excavation works cannot be avoided during the wet season (April to October), temporarily exposed slope / soil surfaces should be covered by a tarpaulin or other means, as far as practicable, and temporary access roads should be protected by crushed stone or gravel, as excavation proceeds. Interception channels should be provided (e.g. along the crest / edge of the excavation) to prevent storm runoff from washing across exposed soil surfaces. Arrangements should always be in place to ensure that adequate surface protection measures can be safely carried out well before the arrival of a rainstorm. Other measures that need to be implemented before, during and after rainstorms are summarised in ProPECC PN 1/94.		N/A
	f) All vehicles and plant should be cleaned before leaving a construction site. An adequately designed and sited wheel washing facility should be provided at every construction site exit where practicable. Wash-water should have sand and silt settled out and removed at least on a weekly basis. The section of access road leading to, and exiting from, the wheel-wash bay to the public road should be paved with sufficient backfall toward the wheel-wash bay to prevent vehicle tracking of soil and silty water to public roads and drains.		N/A
	g) Open stockpiles of construction materials or construction wastes on-site should be covered with tarpaulin or similar fabric during rainstorms.		N/A
5.8.1.2 – 5.8.1.3	<u>General Construction Activities</u> a) Debris and refuse generated on-site should be collected, handled and disposed of properly to avoid entering any nearby water bodies and public drainage		N/A
(C2)	system. b) Stockpiles of cement and other construction materials should be kept covered when not being used.	All construction sites /	NI/A
		construction phase /	N/A
	c) Oils and fuels should only be used and stored in designated areas, which have pollution prevention facilities.	upon completion of all construction activities	N/A
	d) All fuel tanks and storage areas should be provided with locks and be sited on sealed areas, within bunds of a capacity equal to 110% of the storage capacity of the largest tank. Rainwater in the bunds should be cleared after each rain event. Waste oils, fuels and solvents collected within the bund should be handled and treated as chemical waste.	(Contractor)	N/A
5.8.1.4	Sewage Effluent	All construction sites /	
(C3)	Temporary sanitary facilities, such as portable chemical toilets, should be employed on-site where necessary to handle sewage from the workforce. A licensed contractor would be responsible for appropriate disposal of waste matter and maintenance of these facilities.	construction phase / upon completion of all construction activities (Contractor)	N/A



Sai O Trunk Sewer Sewage Pumping Station

EIA Ref. (No.)	Environmental Protection Measures (Construction Phase) ⁽¹⁾ C) Water Ouality	Location & (Implementation Agent)	Implementation Status
5.8.1.5 (C4)	Construction Works in Close Proximity of Inland Waters The practices outlined in ETWB TC (Works) No. 5/2005 "Protection of natural streams/rivers from adverse impacts arising from construction works" should be adopted where applicable to minimise the water quality impacts upon any natural streams or surface water systems.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
Note:		(Contractor)	<u> </u>

(1) Detailed EIA report and EM&A Manual reference refer to the Appendix B of approved EM&A Manual. N/A: Not Available, N/O: Not Observed.



EIA	Environmental Protection Measures (Construction Phase) ⁽¹⁾	Location &	T1
Ref. (No.)	D) Waste Management	(Implementation Agent)	Implementation Status
6.5.1.3	Good Site Practices		
(D1)	Recommendations for good site practices during the construction phase include:		
	a) Nomination of approved personnel, such as a site manager, to be responsible for implementation of good site practices, arrangements for waste collection and effective disposal to an appropriate facility;		N/A
	 b) Training of site personnel in site cleanliness, concepts of waste reduction, reuse and recycling, proper waste management and chemical waste handling procedures; 	All construction sites / construction phase /	N/A
	c) Provision of sufficient waste reception / disposal points, and regular collection of waste;	upon completion of all	N/A
	 d) Adoption of appropriate measures to minimise windblown litter and dust during transportation of waste by either covering trucks or by transporting wastes in enclosed containers; 	construction activities (Contractor)	N/A
	 e) Provision of regular cleaning and maintenance programme for drainage systems, sumps and oil interceptors; 		N/A
	f) Adoption of a recording system for the amount of wastes generated, recycled and disposed (including the disposal sites); and		N/A
	g) Preparation of Waste Management Plan (WMP), as part of the Environmental Management Plan (EMP).		N/A
6.5.1.4	Waste Reduction Measures		1011
(D2)	Recommendations to achieve waste reduction are discussed as follow:	All construction sites /	
	a) Segregate and store different types of construction related waste in different containers, skips or stockpiles to enhance reuse or recycling of materials and their proper disposal:		N/A
	 b) Provide separate labelled bins to segregate recyclable waste such as aluminium cans from other general refuse generated by the work force, and to encourage collection by individual collectors; 	construction phase / upon completion of all	N/A
	c) Recycle any unused chemicals or those with remaining functional capacity;	construction activities (Contractor)	N/A
	d) Maximise the use of reusable steel formwork to reduce the amount of C&D materials;		N/A
	e) Adopt proper storage and site practices to minimise the potential for damage to, or contamination of construction materials;		N/A
	f) Plan the delivery and stock of construction materials carefully to minimise the amount of waste generated; and		N/A
	g) Minimise over ordering and wastage through careful planning during purchasing of construction materials.		N/A
6.5.1.6– 6.5.1.7	Reducing and Reuse of C&D Materials		
(D3)	a) Careful design, planning together with good site management can reduce over-ordering and generation of C&D materials such as concrete, mortar and cement grouts. Formwork should be designed to minimise the use of standard wooden panels, so that high reuse levels can be achieved. Alternatives such as steel formwork or plastic facing should be considered to increase the potential for reuse.	All construction sites / construction phase /	N/A
	b) To minimise off-site disposal of inert C&D material, the excavated inert materials with suitable characteristics / size should be reused on-site as fill material as far as practicable, such as for backfilling of the box culvert and drainage pipe works.	upon completion of all construction activities (Contractor)	N/A
	c) Prior to disposal of non-inert C&D materials, wood, steel and other metals should also be separated for reuse and / or recycle where practicable so as to minimise the quantity of waste to be disposed of to landfill.		N/A
6.5.1.8 (D4)	Storage of C&D Materials Suitable areas should be designated within the works site boundaries for temporary stockpiling of C&D material. Within stockpile areas, the following measures should be taken to control potential environmental impacts or nuisance:	All construction sites / construction phase /	
	a) cover material during heavy rainfall;	upon completion of all construction activities	N/A
	b) locate stockpiles to minimise potential visual impacts; and	(Contractor)	N/A
	c) minimise land intake of stockpile areas as far as possible.		N/A



Sai O Trunk Sewer Sewage Pumping Station

EIA Ref. (No.)	Environmental Protection Measures (Construction Phase) ⁽¹⁾ D) Waste Management	Location & (Implementation Agent)	Implementation Status
6.5.1.9	Disposal of C&D Materials	All construction sites /	
(D5)	a) In order to monitor the disposal of C&D materials at the designated public fill reception facility and landfill and to control fly-tipping, a trip-ticket system should be included.	construction phase /	N/A
	b) When disposing inert C&D materials at a public filling reception facility, the material shall only consist of soil, rock, concrete, brick, cement plaster / mortar, inert building debris, aggregates and asphalt. The material shall be free from marine mud, household refuse, plastic, metals, industrial and chemical waste, animal and vegetable matter, and other material considered to be unsuitable by the Filling Supervisor.	Ided. construction phase / g inert C&D materials at a public filling reception facility, the material shall only consist of soil, rock, concrete, brick, cement plaster / mortar, lebris, aggregates and asphalt. The material shall be free from marine mud, household refuse, plastic, metals, industrial and chemical waster, and other material considered to be unsuitable by the Filling Supervisor. upon completion of all construction activities (Contractor) stet is produced at the construction site / the SPS, the contractor would be required to register with the EPD as a Chemical Waste Producer. construction and incompatible chemicals should be stored separately. bels should be securely attached on each chemical waste container indicating the corresponding chemical characteristics of the chemical waster, shall use a licensed collector to transport and dispose of the chemical wastes at the CWTC or other licensed facility in accordance with the Construction phase / upon completion of all construction of all construction activities (Contractor)	N/A
6.5.1.10	Chemical Wastes		
&	a) If chemical waste is produced at the construction site / the SPS, the contractor would be required to register with the EPD as a Chemical Waste Producer.		N/A
6.5.1.12 (D6)	b) Good quality containers compatible with the chemical wastes should be used, and incompatible chemicals should be stored separately.		N/A
	c) Appropriate labels should be securely attached on each chemical waste container indicating the corresponding chemical characteristics of the chemical waste, such as explosives, flammable, oxidizing, irritant, toxic, harmful, corrosive, etc.		N/A
	d) The contractor shall use a licensed collector to transport and dispose of the chemical wastes at the CWTC or other licensed facility in accordance with the Waste Disposal (Chemical Waste) (General) Regulation.		N/A
6.5.1.11	General Refuse		
& Table	a) General refuse should be stored in enclosed bins or compaction units separate from C&D materials and chemical wastes.		N/A
6.2 (D7)	b) A reputable waste collector should be employed by the contractor to remove general refuse / screenings from the site on a regular basis to minimise odour, pest and litter impacts.		N/A
	c) Clearly labelled recycling bins should be provided on site to encourage segregation and recycling of aluminium and plastic wastes, and wastepaper to reduce general refuse production.	construction phase / upon completion of all construction activities	N/A
	d) The contractor should carry out an education programme for workers in avoiding, reducing, reusing and recycling of materials generation. Posters and leaflets advising on the use of the bins should also be provided in the site as reminders. The recyclable waste materials should then be collected by reliable waste recycling agents on a regular basis.	(Contractor)	N/A
	e) The collected general refuse will be disposed of at NENT landfill.		N/A

-fugro

Note:

(1) Detailed EIA report and EM&A Manual reference refer to the Appendix B of approved EM&A Manual.

N/A: Not Available, N/O: Not Observed.

EIA Ref. (No.)	Environmental Protection Measures (Construction Phase) ⁽¹⁾ E) Landscape and Visual	Location & (Implementation Agent)	Implementation Status
Table 10.9 (E1)	<u>CM1 – Preservation of Trees</u> Trees to be retained in accordance with DEVB TCW No. 4/2020 - Tree Preservation.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
Table 10.9 (E2)	CM2 - Compensatory Tree Planting Any trees to be felled under the Project shall be compensated in accordance with DEVB TCW No. 4/2020 - Tree Preservation.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
Table 10.9 (E3)	<u>CM3 - Control of Night-time Lighting Glare</u> Any lighting provision of the construction works at night shall be carefully controlled to prevent light overspill to the nearby VSRs and into the sky.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
Table 10.9 (E4)	<u>CM4 – Erection of Decorative Screen Hoarding</u> Decorative Hoarding, which is compatible with the surrounding settings, shall be erected during construction to minimise the potential landscape and visual impacts due to the construction works and activities.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
Table 10.9 (E5)	CM5 – Management of Construction Activities and Facilities The facilities and activities at works sites and areas, which include site office, temporary storage areas, temporary works etc., shall be carefully managed and controlled on the height, deposition and arrangement to minimise any potential adverse landscape and visual impacts.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A
Table 10.9 (E6)	<u>CM6 – Reinstatement of Temporarily Disturbed Landscape Areas</u> All hard and soft landscape areas disturbed temporarily during construction due to temporary excavations, temporary works sites and works areas shall be reinstated to equal or better quality, to the satisfaction of the relevant Government Departments.	All construction sites / construction phase / upon completion of all construction activities (Contractor)	N/A

TUGRO

Implementation Status of Environmental Mitigation Measures (Construction Phase)

Note:

(1) Detailed EIA report and EM&A Manual reference refer to the Appendix B of approved EM&A Manual. N/A: Not Available, N/O: Not Observed

Appendix E

Waste Flow Table



Waste Flow Table (April 2022)

		Actual Quantities of Inert C&D Materials Generated Monthly				Actual Quantities of Non-inert C&D Wastes Generated Monthly					
Monthly Ending	Total Quantity Generated	Hard Rock and Large Broken Concrete	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see Note 2)	Chemical Waste	Others, e.g. general refuse
	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)	(in tonnes)
2022 Feb	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
2022 Mar	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
2022 Apr	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
2022 May											
2022 Jun											
2022 Jul											
2022 Aug											
2022 Sep											
2022 Oct											
2022 Nov											
2022 Dec											
Total	0	0	0	0	0	0	0	0	0	0	0

fugro

Note:

1) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.

2) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging materials.

Appendix F

Cumulative Statistics on Environmental Complaints, Notifications of Summons and Successful Prosecutions

Environmental Complaints Log

	Reference No.	Date of Complaint Received	Received From	Received By	Nature of Complaint	Date of Investigation	Outcome	Date of Reply

Cumulative Statistics on Complaints

Environmental Aspects	Cumulative No. Brought Forward	No. of Complaints This Month	Cumulative Project-to- Date
Air	0	0	0
Noise	0	0	0
Water	0	0	0
Waste	0	0	0
Total	0	0	0

Cumulative Statistics on Notification of Summons and Successful Prosecutions

Environmental Aspects	Cumulative No. Brought Forward	No. of Notification of Summons and Prosecutions This Month	Cumulative Project-to- Date
Air	0	0	0
Noise	0	0	0
Water	0	0	0
Waste	0	0	0
Total	0	0	0

