

# VW-VES

VW-VES (HK) Limited

Our Ref: HKSTF-VWVE-EPD-EIA-LE-160808-003

8 August 2016

The EIA Ordinance Register Office  
Environmental Protection Department  
27/F Southorn Centre  
130 Hennessy Road  
Wan Chai, Hong Kong

(By hand)

Attn: Mr Alex Tang

Dear Sir


**Contract No. EP/SP/58/08 – Sludge Treatment Facilities  
Environmental Monitoring Results in Operation Phase – Odour Patrol (July 2016)**

In accordance with the Clause 2.3.2.6 of the EM&A Manual and would like to submit herewith three hard copies and one electronic copy of the captioned subject for your information and record.

Should you have any queries, please do not hesitate to contact our Mr WB Chu on 2910 9666.

Thank you for your kind attention.

Yours faithfully  
For and on behalf of  
VW-VES (HK) LIMITED



\_\_\_\_\_  
Francois Rudloff  
Operation Manager

FR/EZ/WB/sy

Attachment: Odour Patrol results (3 hard copies + 1 CD)

cc: EPD – Davie Kan (w/ 1 hard copy & w/o CD)  
Jacobs (ER) – Leslie Swann (w/ 1 hard copy & w/o CD)

**Sludge Treatment Facilities**

Office: Nim Wan Road, Tsang Tsui, Tuen Mun, New Territories, Hong Kong  
Correspondence: Unit 7601, The Center, 99 Queen's Road Central, Hong Kong  
Tel: +852 2910 9600 • Fax: +852 2430 8011

[www.veolia.com](http://www.veolia.com)

operated by  VEOLIA

**FUGRO TECHNICAL SERVICES LIMITED**

Fugro Development Centre,  
5 Lok Yi Street, Tai Lam,  
Tuen Mun, N.T.,  
Hong Kong.

Tel : +852 2450 8233  
Fax : +852 2450 6138  
E-mail : matlab@fugro.com  
Website : www.materiallab.com.hk

**MaterialLab**

Report No. : 163120EN161626



**Test Report on Odour Monitoring**

**Information Supplied by Client**

Client : VW – VES (HK) LTD.  
Client's address : -  
Project : Independent Odour Patrol  
Location of monitoring : Sludge Treatment Facilities at Nim Wan, Tuen Mun  
Test required : Odour Patrol

**Laboratory Information**

Date of monitoring : 08/07/2016 (Daytime)  
Test method used : Sniff Testing  
Oduor patrol route : As shown in the layout plan

**Results/Observation :**

Location	Time	Weather condition	Temperature (°C)	Wind		Odour Intensity Level		Remarks
				Speed (m/s)	Direction	Panalist		
						A	B	
A	10:14	Sunny	34.0	< 1	Northwest	1	1	DSD sludge truck driving pass and intermittent sludge odour was spotted

Remarks : A layout plan showing the monitoring location is attached for reference.

Supervised by :           K.F. Wong          

Certified by : 

Approved Signatory : HO Kin Man, John  
Manager – Chemistry Department

Date :           4/8/2016            
\*\* End of Report \*

Note : This report refers only to the sample(s) tested.

# FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,  
5 Lok Yi Street, Tai Lam,  
Tuen Mun, N.T.,  
Hong Kong.


Tel : +852 2450 8233  
Fax : +852 2450 6138  
E-mail : matlab@fugro.com  
Website : www.materialab.com.hk

# Materialab

Report No. : 163120EN161626

## Appendix

Photo 1. : A layout plan of monitoring location



*Note : This report refers only to the sample(s) tested.*

The copyright of this document is owned by Fugro Technical Services Limited. It may not be reproduced except with prior written approval from the Company.

**FUGRO TECHNICAL SERVICES LIMITED**

Fugro Development Centre,  
5 Lok Yi Street, Tai Lam,  
Tuen Mun, N.T.,  
Hong Kong.

Tel : +852 2450 8233  
Fax : +852 2450 6138  
E-mail : matlab@fugro.com  
Website : www.materialab.com.hk

**Materialab**

Report No. : 163120EN161626(1)



Page 1 of 1

**Test Report on Odour Monitoring****Information Supplied by Client**

Client : VW – VES (HK) LTD.  
Client's address : -  
Project : Independent Odour Patrol  
Location of monitoring : Sludge Treatment Facilities at Nim Wan, Tuen Mun  
Test required : Odour Patrol

**Laboratory Information**

Date of monitoring : 08/07/2016 (Evening)  
Test method used : Sniff Testing  
Oduor patrol route : As shown in the layout plan

**Results/Observation :**

Location	Time	Weather condition	Temperature (°C)	Wind		Odour Intensity Level		Remarks
				Speed (m/s)	Direction	Panalist		
						A	B	
B	18:19	Fine	34.0	< 1	Southeast	1	1	Odour from landfill
C	18:22	Fine	34.0	1.2	Northwest	1	1	Intermittent sludge odour was spotted

Remarks : A layout plan showing the monitoring location is attached for reference.

Supervised by :           K.F. Wong          
 Certified by :   
 Approved Signatory : HO Kin Man, John  
 Manager – Chemistry Department
Date :           4/8/2016          

\*\* End of Report \*\*

*Note : This report refers only to the sample(s) tested.*

# FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,  
5 Lok Yi Street, Tai Lam,  
Tuen Mun, N.T.,  
Hong Kong.


Tel : +852 2450 8233  
Fax : +852 2450 6138  
E-mail : matlab@fugro.com  
Website : www.materiallab.com.hk

# MaterialLab

Report No. : 163120EN161626(1)

## Appendix

Photo 1 : A layout plan of monitoring location



*Note : This report refers only to the sample(s) tested.*

The copyright of this document is owned by Fugro Technical Services Limited. It may not be reproduced except with prior written approval from the Company.