

VW-VES

VW-VES (HK) Limited

Our Ref: HKSTF-VWVE-EPD-EIA-LE-160908-003

(By hand)

8 September 2016

The EIA Ordinance Register Office
Environmental Protection Department
27/F Southorn Centre
130 Hennessy Road
Wan Chai, Hong Kong

Attn: Mr Alex Tang

Dear Sir

**Contract No. EP/SP/58/08 – Sludge Treatment Facilities
Environmental Monitoring Results in Operation Phase – Odour Patrol (August 2016)**

In accordance with the Clause 2.3.2.6 of the EM&A Manual and would like to submit herewith three hard copies and one electronic copy of the captioned subject for your information and record.

Should you have any queries, please do not hesitate to contact our Mr WB Chu on 2910 9666.

Thank you for your kind attention.

Yours faithfully
For and on behalf of
VW-VES (HK) LIMITED



Vincent Deleu
Project Manager

VD/EZ/WB/hk

Attachment: Odour Patrol results (3 hard copies + 1 CD)

cc: EPD – Davie Kan (w/ 1 hard copy & w/o CD)
Jacobs (ER) – Leslie Swann (w/ 1 hard copy & w/o CD)

T - PARK

No. 25 Nim Wan Road, Tsang Tsui, Tuen Mun, New Territories, Hong Kong
Tel: +852 2910 9600 • Fax: +852 2430 8011

www.veolia.com

operated by  **VEOLIA**

FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,
5 Lok Yi Street, Tai Lam,
Tuen Mun, N.T.,
Hong Kong.

Tel : +852 2450 8233
Fax : +852 2450 6138
E-mail : matlab@fugro.com
Website : www.materialab.com.hk



Report No. : 163120EN162066



Test Report on Odour Monitoring

Information Supplied by Client

Client : VW – VES (HK) LTD.
 Client's address : -
 Project : Independent Odour Patrol
 Location of monitoring : Sludge Treatment Facilities at Nim Wan, Tuen Mun
 Test required : Odour Patrol

Laboratory Information

Date of monitoring : 22/08/2016 (Daytime)
 Test method used : Sniff Testing
 Odour patrol route : As shown in the layout plan

Results/Observation :

Location	Time	Weather condition	Temperature (°C)	Wind		Odour Intensity Level		Remarks
				Speed (m/s)	Direction	Panelist		
						A	B	
A	10:14	Sunny	31.0	1-2	East	1	1	DSD sludge truck driving pass and intermittent sludge odour was spotted

Remarks : A layout plan showing the monitoring location is attached for reference.

Supervised by : K.F. Wong

Certified by : 
 Approved Signatory : HO Kin Man, John
 Manager – Chemistry Department

Date 21/9/2016

** End of Report *

Note : This report refers only to the sample(s) tested.

FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,
5 Lok Yi Street, Tai Lam,
Tuen Mun, N.T.,
Hong Kong.

Tel : +852 2450 8233
Fax : +852 2450 6138
E-mail : matlab@fugro.com
Website : www.materiallab.com.hk


MaterialLab

Report No. : 163120EN162066

Page 2 of 2

Appendix

Photo 1. : A layout plan of monitoring location



Note : This report refers only to the sample(s) tested.

The copyright of this document is owned by Fugro Technical Services Limited. It may not be reproduced except with prior written approval from the Company.

FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,
5 Lok Yi Street, Tai Lam,
Tuen Mun, N.T.,
Hong Kong.

Tel : +852 2450 8233
Fax : +852 2450 6138
E-mail : matlab@fugro.com
Website : www.materialab.com.hk



Report No. : 163120EN162066(1)



Test Report on Odour Monitoring

Information Supplied by Client

Client : VW – VES (HK) LTD.
Client's address : -
Project : Independent Odour Patrol
Location of monitoring : Sludge Treatment Facilities at Nim Wan, Tuen Mun
Test required : Odour Patrol

Laboratory Information

Date of monitoring : 22/08/2016 (Evening)
Test method used : Sniff Testing
Odour patrol route : As shown in the layout plan

Results/Observation :

Location	Time	Weather condition	Temperature (°C)	Wind		Odour Intensity Level		Remarks
				Speed (m/s)	Direction	Panelist		
						A	B	
B	18:08	Fine	32.0	1	Southeast	1	1	DSD sludge truck driving pass and intermittent sludge odour was spotted

Remarks : A layout plan showing the monitoring location is attached for reference.

Supervised by : K.F. Wong

Certified by : 
Approved Signatory : HO Kin Man, John
Manager – Chemistry Department

Date : 21/9/2016
** End of Report **

Note : This report refers only to the sample(s) tested.

FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,
5 Lok Yi Street, Tai Lam,
Tuen Mun, N.T.,
Hong Kong.

Tel : +852 2450 8233
Fax : +852 2450 6138
E-mail : matlab@fugro.com
Website : www.materiallab.com.hk


MaterialLab

Report No. : 163120EN162066(1)

Page 2 of 2

Appendix

Photo 1. : A layout plan of monitoring location



Note : This report refers only to the sample(s) tested.

The copyright of this document is owned by Fugro Technical Services Limited. It may not be reproduced except with prior written approval from the Company.