

**Contract No. CV/2004/15**  
**Fill Bank At Tuen Mun Area 38 – Stage 2**  
**Monthly EM&A Summary Report**  
**for October 2005**

November 2005

  
Reviewed by (PM):

  
Checked by:

  
Approved by:

Report Version: <u>Rev. 0</u>	Date of Submission: <u>11 November 2005</u>
-------------------------------	---

The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

## **TABLE OF CONTENTS**

### **EXECUTIVE SUMMARY**

#### **1. INTRODUCTION**

Background  
Project Organisation  
Construction Works undertaken during the Reporting Month  
Summary of EM&A Requirements

#### **2. AIR QUALITY MONITORING**

Monitoring Requirements  
Monitoring Equipment  
Monitoring Parameters, Frequency and Duration  
Monitoring Locations  
Monitoring Methodology  
Results and Observations

#### **3. WATER QUALITY MONITORING**

Monitoring Requirements  
Monitoring Equipment  
Monitoring Parameters, Frequency and Duration  
Monitoring Locations  
Monitoring Methodology  
Laboratory Analysis  
QA/QC Procedure  
Results and Observations

#### **4. Landscape and Visual**

Landscape and Visual Audit

#### **5. WASTE MANAGEMENT**

Waste Generation Schedule

#### **6. ENVIRONMENTAL AUDIT**

Site Environmental Audit  
Review of Environmental Monitoring Procedures  
Status of Environmental Licensing and permitting  
Implementation Status of Environmental Mitigation Measures  
Implementation Status of Event and Action Plans  
Implementation Status of Environmental Complaint Handling Procedures

#### **7. FUTURE KEY ISSUES**

Key Issues for the Coming Month  
Environmental Monitoring Program for the Next Three Months

#### **8. CONCLUSIONS AND RECOMMENDATIONS**

Conclusions  
Recommendations

## **List of Tables**

Table 2.1	TSP Monitoring Equipment
Table 2.2	Air Quality Monitoring Parameters and Frequency
Table 3.1	Water Quality Monitoring Equipment
Table 3.2	Water Quality Monitoring Parameters and Frequency
Table 3.3	Analytical Methods to be applied to Water Quality Samples
Table 3.4	Water Quality Exceedance Summary
Table 5.1	Actual Amounts of Waste Generated in October 2005
Table 6.1	Summary of Environmental Notification, Licensing and Permit Status

## **List of Figures**

Figure 1.1	Project Organisation
Figure 1.2	Layout of Work Site
Figure 2.1	Location of Air Quality Monitoring Station
Figure 3.1	Locations of Water Quality Monitoring Stations

## **List of Appendices**

Appendix A	Action and Limit Levels
Appendix B	Environmental Monitoring Schedule
Appendix C	Air Quality Monitoring Results
Appendix D	Meteorological Data
Appendix E	Water Quality Monitoring Results
Appendix F	QA/QC Procedures and Results
Appendix G	Summary of Calibration Status
Appendix H	Site Inspection Records
Appendix I	Event and Action Plan
Appendix J	Complaint Flow Diagram and Complaint Log
Appendix K	Contact of Key Environmental Personnel