



Contract No. HY/2003/04

**Improvement to Castle Peak Road
between Ka Loon Tsuen and Siu Lam**

Monthly EM&A Report for June 2006

July 2006

	Name	Signature
Reviewed & Checked:	Florence Yuen	
Approved: (ET Leader)	Y T Tang	

Version:	Revision 0	Date:	14 July 2006
<p>The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.</p> <p>This report is copyright and may not be reproduced in whole or in part without prior written permission.</p>			

MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD

11/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305 Email: mem@maunsell.aecom.com

TABLE OF CONTENTS

EXECUTIVE SUMMARY

1. INTRODUCTION

Background
Scope of Report
Project Organisation
Environmental Status in the Reporting Month
Summary of EM&A Requirements

2. AIR QUALITY

Monitoring Requirements
Monitoring Equipment
Monitoring Parameters, Frequency and Duration
Monitoring Locations
Monitoring Methodology
Results and Observations

3. NOISE MONITORING

Monitoring Requirements
Monitoring Equipment
Monitoring Parameters, Frequency and Duration
Monitoring Locations
Monitoring Methodology
Results and Observations

4. WATER QUALITY

5. ENVIRONMENTAL SITE INSPECTION

Site Inspections
Review of Environmental Monitoring Procedures
Advice on Waste Management Status
Status Environmental Licences and Permits
Implementation Status of Environmental Mitigation Measures
Summary of Exceedances of Environmental Quality Performance Limit
Summary of Environmental Complaints, Notifications of Summons and Successful Prosecutions

6. FUTURE KEY ISSUES

Key Issues for Coming Month
Environmental Monitoring and Audit Schedule for the Coming Months

7. CONCLUSIONS AND RECOMMENDATIONS

Conclusions
Recommendations

List of Tables

Table 2.1	Air Quality Monitoring Equipment
Table 2.2	Air Quality Monitoring Parameters, Frequency and Duration
Table 2.3	Locations of Air Quality Monitoring Stations
Table 2.4	Summary of Impact 1-hour TSP Monitoring Results
Table 2.5	Summary of Impact 24-hour TSP Monitoring Results
Table 3.1	Noise Monitoring Equipment
Table 3.2	Noise Monitoring Parameters, Frequency and Duration
Table 3.3	Locations of Noise Monitoring Stations
Table 3.4	Summary of Impact Noise Monitoring Results during 07:00 – 19:00 on Normal Weekdays
Table 5.1	Summary of Waste Disposal in The Month

List of Figures

Figure 1.1	Project Organisation for Environmental Management
Figure 1.2	Layout of Work Site
Figure 1.2a	Layout of Work Site A
Figure 1.2b	Layout of Work Site B
Figure 1.2c	Layout of Work Site C
Figure 1.2d	Layout of Work Site D
Figure 1.2e	Layout of Work Site E
Figure 2.1	Locations of Air Quality Monitoring Stations
Figure 3.1	Locations of Construction Noise Monitoring Stations
Figure 4.1	Locations of Water Quality Monitoring Stations
Figure 5.1	Complaint Flow Diagram

Appendices

Appendix A	Key Contacts of Environmental Personnel
Appendix B	Construction Programme
Appendix C	Environmental Action and Limit Levels
Appendix D	Environmental Monitoring and Audit Schedules
Appendix E	Calibration Details
Appendix F	Air Quality Monitoring Results and Graphical Presentation
Appendix G	Noise Monitoring Results and Graphical Presentation
Appendix H	Summary of Weekly Environmental Site Inspection Observations
Appendix I	Status of Environmental Permits/Licences
Appendix J	Implementation Schedule of Mitigation Measures
Appendix K	Event and Action Plans
Appendix L	Cumulative Statistics on Complaints, Notification of Summons and Successful Prosecutions and Complaint Log