



CONTRACT NO: CV/2004/02

**RECONSTRUCTION OF WONG SHEK AND
KO LAU WAN PUBLIC PIERS**

**ENVIRONMENTAL MONITORING & AUDIT
MONTHLY REPORT
(WONG SHEK)**

- 9 MAR 2007 – 17 APR 2007 -

CLIENT:

Kin Shing Construction Company Limited

1/F, 27 Yin Chong Street,
Mongkok,
Kowloon, H.K.

Telephone: (852) 2835 7087
Facsimile: (852) 2780-2805

PREPARED BY:

Lam Environmental Services

Room 1411-16
14/F Honour Industrial Centre
6 Sun Yip Street
Chai Wan, H.K.

Telephone: (852) 2897-3282
Facsimile: (852) 2897-5509
E-mail: info@lamlab.com
Website: <http://www.lamlab.com>

CERTIFIED BY:

Raymond Dai
Senior Environmental Scientist

DATE:

15 Jan 2008

MATERIALAB CONSULTANTS LIMITED

Fugro Development Centre

5 Lok Yi Street, 17 M.S. Castle Peak Road,

Tai Lam, Tuen-Mun, N.T., Hong Kong.

Telephone : +852-24508233

Telefax : +852-24506138

Email : mcl@fugro.com.hk

Materialab**FAX MESSAGE**Priority normal / urgent

To Lam Environmental Services

Ref. No. MCLF1894

Country

Fax No. 2897 5509

Attn. Mr. Raymond Dai

Date 15 January 2008

From Joseph Poon

No. of Pages 1 (Incl. this page)

C.c. To Mr. Simon Fok (Kin Shing Con. Co. Ltd.)

Fax No. 2729 7858

Subject **Contract No. CV/2004/02****Reconstruction of Wong Shek and Ko Lau Wan Public Piers
Monthly EM&A Summary Reports**

We refer to the Monthly EM&A reports (Mar to Apr 07) for Wong Shek Pier and Ko Lau Wan Pier that we received through email on 11 January 2008 and are pleased to confirm we have no further comment on the reports.

Should you require further information, please feel free to contact us.

Best regards,



Joseph Poon
Independent Environmental Checker

JP/ac

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us immediately.

(If you do not receive all pages, please fax response or phone +852-24508233.)



CONTENTS

Executive Summary	1
1 Introduction	1
1.1 Scope of the Report.....	1
1.2 Structure of the Report	1
2 Project Background	3
2.1 Scope of the Project and Site Description.....	3
2.2 Project Organization and Contact Personnel	3
2.3 Construction Programme and Works.....	3
3 Implementation Status	4
3.1 Status of Regulatory Compliance.....	4
3.2 Implementation of Pollution Control / Mitigation Measures	4
4 Monitoring Requirements	5
4.1 Water Quality Monitoring	5
4.2 Monitoring Parameters and Frequency.....	8
4.3 Water Quality Criteria	8
4.4 Monitoring Programme	9
5 Monitoring Results.....	10
5.1 Water Quality Monitoring Results	10
5.2 Waste Monitoring Results.....	10
6 Compliance Audit.....	11
7 Site Inspection and Audit.....	12
8 Complaints, Notification of Summons and Prosecution	13
9 Future Key Issues.....	14
10 Conclusion.....	15



LIST OF TABLES

Table 2.2	Contact Details of Key Personnel
Table 3.1	Cumulative Summary of Valid Licences and Permits
Table 4.1a	Water Quality Monitoring Stations
Table 4.1b	Laboratory Test Procedures
Table 4.2	Water Quality Monitoring Parameters and Frequencies
Table 4.3	Action and Limit Levels for Water Quality Monitoring
Table 4.4	Environmental Monitoring Programme – Mar-Apr 07
Table 5.1a	Water Quality Monitoring Results (mid-flood tide) – Mar-Apr 07
Table 5.1b	Water Quality Monitoring Results (mid-ebb tide) – Mar-Apr 07
Table 6.1a	Summary of Water Quality Exceedance (mid-flood tide) – Mar-Apr 07
Table 6.1b	Summary of Water Quality Exceedance (mid-ebb tide) – Mar-Apr 07
Table 7	Summary of Environmental Inspection and Audit – Mar-Apr 07
Table 8a	Environmental Complaints Log
Table 8b	Cumulative Statistics on Complaints
Table 8c	Cumulative Statistics on Successful Prosecutions
Table 8c	Cumulative Statistics on Notification of Summons

LIST OF FIGURES

<u>Figure 2.1</u>	Location Plan
<u>Figure 2.3</u>	Master Construction Programme
<u>Figure 4.1</u>	Layout of Environmental Monitoring Stations
<u>Figure 5.1a-h</u>	Graphical Plots of Water Quality Monitoring Results

LIST OF APPENDICES

<u>Appendix A</u>	Organization Chart
<u>Appendix B</u>	Implementation Schedule of Mitigation Measures
<u>Appendix C</u>	Calibration Certificates for Monitoring Equipment
<u>Appendix D</u>	Water Quality Monitoring Results
<u>Appendix E</u>	Monitoring Schedule - Upcoming month



EXECUTIVE SUMMARY

This is the Monthly Environmental Monitoring and Audit (EM&A) report for Contract No. CV/2004/02 – Reconstruction of Wong Shek and Ko Lau Wan Public Piers. This report presents the environmental monitoring and auditing (EM&A) findings based on data and information recorded from the period 9th Mar to 17th Apr 2007 for the demolition of the Wong Shek Public Pier.

Construction Activities for the Reported Period

During this reporting period, the principal work activities at Wong Shek Pier include:

- Demolition of existing pier

Water Quality Monitoring

10 water quality monitoring events in terms of turbidity, dissolved oxygen, suspended solids, temperature, and salinity was carried out at MW1, MW2, CW1 and CW2 at Wong Shek during the reporting period.

Fluctuations for dissolved oxygen, turbidity and suspended solids resembled those fluctuations at the control stations which indicated that all the exceedances in water quality monitoring were due to natural phenomena and agreed with the changes in the control stations. Causation due to construction activities is unlikely and there were no valid exceedance for this reporting period.

Waste Management

All demolished materials were beneficially reused as artificial coral on site so that no C&D materials were disposed. No general refuse or chemical waste was transported off site in this reporting period.

Complaints, Notifications of Summons and Successful Prosecutions

There was no complaint, notification of prosecution or summon in this reporting period.



Site Inspections and Audit

6 site inspections were conducted by the Environmental Team (ET) in this reported period. Major observations are summarised in the following table. Major observations by the ET, actions by the Contractor and outcome are summarized in the following table.

Item	Date	Observations	Action taken by Contractor	Outcome
-	9 Mar	No particular finding	-	-
-	16-Mar	No particular finding	-	-
-	23-Mar	No particular finding	-	-
-	30-Mar	No particular finding	-	-
-	2-Apr	No particular finding	-	-
-	13-Apr	No particular finding	-	-

Future Key Issues

After 17 Apr 07, all the pier demolition works were completed and post-project water quality monitoring will proceed.



1 INTRODUCTION

1.1 SCOPE OF THE REPORT

Lam Environmental Services (LAM) has been appointed to work as the Environmental Team (ET) for Kin Shing Construction Company Limited to implement the Environmental Monitoring and Audit (EM&A) programme for the Contract No. CV/2004/02 – Reconstruction of Wong Shek and Ko Lau Wan Public Piers.

This report presents the environmental monitoring and auditing work carried out from the period 9th Mar to 17th Apr 2007 for the demolition of Wong Shek Public Pier in accordance to Section 26 of the Particular Specification, Project Profile (PP-191/2003) and Environmental Permit (EP-186/2004) for this Project.

The following information relating to this project is documented in the EM&A Manual and, to avoid duplication, it is not presented in detail within the monthly report.

- Event-Action Plans;
- Full set of environmental mitigation measures and;
- Contracted environmental requirements.

1.2 STRUCTURE OF THE REPORT

Section 1 *Introduction* – details the scope and structure of the report.

Section 2 *Project Background* – summarizes background and scope of the project, site description, project organization and contact details of key personnel, construction programme and works undertaken during the reporting period.

Section 3 *Implementation Status* – summarizes the status of Environmental Permits / Licenses, implementation of environmental protection and pollution control / mitigation measures in an updated schedule for the reporting period.

Section 4 *Monitoring Requirements* – summarizes all monitoring parameters, monitoring methodology and equipment, monitoring locations, monitoring frequency and programmes.



- Section 5** ***Monitoring Results*** – summarizes the monitoring results obtained in the reporting period.
- Section 6** ***Compliance Audit*** – summarizes the auditing of monitoring results, all exceedances environmental parameters.
- Section 7** ***Site Inspection and Audit*** – summarizes the findings of weekly site inspections and independent audit undertaken within the reporting period, with a review of any relevant follow-up actions within the reporting period.
- Section 8** ***Complaints, Notification of Summons and Prosecution*** – summarizes the complaints, notification of summons and successful prosecution for breaches of environmental legislation and the actions taken within the reporting period.
- Section 9** ***Future Key Issues*** – summarizes the upcoming works and a forecast of the environmental impact and monitoring schedule for the next reporting period.
- Section 10** ***Conclusion***

2 PROJECT BACKGROUND

2.1 SCOPE OF THE PROJECT AND SITE DESCRIPTION

The works mainly comprise demolition of the existing piers and construction of reinforced concrete piers with roof covers at Wong Shek. The construction of the Project is scheduled to commence in November 2004 for completion in September 2006. The construction period is 630 days for the entire construction.

The site layout plan is shown in [Figure 2.1](#).

2.2 PROJECT ORGANIZATION AND CONTACT PERSONNEL

Civil Engineering Office of Civil Engineering and Development Department is the project proponent. The organization chart for the EM&A programme is attached in [Appendix A](#).

Under the organization chart, Resident Engineer, Contractor, Independent Environmental Checker, Environmental Team are appointed to manage and control environmental issues for the construction phase of CV/2004/02. Overall responsibilities and duties of the team are found in the corresponding EM&A Manual. Key personnel and contact particulars are summarized in **Table 2.2**:

Table 2.2 Contact Details of Key Personnel

Post	Name	Contact No.	Contact Fax	Mobile No.
Resident Engineer	David C S Leung	2760 5737	2714 2054	9630 1235
Project Manager	K W Li	2729 6779	2729 7858	9104 9463
Independent Environmental Checker (IEC)	Joseph T L Poon	2452 7140	2450 6138	9450 1968
Environmental Team Leader (ETL)	Raymond Dai	2975 3300	2897 5509	9738 0738

2.3 CONSTRUCTION PROGRAMME AND WORKS

Construction works carried out at Wong Shek Pier during this reporting period are:

- Demolition of existing pier

The master construction programme is given in [Figure 2.3](#).



3 IMPLEMENTATION STATUS

3.1 STATUS OF REGULATORY COMPLIANCE

A summary of the current status on licences and/or permits on environmental protection pertinent to the Project is shown in **Table 3.1**.

Table 3.1 Cumulative Summary of Valid Licences and Permits

Permits and/or Licences	Reference No.	Issued Date	Expiry Date	Status
Environmental Permit	EP-186/2004/A	28-04-2005	-	Issued on receipt of VEP-171/2005 dated 14-04-2005
Waste Producer Registration	WPN5213-742-K1081-05	12-05-2005	-	Notified
Construction Noise Permit	-	-	-	No valid CNP granted to the Contractor

3.2 IMPLEMENTATION OF POLLUTION CONTROL / MITIGATION MEASURES

The contractor implemented various environmental mitigation measures as recommended in the Particular Specification and the Environmental Permit. The implementation schedule is presented in [Appendix B](#).

4 **MONITORING REQUIREMENTS**

Locations of environmental monitoring stations are referred in [Figure 4.1](#).

4.1 **WATER QUALITY MONITORING**

The brief for EM&A works details 4 designated stations to be monitored during the construction period comprising 2 monitoring stations and 2 control stations. These stations have been coded as MW1, MW2, CW1 and CW2 respectively.

Table 4.1a *Water Quality Monitoring Stations*

Station	HK Metric Grid (Easting / Northing)	Description
MW1	852 789.231E / 832 978.476N	Impact Monitoring
MW2	852 844.187E / 832 878.676N	Impact Monitoring
CW1	852 922.540E / 833 067.718N	Control during mid-flood
CW2	852 992.314E / 832 853.794N	Control during mid-ebb

Monitoring Methodology

Measurements were be taken under two tidal conditions (mid-flood and mid-ebb) at 3 water depths, namely 1m below the water surface, mid-depth and 1m above the seabed, except where the water depth is less than 6m, the mid-depth sample may be omitted. If the water depth is less than 3m, only the mid-depth will be monitored.

Replicate in-situ measurements and samples were collected from each independent sampling event are required for all parameters to ensure a robust statistical interpretable dataset.

Water quality parameter in terms of: dissolved oxygen (mg/L and % saturation), salinity (ppt), turbidity (NTU), and suspended solids (mg/L) were measured in-situ with portable instruments. Other relevant data was also recorded, including the following:

- monitoring station and position;
- time;
- depth of water;
- tidal status;
- water temperature;
- weather conditions including ambient temperature;
- any special phenomena or activities at the construction site.



For the measurement of dissolved oxygen the probe shall be removed from the water column between each duplicate measurement. If the difference between each duplicate measurement is greater than a 25% then the two sets of data shall be rejected and the measurements re-taken.

Suspended solids (SS) were determined in the laboratory at Chai Wan managed by Lam Laboratories Ltd.

Monitoring Equipment

- **Sample Bottles:** Samples were kept in high density polythene bottles, packed in ice and cooled to 4°C or below, without being frozen, for delivery to the laboratory as soon as possible after collection.
- **Thermometer:** A standard certified laboratory mercury thermometer with an accuracy of at least 0.5°C was employed, calibrated against a certified thermometer of 0.1°C scale. This thermometer was employed for measuring both ambient and water temperatures.
- **Depth Detector:** As the depth of water being sampled was generally shallow, too shallow to allow for the use of an echosounder, a marked depth gSepe was employed to determine water depth at all designated monitoring stations.

All in-situ monitoring equipment shall be checked, verified and calibrated by Lam laboratory at Chai Wan, a HOKLAS accredited laboratory, prior to use on the Works and subsequently thereafter every three months throughout all stages of the water quality monitoring. Responses of the sensors and electrodes shall be checked with certified standard solutions before each use. Wet bulb calibration for a DO meter shall be carried out before measurement.

For in-situ calibration of field equipment, the BS 1427: 1993 "Guide to Field and on-site test methods for the analysis of waters" shall be observed.

A set of backup monitoring instruments and equipment shall be made available so that the monitoring can proceed uninterrupted in case of apparatus malfunction or if equipment has been returned to the laboratory for calibration.

Current calibration certificates are presented in [Appendix C](#).



Laboratory Analysis

All samples are returned to the laboratory at Chai Wan for the determination of SS under a QA / QC scheme inclusive of blank, duplicate and spike recovery analysis under the requirement of HOKLAS. The laboratory test procedures conform to “Standard Methods for the Examination of Water and Wastewater” published by American Public Health Association (APHA) and United State Environmental Protection Agency (USEPA) test methods are summarized in **Table 4.3b**.

Table 4.1b **Laboratory Test Procedures**

Parameter	Methodology	Method Ref.	Detection Limit
SS	Determination of Total Suspended Solids Dried at 103-105°C	APHA 19 th Ed. 2540D	2.0 mg/L

4.2 **MONITORING PARAMETERS AND FREQUENCY**

Water quality monitoring programme has been scheduled according to the requirements stipulated in the EM&A Manual produced for the Project summarized in **Tables 4.2**.

Table 4.2 Water Quality Monitoring Parameters and Frequencies

Station(s)	Parameter	Frequency
MW1, MW2 CW1, CW2	DO, Temperature, Salinity, Turbidity, Suspended Solids, Water Depth	<u>For piling or demolition works</u> 3 days per week at mid-flood and mid-ebb <u>For marine works other than piling or demolition works</u> 1 day per week at mid-flood and mid-ebb

4.3 **WATER QUALITY CRITERIA**

Water quality criteria were determined prior to the commencement of the construction of the project for the purpose of impact monitoring. Various levels established based on the results of baseline monitoring and the Event Action Plan stipulated in the EM&A Manual are summarized in **Tables 4.3**.

Table 4.3 Action and Limit Levels for Water Quality Monitoring

Parameter	Action Level	Target Level
Dissolved Oxygen (Surface, Middle & Bottom)	<u>Surface & Middle</u> For Wong Shek – 6.96	<u>Surface & Middle</u> For Wong Shek – 6.69
	<u>Bottom</u> For Wong Shek – 6.93	<u>Bottom</u> For Wong Shek – 6.71
Turbidity (depth-averaged)	For Wong Shek – 1.47 or 120% of upstream control station's Tby at the same tide of same day, whichever is lower	For Wong Shek – 4.05 or 130% of upstream control station's Tby at the same tide of same day, whichever is lower
Suspended Solids (depth-averaged)	For Wong Shek – 6.85 or 120% of upstream control station's SS at the same tide of same day, whichever is lower	For Wong Shek – 8.85 or 130% of upstream control station's SS at the same tide of same day, whichever is lower

Note:

1. "Depth-averaged" is calculated by taking the arithmetic means of reading all three depths.
2. For Dissolved Oxygen, non-compliance of the water quality limits occurs when monitoring result is lower than the limits.
3. For Turbidity and Suspended Solid, non-compliance of the water quality limits occurs when monitoring result is higher than the limits.
4. All the figures given in the table are used for reference only and the Engineer may amend the figures whenever it is considered as necessary.



4.4 MONITORING PROGRAMME

Environmental monitoring programme for this reporting period was carried out in accordance with the required monitoring frequency. The actual completion of monitoring work during the reporting period is presented in **Tables 4.4**.

Table 4.4 Environmental Monitoring Programme – Mar-Apr 07

Mar / Apr 2007		Water Quality (DO, Turbidity, SS)	Site Inspection
		MW1, MW2, CW1, CW2	
9	Fri	X	X
10	Sat		
11	Sun		
12	Mon	No mid-tides available	No mid-tides available
13	Tue		
14	Wed	No mid-tides available	No mid-tides available
15	Thu		
16	Fri	X	X
17	Sat		
18	Sun		
19	Mon	X	
20	Tue		
21	Wed	X	
22	Thu		
23	Fri	X	X
24	Sat		
25	Sun		
26	Mon	No mid-tides available	No mid-tides available
27	Tue		
28	Wed	No mid-tides available	No mid-tides available
29	Thu		
30	Fri	X	X
31	Sat		
1	Sun		
2	Mon	X	X
3	Tue		
4	Wed	X	
5	Thu		
6	Fri		
7	Sat		
8	Sun		
9	Mon	No mid-tides available	No mid-tides available
10	Tue		
11	Wed	X	
12	Thu		
13	Fri	X	X
14	Sat		
15	Sun		
16	Mon	X	

Note:

- X: Monitoring conducted from 9 Mar to 16 Apr 07 during the pier demolition work.
- Schedule is formulated and with consideration of statutory holidays (shaded in the table).

5 MONITORING RESULTS

5.1 WATER QUALITY MONITORING RESULTS

Water quality monitoring was carried out on 10 occasions at stations MW1, MW2, CW1 and CW2. Calculated water quality monitoring results in this reporting period are reviewed and summarized in **Tables 5.1a and 5.1b**. Details of measured and tested results can be referred in [Appendix D](#). Graphical trend is presented in [Figure 5.1a – 5.1h](#).

Table 5.1a Water Quality Monitoring Results (mid-flood tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle (mg/L)	Averaged DO Bottom (mg/L)	Averaged Turbidity (NTU)	Averaged Suspended Solids (mg/L)
MW1	6.51	6.07	1.22	12.5
MW2	6.22	5.60	1.21	8.2
CW1	6.11	Water depth < 3m	1.19	10.4
CW2	6.10	5.45	1.21	7.5

Table 5.1b Water Quality Monitoring Results (mid-ebb tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle (mg/L)	Averaged DO Bottom (mg/L)	Averaged Turbidity (NTU)	Averaged Suspended Solids (mg/L)
MW1	6.59	6.21	1.23	7.6
MW2	6.35	5.76	1.19	8.1
CW1	6.37	Water depth < 3m	1.30	7.9
CW2	6.25	5.55	1.23	9.2

5.2 WASTE MONITORING RESULTS

All demolished materials were beneficially reused as artificial coral on site so that no C&D materials were disposed. No general refuse or chemical waste was transported off site in this reporting period.

6 COMPLIANCE AUDIT

Results of the calculated water quality results for various are audited against the water quality levels and the number of exceedances are summarized **Tables 6.1a and 6.1b**. Exceedances caused by natural phenomena namely fluctuation of overall water quality by comparing the graphical trends of monitoring and control stations are eliminated in order to identify the valid exceedance due to construction activities.

Table 6.1a Summary of Water Quality Exceedance (mid-flood tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle	Averaged DO Bottom	Averaged Turbidity	Averaged Suspended Solids
MW1	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MW2	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)

Table 6.1b Summary of Water Quality Exceedance (mid-ebb tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle	Averaged DO Bottom	Averaged Turbidity	Averaged Suspended Solids
MW1	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MW2	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)

As shown in the graphical trend, the observed trends and exceedances in dissolved oxygen, turbidity and suspended solids at MW1 and MW2 resemble the fluctuations to the respective control stations, possibly due to variation in water current or tidal effect.

The observed exceedances for turbidity and suspended solids are respectively within 0.5 NTU and 15 mg/L, indicating the fluctuation could possibility due to the natural variation around the small values of suspended solids.

To conclude, the fluctuations for dissolved oxygen, turbidity and suspended solids resembled those fluctuations at the control stations which indicated that all the exceedances in water quality monitoring were due to natural phenomena and agreed with the changes in the control stations. Therefore, causation due to CV/2004/02 construction activities is unlikely and there were no valid exceedance for this reporting period.



7 SITE INSPECTION AND AUDIT

The ET undertook site inspection at least once a week. Monthly joint audit was undertaken by the IEC, the ETL, the Engineer and the Contractor.

The ET carried out 6 inspections during this reporting period. The results of these inspections and outcomes are summarized in **Table 7**.

Table 7 Summary of Environmental Inspection and Audit – Mar-Apr 07

Item	Date	Observations	Action taken by Contractor	Outcome
-	9 Mar	No particular finding	-	-
-	16-Mar	No particular finding	-	-
-	23-Mar	No particular finding	-	-
-	30-Mar	No particular finding	-	-
-	2-Apr	No particular finding	-	-
-	13-Apr	No particular finding	-	-

8 COMPLAINTS, NOTIFICATION OF SUMMONS AND PROSECUTION

No complaint, inspection notice, notification of summons or prosecution was received in this reporting period. Complaint log, summaries of cumulative complaints and successful prosecutions are presented in **Table 8a**, **Table 8b**, **Table 8c** and **Table 8d** respectively.

Table 8a Environmental Complaints Log

Complaint Log No.	Date of Receipt	Received From and By	Nature of Complaint	Date investigated	Outcome	Date of Reply and to Whom
-	-	-	-	-	-	-

Table 8b Cumulative Statistics on Complaints

Environmental Parameters	Cumulative No. Brought Forward	No. of Complaints This Month	Cumulative No. Project-to-Date
Air	-	-	-
Noise	-	-	-
Water	-	-	-
Waste	-	-	-
Total	-	-	-

Table 8c Cumulative Statistics on Successful Prosecutions

Environmental Parameters	Cumulative No. Brought Forward	No. of Successful Prosecutions this month (Offence Date)	Cumulative Number to Date
Air	-	-	-
Noise	-	-	-
Water	-	-	-
Waste	-	-	-
Total	-	-	-

Table 8c Cumulative Statistics on Notification of Summons

Environmental Parameters	Cumulative No. Brought Forward	No. of Successful Summons	Cumulative Number to Date
Air	-	-	-
Noise	-	-	-
Water	-	-	-
Waste	-	-	-
Total	-	-	-



FUTURE KEY ISSUES

After 17 Apr 07, all the pier demolition works were completed and post-project water quality monitoring will proceed. The proposed monitoring schedule for the coming reporting period is detailed in [Appendix E](#).



CONCLUSION

The EM&A programme was carried out in accordance with the EM&A Manual requirements, minor alterations to the programme proposed in the previous EM&A Report were made in response to changing circumstances.



No exceedance due to construction activities was reported in routine environmental monitoring. Such results indicate that the construction operation generally performed reasonably acceptable against environmental auditing criteria.

In summary, environmental mitigation measures are being satisfactorily implemented within the CV/2004/02 project along with the on-going construction activities.



Figure 2.1

Location Plan



NOTES:

1. ALL DIMENSIONS ARE IN MILLIMETRES.
2. ALL LEVELS REFER TO CHART DATUM (C.D.).
3. ALL LEVELS REFER TO CHART DATUM (C.D.).

LEGEND:

- BOLLARD
- * NAVIGATION LIGHT

no.	date	description	designed	approved
1.				
2.				
3.				
4.				

no.	date	description	designed	approved
1.				
2.				
3.				
4.				

contract no.	
file no.	
project no.	
contract	

drawing title
**WONG SHEK PUBLIC PIER
 - GENERAL LAYOUT**

drawing no.	
scale	

office

**CIVIL ENGINEERING
 AND DEVELOPMENT
 DEPARTMENT
 HONG KONG**



COPYRIGHT RESERVED

H AT 841 X 534



Figure 2.3

Master Construction Programme

Contractor: Kin Shing Construction Co. Ltd.
 Commencement Date: 15th Nov 2004
 Completion Date: 6th Aug 2006
 Programme Date: 21st Feb 2005

Master Programme (Version 2)

Contract No.: CV/2004/02
 Reconstruction of Wong Shek and
 Ko Lau Wan Public Piers

ID	Task Name	Duration	Start	Finish	Predecessors
1	Installation of precast abut with in-situ pile caps	60 days	Mon 05/10/10	Thu 05/12/8	SA, SA2A
2	Casting of in-situ pier deck	30 days	Fri 05/12/9	Sat 06/1/7	9, 7B
3	Construction of bollards	30 days	Fri 05/12/9	Sat 06/1/7	30
4	Installation of corrosion monitoring system	91 days	Sun 05/10/9	Sat 06/0/7	
5	Approval of specialist contractor and method statement	61 days	Sun 05/10/9	Thu 05/12/8	
6	Installation of corrosion monitoring system	30 days	Fri 05/12/9	Sat 06/0/7	8, 7A
7	Roof cover system	272 days	Tue 05/8/9	Sun 06/5/7	
8	Approval of specialist contractor	61 days	Tue 05/8/9	Sat 06/1/7	
9	Submission of working drawings for connection details with deck	61 days	Sun 05/10/9	Thu 05/12/8	7
10	Material submissions	91 days	Sun 05/10/9	Sat 06/1/7	7
11	Submission of working drawing for retaining roof system	91 days	Sun 05/10/9	Sat 06/1/7	7
12	Construction of steel work	60 days	Sun 06/1/8	Wed 06/5/8	11, SA, 7B
13	Erection of roof covers	60 days	Thu 06/3/9	Sun 06/5/7	31
14	Marrying-in to lambside	121 days	Wed 06/3/8	Thu 06/7/6	
15	Application of Excavation Permit	90 days	Wed 06/5/8	Mon 06/0/5	
16	Site work	31 days	Tue 06/6/6	Thu 06/7/6	14, 31
17	Electrical system, CLP meter box and lighting system	220 days	Mon 05/10/10	Wed 06/5/17	
18	Approval of specialist contractor	30 days	Mon 05/10/10	Tue 05/11/8	
19	Joinery with CLP and BMSD	60 days	Wed 05/11/9	Sat 06/1/7	37
20	Installation	120 days	Sun 05/12/8	Sun 06/5/7	7, SA
21	Testing	10 days	Mon 06/5/8	Wed 06/5/17	38
22	Construction of floor finish	121 days	Wed 06/3/8	Thu 06/7/6	
23	Material submissions	61 days	Wed 06/3/8	Sun 06/5/7	
24	Site work	60 days	Mon 06/5/8	Thu 06/7/6	32, 32
25	Construction of lateral rilling, setting benches and notice board	150 days	Tue 06/2/7	Thu 06/7/6	
26	Material submission	60 days	Tue 06/2/7	Fri 06/4/7	
27	Construction	90 days	Sat 06/4/8	Thu 06/7/6	11, 3
28	Installation of fender system	190 days	Thu 05/12/9	Thu 06/7/6	
29	Material submission	33 days	Thu 05/12/9	Sat 06/2/8	
30	Ordering of material	60 days	Sun 06/1/9	Tue 06/5/8	19
31	Site work	60 days	Wed 06/5/9	Thu 06/7/6	7, 19
32	Relocation of navigation light by Marine Dept.	92 days	Fri 06/4/7	Fri 06/7/7	
33	Application to Marine Department	91 days	Fri 06/4/7	Thu 06/7/6	

Contract No.: CV/2004/02
 Reconstruction of Wong Shek and
 Ko Lau Wan Public Piers

Master Programme
 (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
 Commencement Date: 15th Nov 2004
 Completion Date: 6th Aug 2006
 Programme Date: 21st Feb 2005

CV	Task Name	Duration	Start	Finish	Predecessors
13	Relocation	1 day	Fri 06/7/04	Fri 06/7/04	103, 104, 105, 106, 107, 108
14	Commissioning of the pier	1 day	Sat 06/7/04	Sat 06/7/04	103
105	Demolition of the temporary berth and the existing pier	151 days	Thu 06/3/04	Sun 06/8/06	
106	Survey of existing structures	31 days	Thu 06/3/04	Sat 06/6/04	
107	Design and ICT checking of demolition plan	61 days	Sun 06/4/04	Thu 06/6/04	106
108	Submission for Engineer's comment	30 days	Fri 06/6/04	Sat 06/7/04	107
109	Obtain consent from Country and Marine Park Authority	30 days	Fri 06/6/04	Sat 06/7/04	107
110	Demolition	29 days	Sun 06/7/04	Sun 06/8/06	106, 109, 108
111	Maintenance Period for the Works	365 days	Mon 06/8/04	Mon 07/8/06	110
112	Section 2 (Ko Lau Wan Public Pier)				
113	Control Survey	626 days	Mon 04/11/05	Wed 06/8/02	
114	Submittal and approval of specification and method statement	75 days	Mon 04/11/05	Wed 05/1/06	
115	Initial crew survey and approval by AFCD	18 days	Sun 05/2/06	Wed 05/3/06	114, 115
116	Cost transmittal	4 days	Thu 05/3/06	Sun 05/3/06	115
117	Post construction survey	4 days	Mon 05/3/06	Thu 05/3/07	116
118	Post-pier construction survey	15 days	Wed 06/7/09	Wed 06/8/02	117
119	Temporary cover to existing pier	123 days	Mon 04/11/05	Thu 05/3/07	
120	Design and ICT checking	60 days	Mon 04/11/05	Wed 05/1/06	
121	Submittal for Engineer's comment	30 days	Thu 05/1/06	Fri 05/2/06	120
122	Execution	22 days	Sat 05/2/06	Sat 05/3/06	121
123	Certified by ICE and commissioning	8 days	Sun 05/3/06	Thu 05/3/07	122
124	Provision of temporary berth	247 days	Mon 04/11/05	Tue 05/7/09	
125	Design and ICT checking of temporary berth	80 days	Mon 04/11/05	Wed 05/2/06	
126	Submission for Engineer's comment	31 days	Thu 05/2/06	Sun 05/4/06	125
127	Piling (Phase 1)	9 days	Mon 05/4/06	Wed 05/5/06	126, 128, 119, 120, 125, 122
128	Piling (Phase 2)	9 days	Fri 05/6/06	Sat 05/6/06	127
129	Dock construction and installation of keelers	25 days	Sun 05/6/06	Wed 05/7/06	128
130	Relocation of navigation light by Marine Dept.	81 days	Mon 05/4/06	Thu 05/7/06	
131	Application to Marine Department	80 days	Mon 05/4/06	Wed 05/7/06	
132	Relocation works	1 day	Thu 05/7/06	Thu 05/7/06	130, 131
133	Certified by ICE, testing and commissioning of berth	5 days	Fri 05/7/06	Tue 05/7/06	132
134	Demolition of part of the existing pier	115 days	Mon 05/6/06	Wed 05/6/06	
135	Survey of existing structures	31 days	Mon 05/6/06	Wed 05/5/06	
136	Design and ICT checking of demolition plan	32 days	Thu 05/5/06	Sun 05/6/06	134



Critical Task (Sec. 1.1.2) Summary Completion Success

Critical Task (Sec. 1.1.2) Critical Task (Sec. 1) Maintenance Period

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005

Master Programme
(Version 2)

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lan Wan Public Piers

Task Name	Duration	Start	Finish	Relationship
Submission for Engineer's comments	30 days	Mon 05/6/20	Tue 05/7/19	136
Consult with local residents	30 days	Mon 05/6/20	Tue 05/7/19	137
Demolition	22 days	Wed 05/7/20	Wed 05/8/10	131,132,137
Ground investigation	120 days	Wed 04/12/29	Fri 05/5/6	
Submission for Engineer's comment	60 days	Wed 04/12/29	Sun 05/3/16	111,120,117
Ground investigation works on site	20 days	Fri 05/3/18	Wed 05/4/16	142
Preparation and approval of reports	16 days	Thu 05/4/17	Fri 05/5/6	143
Submission of reports to determine pile founding levels	20 days	Sun 05/4/17	Tue 05/12/8	
Piling for permanent pier	342 days	Sat 05/1/1	Wed 05/2/23	
Completion of method statement for piling	33 days	Sat 05/1/1	Wed 05/8/10	140
Submission for Engineer's comment	180 days	Thu 05/2/3	Thu 05/8/25	141,139,144
Vertical preliminary pile and testing	15 days	Thu 05/8/25	Wed 05/9/14	147
Vertical main piles (11EA,11DA,11CA,11A)	20 days	Fri 05/8/26	Wed 05/9/14	148
Temporary platform for raking pile	21 days	Thu 05/9/15	Wed 05/10/5	149
Vertical main pile (remaining 9 nos)	45 days	Thu 05/9/15	Sat 05/10/29	148
Raking preliminary piles and testing	16 days	Thu 05/10/6	Fri 05/10/21	149
Raking main piles (remaining 9 nos)	33 days	Sat 05/10/22	Wed 05/11/23	149
Pile tests for main piles	25 days	Thu 05/11/24	Thu 05/12/8	141,133
Construction of pile cap and deck	201 days	Wed 05/8/10	Sun 06/2/26	
Submission and approval of precast yard	60 days	Wed 05/8/10	Sat 05/10/9	
Casting of precast units at precast yard	60 days	Mon 05/10/10	Thu 05/12/8	148
Design and E.C.E. checking of falsework for pile cap and deck construction	60 days	Sat 05/9/10	Tue 05/11/8	
Engineer's approval	30 days	Wed 05/11/9	Thu 05/12/8	148
Erection of falsework for installation of precast units	20 days	Fri 05/12/9	Wed 05/12/26	146,144
Installation of precast units with modular pile caps	55 days	Fri 05/12/9	Wed 06/3/1	145,144
Casting of in-situ pier deck	25 days	Thu 06/2/2	Sun 06/2/26	141,144
Construction of bollards	25 days	Thu 06/2/2	Sun 06/2/26	141
Installation of corrosion monitoring system	88 days	Sun 05/12/4	Sun 06/2/16	
Approval of specialist contractor and method statement	60 days	Sun 05/12/4	Wed 06/2/21	
Installation of corrosion monitoring system	25 days	Thu 06/2/2	Sun 06/2/26	141,145
Construction of walls	110 days	Fri 06/2/17	Tue 06/6/6	142
Concrete structure	50 days	Mon 06/2/27	Mon 06/4/17	
Finishing	110 days	Fri 06/2/17	Tue 06/6/6	
Material sub-contract	60 days	Fri 06/2/17	Mon 06/4/17	
Construction	50 days	Thu 06/4/18	Tue 06/6/6	142,126

Critical Task (Iss. 1 A.2) Critical Task (Iss. 1 B) Critical Task (Iss. 2) Maintenance Period Holiday
 Summary Completion Milestone
 Page: Comment: Milestone
 Sign

Contract No.: CV2004/02
 Reconstruction of Wong Shek and
 Ko Lau Wan Public Piers

Master Programme
 (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
 Commencement Date: 15th Nov 2004
 Completion Date: 6th Aug 2006
 Programme Date: 21st Feb 2005

Sl. No.	Task Name	Duration	Start	Finish	Professors
1	Construction of walking cover 1 & 2	245 days	Wed 05/10/05	Tue 06/06/06	
2	Approval of specialist contractor	60 days	Wed 05/10/05	Sat 05/12/05	
3	Submission of workshop drawings for connection details with deck	60 days	Sun 05/11/05	Wed 06/02/06	171
4	Material submissions	85 days	Sun 05/11/05	Sun 06/02/06	171
5	Submission of workshop drawing for remaining roof system	85 days	Sun 05/11/05	Sun 06/02/06	171
6	Construction of steel works	50 days	Mon 06/04/06	Mon 06/04/07	171, 182, 183
7	erection of roof covers	50 days	Tue 06/04/06	Tue 06/05/06	171
8	Electrical system, CLP meter box and lighting system	240 days	Tue 05/11/05	Fri 06/06/06	
9	Approval of specialist contractor	30 days	Thu 05/11/05	Wed 05/12/05	180
10	Liaison with CLP and GMSD	60 days	Thu 05/11/05	Sun 06/02/06	180
11	Installation	100 days	Mon 06/02/06	Tue 06/06/06	180, 181
12	Testing	10 days	Wed 06/07/06	Fri 06/08/06	181
13	Construction of floor finish	130 days	Thu 06/08/06	Sun 06/07/06	181
14	Material submissions	90 days	Thu 06/08/06	Tue 06/06/06	
15	Site works	40 days	Wed 06/08/06	Sun 06/07/06	181, 182, 183
16	Construction of land railing, setting benches and notice boards	150 days	Fri 06/02/07	Sun 06/07/06	
17	Material submission	60 days	Fri 06/02/07	Mon 06/04/07	183
18	Construction	190 days	Tue 06/04/06	Sun 06/07/06	183
19	Material submission	31 days	Sun 06/07/06	Tue 06/07/06	
20	Ordering of material	59 days	Wed 06/02/08	Fri 06/04/07	181
21	Site works	100 days	Sat 06/04/08	Sun 06/07/06	182
22	Relocation of navigation light by Marine Dept.	92 days	Mon 06/04/07	Mon 06/07/07	
23	Application to Marine Department	91 days	Mon 06/04/07	Sun 06/07/06	180, 181, 182, 183, 184
24	Relocation	1 day	Mon 06/07/07	Mon 06/07/07	184
25	Commissioning of the pier	1 day	Tue 06/07/08	Tue 06/07/08	184
26	Demolition of the temporary berth and the existing pier	141 days	Sun 06/03/09	Sun 06/08/06	
27	Survey of existing structure	31 days	Sun 06/03/09	Tue 06/04/08	184
28	Design and ICE checking of demolition plan	61 days	Wed 06/04/09	Sun 06/06/08	184
29	Submission for Engineer's comment	30 days	Mon 06/06/09	Fri 06/07/08	184
30	Liaison with local residents	30 days	Mon 06/06/09	Tue 06/07/08	184
31	Demolition	19 days	Wed 06/07/09	Sun 06/08/06	185, 186, 187
32	Maintenance Period for the Works	365 days	Mon 06/08/07	Mon 07/08/06	187

Contract No.: CV2004/02
 Reconstruction of Wong Shek and Ko Lau Wan Public Piers


Version 2

Page 5

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Contract No. CV/2004/02 View Document/Version 21	Normal Task Split	Summary Completion Milestone	Critical Task (Esc 1 & 2) Critical Task (Esc 1)	Critical Task (Esc 2) Maintenance Period
---	----------------------	---------------------------------	--	---

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Contract No.: CV/2004/02	Project Name: Ko Lau Wan and Wong Shek	Summary	Calendar Task (Gantt)	Critical Task (Gantt)
Client: Government	Contractor: Kin Shing Construction Co. Ltd.	Exceptional Milestone	Calendar Task (Gantt 1 & 2)	Maintenance Pulse
Version: 2	Programme Date: 21st Feb 2005		Calendar Task (Gantt 3)	

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Normal Task: [Pattern] Fragments: [Pattern] Summary: [Pattern] Completion Milestone: [Pattern] Critical Task (05-1): [Pattern] Critical Task (06-2): [Pattern] Maintenance Period: [Pattern]

Contract No.: CY/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Programme Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Start Task	833333333333	Progress	■	Summary	○	Construction Delayed	▨	Construction Delayed	▨	Construction Delayed	▨
End Task	333333333333	Construction Delayed	▨	Construction Delayed	▨	Construction Delayed	▨	Construction Delayed	▨	Construction Delayed	▨

Contractor: Kin Sating Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005

Master Programme
 (Version 2)

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers




148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171
Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete
Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	Steel	
Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	Formwork	
Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	Excavation	
Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	Foundation	
Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	Structural	
Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	Roofing	
Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	Finishing	
Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	

Summary	Completion Milestone
Client Task (Sec 1 & 2)	Client Task (Sec 1)
Contract Task (Sec 2)	Maintenance Period

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Not Started
 In Progress
 Completed
 Critical Path (C=1)
 Critical Path (C=2)
 Critical Path (C=3)
 Milestone Point
 Activity Float



Figure 4.1

Layout of Environmental Monitoring Stations



REV. : A
 DATE : 30 JUL 05
 SCALE : N.T.S.

FIGURE 4.1 LAYOUT OF ENVIRONMENTAL MONITORING STATIONS
 (WONG SHEK)

Lam Environmental Services
 Test Specialists and Environmental Analysts





Figure 5.1a-h

Graphical Plots of Water Quality Monitoring Results

Figure 5.1a - Dissolved Oxygen (Surface & Middle Averaged) - Mid-Flood
(Wong Shek)




Figure 5.1b - Dissolved Oxygen (Surface & Middle Averaged) - Mid-Ebb
(Wong Shek)




Figure 5.1c - Dissolved Oxygen (Bottom Averaged) - Mid-Flood
(Wong Shek)




Figure 5.1d - Dissolved Oxygen (Bottom Averaged) - Mid-Ebb
(Wong Shek)




Figure 5.1e - Turbidity (Depth Averaged) - Mid-Flood
(Wong Shek)




Figure 5.1f - Turbidity (Depth Averaged) - Mid-Ebb
(Wong Shek)




Figure 5.1g - Suspended Solids (Depth Averaged) - Mid-Flood
(Wong Shek)






Figure 5.1h - Suspended Solids (Depth Averaged) - Mid-Ebb
(Wong Shek)





Appendix A

Organization Chart





Appendix B

Implementation Schedule of Mitigation Measures



Implementation Schedule of Mitigation Measures – Wong Shek

Environmental Aspect	No.	Mitigation Measures	Implementation Status	Follow Up action(s)
Air Quality	AQ01	Provide a wash-pit or a wheel washing and/or vehicle cleaning facility at the exits.	Not applicable at this stage	-
	AQ02	Provide a hard surfaced road between the wheel washing facilities and any finished road.	Not applicable at this stage	-
	AQ03	No burning of construction wastes or vegetation shall be allowed on the Site.	Implemented	-
	AQ04	In the process of material handling, any material which has the potential to create dust shall be treated with water or sprayed with wetting agent.	Not applicable at this stage	-
	AQ05	Any vehicle with an open load carrying area used for moving materials which has the potential to create dust shall have properly fitting side and tail boards.	Not applicable at this stage	-
	AQ06	Materials having the potential to create dust shall not be loaded to a level higher than the side and tail boards, and shall be covered by a clean tarpaulin.	Implemented	-
	AQ07	Stockpiles of sand, aggregate and construction and demolition material greater than 20m ³ shall be enclosed on three sides, with walls extending above the pile and 2 meters beyond the front of the pile.	Not applicable at this stage	-
	AQ08	Water sprays shall be provided and used both to dampen stored materials and when receiving raw materials.	Not applicable at this stage	-
	AQ09	Clean and water the Site to minimize the fugitive dust emissions.	Implemented	-
	AQ10	Furnace, boiler or other plant or equipment or use any fuel that might in any circumstances produce smoke or any other air pollution should not be installed.	Implemented	-
Noise	N01	All plant and equipment to be used on Site are properly maintained in good operating condition and noisy construction activities shall be effectively sound-reduced by means of silencers, mufflers, acoustic linings or shields, acoustic sheds or screens or other means to avoid disturbance to any nearby noise sensitive receivers.	Implemented	-
	N02	No excavator mounted breaker shall be used within 125m from any nearby noise sensitive receivers. Use hydraulic concrete crusher whenever applicable.	Implemented	-
	N03	All construction works should stop on Sundays and General Holidays.	Implemented	-
Water Quality	WQ01	Water in wheel washing facilities shall be changed at frequent intervals and sediments shall be removed regularly.	Not applicable	-
	WQ02	The polluted water from the wheel washing facilities would not be discharged into all existing stream courses/drains and nearby waterbodies.	Not applicable	-
	WQ03	All existing stream courses and drains within, and adjacent to the Site should be kept free from any debris and any excavated materials arising from the Works	Implemented	-
	WQ04	Chemicals and concrete agitator washings should not be deposited in watercourses.	Implemented	-
	WQ05	The effluent shall comply with the standards stated in the "Technical Memorandum on Standards and Effluent discharges into Drainage and Sewerage Systems, Inland and Coastal Waters" for the appropriate Water Control Zone.	Implemented	-
	WQ06	No spoil or debris of any kind is allowed to be pushed, washed down, fall or be deposited on land or on the seabed adjacent to the Site.	Implemented	-
	WQ07	Maintain any existing site drainage system at all times including removal of solids in sand traps, manholes and stream beds.	Implemented	-
	WQ08	Material from any earthworks should not be washed into the drainage system.	Implemented	-
	WQ09	Silt curtain shall be provided during all demolition works and piling works with the Site.	Not applicable at this stage	-



Implementation Schedule of Mitigation Measures – Wong Shek

Environmental Aspect	No.	Mitigation Measures	Implementation Status	Follow Up action(s)
	WQ10	Silt curtain shall be formed from tough, abrasion-resistant permeable membranes suitable for the purpose, supported on floating booms in such a way as to ensure that the passage of turbid water to the surrounding water shall be restricted.	Not applicable at this stage	-
	WQ11	No dredging and spoil dumping shall be conducted.	Not applicable at this stage	-
Ecology	E01	Marker buoys shall be set up to indicate the location of the "Coral Exclusion Zone". All working vessels shall be restricted to encroach the "Coral Exclusion Zone"	Implemented	-
	E02	No overloading of the working barges during operation and no movement of the working barges, particularly close to the pier and shallow areas, during low tide should be allowed.	Not applicable at this stage	-
	E03	No coral shall be enclosed by the silt curtain.	Not applicable at this stage	-
Waste	W01	All excavated materials should be sorted to recover the inert portions for reuse on site or disposal to designated outlets.	Not applicable at this stage	-
	W02	All metals should be recovered on site for collection by recycling contractors.	Implemented	-
	W03	All cardboard and paper packaging should be recovered on site, properly stockpiled in dry condition and covered to prevent cross contamination by other C&D materials.	Implemented	-
	W04	All demolition debris from demolition works should be sorted to recover on site broken concrete, reinforcement bars, mechanical and electrical fittings as well as other building services fittings/materials that have established recycling outlets.	Implemented	-



Appendix C

Calibration Certificates for Monitoring Equipment

Record sheet for calibration of Water Sonde

Item Stock No : 7144 Date of Calibration : 1/11/2006 Procedure Used : IC 34
Temp.: 20 °C Operator : Bm Signature : [Signature]

A Temperature Check

Reference Equipment Used : Mercury-in- Glass thermometer Stock No.: C51

Reference Equipment reading : 23.0 °C Sonde reading 23.6 °C

Reference Equipment reading : 23.0 °C Sonde reading : 23.6 °C

(Note: Difference between the two readings to be <0.5°C.)

B DO (% Saturation) Calibration

To be performed in aerated clean sea water before use and checked after use. Difference should be less than 10%.

Laboratory Check

Zero DO check (prepared in clean sea water according to APHA 4500-O G, section 3a.)

probe reading 0.01 %

C Conductivity (Salinity Calibration)

Standards Used : 35 ppt , / ,

Check Standard : 35 ppt Readout Value : 34.24 ppt

Difference between readout value and actual value should be less than 3%.

D Conductivity Calibration

Standards Used : 1 , / , / (mS/cm) Bm
1/11/06

Check Standard : / Readout Value : / (mS/cm)

Difference between readout value and actual value should be less than 2%.

E Turbidity Calibration

Standards Used : / , / , / (NTU)

Check Standard : / Readout Value : / (NTU)

Difference between readout value and actual value should be less than 10% .

F pH check


Standard Used : pH 7.00 , pH 10.00 .

Buffer standard : pH 9.00

QC Check Standard : pH 9.182 . Readout Value : pH 9.15

Certified by: Linda
Section Manager

Date : 04/11/2016



1412 Honour Ind. Centre
6 Sun Yip St. Chai Wan
Hong Kong

CERTIFICATE OF CALIBRATION
IN - HOUSE

Date Of Issue : _____ Serial No : IC 42a / / EL

Item Being Calibrated : Turbidity Standards (Gelex) Date Of Calibration : 22/1/07
 Item Stock No : EL471 Operator : ming
 Environment Temp. °C : 25°C Procedure No Used : IC 42 (Revision No. 0)

Primary Standards used 20, 100 and 800 NTU Formazin standards prepared fresh.

Ref. Equip.used/ Stock No : G07R003, G06R003, G05R003

Gelex Standards	Last assigned value Date: (NTU)	New measured value (NTU)	Agreement %	Requirement %
0 - 10 NTU	45	46.5	3%	± 5
10 - 100 NTU	48	49.1	2%	± 5
100 - 1000 NTU	482	463	4%	± 5

Comments : *The equipment and Gelex Standards complies / does not comply with the Manufacturer's recommendation.*

Input data checked by : _____

Certified by: _____
Operations Manager



1412 Honour Ind. Centre
6 Sun Yip St. Chai Wan
Hong Kong

CERTIFICATE OF CALIBRATION

IN - HOUSE

Date Of Issue : _____ Serial No : IC 42b / /EL

Item Being Calibrated : **Turbidity Standards (Gelex)** Date Of Calibration : 22/1/07
 Item Stock No : EL 41 Operator : ly
 Environment Temp. °C : 25°C Procedure No Used : IC 42 (Revision No. 0)
 Primary Standards use 20, 100 and 800 NTU Formazin standards prepared fresh.
 Ref. Equip.used/ Stock No : _____

Gelex Standards	Turbidity of standard solution used (NTU)	Measured Value (NTU)	R ²	Requirement R ²
0 - 10 NTU	1	0.9	0.9999	> 0.996
	5	5.4		
	10	11.2		
10 - 100 NTU	20	20.6	0.9963	> 0.996
	50	54		
	80	81		
100 - 1000 NTU	100	102	0.9978	> 0.996
	400	394		
	800	802		

Comments : *The equipment and Gelex Standards complies / does not comply with the Manufacturer's recommendation.*

Input data checked by : ly Certified by: [Signature]
Operations Manager



Appendix D

Water Quality Monitoring Results

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 9/3/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 29

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average		
MW1 S	9:20	small wave	4	1	28.3	28.3	7.13	7.13	7.13	109.3	109.3	109.3	34.4	34.4	1.15	1.24	1.14	16		11.7	
MW1 M	9:23																				
MW1 B	9:26			3	28.0	28.0	6.73	6.72	6.73	99.7	99.8	99.8	34.6	34.6	1.10	1.06		7.4			
MW2 S	9:00	small wave	10	1	28.4	28.4	7.04	7.04	6.70	106.4	106.4	100.7	34.5	34.5	1.26	1.33	1.20	11		9.0	
MW2 M	9:03			5	28.1	28.1	6.33	6.40		94.8	95.1		34.7	34.7	1.17	1.20			<5.0		
MW2 B	9:06			9	27.7	27.7	5.93	5.96	5.95	90.4	90.3	90.4	34.9	34.9	1.08	1.15			7.0		
CW1 S	9:30	small wave	3						6.80			100.6					1.18			16.0	
CW1 M	9:33			1.5	28.0	28.0	6.80	6.80		100.6	100.5		34.6	34.6	1.19	1.17			16		
CW1 B	9:36																				
CW2 S	9:10	small wave	13	1	28.2	28.2	6.98	7.00	6.61	101.0	101.1	98.0	34.6	34.6	0.95	1.34	1.10	<5.0	6.2	7.8	
CW2 M	9:13			6.5	28.0	28.0	6.23	6.24		95.0	95.0		34.7	34.7	1.27	1.05			9.8		<5.0
CW2 B	9:16			12	27.7	27.7	5.94	5.98	5.96	88.3	88.6	88.5	34.8	34.8	1.18	0.83			9.4		5.6

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 9.7 NTU: 9.7 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 16/3/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 9/3/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 29

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average			
MW1 S	15:20	small wave	4	1	28.2	28.2	7.02	7.04	7.03	110.3	110.2	110.3	34.5	34.5	1.22	1.27	1.17	7.0		7.7		
MW1 M	15:23																					
MW1 B	15:26			3	28.0	28.0	6.83	6.83	6.83	100.6	100.6	100.6	34.6	34.6	1.13	1.04			8.4			
MW2 S	15:00	small wave	10	1	28.3	28.3	7.00	6.95	6.67	104.3	104.0	100.7	34.4	34.4	1.02	1.17	1.11	7.2		6.9		
MW2 M	15:03			5	28.0	28.0	6.34	6.40		97.4	97.0		34.6	34.6	1.30	1.10			<5.0			
MW2 B	15:06			9	27.8	27.8	6.11	6.10	6.11	94.0	94.0	94.0	34.8	34.7	1.07	1.00			6.6			
CW1 S	15:30	small wave	3						7.10			108.4					1.23			9.4		
CW1 M	15:33			1.5	28.1	28.2	7.10	7.10		108.3	108.4		34.6	34.6	1.13	1.33			9.4			
CW1 B	15:36																					
CW2 S	15:10	small wave	12	1	28.2	28.2	6.95	6.92	6.67	103.0	102.7	99.9	34.5	34.5	1.06	1.17	1.22	10	9.2	12.5		
CW2 M	15:13			6	27.9	27.9	6.40	6.40		97.0	97.0		34.7	34.7	1.44	1.20			16		11	
CW2 B	15:16			11	27.7	27.7	5.83	5.83	5.83	90.4	90.3	90.4	34.9	34.8	1.30	1.15			12		17	

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 9.7 NTU: 9.7 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 16/3/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 16/3/2007

 Weather Condition: rainy

 Ambient Temperature, °C: 27

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average			Depth Average
MW1 S	15:05	small wave	4	1	26.6	26.6	6.73	6.73	6.73	104.2	104.1	104.2	34.6	34.6	1.16	1.23	1.13	29		18.5	
MW1 M	15:08																				
MW1 B	15:11			3	26.4	26.4	6.46	6.46	6.46	96.4	96.4	96.4	34.8	34.8	1.06	1.08			8.0		
MW2 S	14:45	small wave	10	1	26.5	26.5	6.90	6.90	6.76	110.6	110.6	104.3	34.5	34.5	0.95	0.90	1.09	8.4		8.6	
MW2 M	14:48			5	26.3	26.2	6.63	6.62		98.0	98.0		34.7	34.7	1.09	1.13			6.4		
MW2 B	14:51			9	26.0	26.0	6.38	6.38	6.38	93.6	94.0	93.8	34.9	34.9	1.19	1.30			11		
CW1 S	15:15	small wave	3						6.76			99.3					1.17			<5.0	
CW1 M	15:18			1.5	26.4	26.4	6.76	6.76		99.3	99.3		34.8	34.7	1.22	1.11			<5.0		
CW1 B	15:21																				
CW2 S	14:55	small wave	13	1	26.5	26.5	6.83	6.88	6.52	101.6	102.1	97.3	34.6	34.6	1.06	1.11	1.15	7.4	7.2	7.7	
CW2 M	14:58			6.5	26.3	26.3	6.18	6.19		92.6	93.0		34.8	34.8	1.30	1.37			8.0		7.8
CW2 B	15:01			12	25.9	25.9	5.99	6.01	6.00	90.3	90.3	90.3	34.9	34.9	1.10	0.98			7.8		7.8

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.4 ppt: 35.4 Date: 23/3/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 16/3/2007

 Weather Condition: rainy

 Ambient Temperature, °C: 27

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average			Depth Average
MW1 S	10:40	small wave	4	1	26.6	26.6	6.88	6.91	6.90	97.4	97.4	97.4	34.5	34.5	1.36	1.20	1.18	6.6		8.8	
MW1 M	10:43																				
MW1 B	10:46			1.5	26.5	26.5	6.63	6.62	6.63	93.1	93.1	93.1	34.7	34.7	1.04	1.10			11		
MW2 S	10:20	small wave	9	1	26.6	26.6	7.03	7.05	6.83	101.0	100.7	96.6	34.6	34.6	1.13	1.05	1.14	6.0		7.5	
MW2 M	10:23			4.5	26.4	26.4	6.62	6.60		92.3	92.4		34.6	34.6	1.26	1.31			8.6		
MW2 B	10:26			8	26.3	26.3	6.28	6.28	6.28	88.4	88.4	88.4	34.7	34.7	1.00	1.09			7.8		
CW1 S	10:50	small wave	3						6.73			95.4					1.21			7.2	
CW1 M	10:53			1.5	26.5	26.5	6.73	6.73		95.3	95.4		34.6	34.6	1.27	1.15			7.2		
CW1 B	10:56																				
CW2 S	10:30	small wave	11	1	26.5	26.5	6.90	6.90	6.68	99.9	99.9	96.6	34.5	34.5	1.03	1.07	1.14	<5.0	<5.0	6.4	
CW2 M	10:33			5.5	26.2	26.2	6.45	6.46		93.4	93.3		34.6	34.7	0.96	1.18			6.0		6.4
CW2 B	10:36			10	25.9	25.9	6.20	6.20	6.20	89.3	89.3	89.3	34.6	34.6	1.30	1.32			6.6		6.6

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.4 ppt: 35.4 Date: 23/3/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 19/3/2007

 Weather Condition: cloudy

 Ambient Temperature, °C: 27

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average		
MW1 S	9:25	small wave	4	1	25.4	25.4	7.13	7.13	7.13	116.3	116.1	116.2	35.1	35.1	1.16	1.29	1.06	10		11.5	
MW1 M	9:28																				
MW1 B	9:31			3	25.2	25.2	6.34	6.34	6.34	102.4	102.3	102.4	35.3	35.3	0.83	0.95		13			
MW2 S	9:05	small wave	9	1	25.3	25.3	7.05	7.00	6.78	110.7	110.7	109.0	34.9	34.9	1.05	1.21	1.21	10		12.0	
MW2 M	9:08			4.5	25.0	25.0	6.53	6.53		107.2	107.2		35.1	35.1	1.36	1.40		14			
MW2 B	9:11			8	24.9	24.8	6.03	6.00	6.02	94.4	94.3	94.4	35.2	35.2	1.15	1.10		12			
CW1 S	9:35	small wave	3						6.44			93.1					1.26			9.8	
CW1 M	9:38			1.5	25.3	25.3	6.44	6.44		93.2	93.0		35.0	35.0	1.28	1.24		10			
CW1 B	9:41																				
CW2 S	9:15	small wave	12	1	25.2	25.2	6.93	6.88	6.52	103.3	103.3	99.9	34.8	34.9	1.19	1.33	1.13	12	13	10.5	
CW2 M	9:18			6	24.9	24.9	6.14	6.12		96.4	96.4		35.1	35.1	1.06	1.11		12	12		
CW2 B	9:21			11	24.7	24.7	5.74	5.70	5.72	89.9	90.0	90.0	35.4	35.4	0.92	1.18		7.2	6.8		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 9.9 NTU: 9.9 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35 ppt: 35 Date: 26/3/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 19/3/2007

 Weather Condition: cloudy

 Ambient Temperature, °C: 27

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average		
MW1 S	14:50	small wave	4	1	25.2	25.2	6.98	6.98	6.98	106.5	106.5	106.5	35.0	35.1	1.25	1.19	1.16	12		10.6	
MW1 M	14:53																				
MW1 B	14:56			3	25.0	25.0	6.04	6.03	6.04	97.2	97.2	97.2	35.2	35.2	1.17	1.02		9.2			
MW2 S	14:30	small wave	8	1	25.2	25.2	6.73	6.73	6.58	100.8	100.8	98.0	35.1	35.1	0.88	0.80	1.05	8.8		10.3	
MW2 M	14:33			4	25.0	25.0	6.42	6.42		95.2	95.3		35.3	35.3	1.15	1.36		10			
MW2 B	14:36			7	24.8	24.8	5.97	5.99	5.98	88.3	88.4	88.4	35.5	35.5	1.08	1.03		12			
CW1 S	15:00	small wave	3						7.07			110.5					1.29			13.0	
CW1 M	15:03			1.5	25.0	25.1	7.06	7.07		110.6	110.4		35.1	35.1	1.37	1.20		13			
CW1 B	15:06																				
CW2 S	14:40	small wave	10	1	25.3	25.3	7.19	7.19	6.79	109.3	109.0	101.4	35.2	35.2	1.10	1.18	1.12	20	24	19.0	
CW2 M	14:43			5	25.1	25.1	6.38	6.38		93.7	93.7		35.4	35.4	1.25	1.22		21	17		
CW2 B	14:46			9	24.8	24.8	5.80	5.80	5.80	85.6	85.6	85.6	35.6	35.6	1.06	0.92		15	17		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 9.9 NTU: 9.9 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35 ppt: 35 Date: 26/3/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 21/3/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 23

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average			Depth Average	
MW1 S	12:20	small wave	4	1	21.6	21.6	7.62	7.62	7.62	113.4	113.4	113.4	34.9	34.9	1.16	1.05	1.18	6.4		6.4		
MW1 M	12:23																					
MW1 B	12:26			3	21.3	21.3	7.60	7.55	7.58	110.6	110.6	110.6	35.1	35.0	1.34	1.18			<5.0			
MW2 S	12:00	small wave	10	1	21.5	21.5	7.38	7.38	7.22	117.9	117.4	111.0	34.6	34.6	1.26	1.20	1.16	<5.0		<5.0		
MW2 M	12:03			5	21.2	21.2	7.06	7.06		104.3	104.2		34.8	34.8	1.07	1.14			<5.0			
MW2 B	12:06			9	21.0	21.0	7.03	6.94	6.99	100.8	100.9	100.9	35.0	35.0	1.15	1.15			<5.0			
CW1 S	12:30	small wave	3						6.93			100.7					1.03	<5.0		<5.0		
CW1 M	12:33			1.5	21.3	21.3	6.94	6.91		100.7	100.6		35.0	35.0	1.06	1.00			<5.0			
CW1 B	12:36																					
CW2 S	12:10	small wave	13	1	21.4	21.4	7.07	7.07	6.95	106.6	106.6	102.7	34.7	34.7	1.07	1.20	1.11	<5.0	<5.0	<5.0		
CW2 M	12:13			6.5	21.0	21.0	6.84	6.83		98.7	98.7		34.9	34.9	1.15	1.13			<5.0	<5.0		
CW2 B	12:16			12	20.9	20.9	6.71	6.70	6.71	97.4	97.4	97.4	35.0	35.0	1.02	1.09			<5.0	<5.0		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.3 NTU: 10.3 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 28/3/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 21/3/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 23

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average			Depth Average	
MW1 S	17:40	small wave	4	1	21.4	21.4	7.34	7.34	7.34	114.0	114.0	114.0	34.7	34.7	0.94	1.08	1.13	<5.0		<5.0		
MW1 M	17:43																					
MW1 B	17:46			3	21.2	21.2	7.16	7.16	7.16	108.3	108.3	108.3	34.8	34.8	1.22	1.26			<5.0			
MW2 S	17:20	small wave	9	1	21.5	21.6	7.19	7.19	7.13	107.5	107.4	103.5	34.6	34.6	1.16	1.17	1.18	<5.0		<5.0		
MW2 M	17:23			4.5	21.3	21.3	7.06	7.06		99.3	99.7		34.9	34.9	1.02	1.11			<5.0			
MW2 B	17:26			8	21.3	21.2	6.93	6.93	6.93	91.6	91.6	91.6	35.0	35.0	1.34	1.30			<5.0			
CW1 S	17:50	small wave	3						7.08			102.2					1.17	<5.0		<5.0		
CW1 M	17:53			1.5	21.4	21.4	7.08	7.08		102.2	102.3		34.9	34.8	1.08	1.25			<5.0			
CW1 B	17:56																					
CW2 S	17:30	small wave	11	1	21.3	21.3	7.20	7.20	7.09	110.4	110.1	107.7	34.7	34.7	1.20	1.25	1.14	<5.0	<5.0	<5.0		
CW2 M	17:33			5	21.1	21.0	6.97	6.97		105.1	105.0		34.9	34.9	1.08	1.13			<5.0	<5.0		
CW2 B	17:36			9	20.8	20.8	6.90	6.90	6.90	105.0	104.8	104.9	35.0	35.0	1.04	1.15			<5.0	<5.0		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.3 NTU: 10.3 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 28/3/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 23/3/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 26

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average		
MW1 S	9:20	small wave	5	1	24.6	24.6	6.62	6.65	6.64	104.4	104.4	104.4	34.6	34.6	1.44	1.18	1.16	<5.0			
MW1 M	9:23																				<5.0
MW1 B	9:26			4	24.4	24.4	6.15	6.08	6.12	97.7	97.6	97.7	34.6	34.6	1.06	0.95					
MW2 S	9:00	small wave	10	1	24.7	24.8	6.88	6.89	6.61	105.8	105.9	102.1	34.4	34.4	1.18	1.23	1.14	<5.0			
MW2 M	9:03			5	24.6	24.6	6.32	6.33		98.2	98.3		34.6	34.6	1.04	1.23		9.8		9.8	
MW2 B	9:06			9	24.4	24.5	5.97	5.95	5.96	88.7	89.7	89.2	34.6	34.6	1.15	1.00		<5.0			
CW1 S	9:30	small wave	3					6.36									1.10				
CW1 M	9:33			1.5	24.6	24.6	6.36	6.36		99.5	99.5		34.5	34.6	1.02	1.18		<5.0		<5.0	
CW1 B	9:36																				
CW2 S	9:10	small wave	13	1	24.7	24.7	6.77	6.78	6.50	100.8	100.9	98.6	34.5	34.4	1.14	1.18	1.17	<5.0	<5.0		
CW2 M	9:13			6.5	24.5	24.5	6.22	6.22		96.4	96.4		34.7	34.6	1.33	1.33		<5.0	<5.0	<5.0	
CW2 B	9:16			12	24.1	24.1	5.88	5.87	5.88	88.8	89.2	89.0	34.7	34.7	1.07	0.94		<5.0	<5.0		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.5 NTU: 10.5 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.1 ppt: 35.1 Date: 30/3/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 23/3/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 26

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average		
MW1 S	15:20	small wave	5	1	24.8	24.8	7.03	7.03	7.03	104.4	104.3	104.4	34.6	34.6	1.30	1.19	1.15	<5.0			
MW1 M	15:23																				<5.0
MW1 B	15:26			4	24.6	24.6	6.70	6.70	6.70	95.8	95.8	95.8	34.7	34.7	1.03	1.06		<5.0			
MW2 S	15:00	small wave	10	1	24.7	24.7	6.94	6.94	6.74	101.3	101.4	97.4	34.4	34.4	1.14	1.05	1.07	<5.0			
MW2 M	15:03			5	24.5	24.5	6.54	6.54		93.4	93.5		34.6	34.6	0.94	1.00		<5.0		<5.0	
MW2 B	15:06			9	24.3	24.4	6.23	6.22	6.23	90.2	90.2	90.2	34.6	34.6	1.20	1.07		<5.0			
CW1 S	15:30	small wave	3					6.88									1.22				
CW1 M	15:33			1.5	24.6	24.6	6.88	6.88		99.7	99.7		34.6	34.6	1.16	1.27		5.4		5.4	
CW1 B	15:36																				
CW2 S	15:10	small wave	11	1	24.6	24.6	6.90	6.85	6.64	102.4	102.3	99.8	34.4	34.4	1.06	1.13	1.18	<5.0	11		
CW2 M	15:13			5.5	24.4	24.4	6.40	6.40		97.2	97.2		34.5	34.5	1.13	1.28		5.6	<5.0	8.3	
CW2 B	15:16			10	24.4	24.3	5.83	5.83	5.83	90.3	90.0	90.2	34.6	34.6	1.18	1.30		<5.0	<5.0		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.5 NTU: 10.5 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.1 ppt: 35.1 Date: 30/3/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 30/3/2007

 Weather Condition: cloudy

 Ambient Temperature, °C: 19

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average	Depth Average	
MW1 S	15:05	small wave	5	1	19.1	19.1	5.16	5.16	5.16	81.6	81.7	81.7	34.8	34.8	1.17	1.11	1.13	<5.0		
MW1 M	15:08			4	18.8	18.8	4.38	4.38	4.38	73.4	73.0	73.2	34.8	34.8	1.20	1.04		<5.0		
MW1 B	15:11																			
MW2 S	14:45	small wave	10	1	18.6	18.6	4.86	4.82	4.46	78.4	78.3	74.2	34.7	34.7	1.05	1.30	1.13	<5.0		
MW2 M	14:48			5	18.4	18.4	4.07	4.07		70.1	70.1		34.8	34.8	1.17	1.06		<5.0		
MW2 B	14:51			9	18.3	18.3	3.66	3.66	3.66	66.4	66.4	66.4	34.9	34.9	0.97	1.20		<5.0		
CW1 S	15:15	small wave	3						4.41			71.7					1.13	<5.0		
CW1 M	15:18			1.5	18.7	18.7	4.41	4.41		71.7	71.7		34.9	34.9	1.12	1.14		<5.0		
CW1 B	15:21																			
CW2 S	14:55	small wave	12	1	18.6	18.6	5.10	5.07	4.80	79.6	79.6	76.4	34.8	34.8	1.20	1.03	1.14	<5.0	7.2	
CW2 M	14:58			6	18.3	18.3	4.53	4.50		73.1	73.1		34.9	34.9	0.80	1.02		<5.0	<5.0	7.2
CW2 B	15:01			11	18.3	18.3	3.74	3.70	3.72	68.6	68.5	68.6	35.0	35.1	1.37	1.40		<5.0	<5.0	

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 6/4/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 30/3/2007

 Weather Condition: cloudy

 Ambient Temperature, °C: 19

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average	Depth Average	
MW1 S	10:40	small wave	4	1	18.4	18.4	5.34	5.30	5.32	82.8	82.7	82.8	34.7	34.8	1.18	1.27	1.21	<5.0		
MW1 M	10:43			7	18.4	18.4	4.91	4.90	4.91	78.8	78.9	78.9	34.9	34.9	1.29	1.10		<5.0		
MW1 B	10:46																			
MW2 S	10:20	small wave	10	1	18.3	18.3	5.08	5.09	4.86	80.3	80.4	77.9	34.8	34.8	1.04	1.01	1.07	5.4		
MW2 M	10:23			5	18.3	18.3	4.63	4.62		75.6	75.4		34.9	34.9	0.88	1.14		9.2		7.3
MW2 B	10:26			9	18.2	18.2	3.97	3.96	3.97	67.9	68.0	68.0	35.0	35.0	1.18	1.17		<5.0		
CW1 S	10:50	small wave	3						4.51			74.3					1.30			
CW1 M	10:53			1.5	18.3	18.3	4.51	4.50		74.3	74.3		34.9	34.9	1.34	1.26		5.6		5.6
CW1 B	10:56																			
CW2 S	10:30	small wave	11	1	18.3	18.3	4.97	4.95	4.57	81.3	81.3	77.7	34.9	34.9	0.95	1.03	1.12	<5.0	5.8	
CW2 M	10:33			5.5	18.2	18.2	4.18	4.17		74.0	74.0		35.0	35.0	1.17	1.11		<5.0	5.4	5.5
CW2 B	10:36			10	18.0	18.0	3.66	3.64	3.65	67.9	68.3	68.1	35.1	35.1	1.06	1.38		<5.0	5.4	

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 6/4/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 4/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 26

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average			
MW1 S	7:50	small wave	5	1	26.1	26.1	6.30	6.30	6.30	98.9	98.9	98.9	34.6	34.6	1.16	1.34	1.15	8.0		8.0		
MW1 M	7:53																					
MW1 B	7:56			4	26.0	26.0	6.04	6.04	6.04	95.1	95.1	95.1	34.8	34.8	1.04	1.05			8.0			
MW2 S	7:30	small wave	10	1	25.9	26.0	6.52	6.53	6.22	97.4	97.5	95.0	34.5	34.5	1.28	1.16	1.11	<5.0				
MW2 M	7:33			5	25.8	25.8	5.90	5.93		92.6	92.6		34.7	34.7	1.13	1.16			7.0		7.0	
MW2 B	7:36			9	25.7	25.7	5.72	5.70	5.71	89.4	89.4	89.4	34.9	34.9	0.94	0.99			7.0			
CW1 S	8:00	small wave	3					6.02									1.20					
CW1 M	8:03			1.5	25.8	25.8	6.03	6.01		91.7	91.4	91.6	34.7	34.8	1.24	1.16			<5.0		<5.0	
CW1 B	8:06																					
CW2 S	7:40	small wave	12	1	26.0	26.0	6.48	6.48	6.17	96.8	96.6	93.7	34.6	34.6	1.15	1.25	1.14	5.0	7.0			
CW2 M	7:43			6	25.7	25.7	5.86	5.86		90.7	90.6		34.7	34.7	1.06	1.15			<5.0	<5.0	5.9	
CW2 B	7:46			11	25.7	25.7	5.61	5.60	5.61	87.4	87.4	87.4	34.8	34.8	1.03	1.18			5.8	5.6		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 11/4/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 4/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 26

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average			
MW1 S	13:50	small wave	4	1	26.4	26.4	6.56	6.55	6.56	101.3	101.5	101.4	34.5	34.5	1.09	1.20	1.18	7.6				
MW1 M	13:53																					
MW1 B	13:56			3	26.2	26.3	6.24	6.24	6.24	96.7	97.0	96.9	34.6	34.6	1.17	1.25			6.0			
MW2 S	13:30	small wave	9	1	26.3	26.3	7.06	6.87	6.70	109.5	109.5	103.7	34.5	34.5	1.41	1.34	1.14	8.8				
MW2 M	13:33			4.5	26.1	26.1	6.43	6.43		97.8	97.9		34.6	34.6	1.08	1.04			8.8		8.6	
MW2 B	13:36			8	25.9	25.9	6.15	6.14	6.15	93.8	93.7	93.8	34.7	34.7	0.85	1.09			8.2			
CW1 S	14:00	small wave	3					6.68									1.19					
CW1 M	14:03			1.5	26.3	26.3	6.68	6.68		99.4	99.4	99.4	34.6	34.5	1.15	1.23			8.4		8.4	
CW1 B	14:06																					
CW2 S	13:40	small wave	11	1	26.2	26.2	6.94	6.93	6.70	106.6	106.6	102.5	34.5	34.5	1.26	1.20	1.12	<5.0	5.4			
CW2 M	13:43			5.5	26.0	26.0	6.48	6.45		98.5	98.3		34.6	34.6	1.18	1.04			<5.0	5.0	5.7	
CW2 B	13:46			10	25.9	25.9	6.05	6.05	6.05	93.2	93.2	93.2	34.7	34.7	1.04	1.00			<5.0	6.8		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 11/4/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 11/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 29

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C			Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks
					a	b		a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average	
MW1 S	8:20	small wave	5	1	26.8	26.8	6.18	6.18	6.18	85.8	85.7	85.8	34.2	34.2	1.22	1.09	1.14	26.0		17.3	
MW1 M	8:23																				
MW1 B	8:26			4	26.6	26.6	6.04	6.04	6.04	83.3	83.3	83.3	34.3	34.3	1.11	1.15		8.6			
MW2 S	8:00	small wave	10	1	26.6	26.6	6.10	6.10	5.92	86.1	86.4	84.7	34.2	34.2	1.14	1.22	1.14	6.6		7.3	
MW2 M	8:03			5	26.4	26.4	5.74	5.74		83.2	83.2		34.4	34.4	1.17	1.19		10.0			
MW2 B	8:06			9	26.3	26.3	5.40	5.39	5.40	80.2	80.0	80.1	34.4	34.4	1.08	1.06		5.2			
CW1 S	8:30	small wave	3						6.02			86.6				0.92			<5.0		
CW1 M	8:33			1.5	26.6	26.6	6.02	6.02		86.6	86.6		34.3	34.3	0.94		0.89	<5.0		<5.0	
CW1 B	8:36																				
CW2 S	8:10	small wave	11	1	26.6	26.6	5.98	5.97	5.79	86.4	86.4	84.4	34.1	34.1	1.17	1.28	1.11	8.8	<5.0	7.2	
CW2 M	8:13			5.5	26.4	26.4	5.61	5.61		82.3	82.3		34.3	34.3	1.04	1.13		6.6	6.4		
CW2 B	8:16			10	26.2	26.2	5.34	5.34	5.34	79.0	79.1	79.1	34.5	34.5	1.02	1.00		6.0	8.2		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.1 NTU: 10.1 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 18/4/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 11/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 19

 Tide State: No Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C			Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks
					a	b		a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average	
MW1 S																					
MW1 M																					
MW1 B																					
MW2 S																					
MW2 M																					
MW2 B																					
CW1 S																					
CW1 M																					
CW1 B																					
CW2 S																					
CW2 M																					
CW2 B																					

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 18/4/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 13/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 26

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average			
MW1 S	14:40	small wave	5	1	25.8	25.8	6.55	6.54	6.55	106.3	106.0	106.2	34.5	34.5	1.15	1.04	1.12	14.0		14.0		
MW1 M	14:43																					
MW1 B	14:46			4	25.7	25.7	6.03	6.04	6.04	99.7	99.9	99.8	34.7	34.6	1.20	1.08			<5.0			
MW2 S	15:00	small wave	11	1	25.9	25.9	6.34	6.30	6.09	102.0	101.8	99.2	34.4	34.4	1.28	1.30	1.16	5.2		5.7		
MW2 M	15:03			5.5	25.5	25.5	5.86	5.86		96.4	96.4		34.6	34.6	1.04	1.10			<5.0			
MW2 B	15:06			10	25.5	25.5	5.40	5.40	5.40	91.0	91.0	91.0	34.8	34.8	1.08	1.15			6.2			
CW1 S	15:10	small wave	3						6.28			100.8					1.14			<5.0	<5.0	
CW1 M	15:13			1.5	25.6	25.6	6.28	6.28		100.8	100.8		34.6	34.5	1.08	1.19						
CW1 B	15:16																					
CW2 S	14:50	small wave	13	1	25.8	25.8	6.19	6.20	5.93	99.9	99.6	96.4	34.5	34.5	1.30	1.24	1.16	7.4	5.4	6.4		
CW2 M	14:53			6.5	25.6	25.6	5.67	5.67		93.0	93.0		34.6	34.6	1.03	1.11			<5.0	<5.0		
CW2 B	14:56			12	25.5	25.5	5.30	5.30	5.30	88.4	88.4	88.4	34.9	34.9	1.07	1.18			<5.0	<5.0		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.7 NTU: 10.7 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.2 ppt: 35.2 Date: 20/4/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 13/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 26

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks		
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average		Depth Average			
MW1 S	10:10	small wave	4	1	25.7	25.7	6.74	6.77	6.76	108.4	108.5	108.5	34.4	34.4	1.13	1.06	1.13	5.4		6.2		
MW1 M	10:13																					
MW1 B	10:16			3	25.7	25.7	6.34	6.34	6.34	101.3	101.3	101.3	34.5	34.5	1.20	1.13			7.0			
MW2 S	9:50	small wave	10	1	25.8	25.8	6.65	6.60	6.36	106.3	106.2	102.6	34.5	34.5	1.07	1.14	1.18	9.0		8.5		
MW2 M	9:53			5	25.6	25.6	6.10	6.07		98.9	98.9		34.6	34.6	1.25	1.20			9.2			
MW2 B	9:56			9	25.5	25.5	5.43	5.51	5.47	89.4	89.8	89.6	34.7	34.7	1.18	1.21			7.4			
CW1 S	10:20	small wave	3						6.20			100.9					1.14			<5.0	<5.0	
CW1 M	10:23			1.5	25.6	25.6	6.20	6.20		101.0	100.7		34.6	34.6	1.08	1.19						
CW1 B	10:26																					
CW2 S	10:00	small wave	11	1	25.7	25.7	6.40	6.38	6.16	100.3	100.4	98.4	34.6	34.6	1.24	1.30	1.13	6.2	<5.0	7.6		
CW2 M	10:03			5.5	25.5	25.5	5.94	5.93		96.4	96.4		34.6	34.6	1.14	1.11			5.6	<5.0		
CW2 B	10:06			10	25.5	25.5	5.34	5.36	5.35	89.0	89.0	89.0	34.8	34.8	1.06	0.95			<5.0	11.0		

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.7 NTU: 10.7 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.2 ppt: 35.2 Date: 20/4/2007

 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Wong Shek)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 16/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 30

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average			Depth Average
MW1 S	16:28	small wave	5	1	27.4	27.4	5.66	5.66	5.66	89.5	89.5	89.5	34.3	34.3	2.08	1.86	1.95	<5.0			
MW1 M	16:31																				
MW1 B	16:34			4	27.1	27.1	4.95	4.95	4.95	82.2	82.2	82.2	34.5	34.5	1.95	1.90			<5.0		
MW2 S	16:08	small wave	11	1	27.5	27.5	5.74	5.74	5.43	91.4	91.4	87.4	34.5	34.5	1.76	1.76	1.78	<5.0			
MW2 M	16:11			5.5	27.3	27.3	5.11	5.11		83.3	83.3		34.5	34.6	1.85	1.89			6.4		
MW2 B	16:14			10	27.2	27.2	4.54	4.54	4.54	76.6	76.4	76.5	34.7	34.7	1.70	1.74			<5.0		
CW1 S	16:38	small wave	3						5.06			85.9					1.83				
CW1 M	16:41			1.5	27.4	27.4	5.05	5.06		85.8	86.0		34.4	34.3	1.77	1.88			5.4		
CW1 B	16:44																				
CW2 S	16:18	small wave	13	1	27.5	27.5	5.57	5.56	5.20	90.4	90.4	87.2	34.4	34.4	2.04	2.11	1.85	5.4	10		
CW2 M	16:21			6.5	27.2	27.2	4.83	4.85		84.0	84.0		34.5	34.5	1.80	1.77			<5.0	7.0	
CW2 B	16:24			12	27.0	27.0	4.30	4.30	4.30	80.2	80.3	80.3	34.7	34.7	1.65	1.74			<5.0	5.6	

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.6 NTU: 10.6 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35 ppt: 35 Date: 23/4/2007

 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 16/4/2007

 Weather Condition: sunny

 Ambient Temperature, °C: 30

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU			Suspended Solids, mg/L		Remarks	
					a	b	a	b	Average	a	b	Average	a	b	Average	a	b	Average			Depth Average
MW1 S	11:25	small wave	4	1	27.3	27.3	5.43	5.43	5.43	87.7	87.7	87.7	34.4	34.4	1.66	1.70	1.76	<5.0			
MW1 M	11:28																				
MW1 B	11:31			3	27.1	27.1	5.04	5.05	5.05	83.1	83.1	83.1	34.5	34.5	1.85	1.83			5.4		
MW2 S	11:05	small wave	10	1	27.5	27.5	5.60	5.60	5.32	90.4	90.5	88.0	34.4	34.4	1.75	1.76	1.80	7.6			
MW2 M	11:08			5	27.3	27.3	5.04	5.05		85.6	85.4		34.5	34.5	2.04	2.01			7.2		
MW2 B	11:11			9	27.1	27.1	4.73	4.73	4.73	81.1	81.1	81.1	34.6	34.6	1.65	1.58			7.8		
CW1 S	11:35	small wave	3						5.11			86.4					2.00				
CW1 M	11:38			1.5	27.3	27.3	5.10	5.11		86.4	86.4		34.4	34.4	1.95	2.05			6.4		
CW1 B	11:41																				
CW2 S	11:15	small wave	12	1	27.4	27.4	5.18	5.19	4.92	86.1	86.2	83.7	34.3	34.3	2.09	2.18	1.92	7.4	12		
CW2 M	11:18			6	27.2	27.2	4.67	4.65		81.2	81.2		34.5	34.5	1.76	1.83			8.6	5.8	
CW2 B	11:21			11	27.1	27.1	4.30	4.30	4.30	77.6	77.6	77.6	34.7	34.7	1.86	1.80			9.0	8.8	

 Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100% Sampled By: Cheng Yi

 Turbidity Meter: EM 2365 Calibration Check: 10.6 NTU: 10.6 Checked By: Raymond Dai

 Salinity Meter: EM 6167 Calibration Check: 35.0 ppt: 35.0 Date: 23/4/2007

 Thermometer: EM 6167



Appendix E

Monitoring Schedule - Upcoming month


CEDD Construction No. CV/2004/02
Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Water Quality Monitoring Schedule - Post-project
April - May 2007

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
15-Apr	16-Apr	17-Apr	18-Apr	19-Apr	20-Apr	21-Apr
			*WQM ³ (Ebb: 13:03) (Flood: 19:19)		*WQM ³ (Ebb: 14:32) (Flood: 07:53)	
22-Apr	23-Apr	24-Apr	25-Apr	26-Apr	27-Apr	28-Apr
	*WQM ³ (Ebb: 17:24) (Flood: 12:40)		*WQM ³ (Ebb: 19:42) No mid-flood tides		*WQM ³ (Ebb: 09:38) (Flood: 15:02)	
29-Apr	30-Apr	1-May	2-May	3-May	4-May	5-May
	Boat repair	Public Holiday	[Post-project] *WQM ³ (Ebb: 12:32) (Flood: 06:06)		[Post-project] *WQM ³ (Ebb: 12:06) (Flood: 20:06)	
6-May	7-May	8-May	9-May	10-May	11-May	12-May
	[Post-project] *WQM ³ (Ebb: 14:02) (Flood: 06:15)		[Post-project] *WQM ³ (Ebb: 10:29) No mid-flood tides		[Post-project] *WQM ³ (Ebb: 19:34) (Flood: 12:29)	
13-May	14-May	15-May	16-May	17-May	18-May	19-May
	[Post-project] *WQM ³ (Ebb: 10:19) (Flood: 16:27)		[Post-project] *WQM ³ (Ebb: 11:56) (Flood: 18:19)			

Notes:

1. WQM - water quality monitoring on mid-flood and mid-ebb tides at Wong Shek (CW1, CW2, MW1 & MW2)
 2. WQM - water quality monitoring on mid-flood and mid-ebb tides at Ko Lau Wan (CK1, CK2, MK1, MK2, MK3 & MK4)
 3. WQM - water quality monitoring on mid-flood and mid-ebb tides at Ko Lau (CK1, CK2, MK1, MK2, MK3 & MK4) and Wong Shek (CW1, CW2, MW1 & MW2)
 4. All monitoring shall be carried out 3 times a week due to pier demolition works.
- * Post-project monitoring will be commenced from 18 Apr onwards for 4 more weeks after the completion of pier demolition on 17 Apr 07.



CONTRACT NO: CV/2004/02

**RECONSTRUCTION OF WONG SHEK AND
KO LAU WAN PUBLIC PIERS**

**ENVIRONMENTAL MONITORING & AUDIT
MONTHLY REPORT
(KO LAU WAN)**

- 9 MAR 2007 – 17 APR 2007 -

CLIENT:

Kin Shing Construction Company Limited

1/F, 27 Yin Chong Street,
Mongkok,
Kowloon, H.K.

Telephone: (852) 2835 7087
Facsimile: (852) 2780-2805

PREPARED BY:

Lam Environmental Services

Room 1411-16
14/F Honour Industrial Centre
6 Sun Yip Street
Chai Wan, H.K.

Telephone: (852) 2897-3282
Facsimile: (852) 2897-5509
E-mail: info@lamlab.com
Website: <http://www.lamlab.com>

CERTIFIED BY:

Raymond Dai
Senior Environmental Scientist

DATE:

15 Jan 2008

MATERIALAB CONSULTANTS LIMITED

Fugro Development Centre

5 Lok Yi Street, 17 M.S. Castle Peak Road,

Tai Lam, Tuen-Mun, N.T., Hong Kong.

Telephone : +852-24508233

Telefax : +852-24506138

Email : mcl@fugro.com.hk

Materialab**FAX MESSAGE**Priority normal / urgent

To Lam Environmental Services

Ref. No. MCLF1894

Country

Fax No. 2897 5509

Attn. Mr. Raymond Dai

Date 15 January 2008

From Joseph Poon

No. of Pages 1 (Incl. this page)

C.c. To Mr. Simon Fok (Kin Shing Con. Co. Ltd.)

Fax No. 2729 7858

Subject **Contract No. CV/2004/02****Reconstruction of Wong Shek and Ko Lau Wan Public Piers
Monthly EM&A Summary Reports**

We refer to the Monthly EM&A reports (Mar to Apr 07) for Wong Shek Pier and Ko Lau Wan Pier that we received through email on 11 January 2008 and are pleased to confirm we have no further comment on the reports.

Should you require further information, please feel free to contact us.

Best regards,



Joseph Poon
Independent Environmental Checker

JP/ac

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us immediately.

(If you do not receive all pages, please fax response or phone +852-24508233.)



CONTENTS

Executive Summary	1
1 Introduction	1
1.1 Scope of the Report.....	1
1.2 Structure of the Report	1
2 Project Background	3
2.1 Scope of the Project and Site Description.....	3
2.2 Project Organization and Contact Personnel	3
2.3 Construction Programme and Works.....	3
3 Implementation Status	4
3.1 Status of Regulatory Compliance.....	4
3.2 Implementation of Pollution Control / Mitigation Measures	4
4 Monitoring Requirements	5
4.1 Water Quality Monitoring	5
4.2 Monitoring Parameters and Frequency.....	8
4.3 Water Quality Criteria	8
4.4 Monitoring Programme	9
5 Monitoring Results.....	10
5.1 Water Quality Monitoring Results	10
5.2 Waste Monitoring Results.....	10
6 Compliance Audit.....	11
7 Site Inspection and Audit.....	12
8 Complaints, Notification of Summons and Prosecution	13
9 Future Key Issues.....	14
10 Conclusion.....	15



LIST OF TABLES

Table 2.2	Contact Details of Key Personnel
Table 3.1	Cumulative Summary of Valid Licences and Permits
Table 4.1a	Water Quality Monitoring Stations
Table 4.1b	Laboratory Test Procedures
Table 4.2	Water Quality Monitoring Parameters and Frequencies
Table 4.3	Action and Limit Levels for Water Quality Monitoring
Table 4.4	Environmental Monitoring Programme – Mar-Apr 07
Table 5.1a	Water Quality Monitoring Results (mid-flood tide) – Mar-Apr 07
Table 5.1b	Water Quality Monitoring Results (mid-ebb tide) – Mar-Apr 07
Table 6.1a	Summary of Water Quality Exceedance (mid-flood tide) – Mar-Apr 07
Table 6.1b	Summary of Water Quality Exceedance (mid-ebb tide) – Mar-Apr 07
Table 7	Summary of Environmental Inspection and Audit – Mar-Apr 07
Table 8a	Environmental Complaints Log
Table 8b	Cumulative Statistics on Complaints
Table 8c	Cumulative Statistics on Successful Prosecutions
Table 8c	Cumulative Statistics on Notification of Summons

LIST OF FIGURES

<u>Figure 2.1</u>	Location Plan
<u>Figure 2.3</u>	Master Construction Programme
<u>Figure 4.1</u>	Layout of Environmental Monitoring Stations
<u>Figure 5.1a-h</u>	Graphical Plots of Water Quality Monitoring Results

LIST OF APPENDICES

<u>Appendix A</u>	Organization Chart
<u>Appendix B</u>	Implementation Schedule of Mitigation Measures
<u>Appendix C</u>	Calibration Certificates for Monitoring Equipment
<u>Appendix D</u>	Water Quality Monitoring Results
<u>Appendix E</u>	Monitoring Schedule - Upcoming month



EXECUTIVE SUMMARY

This is the Monthly Environmental Monitoring and Audit (EM&A) report for Contract No. CV/2004/02 – Reconstruction of Wong Shek and Ko Lau Wan Public Piers. This report presents the environmental monitoring and auditing (EM&A) findings based on data and information recorded from the period 9th Mar to 17th Apr 2007 for the demolition of Ko Lau Wan Public Pier.

Construction Activities for the Reported Period

During this reporting period, the principal work activities at Ko Lau Wan Pier include:

- Demolition of existing pier

Water Quality Monitoring

10 water quality monitoring events in terms of turbidity, dissolved oxygen, suspended solids, temperature, and salinity was carried out at MK1, MK2, MK3, MK4, CK1 and CK2 at Ko Lau Wan during the reporting period.

Fluctuations for dissolved oxygen, turbidity and suspended solids resembled those fluctuations at the control stations which indicated that all the exceedances in water quality monitoring were due to natural phenomena and agreed with the changes in the control stations. Causation due to construction activities is unlikely and there were no valid exceedance for this reporting period.

Waste Management

All demolished materials were beneficially reused as artificial coral on site so that no C&D materials were disposed. No general refuse or chemical waste was transported off site in this reporting period.

Complaints, Notifications of Summons and Successful Prosecutions

There was no complaints, notification of prosecutions or summons in this reporting period.



Site Inspections and Audit

6 site inspections were conducted by the Environmental Team (ET) in this reported period. Major observations are summarised in the following table. Major observations by the ET, actions by the Contractor and outcome are summarized in the following table.

Item	Date	Observations	Action taken by Contractor	Outcome
-	9 Mar	No particular finding	-	-
-	16-Mar	No particular finding	-	-
-	23-Mar	No particular finding	-	-
-	30-Mar	No particular finding	-	-
-	2-Apr	No particular finding	-	-
-	13-Apr	No particular finding	-	-

Future Key Issues

After 17 Apr 07, all the pier demolition works were completed and post-project water quality monitoring will proceed.



1 INTRODUCTION

1.1 SCOPE OF THE REPORT

Lam Environmental Services (LAM) has been appointed to work as the Environmental Team (ET) for Kin Shing Construction Company Limited to implement the Environmental Monitoring and Audit (EM&A) programme for the Contract No. CV/2004/02 – Reconstruction of Wong Shek and Ko Lau Wan Public Piers.

This report presents the environmental monitoring and auditing work carried out from the period 9th Mar to 16th Apr 2007 for the demolition of Ko Lau Wan Public Pier in accordance to Section 26 of the Particular Specification, Project Profile (PP-191/2003) and Environmental Permit (EP-186/2004) for this Project.

The following information relating to this project is documented in the EM&A Manual and, to avoid duplication, it is not presented in detail within the monthly report.

- Event-Action Plans;
- Full set of environmental mitigation measures and;
- Contracted environmental requirements.

1.2 STRUCTURE OF THE REPORT

Section 1 *Introduction* – details the scope and structure of the report.

Section 2 *Project Background* – summarizes background and scope of the project, site description, project organization and contact details of key personnel, construction programme and works undertaken during the reporting period.

Section 3 *Implementation Status* – summarizes the status of Environmental Permits / Licenses, implementation of environmental protection and pollution control / mitigation measures in an updated schedule for the reporting period.

Section 4 *Monitoring Requirements* – summarizes all monitoring parameters, monitoring methodology and equipment, monitoring locations, monitoring frequency and programmes.



-
- Section 5** ***Monitoring Results*** – summarizes the monitoring results obtained in the reporting period.
- Section 6** ***Compliance Audit*** – summarizes the auditing of monitoring results, all exceedances environmental parameters.
- Section 7** ***Site Inspection and Audit*** – summarizes the findings of weekly site inspections and independent audit undertaken within the reporting period, with a review of any relevant follow-up actions within the reporting period.
- Section 8** ***Complaints, Notification of Summons and Prosecution*** – summarizes the complaints, notification of summons and successful prosecution for breaches of environmental legislation and the actions taken within the reporting period.
- Section 9** ***Future Key Issues*** – summarizes the upcoming works and a forecast of the environmental impact and monitoring schedule for the next reporting period.
- Section 10** ***Conclusion***

2 PROJECT BACKGROUND

2.1 SCOPE OF THE PROJECT AND SITE DESCRIPTION

The works mainly comprise demolition of the existing piers and construction of reinforced concrete piers with roof covers at Ko Lau Wan. The construction of the Project is scheduled to commence in November 2004 for completion in September 2006. The construction period is 630 days for the entire construction.

The site layout plan is shown in [Figure 2.1](#).

2.2 PROJECT ORGANIZATION AND CONTACT PERSONNEL

Civil Engineering Office of Civil Engineering and Development Department is the project proponent. The organization chart for the EM&A programme is attached in [Appendix A](#).

Under the organization chart, Resident Engineer, Contractor, Independent Environmental Checker, Environmental Team are appointed to manage and control environmental issues for the construction phase of CV/2004/02. Overall responsibilities and duties of the team are found in the corresponding EM&A Manual. Key personnel and contact particulars are summarized in **Table 2.2**:

Table 2.2 Contact Details of Key Personnel

Post	Name	Contact No.	Contact Fax	Mobile No.
Resident Engineer	David C S Leung	2760 5737	2714 2054	9630 1235
Project Manager	K W Li	2729 6779	2729 7858	9104 9463
Independent Environmental Checker (IEC)	Joseph T L Poon	2452 7140	2450 6138	9450 1968
Environmental Team Leader (ETL)	Raymond Dai	2975 3300	2897 5509	9738 0738

2.3 CONSTRUCTION PROGRAMME AND WORKS

Construction works carried out at Ko Lau Wan Pier during this reporting period are:

- Demolition of existing pier

The master construction programme is given in [Figure 2.3](#).



3 IMPLEMENTATION STATUS

3.1 STATUS OF REGULATORY COMPLIANCE

A summary of the current status on licences and/or permits on environmental protection pertinent to the Project is shown in **Table 3.1**.

Table 3.1 Cumulative Summary of Valid Licences and Permits

Permits and/or Licences	Reference No.	Issued Date	Expiry Date	Status
Environmental Permit	EP-186/2004/A	28-04-2005	-	Issued on receipt of VEP-171/2005 dated 14-04-2005
Waste Producer Registration	WPN5213-742-K1081-05	12-05-2005	-	Notified
Construction Noise Permit	-	-	-	No valid CNP granted to the Contractor

3.2 IMPLEMENTATION OF POLLUTION CONTROL / MITIGATION MEASURES

The contractor implemented various environmental mitigation measures as recommended in the Particular Specification and the Environmental Permit. The implementation schedule is presented in [Appendix B](#).

4 **MONITORING REQUIREMENTS**

Locations of environmental monitoring stations are referred in [Figure 4.1](#).

4.1 **WATER QUALITY MONITORING**

The brief for EM&A works details 6 designated stations to be monitored during the construction period comprising 4 monitoring stations and 2 control stations. These stations have been coded as MK1, MK2, MK3, MK4, CK1 and CK2 respectively.

Table 4.1a *Water Quality Monitoring Stations*

Station	HK Metric Grid (Easting / Northing)	Description
MK1	855 212.850E / 835 496.101N	Impact Monitoring
MK2	855 158.643E / 835 539.315N	Impact Monitoring
MK3	855 170.762E / 835 401.962N	Impact Monitoring
MK4	855 108.767E / 835 402.196N	Impact Monitoring
CK1	854 822.145E / 835 428.000N	Control during mid-ebb
CK2	854 996.976E / 835 675.135N	Control during mid-flood

Monitoring Methodology

Measurements were be taken under two tidal conditions (mid-flood and mid-ebb) at 3 water depths, namely 1m below the water surface, mid-depth and 1m above the seabed, except where the water depth is less than 6m, the mid-depth sample may be omitted. If the water depth is less than 3m, only the mid-depth will be monitored.

Replicate in-situ measurements and samples were collected from each independent sampling event are required for all parameters to ensure a robust statistical interpretable dataset.



Water quality parameter in terms of: dissolved oxygen (mg/L and % saturation), salinity (ppt), turbidity (NTU), and suspended solids (mg/L) were measured in-situ with portable instruments. Other relevant data was also recorded, including the following:

- monitoring station and position;
- time;
- depth of water;
- tidal status;
- water temperature;
- weather conditions including ambient temperature;
- any special phenomena or activities at the construction site.

For the measurement of dissolved oxygen the probe shall be removed from the water column between each duplicate measurement. If the difference between each duplicate measurement is greater than a 25% then the two sets of data shall be rejected and the measurements re-taken.

Suspended solids (SS) were determined in the laboratory at Chai Wan managed by Lam Environmental Services Ltd.

Monitoring Equipment

- **Sample Bottles:** Samples were kept in high density polythene bottles, packed in ice and cooled to 4°C or below, without being frozen, for delivery to the laboratory as soon as possible after collection.
- **Thermometer:** A standard certified laboratory mercury thermometer with an accuracy of at least 0.5°C was employed, calibrated against a certified thermometer of 0.1°C scale. This thermometer was employed for measuring both ambient and water temperatures.
- **Depth Detector:** As the depth of water being sampled was generally shallow, too shallow to allow for the use of an echosounder, a marked depth gSepe was employed to determine water depth at all designated monitoring stations.

All in-situ monitoring equipment shall be checked, verified and calibrated by Lam laboratory at Chai Wan, a HOKLAS accredited laboratory, prior to use on the Works and subsequently thereafter every three months throughout all stages of the water quality monitoring. Responses of the sensors and electrodes shall be checked with certified standard solutions before each use. Wet bulb calibration for a DO meter shall be carried out before measurement.



For in-situ calibration of field equipment, the BS 1427: 1993 “Guide to Field and on-site test methods for the analysis of waters” shall be observed.

A set of backup monitoring instruments and equipment shall be made available so that the monitoring can proceed uninterrupted in case of apparatus malfunction or if equipment has been returned to the laboratory for calibration.

Current calibration certificates are presented in [Appendix C](#).

Laboratory Analysis

All samples are returned to the laboratory at Chai Wan for the determination of SS under a QA / QC scheme inclusive of blank, duplicate and spike recovery analysis under the requirement of HOKLAS. The laboratory test procedures conform to “Standard Methods for the Examination of Water and Wastewater” published by American Public Health Association (APHA) and United State Environmental Protection Agency (USEPA) test methods are summarized in **Table 4.3b**.

Table 4.1b **Laboratory Test Procedures**

Parameter	Methodology	Method Ref.	Detection Limit
SS	Determination of Total Suspended Solids Dried at 103-105°C	APHA 19 th Ed. 2540D	2.0 mg/L

4.2 **MONITORING PARAMETERS AND FREQUENCY**

Water quality monitoring programme has been scheduled according to the requirements stipulated in the EM&A Manual produced for the Project summarized in **Tables 4.2**.

Table 4.2 Water Quality Monitoring Parameters and Frequencies

Station(s)	Parameter	Frequency
MK1, MK2 MK3, MK4 CK1, CK2	DO, Temperature, Salinity, Turbidity, Suspended Solids, Water Depth	<u>For piling or demolition works</u> 3 days per week at mid-flood and mid-ebb <u>For marine works other than piling or demolition works</u> 1 day per week at mid-flood and mid-ebb

4.3 **WATER QUALITY CRITERIA**

Water quality criteria were determined prior to the commencement of the construction of the project for the purpose of impact monitoring. Various levels established based on the results of baseline monitoring and the Event Action Plan stipulated in the EM&A Manual are summarized in **Tables 4.3**.

Table 4.3 Action and Limit Levels for Water Quality Monitoring

Parameter	Action Level	Target Level
Dissolved Oxygen (Surface, Middle & Bottom)	<u>Surface & Middle</u> For Ko Lau Wan – 6.90	<u>Surface & Middle</u> For Ko Lau Wan – 6.79
	<u>Bottom</u> For Ko Lau Wan – 6.75	<u>Bottom</u> For Ko Lau Wan – 5.63
Turbidity (depth-averaged)	For Ko Lau Wan – 1.25 or 120% of upstream control station's Tby at the same tide of same day, whichever is lower	For Ko Lau Wan – 1.60 or 130% of upstream control station's Tby at the same tide of same day, whichever is lower
Suspended Solids (depth-averaged)	For Ko Lau Wan – 6.30 or 120% of upstream control station's SS at the same tide of same day, whichever is lower	For Ko Lau Wan – 6.87 or 130% of upstream control station's SS at the same tide of same day, whichever is lower

Note:

1. "Depth-averaged" is calculated by taking the arithmetic means of reading all three depths.
2. For Dissolved Oxygen, non-compliance of the water quality limits occurs when monitoring result is lower than the limits.
3. For Turbidity and Suspended Solid, non-compliance of the water quality limits occurs when monitoring result is higher than the limits.
4. All the figures given in the table are used for reference only and the Engineer may amend the figures whenever it is considered as necessary.

4.4 MONITORING PROGRAMME

Environmental monitoring programme for this reporting period was carried out in accordance with the required monitoring frequency. The actual completion of monitoring work during the reporting period is presented in **Tables 4.4**.

Table 4.4 Environmental Monitoring Programme – Mar-Apr 07

Mar / Apr 2007		Water Quality (DO, Turbidity, SS)	Site Inspection
		MW1, MW2, CW1, CW2	
9	Fri	X	X
10	Sat		
11	Sun		
12	Mon	No mid-tides available	No mid-tides available
13	Tue		
14	Wed	No mid-tides available	No mid-tides available
15	Thu		
16	Fri	X	X
17	Sat		
18	Sun		
19	Mon	X	
20	Tue		
21	Wed	X	
22	Thu		
23	Fri	X	X
24	Sat		
25	Sun		
26	Mon	No mid-tides available	No mid-tides available
27	Tue		
28	Wed	No mid-tides available	No mid-tides available
29	Thu		
30	Fri	X	X
31	Sat		
1	Sun		
2	Mon	X	X
3	Tue		
4	Wed	X	
5	Thu		
6	Fri		
7	Sat		
8	Sun		
9	Mon	No mid-tides available	No mid-tides available
10	Tue		
11	Wed	X	
12	Thu		
13	Fri	X	X
14	Sat		
15	Sun		
16	Mon	X	

Note:

- X: Monitoring conducted from 9 Mar to 16 Apr 07 during the pier demolition work.
- Schedule is formulated and with consideration of statutory holidays (shaded in the table).

5 MONITORING RESULTS

5.1 WATER QUALITY MONITORING RESULTS

Water quality monitoring was carried out on 10 occasions at stations MK1, MK2, MK3, MK4, CK1 and CK2. Calculated water quality monitoring results in this reporting period are reviewed and summarized in **Tables 5.1a and 5.1b**. Details of measured and tested results can be referred in [Appendix D](#). Graphical trend is presented in [Figure 5.1a – 5.1h](#).

Table 5.1a Water Quality Monitoring Results (mid-flood tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle (mg/L)	Averaged DO Bottom (mg/L)	Averaged Turbidity (NTU)	Averaged Suspended Solids (mg/L)
MK1	6.28	5.72	1.17	8.5
MK2	6.22	5.59	1.20	9.1
MK3	6.36	5.73	1.19	7.8
MK4	6.30	5.60	1.19	10.0
CK1	6.23	5.30	1.25	7.9
CK2	6.19	5.25	1.24	8.5

Table 5.1b Water Quality Monitoring Results (mid-ebb tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle (mg/L)	Averaged DO Bottom (mg/L)	Averaged Turbidity (NTU)	Averaged Suspended Solids (mg/L)
MK1	6.39	5.80	1.19	8.8
MK2	6.31	5.74	1.22	9.6
MK3	6.38	5.81	1.18	8.2
MK4	6.35	5.75	1.20	8.5
CK1	6.28	5.44	1.21	10.0
CK2	6.27	5.37	1.24	8.5

5.2 WASTE MONITORING RESULTS

All demolished materials were beneficially reused as artificial coral on site so that no C&D materials were disposed. No general refuse or chemical waste was transported off site in this reporting period.

6 COMPLIANCE AUDIT

Results of the calculated water quality results for various are audited against the water quality levels and the number of exceedances are summarized **Tables 6.1a and 6.1b**. Exceedances caused by natural phenomena namely fluctuation of overall water quality by comparing the graphical trends of monitoring and control stations are eliminated in order to identify the valid exceedance due to construction activities.

Table 6.1a Summary of Water Quality Exceedance (mid-flood tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle	Averaged DO Bottom	Averaged Turbidity	Averaged Suspended Solids
MK1	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MK2	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MK3	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MK4	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)

Table 6.1b Summary of Water Quality Exceedance (mid-ebb tide) – Mar-Apr 07

Station	Averaged DO Surface & Middle	Averaged DO Bottom	Averaged Turbidity	Averaged Suspended Solids
MK1	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MK2	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MK3	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)
MK4	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)	0 (AL); 0 (LL)

As shown in the graphical trend, the observed trends and exceedances in dissolved oxygen, turbidity and suspended solids at MK1, MK2, MK3 and MK4 resemble the fluctuations to the respective control stations, possibly due to variation in water current or tidal effect.

The observed exceedances for turbidity and suspended solids are respectively within 0.5 NTU and 7 mg/L, indicating the fluctuation could possibility due to the natural variation around the small values of suspended solids.

To conclude, the fluctuations for dissolved oxygen, turbidity and suspended solids resembled those fluctuations at the control stations which indicated that all the exceedances in water quality monitoring were due to natural phenomena and agreed with the changes in the control stations. Therefore, causation due to CV/2004/02 construction activities is unlikely and there were no valid exceedance for this reporting period.



7 SITE INSPECTION AND AUDIT

The ET undertook site inspection at least once a week. Monthly joint audit was undertaken by the IEC, the ETL, the Engineer and the Contractor.

The ET carried out 6 inspections during this reporting period. The results of these inspections and outcomes are summarized in **Table 7**.

Table 7 Summary of Environmental Inspection and Audit – Mar-Apr 07

Item	Date	Observations	Action taken by Contractor	Outcome
-	9 Mar	No particular finding	-	-
-	16-Mar	No particular finding	-	-
-	23-Mar	No particular finding	-	-
-	30-Mar	No particular finding	-	-
-	2-Apr	No particular finding	-	-
-	13-Apr	No particular finding	-	-

8 COMPLAINTS, NOTIFICATION OF SUMMONS AND PROSECUTION

No complaint, inspection notice, notification of summons or prosecution was received in this reporting period. Complaint log, summaries of cumulative complaints and successful prosecutions are presented in **Table 8a**, **Table 8b**, **Table 8c** and **Table 8d** respectively.

Table 8a Environmental Complaints Log

Complaint Log No.	Date of Receipt	Received From and By	Nature of Complaint	Date investigated	Outcome	Date of Reply and to Whom
-	-	-	-	-	-	-

Table 8b Cumulative Statistics on Complaints

Environmental Parameters	Cumulative No. Brought Forward	No. of Complaints This Month	Cumulative No. Project-to-Date
Air	-	-	-
Noise	-	-	-
Water	-	-	-
Waste	-	-	-
Total	-	-	-

Table 8c Cumulative Statistics on Successful Prosecutions

Environmental Parameters	Cumulative No. Brought Forward	No. of Successful Prosecutions this month (Offence Date)	Cumulative Number to Date
Air	-	-	-
Noise	-	-	-
Water	-	-	-
Waste	-	-	-
Total	-	-	-

Table 8c Cumulative Statistics on Notification of Summons

Environmental Parameters	Cumulative No. Brought Forward	No. of Successful Summons	Cumulative Number to Date
Air	-	-	-
Noise	-	-	-
Water	-	-	-
Waste	-	-	-
Total	-	-	-



FUTURE KEY ISSUES

After 17 Apr 07, all the pier demolition works were completed and post-project water quality monitoring will proceed.



CONCLUSION

The EM&A programme was carried out in accordance with the EM&A Manual requirements, minor alterations to the programme proposed in the previous EM&A Report were made in response to changing circumstances.


No exceedance due to construction activities was reported in routine environmental monitoring. Such results indicate that the construction operation generally performed reasonably acceptable against environmental auditing criteria.

In summary, environmental mitigation measures are being satisfactorily implemented within the CV/2004/02 project along with the on-going construction activities.



Figure 2.1

Location Plan



NOTES:

1. ALL DIMENSIONS ARE IN MILLIMETRES.
2. ELEVATIONS ARE IN METRES. GEODETIC DATUM 1980 AND ARE IN METRES.
3. ALL LEVELS REFER TO CHART DATUM (C.D.). AND ARE IN METRES.

LEGEND:

- BOLLARD
- * NAVIGATION LIGHT



no.	date	description	designed	approved
REVISION				
1			designed	approved
2			drawn	
3			checked	
4			approved	

contract no.	
file no.	
project no.	
concept	

drawing title



**KO LAU WAN PUBLIC PIER
- GENERAL LAYOUT**

drawing no. _____
scale _____

office _____



CIVIL ENGINEERING AND DEVELOPMENT DEPARTMENT HONG KONG



COPYRIGHT RESERVED

H AT 841 X 594




Figure 2.3

Master Construction Programme

Contractor: Kin Shing Construction Co. Ltd.
 Commencement Date: 15th Nov 2004
 Completion Date: 6th Aug 2006
 Programme Date: 21st Feb 2005

Master Programme (Version 2)

Contract No.: CV/2004/02
 Reconstruction of Wong Shek and
 Ko Lau Wan Public Piers



Version No. CV/2004/02
 Master Programme (Version 2)

Project Task: **123333333333** Pages: **123333333333** Commencement Milestone: **◆** Status: **■** Completion Milestone: **★**

Scale: **1:100** Critical Path (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1 & 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 1): **1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68**

Other Task (Sec. 2): **1-2-3-4-5-6-7-8-**

Contractor: Kin Shing Construction Co. Ltd.
 Commencement Date: 15th Nov 2004
 Completion Date: 6th Aug 2006
 Programme Date: 21st Feb 2005

Master Programme (Version 2)

Contract No.: CV/2004/02
 Reconstruction of Wong Shek and
 Ko Lau Wan Public Piers

ID	Task Name	Duration	Start	Finish	Predecessors
1	Installation of precast abut with in-situ pile caps	60 days	Mon 05/10/10	Thu 05/12/8	SA, SA2A
2	Casting of in-situ pier deck	30 days	Fri 05/12/9	Sat 06/1/7	9, 7B
3	Construction of bollards	30 days	Fri 05/12/9	Sat 06/1/7	30
4	Installation of corrosion monitoring system	91 days	Sun 05/10/9	Sat 06/0/7	
5	Approval of specialist contractor and method statement	61 days	Sun 05/10/9	Thu 05/12/8	
6	Installation of corrosion monitoring system	30 days	Fri 05/12/9	Sat 06/0/7	8, 7A
7	Roof cover system	272 days	Tue 05/8/9	Sun 06/5/7	
8	Approval of specialist contractor	61 days	Tue 05/8/9	Sat 06/1/7	
9	Submission of working drawings for connection details with deck	61 days	Sun 05/10/9	Thu 05/12/8	7
10	Material submissions	91 days	Sun 05/10/9	Sat 06/1/7	7
11	Submission of working drawing for retaining roof system	91 days	Sun 05/10/9	Sat 06/1/7	7
12	Construction of steel work	60 days	Sun 06/1/8	Wed 06/5/8	11, SA, 7B
13	Erection of roof covers	60 days	Thu 06/3/9	Sun 06/5/7	31
14	Marrying-in to lambside	121 days	Wed 06/3/8	Thu 06/7/6	
15	Application of Excavation Permit	90 days	Wed 06/5/8	Mon 06/0/5	
16	Site work	31 days	Tue 06/6/6	Thu 06/7/6	14, 31
17	Electrical system, CLP meter box and lighting system	220 days	Mon 05/10/10	Wed 06/5/17	
18	Approval of specialist contractor	30 days	Mon 05/10/10	Tue 05/11/8	
19	Joinery with CLP and BMSD	60 days	Wed 05/11/9	Sat 06/1/7	37
20	Installation	120 days	Sun 05/12/8	Sun 06/5/7	7, SA
21	Testing	10 days	Mon 06/5/8	Wed 06/5/17	38
22	Construction of floor finish	121 days	Wed 06/3/8	Thu 06/7/6	
23	Material submissions	61 days	Wed 06/3/8	Sun 06/5/7	32, 32
24	Site work	60 days	Mon 06/5/8	Thu 06/7/6	
25	Construction of lateral rilling, setting benches and notice board	150 days	Tue 06/2/7	Thu 06/7/6	
26	Material submission	60 days	Tue 06/2/7	Fri 06/4/7	
27	Construction	90 days	Sat 06/4/8	Thu 06/7/6	11, 3
28	Installation of fender system	190 days	Thu 05/12/9	Thu 06/7/6	
29	Material submission	33 days	Thu 05/12/9	Sat 06/2/8	
30	Ordering of material	60 days	Sun 06/1/9	Tue 06/5/8	1, 9
31	Site work	60 days	Wed 06/5/9	Thu 06/7/6	7, 1, 9
32	Relocation of navigation light by Marine Dept.	92 days	Fri 06/4/7	Fri 06/7/7	
33	Application to Marine Department	91 days	Fri 06/4/7	Thu 06/7/6	

Contract No.: CV2004/02
 Reconstruction of Wong Shek and
 Ko Lau Wan Public Piers

Master Programme
 (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
 Commencement Date: 15th Nov 2004
 Completion Date: 6th Aug 2006
 Programme Date: 21st Feb 2005


Sl. No.	Task Name	Duration	Start	Finish	Professors
1	Construction of walking cover 1 & 2	245 days	Wed 05/10/05	Tue 06/06/06	
2	Approval of specialist contractor	60 days	Wed 05/10/05	Sat 05/12/05	
3	Submission of workshop drawings for connection details with deck	60 days	Sun 05/11/05	Wed 06/02/06	171
4	Material submissions	85 days	Sun 05/11/05	Sun 06/22/06	171
5	Submission of workshop drawing for remaining roof system	85 days	Sun 05/11/05	Sun 06/22/06	171
6	Construction of steel works	50 days	Mon 06/02/06	Mon 06/04/07	171, 162, 175
7	erection of roof covers	50 days	Tue 06/04/06	Tue 06/05/06	171
8	Electrical system, CLP meter box and lighting system	240 days	Tue 05/11/05	Fri 06/06/06	
9	Approval of specialist contractor	30 days	Thu 05/11/05	Wed 05/11/05	160
10	Liaison with CLP and GMSD	60 days	Thu 05/11/05	Sun 06/22/06	160, 161
11	Installation	100 days	Mon 06/02/06	Tue 06/05/06	160, 161
12	Testing	10 days	Wed 06/03/06	Fri 06/06/06	160
13	Construction of floor finish	130 days	Thu 06/03/06	Sun 06/07/06	160
14	Material submissions	90 days	Thu 06/03/06	Tue 06/05/06	
15	Site works	40 days	Wed 06/03/06	Sun 06/07/06	161, 165, 171
16	Construction of land railing, setting benches and notice boards	150 days	Fri 06/02/07	Sun 06/07/06	
17	Material submission	60 days	Fri 06/03/07	Mon 06/04/07	163
18	Construction	190 days	Tue 06/04/06	Sun 06/07/06	163
19	Material submission	31 days	Sun 06/07/06	Tue 06/27/07	
20	Ordering of material	59 days	Wed 06/28/06	Fri 06/04/07	161
21	Site works	100 days	Sat 06/04/06	Sun 06/07/06	162
22	Relocation of navigation light by Marine Dept.	92 days	Mon 06/04/07	Mon 06/07/07	
23	Application to Marine Department	91 days	Mon 06/04/07	Sun 06/07/06	160, 161, 165, 166, 168
24	Relocation	1 day	Mon 06/07/07	Mon 06/07/07	168
25	Commissioning of the pier	1 day	Tue 06/07/06	Tue 06/07/06	
26	Demolition of the temporary berth and the existing pier	141 days	Sun 06/03/05	Sun 06/08/06	
27	Survey of existing structure	31 days	Sun 06/11/05	Tue 06/04/06	
28	Design and ICE checking of demolition plan	61 days	Wed 06/04/05	Sun 06/06/06	165
29	Submission for Engineer's comment	30 days	Mon 06/07/05	Fri 06/07/06	166
30	Liaison with local residents	30 days	Mon 06/07/05	Tue 06/07/06	166
31	Demolition	19 days	Wed 06/07/05	Sun 06/08/06	167, 168, 169
32	Maintenance Period for the Works	365 days	Mon 06/08/07	Mon 07/08/06	200

Contract No.: CV2004/02
 Project Name: Reconstruction of Wong Shek and Ko Lau Wan Public Piers
 Version: 2
 Date: 21st Feb 2005
 Prepared by: [Name]
 Checked by: [Name]
 Approved by: [Name]

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Contract No. CV/2004/02 View Document/Version 21	Normal Task Split	Summary Completion Milestone	Critical Task (Esc 1 & 2) Critical Task (Esc 1)	Critical Task (Esc 2) Maintenance Period	Summary Completion Milestone
---	----------------------	---------------------------------	--	---	---------------------------------

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Contract No.: CV/2004/02 Master Programme Volume 2	Name of Task: SSA	Project: Reconstruction of Wong Shek and Ko Lau Wan Public Piers	Summary: Exceptional Milestone	Calendar Task (Gantt): [Symbol]	Critical Task (Gantt): [Symbol]	Maintenance Policy: [Symbol]
---	----------------------	---	-----------------------------------	------------------------------------	------------------------------------	---------------------------------

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Normal Task: [Pattern] Fragments: [Pattern] Summary: [Pattern] Completion Milestone: [Pattern] Critical Task (05-1): [Pattern] Critical Task (06-2): [Pattern] Maintenance Period: [Pattern]

Contract No.: CY/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Plazs

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Programme Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Start Task	83333333333333	Progress	Summary	Completion Bill/Item	Costed Task (See A)	Costed Task (See B)	Critical Task (See D)	Minimum Resource
End Task

Contractor: Kin Sating Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005

Master Programme
 (Version 2)

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers




Client Task (Sec 1 & 2)	Client Task (Sec 1)	Critical Task (Sec 2)	Maintenance Period
Summary	Completion Markers	Concrete/Structure	Piling

Contract No.: CV/2004/02
Reconstruction of Wong Shek and
Ko Lau Wan Public Piers

Master Programme (Version 2)

Contractor: Kin Shing Construction Co. Ltd.
Commencement Date: 15th Nov 2004
Completion Date: 6th Aug 2006
Programme Date: 21st Feb 2005




Not Started
 In Progress
 Completed
 Critical Task (C=1)
 Critical Task (C=2)
 Critical Task (C=3)
 Milestone Point
 Milestone Point
 Milestone Point



Figure 4.1

Layout of Environmental Monitoring Stations



COORDINATES OF MONITORING STATION

STATION	Easting (m)	Northing (m)
M1	495 212.474	495 162.474
M2	495 192.474	495 182.474
M3	495 212.474	495 192.474
M4	495 192.474	495 172.474
M5	495 192.474	495 152.474
M6	495 192.474	495 132.474
M7	495 192.474	495 112.474
M8	495 192.474	495 92.474
M9	495 192.474	495 72.474
M10	495 192.474	495 52.474
M11	495 192.474	495 32.474
M12	495 192.474	495 12.474

COORDINATES OF SURVEY POINT

POINT	Easting (m)	Northing (m)
SP1	495 212.474	495 162.474
SP2	495 212.474	495 172.474
SP3	495 212.474	495 182.474
SP4	495 212.474	495 192.474
SP5	495 212.474	495 202.474
SP6	495 212.474	495 212.474
SP7	495 212.474	495 222.474
SP8	495 212.474	495 232.474
SP9	495 212.474	495 242.474
SP10	495 212.474	495 252.474
SP11	495 212.474	495 262.474
SP12	495 212.474	495 272.474
SP13	495 212.474	495 282.474
SP14	495 212.474	495 292.474
SP15	495 212.474	495 302.474
SP16	495 212.474	495 312.474
SP17	495 212.474	495 322.474
SP18	495 212.474	495 332.474
SP19	495 212.474	495 342.474
SP20	495 212.474	495 352.474

REV. : A
 DATE : 30 JUL 05
 SCALE : N.T.S.

FIGURE 4.1 LAYOUT OF ENVIRONMENTAL MONITORING STATIONS
 (KO LAU WAN)

Lam Environmental Services
 Test Specialists and Environmental Analysts





Figure 5.1a-h

Graphical Plots of Water Quality Monitoring Results

Figure 5.1c - Dissolved Oxygen (Bottom Averaged) - Mid-Flood
(Ko Lau Wan)




Figure 5.1d - Dissolved Oxygen (Bottom Averaged) - Mid-Ebb
(Ko Lau Wan)




Figure 5.1e - Turbidity (Depth Averaged) - Mid-Flood
(Ko Lau Wan)




Figure 5.1f - Turbidity (Depth Averaged) - Mid-Ebb
(Ko Lau Wan)




Figure 5.1g - Suspended Solids (Depth Averaged) - Mid-Flood
(Ko Lau Wan)






Figure 5.1h - Suspended Solids (Depth Averaged) - Mid-Ebb
(Ko Lau Wan)





Appendix A

Organization Chart





Appendix B

Implementation Schedule of Mitigation Measures



Implementation Schedule of Mitigation Measures – Ko Lau Wan

Environmental Aspect	No.	Mitigation Measures	Implementation Status	Follow Up Action(s)
Air Quality	AQ01	Provide a wash-pit or a wheel washing and/or vehicle cleaning facility at the exits.	Not applicable at this stage	-
	AQ02	Provide a hard surfaced road between the wheel washing facilities and any finished road.	Not applicable at this stage	-
	AQ03	No burning of construction wastes or vegetation shall be allowed on the Site.	Implemented	-
	AQ04	In the process of material handling, any material which has the potential to create dust shall be treated with water or sprayed with wetting agent.	Not applicable at this stage	-
	AQ05	Any vehicle with an open load carrying area used for moving materials which has the potential to create dust shall have properly fitting side and tail boards.	Not applicable at this stage	-
	AQ06	Materials having the potential to create dust shall not be loaded to a level higher than the side and tail boards, and shall be covered by a clean tarpaulin.	Not applicable at this stage	-
	AQ07	Stockpiles of sand, aggregate and construction and demolition material greater than 20m ³ shall be enclosed on three sides, with walls extending above the pile and 2 meters beyond the front of the pile.	Not applicable at this stage	-
	AQ08	Water sprays shall be provided and used both to dampen stored materials and when receiving raw materials.	Not applicable at this stage	-
	AQ09	Clean and water the Site to minimize the fugitive dust emissions.	Implemented	-
	AQ10	Furnace, boiler or other plant or equipment or use any fuel that might in any circumstances produce smoke or any other air pollution should not be installed.	Implemented	-
Noise	N01	All plant and equipment to be used on Site are properly maintained in good operating condition and noisy construction activities shall be effectively sound-reduced by means of silencers, mufflers, acoustic linings or shields, acoustic sheds or screens or other means to avoid disturbance to any nearby noise sensitive receivers.	Implemented	-
	N02	No excavator mounted breaker shall be used within 125m from any nearby noise sensitive receivers. Use hydraulic concrete crusher whenever applicable.	Implemented	-
	N03	All construction works should stop on Sundays and General Holidays.	Implemented	-
Water Quality	WQ01	Water in wheel washing facilities shall be changed at frequent intervals and sediments shall be removed regularly.	Not applicable at this stage	-
	WQ02	The polluted water from the wheel washing facilities would not be discharged into all existing stream courses/drains and nearby waterbodies.	Not applicable at this stage	-
	WQ03	All existing stream courses and drains within, and adjacent to the Site should be kept free from any debris and any excavated materials arising from the Works	Implemented	-
	WQ04	Chemicals and concrete agitator washings should not be deposited in watercourses.	Implemented	-
	WQ05	The effluent shall comply with the standards stated in the "Technical Memorandum on Standards and Effluent discharges into Drainage and Sewerage Systems, Inland and Coastal Waters" for the appropriate Water Control Zone.	Implemented	-
	WQ06	No spoil or debris of any kind is allowed to be pushed, washed down, fall or be deposited on land or on the seabed adjacent to the Site.	Implemented	-
	WQ07	Maintain any existing site drainage system at all times including removal of solids in sand traps, manholes and stream beds.	Implemented	-
	WQ08	Material from any earthworks should not be washed into the drainage system.	Implemented	-
	WQ09	Silt curtain shall be provided during all demolition works and piling works with the Site.	Not applicable at this stage	-



Implementation Schedule of Mitigation Measures – Ko Lau Wan

Environmental Aspect	No.	Mitigation Measures	Implementation Status	Follow Up Action(s)
	WQ10	Silt curtain shall be formed from tough, abrasion-resistant permeable membranes suitable for the purpose, supported on floating booms in such a way as to ensure that the passage of turbid water to the surrounding water shall be restricted.	Not applicable at this stage	-
	WQ11	No dredging and spoil dumping shall be conducted.	Not applicable at this stage	-
Ecology	E01	Marker buoys shall be set up to indicate the location of the "Coral Exclusion Zone". All working vessels shall be restricted to encroach the "Coral Exclusion Zone"	Implemented	-
	E02	No overloading of the working barges during operation and no movement of the working barges, particularly close to the pier and shallow areas, during low tide should be allowed.	Not applicable at this stage	-
	E03	No coral shall be enclosed by the silt curtain.	Not applicable at this stage	-
Waste	W01	All excavated materials should be sorted to recover the inert portions for reuse on site or disposal to designated outlets.	Implemented	-
	W02	All metals should be recovered on site for collection by recycling contractors.	Implemented	-
	W03	All cardboard and paper packaging should be recovered on site, properly stockpiled in dry condition and covered to prevent cross contamination by other C&D materials.	Implemented	-
	W04	All demolition debris from demolition works should be sorted to recover on site broken concrete, reinforcement bars, mechanical and electrical fittings as well as other building services fittings/materials that have established recycling outlets.	Implemented	-



Appendix C

Calibration Certificates for Monitoring Equipment

Record sheet for calibration of Water Sonde

Item Stock No : 7144 Date of Calibration : 1/11/2006 Procedure Used : IC 34
Temp.: 20 °C Operator : Bm Signature : [Signature]

A Temperature Check

Reference Equipment Used : Mercury-in- Glass thermometer Stock No.: C51

Reference Equipment reading : 23.0 °C Sonde reading 23.6 °C

Reference Equipment reading : 23.0 °C Sonde reading : 23.6 °C

(Note: Difference between the two readings to be <0.5°C.)

B DO (% Saturation) Calibration

To be performed in aerated clean sea water before use and checked after use. Difference should be less than 10%.

Laboratory Check

Zero DO check (prepared in clean sea water according to APHA 4500-O G, section 3a.)

probe reading 0.01 %

C Conductivity (Salinity Calibration)

Standards Used : 35 ppt , / ,

Check Standard : 35 ppt Readout Value : 34.24 ppt

Difference between readout value and actual value should be less than 3%.

D Conductivity Calibration

Standards Used : 1 , / , / (mS/cm) Bm
1/11/06

Check Standard : / Readout Value : / (mS/cm)

Difference between readout value and actual value should be less than 2%.

E Turbidity Calibration

Standards Used : / , / , / (NTU)

Check Standard : / Readout Value : / (NTU)

Difference between readout value and actual value should be less than 10% .

F pH check

Standard Used : pH 7.00 , pH 10.00 .

Buffer standard : pH 9.00

QC Check Standard : pH 9.182 . Readout Value : pH 9.15

Certified by: Linda
Section Manager

Date : 04/11/2016



Appendix D

Water Quality Monitoring Results

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 9/3/2007

Weather Condition: sunny

Ambient Temperature, °C: 29

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C			Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	Average	a	b	Average	a	b	Average	a	b	Average	Depth Average			
MK1 S	10:20	mid wave	6	1	28.1	28.1	7.03	7.03	6.84	108.3	108.4	101.9	34.5	34.5	1.16	1.05	1.07	7.2	9.9	
MK1 M	10:23			3	27.9	27.9	6.66	6.63	95.4	95.4	34.7	34.7	1.14	0.93	17					
MK1 B	10:26			5	27.7	27.7	6.22	6.21	6.22	91.9	91.8	91.9	34.9	34.9	1.06	1.05	5.4			
MK2 S	10:30	mid wave	8	1	28.0	28.0	6.89	6.91	6.68	99.4	99.5	96.7	34.6	34.6	1.19	1.30	1.18	9.8	9.1	
MK2 M	10:33			4	27.8	27.8	6.45	6.45	94.0	94.0	34.7	34.7	1.36	1.04	7.6					
MK2 B	10:36			7	27.7	27.7	6.03	6.04	6.04	90.9	90.3	90.6	34.9	34.9	1.15	1.02	9.8			
MK3 S	10:00	mid wave	6	1	28.2	28.2	7.13	7.13	7.05	104.7	104.7	102.8	34.6	34.6	1.00	1.15	1.15	11	8.5	
MK3 M	10:03			3	28.0	28.0	6.95	6.98	100.8	100.8	34.8	34.8	1.20	1.34	5.8					
MK3 B	10:06			5	27.8	27.8	6.53	6.53	6.53	94.0	93.7	93.9	34.9	35.0	1.08	1.15	8.6			
MK4 S	10:10	mid wave	8	1	28.2	28.2	7.07	7.08	6.85	100.6	101.0	99.0	34.6	34.7	1.11	1.08	1.11	18	12.8	
MK4 M	10:13			4	28.0	28.0	6.62	6.63	97.3	97.2	34.9	34.9	1.03	1.20	13					
MK4 B	10:16			7	27.8	27.7	6.30	6.30	6.30	91.8	91.6	91.7	35.0	35.0	1.14	1.07	7.4			
CK1 S	10:50	mid wave	20	1	28.0	28.0	6.99	6.91	6.57	98.9	98.9	94.8	34.8	34.8	1.16	1.07	1.23	7.4	8.9	
CK1 M	10:53			10	27.5	27.5	6.18	6.18	90.6	90.6	35.1	35.1	1.38	1.41	9.4					
CK1 B	10:56			19	27.3	27.3	5.56	5.56	5.56	83.6	83.7	83.7	35.3	35.3	1.05	1.29	9.8			
CK2 S	10:40	mid wave	18	1	28.0	28.0	6.88	6.84	6.46	101.3	101.4	95.9	34.9	34.9	1.08	0.88	1.20	<5.0	17.0	
CK2 M	10:43			9	27.6	27.6	6.06	6.05	90.4	90.6	35.2	35.1	1.14	1.20	17					
CK2 B	10:46			17	27.3	27.2	5.47	5.47	5.47	85.6	85.0	85.3	35.3	35.3	1.41	1.47	17			

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 9.7 NTU: 9.7 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 16/3/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 9/3/2007

Weather Condition: sunny

Ambient Temperature, °C: 29

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C			Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	Average	a	b	Average	a	b	Average	a	b	Average	Depth Average			
MK1 S	16:20	mid wave	7	1	28.0	27.9	6.99	6.98	6.64	95.7	95.8	92.1	34.4	34.4	1.17	1.34	1.18	12	13.3	
MK1 M	16:23			3.5	27.8	27.8	6.30	6.30	88.4	88.4	34.6	34.6	1.20	1.03	7.8					
MK1 B	16:26			6	27.8	27.8	5.80	5.80	5.80	82.0	82.1	82.1	34.7	34.7	1.24	1.09	20			
MK2 S	16:30	mid wave	10	1	28.0	28.0	7.07	7.07	6.79	98.8	98.8	95.2	34.5	34.5	1.04	1.13	1.14	17	13.9	
MK2 M	16:33			5	27.9	27.9	6.50	6.50	91.6	91.7	34.6	34.6	1.18	1.24	17					
MK2 B	16:36			9	27.8	27.8	6.04	6.06	6.05	83.4	83.7	83.6	34.7	34.7	1.05	1.18	7.6			
MK3 S	16:00	mid wave	7	1	28.0	28.0	7.10	7.04	6.73	100.6	110.0	98.7	34.4	34.4	1.24	1.20	1.11	11	10.7	
MK3 M	16:03			3.5	27.8	27.8	6.38	6.39	92.0	92.0	34.6	34.6	1.07	1.11	8.2					
MK3 B	16:06			6	27.6	27.7	6.43	6.46	6.45	87.7	87.7	87.7	34.8	34.8	1.01	1.04	13			
MK4 S	16:10	mid wave	9	1	28.0	28.0	6.95	6.90	6.66	106.6	106.5	100.0	34.3	34.3	1.06	1.19	1.20	7.4	9.8	
MK4 M	16:13			4.5	27.8	27.8	6.40	6.40	93.4	93.4	34.6	34.6	1.04	1.27	17					
MK4 B	16:16			8	27.7	27.7	6.05	6.06	6.06	90.6	90.6	90.6	34.8	34.8	1.33	1.30	5.0			
CK1 S	16:50	mid wave	18	1	27.8	27.8	6.77	6.79	6.63	95.4	95.4	93.0	34.4	34.4	1.22	1.25	1.23	5.2	9.7	
CK1 M	16:53			9	27.5	27.5	6.53	6.44	90.6	90.6	34.6	34.6	1.09	1.01	15					
CK1 B	16:56			17	27.4	27.4	5.96	5.96	5.96	86.4	86.4	86.4	34.8	34.8	1.36	1.44	8.8			
CK2 S	16:40	mid wave	18	1	27.8	27.8	6.92	6.98	6.64	97.1	97.1	94.1	34.3	34.4	1.20	1.08	1.25	9.8	10.3	
CK2 M	16:43			9	27.5	27.4	6.32	6.34	91.0	91.0	34.6	34.6	1.49	1.52	11					
CK2 B	16:46			17	27.3	27.3	5.78	5.78	5.78	88.8	88.8	88.8	34.8	34.8	1.07	1.16	10			

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 9.7 NTU: 9.7 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 16/3/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 16/3/2007

 Weather Condition: rainy

 Ambient Temperature: °C: 27

 Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L		Average	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Average	Suspended Solids, mg/L		Remarks
					a	b	a	b		a	b	a	b	a	b	Depth		Average		
MK1 S	15:55	mid wave	7	1	26.8	26.8	7.01	7.03	6.77	106.8	106.8	102.4	34.5	34.5	1.09	1.17	1.09	7.0		7.2
MK1 M	15:58			3.5	26.6	26.6	6.54	6.50		98.3	98.2		34.7	34.7	1.18	1.11		7.3		
MK1 B	16:01			6	26.4	26.4	6.11	6.10	6.11	90.0	90.2	90.1	34.8	34.8	1.04	0.93		<5.0		
MK2 S	16:05	mid wave	10	1	26.7	26.7	6.93	6.98	6.69	100.7	100.8	98.7	34.5	34.5	1.28	1.34	1.18	12		10.7
MK2 M	16:08			5	26.6	26.6	6.43	6.40		96.6	96.6		34.7	34.7	1.16	1.14		9.4		
MK2 B	16:11			9	26.4	26.5	5.80	5.80	5.80	88.4	88.4	88.4	34.7	34.7	0.97	1.18		<5.0		
MK3 S	15:35	mid wave	7	1	26.8	26.8	6.99	6.95	6.64	101.4	101.4	97.9	34.4	34.4	1.17	1.08	1.20	6.2		6.6
MK3 M	15:38			3.5	26.6	26.6	6.30	6.30		94.3	94.3		34.7	34.7	1.26	1.34		7.2		
MK3 B	15:41			6	26.5	26.5	6.04	6.04	6.04	90.2	90.2	90.2	34.8	34.8	1.15	1.22		6.4		
MK4 S	15:45	mid wave	11	1	26.8	26.8	7.03	7.03	6.72	103.4	103.0	100.1	34.5	34.5	1.18	1.42	1.18	13		12.5
MK4 M	15:48			5.5	26.5	26.5	6.40	6.41		97.0	97.0		34.6	34.6	1.04	0.99		9.6		
MK4 B	15:51			10	26.5	26.5	5.92	5.92	5.92	90.1	90.1	90.1	34.6	34.6	1.20	1.23		15		
CK1 S	16:25	mid wave	19	1	26.6	26.6	6.68	6.69	6.63	95.6	95.8	93.4	34.6	34.5	1.15	1.22	1.19	9.4		10.2
CK1 M	16:28			9.5	26.1	26.1	6.58	6.57		91.1	91.1		34.8	34.8	1.09	1.23		11		
CK1 B	16:31			18	25.8	25.8	6.06	6.07	6.07	88.4	88.3	88.4	34.9	34.9	1.22	1.22		<5.0		
CK2 S	16:15	mid wave	20	1	26.5	26.6	6.84	6.84	6.58	96.7	97.0	93.6	34.5	34.5	1.19	1.07	1.13	8.6		11.5
CK2 M	16:18			10	26.0	26.0	6.32	6.32		90.4	90.3		34.7	34.7	1.00	1.16		15		
CK2 B	16:21			19	25.7	25.7	5.90	5.90	5.90	86.4	86.4	86.4	34.9	34.9	1.10	1.25		11		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.4 ppt Date: 23/3/2007
 Thermometer: EM 6167

 Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

 Client: Kin Shing Construction Co., Ltd.

 Job No.: J429

 Date of Sampling: 16/3/2007

 Weather Condition: rainy

 Ambient Temperature: °C: 27

 Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L		Average	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Average	Suspended Solids, mg/L		Remarks
					a	b	a	b		a	b	a	b	a	b	Depth		Average		
MK1 S	11:30	mid wave	7	1	26.7	26.7	7.13	7.15	6.93	108.4	109.3	103.0	34.6	34.6	1.34	1.17	1.12	7.0		6.4
MK1 M	11:33			3.5	26.5	26.5	6.73	6.70		97.2	97.1		34.7	34.7	1.20	1.09		6.0		
MK1 B	11:36			6	26.4	26.3	6.34	6.40	6.37	94.4	93.6	94.0	34.7	34.7	0.89	1.01		6.2		
MK2 S	11:40	mid wave	9	1	26.7	26.7	6.90	6.93	6.76	99.8	99.7	97.2	34.6	34.6	1.06	1.17	1.17	<5.0		9.1
MK2 M	11:43			4.5	26.5	26.5	6.60	6.61		94.6	94.7		34.8	34.8	1.24	1.17		12		
MK2 B	11:46			8	26.5	26.5	6.13	6.14	6.14	90.6	90.6	90.6	34.8	34.8	1.17	1.20		6.2		
MK3 S	11:10	mid wave	6	1	26.6	26.6	6.84	6.84	6.63	100.3	100.4	97.5	34.5	34.5	1.19	1.03	1.09	8.0		8.3
MK3 M	11:13			3	26.4	26.4	6.41	6.41		94.5	94.6		34.7	34.7	1.28	0.94		8.2		
MK3 B	11:16			5	26.3	26.3	5.94	5.99	5.97	89.3	89.3	89.3	34.8	34.8	1.06	1.06		8.8		
MK4 S	11:20	mid wave	8	1	26.7	26.7	7.01	7.03	6.78	102.6	102.6	98.2	34.6	34.6	0.98	0.97	1.14	7.2		8.6
MK4 M	11:23			4	26.4	26.4	6.53	6.53		93.7	93.8		34.8	34.8	1.18	1.23		10		
MK4 B	11:26			7	26.4	26.4	5.94	5.93	5.94	88.4	88.8	88.6	34.8	34.8	1.30	1.19		<5.0		
CK1 S	12:00	mid wave	18	1	26.6	26.6	6.94	6.95	6.67	99.5	99.6	96.5	34.7	34.7	1.06	1.30	1.16	13		9.2
CK1 M	12:03			9	26.3	26.3	6.40	6.37		93.4	93.4		34.7	34.7	1.17	1.25		6.0		
CK1 B	12:06			17	26.0	25.9	6.03	6.04	6.04	90.0	90.2	90.1	34.9	34.9	1.16	1.04		8.6		
CK2 S	11:50	mid wave	18	1	26.5	26.5	7.11	7.16	6.88	103.3	103.7	97.8	34.7	34.7	1.20	1.22	1.21	12		14.7
CK2 M	11:53			9	26.1	26.1	6.64	6.62		92.2	91.8		34.9	34.9	1.10	1.03		18		
CK2 B	11:56			17	25.8	25.8	5.83	5.82	5.83	85.6	85.6	85.6	35.0	35.0	1.38	1.33		14		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.4 ppt Date: 23/3/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 19/3/2007

Weather Condition: cloudy

Ambient Temperature, °C: 27

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average	Depth Average	
MK1 S	13:10	small wave	7	1	24.8	24.8	6.88	6.88	6.62	102.5	102.5	100.4	34.8	34.8	1.20	0.89	16		14.0
MK1 M	13:13			3.5	24.6	24.6	6.35	6.35		98.4	98.0		34.9	34.9	1.16	0.93	12		
MK1 B	13:16			6	24.5	24.5	5.90	5.90	5.90	91.9	91.9	91.9	35.0	35.0	1.06	1.11	14		
MK2 S	13:20	small wave	10	1	24.9	24.9	7.00	6.93	6.68	113.4	113.4	104.9	34.8	34.8	1.03	1.17	9.8		11.3
MK2 M	13:23			5	24.6	24.6	6.40	6.40		95.6	97.3		34.9	34.9	1.00	1.22	14		
MK2 B	13:26			9	24.4	24.4	5.97	5.97	5.97	88.4	88.4	88.4	35.0	35.0	1.18	1.10	10		
MK3 S	12:50	small wave	7	1	25.0	25.0	7.11	7.10	6.99	106.6	106.5	101.4	34.7	34.7	0.93	1.07	12		12.0
MK3 M	12:53			3.5	24.8	24.8	6.88	6.88		96.3	96.3		34.8	34.8	1.08	1.19	13		
MK3 B	12:56			6	24.5	24.5	6.32	6.32	6.32	90.0	90.3	90.2	35.0	35.0	1.24	1.33	11		
MK4 S	13:00	small wave	9	1	25.0	25.0	6.93	6.93	6.86	105.0	103.7	98.9	34.7	34.7	1.06	1.14	11		9.9
MK4 M	13:03			4.5	24.7	24.7	6.78	6.79		93.4	93.4		34.8	34.8	1.30	1.13	9.0		
MK4 B	13:06			8	24.5	24.5	6.24	6.24	6.24	87.3	87.2	87.3	34.9	34.9	0.94	1.20	10		
CK1 S	13:40	small wave	20	1	24.7	24.7	6.83	6.83	6.41	98.6	98.5	91.2	34.5	34.5	1.18	1.22	9.0		7.7
CK1 M	13:43			10	24.3	24.3	5.96	6.01		83.6	83.9		34.9	34.9	1.03	1.33	5.8		
CK1 B	13:46			19	23.9	23.9	5.46	5.46	5.46	79.2	79.2	79.2	35.3	35.2	1.07	1.15	8.4		
CK2 S	13:30	small wave	19	1	24.8	24.7	6.88	6.95	6.51	99.5	99.5	92.6	34.7	34.7	1.15	1.19	6.8		9.4
CK2 M	13:33			9.5	24.2	24.2	6.11	6.11		85.4	86.0		35.1	35.1	1.06	1.34	<5.0		
CK2 B	13:36			18	23.8	23.8	5.58	5.58	5.58	78.0	78.3	78.2	35.4	35.3	1.27	1.06	12		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 9.9 NTU: 9.9 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35 ppt: 35 Date: 26/3/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 19/3/2007

Weather Condition: cloudy

Ambient Temperature, °C: 27

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b	Average	a	b	Average	a	b	a	b	Average	Depth Average	
MK1 S	19:20	small wave	7	1	24.9	24.9	7.06	7.06	6.89	103.7	103.5	101.0	35.0	34.8	1.06	1.23	<5.0		14.4
MK1 M	19:23			3.5	24.7	24.7	6.73	6.72		98.4	98.4		34.9	35.0	1.17	1.26	21		
MK1 B	19:26			6	24.5	24.5	6.44	6.44	6.44	93.2	93.2	93.2	35.1	35.1	1.09	0.97	7.8		
MK2 S	19:30	small wave	9	1	24.9	24.9	6.95	6.95	6.79	102.6	102.6	99.6	34.7	34.8	1.08	0.99	13		14.0
MK2 M	19:33			4.5	24.6	24.6	6.63	6.63		96.6	96.7		34.7	34.9	1.17	1.16	13		
MK2 B	19:36			8	24.4	24.4	6.34	6.33	6.34	92.2	92.0	92.1	35.1	35.1	1.38	1.40	16		
MK3 S	19:00	small wave	7	1	24.8	24.8	6.88	6.88	6.72	100.5	100.4	97.4	34.8	34.9	1.22	1.26	5.5		11.5
MK3 M	19:03			3.5	24.5	24.5	6.56	6.56		94.3	94.3		34.9	34.9	1.07	0.82	12		
MK3 B	19:06			8	24.3	24.3	6.30	6.30	6.30	91.2	91.5	91.4	35.0	35.0	1.19	1.10	17		
MK4 S	19:10	small wave	9	1	24.8	24.8	6.95	6.95	6.83	106.3	106.3	99.9	34.8	34.8	1.04	1.22	12		13.0
MK4 M	19:13			4.5	24.5	24.5	6.70	6.70		93.4	93.4		35.0	35.0	1.08	1.15	18		
MK4 B	19:16			8	24.3	24.3	6.41	6.40	6.41	90.0	90.0	90.0	35.0	35.0	1.29	1.33	9.0		
CK1 S	19:50	small wave	18	1	24.8	24.8	7.11	7.08	6.88	113.4	112.6	103.4	34.9	34.9	1.08	1.04	19		18.0
CK1 M	19:53			9	24.3	24.3	6.66	6.65		93.7	93.7		35.2	35.2	1.18	1.23	<5.0		
CK1 B	19:56			17	24.0	23.9	6.18	6.21	6.20	86.6	86.4	86.5	35.3	35.3	1.15	1.23	17		
CK2 S	19:40	small wave	18	1	24.8	24.8	6.95	6.90	6.68	110.9	110.9	103.9	34.9	34.9	1.40	1.43	18		11.1
CK2 M	19:43			9	24.3	24.3	6.43	6.42		96.6	97.3		35.1	35.2	1.08	1.16	8.4		
CK2 B	19:46			17	23.9	23.9	6.05	6.05	6.05	89.5	90.2	89.9	35.3	35.4	1.23	1.18	7.0		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 9.9 NTU: 9.9 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35 ppt: 35 Date: 26/3/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 21/3/2007

Weather Condition: sunny

Ambient Temperature, °C: 23

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L		Average	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		a	b	Average	a	b	a	b	Average	Depth Average	
MK1 S	10:10	mid wave	6	1	21.1	21.1	7.59	7.58	7.46	101.7	101.8	99.6	34.3	34.3	1.04	0.96	1.11	<5.0	<5.0
MK1 M	10:13			3	20.7	20.7	7.34	7.34	7.46	97.4	97.4	99.6	34.5	34.5	1.16	1.17	1.11	<5.0	
MK1 B	10:16			5	20.5	20.5	7.16	7.16	7.16	94.8	94.9	94.9	34.5	34.5	1.05	1.30	1.11	<5.0	
MK2 S	10:20	mid wave	9	1	21.0	21.0	7.48	7.40	7.26	99.3	99.7	98.9	34.3	34.3	1.28	1.11	1.16	<5.0	<5.0
MK2 M	10:23			4.5	20.7	20.7	7.09	7.08	7.26	98.2	98.2	98.9	34.5	34.5	1.07	1.05	1.16	<5.0	
MK2 B	10:26			8	20.4	20.4	7.04	7.04	7.04	97.3	98.0	97.7	34.5	34.5	1.22	1.24	1.16	<5.0	
MK3 S	9:50	mid wave	6	1	21.4	21.4	7.18	7.18	7.26	104.3	104.3	107.5	34.2	34.2	1.08	1.09	1.14	<5.0	<5.0
MK3 M	9:53			3	20.9	20.9	7.33	7.33	7.26	110.6	110.6	107.5	34.4	34.4	0.87	1.00	1.14	<5.0	
MK3 B	9:56			5	20.4	20.5	7.04	7.08	7.06	101.8	104.3	103.1	34.6	34.6	1.37	1.43	1.14	<5.0	
MK4 S	10:00	mid wave	10	1	21.5	21.5	7.26	7.26	7.20	106.8	106.8	104.4	34.3	34.3	1.19	1.02	1.19	<5.0	<5.0
MK4 M	10:03			5	21.1	21.1	7.15	7.13	7.20	102.0	101.9	104.4	34.5	34.5	1.18	1.54	1.19	<5.0	
MK4 B	10:06			9	20.8	20.7	6.94	6.96	6.95	99.9	99.9	99.9	34.7	34.7	1.06	1.13	1.19	<5.0	
CK1 S	10:40	mid wave	18	1	21.6	21.6	7.18	7.18	7.01	105.3	105.3	101.0	34.2	34.1	1.06	1.18	1.15	<5.0	<5.0
CK1 M	10:43			9	20.8	20.8	6.84	6.84	7.01	96.6	96.6	101.0	34.6	34.7	1.09	1.24	1.15	<5.0	
CK1 B	10:46			17	20.0	19.9	6.53	6.53	6.53	91.8	91.8	91.8	35.2	35.2	1.00	1.30	1.15	<5.0	
CK2 S	10:30	mid wave	18	1	21.5	21.4	7.26	7.20	6.98	104.2	104.2	99.0	34.0	34.3	1.34	1.28	1.23	<5.0	<5.0
CK2 M	10:33			9	20.5	20.6	6.73	6.73	6.98	93.8	93.8	99.0	34.8	34.6	1.13	1.10	1.23	<5.0	
CK2 B	10:36			17	18.9	19.1	6.41	6.41	6.41	89.9	88.3	89.1	35.3	35.3	1.09	1.43	1.23	<5.0	

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.3 NTU: 10.3 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 28/3/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 21/3/2007

Weather Condition: sunny

Ambient Temperature, °C: 23

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C		Dissolved Oxygen, mg/L		Average	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		a	b	Average	a	b	a	b	Average	Depth Average	
MK1 S	15:35	mid wave	6	1	21.3	21.3	7.30	7.30	7.23	116.6	116.5	110.0	34.3	34.3	1.09	1.26	1.15	<5.0	11.0
MK1 M	15:38			3	21.0	21.0	7.16	7.16	7.23	103.4	103.4	110.0	34.4	34.5	1.18	1.15	1.15	<5.0	
MK1 B	15:41			5	20.8	20.8	7.02	7.03	7.03	100.3	101.0	100.7	34.7	34.7	1.07	1.17	1.15	11	
MK2 S	15:45	mid wave	9	1	21.2	21.2	7.30	7.30	7.22	113.2	113.0	109.3	34.2	34.2	1.27	1.29	1.16	<5.0	<5.0
MK2 M	15:48			4.5	21.0	21.0	7.14	7.14	7.22	105.4	105.4	109.3	34.4	34.4	1.20	1.13	1.16	<5.0	
MK2 B	15:51			8	20.8	20.8	7.00	7.00	7.00	99.8	99.8	99.8	34.7	34.7	0.90	1.14	1.16	<5.0	
MK3 S	15:15	mid wave	6	1	21.4	21.4	7.24	7.24	7.17	114.6	120.3	114.8	34.1	34.1	1.17	1.33	1.21	6.4	6.4
MK3 M	15:18			3	21.1	21.1	7.10	7.10	7.17	112.2	112.2	114.8	34.5	34.5	1.37	1.22	1.21	<5.0	
MK3 B	15:21			5	20.7	20.7	6.93	6.93	6.93	103.4	103.1	103.3	34.8	34.8	1.06	1.11	1.21	<5.0	
MK4 S	15:25	mid wave	8	1	21.3	21.3	7.16	7.16	7.09	121.2	121.2	115.8	34.0	34.0	1.42	1.28	1.14	<5.0	<5.0
MK4 M	15:28			4	20.9	20.9	7.02	7.00	7.09	110.4	110.4	115.8	34.4	34.4	1.06	1.16	1.14	<5.0	
MK4 B	15:31			7	20.5	20.5	6.83	6.82	6.83	107.4	107.3	107.4	34.7	34.7	1.05	0.84	1.14	<5.0	
CK1 S	16:05	mid wave	17	1	21.1	21.1	7.06	7.06	6.90	108.3	108.3	105.2	34.3	34.3	1.12	1.26	1.22	<5.0	<5.0
CK1 M	16:08			8.5	20.5	20.5	6.73	6.73	6.90	102.1	102.1	105.2	34.8	34.8	1.38	1.30	1.22	<5.0	
CK1 B	16:11			16	20.1	19.8	6.32	6.32	6.32	97.4	97.4	97.4	35.2	35.2	1.06	1.20	1.22	<5.0	
CK2 S	15:55	mid wave	18	1	21.2	21.2	7.16	7.14	6.88	113.4	113.4	107.3	34.2	34.2	0.92	0.97	1.17	<5.0	<5.0
CK2 M	15:58			9	20.4	20.4	6.62	6.61	6.88	101.2	101.2	107.3	34.7	34.7	1.06	1.34	1.17	<5.0	
CK2 B	16:01			17	19.7	19.3	6.07	6.07	6.07	96.4	96.4	96.4	35.3	35.3	1.29	1.44	1.17	<5.0	

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.3 NTU: 10.3 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.3 ppt: 35.3 Date: 28/3/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 23/3/2007

Weather Condition: sunny

Ambient Temperature: °C: 26

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	a	b	
MK1 S	10:20	mid wave	8	1	24.5	24.5	6.48	6.49	6.21	98.4	98.8	95.1	34.5	34.5	1.17	1.22	6.6		
MK1 M	10:23			4	24.3	24.3	5.93	5.93		91.6	91.6		34.6	34.6	1.08	1.14	1.21	<5.0	6.6
MK1 B	10:26			7	24.2	24.2	5.66	5.64	5.65		88.8	89.0	88.9	34.7	34.7	1.34	1.30		<5.0
MK2 S	10:30	mid wave	11	1	24.5	24.5	6.70	6.70	6.29	100.8	100.7	97.0	34.4	34.4	0.94	1.17		<5.0	
MK2 M	10:33			5.5	24.4	24.4	5.88	5.87		93.4	93.0		34.6	34.6	1.02	1.06	1.10	<5.0	<5.0
MK2 B	10:36			10	24.3	24.3	5.55	5.54	5.55		91.9	91.1	91.5	34.7	34.7	1.19	1.23		<5.0
MK3 S	10:00	mid wave	8	1	24.6	24.6	7.17	7.17	6.91	110.0	109.7	101.6	34.5	34.5	1.05	1.11		<5.0	
MK3 M	10:03			4	24.4	24.4	6.65	6.65		93.4	93.3		34.6	34.6	1.02	1.19	1.13	<5.0	<5.0
MK3 B	10:06			7	24.3	24.3	6.24	6.23	6.24		89.5	89.4	89.5	34.6	34.6	1.07	1.34		<5.0
MK4 S	10:10	mid wave	12	1	24.5	24.6	7.04	7.00	6.77	107.7	107.7	104.6	34.5	34.5	1.07	0.83		5.2	
MK4 M	10:13			6	24.3	24.4	6.53	6.52		101.6	101.5		34.6	34.6	1.34	1.42	1.19	<5.0	5.2
MK4 B	10:16			11	24.3	24.3	6.10	6.10	6.10		95.8	95.8	95.8	34.7	34.7	1.20	1.25		5.2
CK1 S	10:50	mid wave	21	1	24.4	24.4	6.94	6.93	6.37	104.4	104.3	98.5	34.5	34.5	1.19	1.04		<5.0	
CK1 M	10:53			10.5	24.2	24.2	5.80	5.80		92.6	92.6		34.7	34.7	1.08	1.26	1.16	<5.0	<5.0
CK1 B	10:56			20	24.1	24.0	5.33	5.33	5.33		88.4	88.4	88.4	34.8	34.9	1.29	1.07		<5.0
CK2 S	10:40	mid wave	22	1	24.4	24.4	6.64	6.63	6.38	97.7	97.6	93.9	34.5	34.5	1.18	1.45		<5.0	
CK2 M	10:43			11	24.4	24.4	6.11	6.14		90.3	90.1		34.8	34.7	1.06	1.18	1.18	<5.0	5.4
CK2 B	10:46			21	23.9	23.9	5.78	5.66	5.72		85.6	85.6	85.6	34.9	34.9	1.16	1.06		5.4

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.5 NTU: 10.5 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.1 ppt: 35.1 Date: 30/3/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 23/3/2007

Weather Condition: sunny

Ambient Temperature: °C: 26

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	a	b	
MK1 S	16:00	mid wave	7	1	24.4	24.4	6.83	6.85	6.62	103.4	103.4	34.7	34.5	34.5	1.10	1.32		<5.0	
MK1 M	16:03			3.5	24.3	24.3	6.38	6.40		98.0	98.0		34.7	34.7	1.04	1.11	1.14	8.6	
MK1 B	16:06			6	24.3	24.3	6.04	6.04	6.04		94.3	94.3	94.3	34.7	34.7	1.20	1.08		<5.0
MK2 S	16:10	mid wave	10	1	24.5	24.5	6.44	6.45	6.29	99.5	99.7	96.5	34.4	34.4	1.06	1.13		<5.0	
MK2 M	16:13			5	24.3	24.3	6.15	6.13		93.4	93.2		34.6	34.6	1.26	1.04	1.09	6.8	6.8
MK2 B	16:16			9	24.3	24.3	5.80	5.80	5.80		89.4	89.5	89.5	34.7	34.7	0.98	1.08		<5.0
MK3 S	15:40	mid wave	7	1	24.5	24.5	7.10	7.04	6.83	107.3	107.2	104.4	34.6	34.6	1.18	1.20		<5.0	
MK3 M	15:43			3.5	24.3	24.3	6.60	6.58		101.5	101.5		34.7	34.7	1.30	1.16	1.13	5.8	5.8
MK3 B	15:46			6	24.2	24.2	6.02	6.01	6.02		93.4	93.4	93.4	34.8	34.8	1.02	0.93		<5.0
MK4 S	15:50	mid wave	9	1	24.4	24.4	6.91	6.91	6.64	104.4	104.3	102.0	34.6	34.6	1.25	1.21		<5.0	
MK4 M	15:53			4.5	24.3	24.3	6.38	6.37		99.5	99.6		34.7	34.7	1.14	1.09	1.13	<5.0	<5.0
MK4 B	15:56			8	24.2	24.2	6.12	6.12	6.12		96.1	96.1	96.1	34.7	34.7	0.95	1.13		<5.0
CK1 S	16:30	mid wave	20	1	24.4	24.4	6.70	6.68	6.45	100.3	100.4	98.3	34.5	34.5	1.22	1.19		<5.0	
CK1 M	16:33			10	24.2	24.2	6.22	6.20		96.2	96.1		34.7	34.7	1.05	0.83	1.15	8.0	8.0
CK1 B	16:36			19	24.1	24.1	5.66	5.64	5.65		87.3	87.3	87.3	35.0	34.9	1.34	1.25		<5.0
CK2 S	16:20	mid wave	20	1	24.4	24.4	7.17	7.17	6.78	108.6	108.6	102.2	34.6	34.6	1.17	1.06		5.2	
CK2 M	16:23			10	24.2	24.1	6.38	6.38		95.7	95.7		34.8	34.8	1.08	1.01	1.12	<5.0	5.2
CK2 B	16:26			19	24.0	24.0	5.89	5.89	5.89		87.0	87.0	87.0	35.0	35.0	1.20	1.20		<5.0

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.5 NTU: 10.5 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.1 ppt: 35.1 Date: 30/3/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 30/3/2007

Weather Condition: cloudy

Ambient Temperature, °C: 19

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C			Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	Average	a	b	Average	a	b	Average	a	b	Average	Depth Average			
MK1 S	15:55	mid wave	7	1	18.7	18.7	5.03	5.03	4.76	93.4	93.4	90.2	35.0	35.0	1.17	1.40	1.19	5.6	5.8	
MK1 M	15:58			3.5	18.5	18.5	4.47	4.49	87.6	86.4	35.1	35.1	1.21	1.14	6.0					
MK1 B	16:01			6	18.3	18.3	4.18	4.19	4.19	76.5	76.6	76.6	35.2	35.2	1.06	1.15	<5.0			
MK2 S	16:05	mid wave	10	1	18.7	18.7	4.97	4.97	4.60	90.6	90.6	86.7	34.9	34.9	1.08	1.25	1.11	<5.0	7.6	
MK2 M	16:08			5	18.5	18.5	4.23	4.23	82.8	82.7	35.1	35.1	1.11	1.00	<5.0					
MK2 B	16:11			9	18.3	18.3	3.80	3.80	3.80	74.4	74.4	74.4	35.1	35.1	1.07	1.13	7.6			
MK3 S	15:35	mid wave	8	1	18.6	18.4	5.11	5.13	4.79	94.4	94.4	90.7	34.9	34.9	1.04	1.19	1.16	<5.0	7.6	
MK3 M	15:38			4	18.3	18.3	4.46	4.46	87.0	86.8	35.0	35.0	1.25	1.14	<5.0					
MK3 B	15:41			7	18.1	18.1	4.00	3.97	3.99	84.0	83.4	83.7	35.1	35.1	1.26	1.10	7.6			
MK4 S	15:45	mid wave	11	1	18.6	18.6	5.04	5.00	4.68	90.7	90.9	87.0	34.9	34.9	1.09	1.13	1.16	<5.0	8.8	
MK4 M	15:48			5.5	18.3	18.3	4.34	4.32	83.2	83.3	35.0	35.0	1.05	1.01	<5.0					
MK4 B	15:51			10	18.1	18.1	3.84	3.85	3.85	77.4	77.4	77.4	35.1	35.1	1.35	1.30	8.8			
CK1 S	16:25	mid wave	19	1	18.5	18.5	4.95	4.94	4.57	90.4	90.4	85.8	35.0	35.0	1.18	1.25	1.16	<5.0	<5.0	
CK1 M	16:28			9.5	18.2	18.2	4.18	4.19	81.3	81.0	35.2	35.2	1.01	0.93	<5.0					
CK1 B	16:31			18	17.9	17.9	3.72	3.72	3.72	76.6	76.6	76.6	35.3	35.3	1.24	1.36	<5.0			
CK2 S	16:15	mid wave	19	1	18.4	18.4	4.88	4.88	4.40	89.3	89.3	83.9	35.0	35.0	1.30	1.18	1.12	5.6	5.5	
CK2 M	16:18			9.5	18.2	18.2	3.92	3.92	78.6	78.5	35.1	35.1	1.06	1.12	<5.0					
CK2 B	16:21			18	17.9	17.9	3.24	3.24	3.24	70.3	70.3	70.3	35.3	35.4	0.98	1.06	5.4			

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt Date: 6/4/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 30/3/2007

Weather Condition: cloudy

Ambient Temperature, °C: 19

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C			Dissolved Oxygen, mg/L			Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	Average	a	b	Average	a	b	Average	a	b	Average	Depth Average			
MK1 S	11:30	mid wave	7	1	18.4	18.4	5.10	5.08	4.69	94.6	94.6	89.2	35.0	35.0	1.27	1.19	1.18	<5.0	5.1	
MK1 M	11:33			3.5	18.2	18.2	4.29	4.29	83.7	83.7	35.1	35.2	1.08	1.11	5					
MK1 B	11:36			6	18.1	18.1	3.84	3.84	3.84	76.6	76.0	76.3	35.3	35.3	1.30	1.10	5.2			
MK2 S	11:40	mid wave	9	1	18.5	18.5	4.96	4.96	4.53	91.7	91.8	88.0	35.0	35.0	0.94	1.08	1.18	<5.0	8.0	
MK2 M	11:43			4.5	18.3	18.3	4.10	4.10	84.3	84.0	35.2	35.2	1.17	1.30	8.0					
MK2 B	11:46			8	18.1	18.1	3.72	3.72	3.72	73.8	73.8	73.8	35.3	35.3	1.32	1.24	<5.0			
MK3 S	11:10	mid wave	7	1	18.5	18.5	5.04	5.03	4.67	93.0	93.2	89.4	35.1	35.1	1.25	1.23	1.18	7.4	7.9	
MK3 M	11:13			3.5	18.2	18.2	4.31	4.30	85.6	85.6	35.2	35.2	1.16	1.13	9.8					
MK3 B	11:16			6	18.0	18.0	3.92	3.93	3.93	74.4	74.4	74.4	35.3	35.3	1.12	1.21	6.6			
MK4 S	11:20	mid wave	10	1	18.4	18.4	4.98	4.99	4.60	92.8	92.8	88.6	35.1	35.1	1.18	1.21	1.22	7.6	6.9	
MK4 M	11:23			5	18.2	18.2	4.22	4.21	84.3	84.3	35.2	35.2	1.07	1.29	7.2					
MK4 B	11:26			9	18.1	18.1	3.69	3.69	3.69	71.7	71.7	71.7	35.3	35.4	1.34	1.23	5.8			
CK1 S	12:00	mid wave	18	1	18.3	18.3	5.16	5.07	4.73	91.5	90.9	88.2	35.2	35.2	1.19	1.11	1.14	<5.0	11.5	
CK1 M	12:03			9	18.1	18.1	4.34	4.36	85.2	85.2	35.4	35.4	1.16	0.93	10					
CK1 B	12:06			17	17.9	17.9	3.39	3.39	3.39	69.8	70.4	70.1	35.5	35.5	1.26	1.18	13			
CK2 S	11:50	mid wave	18	1	18.2	18.2	5.06	5.05	4.62	90.8	90.6	87.2	35.1	35.1	1.29	1.34	1.21	7.8	7.8	
CK2 M	11:53			9	18.0	18.0	4.19	4.18	83.6	83.6	35.4	35.4	1.17	1.24	<5.0					
CK2 B	11:56			17	17.8	17.8	3.53	3.47	3.50	71.5	71.9	71.7	35.6	35.6	1.20	1.03	<5.0			

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt Date: 6/4/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 4/4/2007

Weather Condition: sunny

Ambient Temperature: °C: 26

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	Depth Average		
MK1 S	8:50	mid wave	7	1	26.3	26.2	6.55	6.55	6.19	98.4	98.3	94.7	34.5	34.5	1.30	1.24	1.15	8.6	8.1
MK1 M	8:53			3.5	26.0	26.0	5.83	5.83		91.0	91.0		34.6	34.6	1.16	1.08		8.8	
MK1 B	8:56			6	25.9	25.9	5.61	5.60		5.61	87.3		87.3	87.3	34.7	34.7		1.04	
MK2 S	9:00	mid wave	10	1	26.2	26.2	6.73	6.73	6.46	98.8	98.6	95.6	34.5	34.5	1.15	1.16	1.07	<5.0	7.2
MK2 M	9:03			5	26.0	26.0	6.19	6.17		92.5	92.5		34.6	34.6	1.04	1.00		6.6	
MK2 B	9:06			9	25.8	25.8	5.93	5.94		5.94	88.4		88.4	88.4	34.7	34.7		0.94	
MK3 S	8:30	mid wave	7	1	26.3	26.3	6.90	6.90	6.61	103.3	103.3	99.1	34.6	34.6	1.28	1.17	1.20	<5.0	6.8
MK3 M	8:33			3.5	26.1	26.1	6.31	6.31		94.6	95.0		34.6	34.6	1.06	1.23		6.8	
MK3 B	8:36			6	25.8	25.9	6.04	6.02		6.03	91.2		90.3	90.8	34.8	34.8		1.18	
MK4 S	8:40	mid wave	10	1	26.3	26.3	6.73	6.74	6.47	100.6	100.8	97.9	34.5	34.5	1.30	1.44	1.25	5.4	8.6
MK4 M	8:43			5	26.0	26.0	6.20	6.20		95.0	95.0		34.6	34.6	1.08	1.17		9.4	
MK4 B	8:46			9	25.9	25.9	5.66	5.66		5.66	89.4		89.4	89.4	34.8	34.8		1.20	
CK1 S	9:20	mid wave	19	1	26.1	26.2	7.08	7.11	6.68	106.8	105.3	100.1	34.6	34.6	1.15	1.03	1.22	<5.0	8.1
CK1 M	9:23			9.5	25.9	25.9	6.32	6.19		94.1	94.0		34.9	34.9	1.26	1.45		8.4	
CK1 B	9:26			18	25.7	25.7	5.72	5.70		5.71	85.6		85.4	85.5	35.2	35.2		1.20	
CK2 S	9:10	mid wave	20	1	26.2	26.2	6.95	6.83	6.48	104.9	105.0	98.2	34.6	34.6	1.08	1.20	1.22	<5.0	8.0
CK2 M	9:13			10	25.9	25.9	6.15	6.00		91.9	91.0		34.9	34.9	1.30	1.21		<5.0	
CK2 B	9:16			19	25.7	25.7	5.66	5.63		5.65	83.7		83.6	83.7	35.3	35.2		1.34	

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 11/4/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 4/4/2007

Weather Condition: sunny

Ambient Temperature: °C: 26

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	Depth Average		
MK1 S	14:50	mid wave	6	1	26.3	26.3	6.34	6.34	6.28	96.8	96.8	95.9	34.4	34.4	1.22	1.30	1.16	6.4	6.6
MK1 M	14:53			3	26.2	26.2	6.20	6.25		95.0	95.0		34.6	34.6	1.17	1.05		7.2	
MK1 B	14:56			5	25.9	26.0	5.78	5.78		5.78	89.4		88.8	89.1	34.6	34.6		1.10	
MK2 S	15:00	mid wave	9	1	26.3	26.3	6.41	6.41	6.25	95.9	95.9	93.8	34.4	34.4	1.08	1.15	1.17	5.6	7.8
MK2 M	15:03			4.5	26.1	26.1	6.08	6.09		91.6	91.6		34.6	34.6	1.26	1.33		12.0	
MK2 B	15:06			8	26.0	26.0	5.81	5.76		5.79	88.6		88.8	88.7	34.7	34.7		1.09	
MK3 S	14:30	mid wave	7	1	26.4	26.3	6.69	6.67	6.39	97.1	97.0	93.3	34.3	34.3	1.18	1.10	1.13	8.2	6.4
MK3 M	14:33			3.5	26.2	26.2	6.10	6.10		89.6	89.5		34.5	34.5	1.04	1.22		5.2	
MK3 B	14:36			6	26.1	26.1	5.66	5.74		5.70	85.2		85.1	85.2	34.7	34.7		1.05	
MK4 S	14:40	mid wave	9	1	26.4	26.4	6.50	6.50	6.32	96.0	96.1	93.0	34.4	34.4	1.29	1.20	1.14	<5.0	7.3
MK4 M	14:43			4.5	26.2	26.2	6.14	6.12		90.0	90.0		34.5	34.5	1.15	1.16		7.4	
MK4 B	14:46			8	26.0	26.0	5.84	5.88		5.86	86.1		86.1	86.1	34.7	34.7		1.04	
CK1 S	15:20	mid wave	18	1	26.3	26.2	7.03	7.02	6.72	103.4	103.2	97.1	34.3	34.3	1.18	1.15	1.08	6.0	6.8
CK1 M	15:23			9	26.0	26.0	6.43	6.40		90.6	91.1		34.6	34.6	1.06	1.14		<5.0	
CK1 B	15:26			17	25.8	25.7	5.94	5.90		5.92	85.2		84.4	84.8	34.9	34.9		1.02	
CK2 S	15:10	mid wave	18	1	26.2	26.2	6.85	6.81	6.45	102.6	102.6	97.2	34.3	34.3	1.19	1.07	1.19	<5.0	5.7
CK2 M	15:13			9	26.0	26.0	6.10	6.03		91.7	91.7		34.6	34.6	1.26	1.45		5.8	
CK2 B	15:16			17	25.8	25.8	5.60	5.58		5.59	84.8		84.8	84.8	34.9	34.9		1.08	

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 11/4/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 11/4/2007

Weather Condition: sunny

Ambient Temperature, °C: 19

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	a	b	Average	
MK1 S	9:00	mid wave	7	1	26.2	26.2	6.18	6.18	5.90	113.2	113.1	105.8	34.0	34.0	0.94	0.99	1.10	7.2	7.2
MK1 M	9:03			3.5	26.0	26.0	5.62	5.63	98.4	98.3	34.3	34.3	1.10	1.14	<5.0				
MK1 B	9:06			6	25.9	25.9	5.23	5.23	5.23	91.5	91.5	91.5	34.6	34.6	1.19	1.24	<5.0		
MK2 S	9:10	mid wave	10	1	26.2	26.2	6.04	6.03	5.74	108.4	108.5	102.3	34.1	34.1	1.07	1.11	1.19	<5.0	<5.0
MK2 M	9:13			5	26.0	26.0	5.43	5.44	96.2	96.1	34.3	34.3	1.30	1.28	<5.0				
MK2 B	9:16			9	25.8	25.8	5.09	5.10	5.10	90.3	90.4	90.4	34.5	34.5	1.17	1.20	<5.0		
MK3 S	8:40	mid wave	8	1	26.0	26.1	5.88	5.92	5.55	102.2	102.3	98.7	34.1	34.1	1.04	0.99	1.15	<5.0	5.6
MK3 M	8:43			3.5	25.8	25.8	5.20	5.21	95.2	95.2	34.3	34.3	1.18	1.22	<5.0				
MK3 B	8:46			6	25.7	25.7	4.73	4.73	4.73	88.4	88.4	88.4	34.5	34.5	1.27	1.22	5.6		
MK4 S	8:50	mid wave	11	1	26.0	26.0	5.94	5.93	5.54	101.5	101.9	97.5	34.1	34.1	1.02	1.05	1.13	<5.0	10.8
MK4 M	8:53			4.5	25.8	25.8	5.13	5.14	93.4	93.3	34.3	34.3	1.23	1.20	7.5				
MK4 B	8:56			8	25.7	25.7	4.68	4.65	4.67	85.6	85.6	85.6	34.5	34.5	1.09	1.17	14.0		
CK1 S	9:30	mid wave	19	1	25.8	25.8	6.00	6.00	5.54	99.9	100.4	92.1	34.0	34.0	1.10	1.07	1.25	<5.0	8.4
CK1 M	9:33			9	25.5	25.5	5.10	5.07	84.2	84.0	34.4	34.4	1.18	1.29	<5.0				
CK1 B	9:36			17	25.3	25.3	4.34	4.30	4.32	72.2	72.4	72.3	34.8	34.9	1.41	1.45	8.4		
CK2 S	9:20	mid wave	19	1	25.8	25.8	6.14	6.14	5.68	101.1	101.3	95.0	34.0	34.0	1.07	1.08	1.25	<5.0	6.8
CK2 M	9:23			9	25.5	25.5	5.22	5.22	88.7	88.7	34.5	34.5	1.40	1.34	<5.0				
CK2 B	9:26			17	25.2	25.2	4.19	4.20	4.20	75.6	75.4	75.5	34.9	35.0	1.29	1.33	6.8		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 18/4/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 11/4/2007

Weather Condition: sunny

Ambient Temperature, °C: 19

Tide State: No Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	a	b	Average	
MK1 S																			
MK1 M																			
MK1 B																			
MK2 S																			
MK2 M																			
MK2 B																			
MK3 S																			
MK3 M																			
MK3 B																			
MK4 S																			
MK4 M																			
MK4 B																			
CK1 S																			
CK1 M																			
CK1 B																			
CK2 S																			
CK2 M																			
CK2 B																			

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.4 NTU: 10.4 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.5 ppt: 35.5 Date: 18/4/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 13/4/2007

Weather Condition: sunny

Ambient Temperature: °C: 26

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	a	b	
MK1 S	16:00	mid wave	7	1	25.7	25.7	6.29	6.30	6.19	103.4	103.5	101.7	34.5	34.3	1.17	1.24	1.18	9.2	10.0
MK1 M	16:03			3.5	25.5	25.6	6.08	6.08		99.7	100.0		34.4	34.4	1.20	1.34		11.0	
MK1 B	16:06			6	25.4	25.4	5.82	5.80		5.81	95.4		95.4	95.4	34.5	34.5		1.05	
MK2 S	16:10	mid wave	11	1	25.7	25.7	6.43	6.43	6.18	104.8	104.9	100.7	34.3	34.3	1.06	1.15	1.16	<5.0	<5.0
MK2 M	16:13			5.5	25.5	25.5	5.93	5.94		96.6	96.6		34.4	34.4	1.28	1.20		<5.0	
MK2 B	16:16			10	25.5	25.3	5.64	5.64		5.64	93.4		93.0	93.2	34.5	34.5		1.09	
MK3 S	15:40	mid wave	7	1	25.7	25.7	6.77	6.77	6.43	105.8	105.9	101.3	34.4	34.4	1.05	1.11	1.16	<5.0	<5.0
MK3 M	15:43			3.5	25.5	25.5	6.08	6.08		96.8	96.8		34.4	34.4	1.28	1.26		<5.0	
MK3 B	15:46			6	25.5	25.5	5.55	5.56		5.56	91.7		91.7	91.7	34.5	34.5		1.17	
MK4 S	15:50	mid wave	11	1	25.7	25.7	6.83	6.83	6.56	106.4	106.4	101.9	34.4	34.4	1.14	1.01	1.19	<5.0	12.3
MK4 M	15:53			5.5	25.5	25.5	6.29	6.29		97.4	97.4		34.5	34.5	1.20	1.33		8.6	
MK4 B	15:56			10	25.4	25.4	5.49	5.49		5.49	90.8		90.8	90.8	34.6	34.6		1.25	
CK1 S	16:30	mid wave	20	1	25.6	25.6	7.10	7.07	6.73	108.8	108.9	102.9	34.3	34.3	1.08	1.12	1.14	<5.0	5.5
CK1 M	16:33			10	25.3	25.3	6.38	6.38		97.0	97.0		34.4	34.4	1.00	0.94		5.4	
CK1 B	16:36			19	25.0	25.0	5.51	5.53		5.52	88.6		88.5	88.6	34.6	34.6		1.27	
CK2 S	16:20	mid wave	19	1	25.6	25.6	7.03	7.04	6.73	104.6	104.6	101.4	34.3	34.3	1.12	1.11	1.20	5.4	5.7
CK2 M	16:23			9.5	25.2	25.2	6.41	6.43		98.1	98.1		34.5	34.5	1.23	1.08		5.4	
CK2 B	16:26			18	24.9	24.9	5.48	5.51		5.50	85.8		85.8	85.8	34.7	34.7		1.34	

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.7 NTU: 10.7 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.2 ppt: 35.2 Date: 20/4/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 13/4/2007

Weather Condition: sunny

Ambient Temperature: °C: 26

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	a	b	
MK1 S	11:00	mid wave	7	1	25.8	25.8	6.83	6.83	6.52	103.4	103.4	98.1	34.6	34.6	1.16	1.09	1.13	5.4	6.9
MK1 M	11:03			3.5	25.6	25.6	6.20	6.20		92.7	92.7		34.7	34.7	1.35	1.24		7.2	
MK1 B	11:06			6	25.4	25.4	5.92	5.91		5.92	90.6		90.3	90.5	34.8	34.8		1.07	
MK2 S	11:10	mid wave	10	1	25.8	25.8	6.95	6.95	6.63	108.8	108.8	101.0	34.5	34.5	1.06	1.16	1.21	6.8	10.4
MK2 M	11:13			5	25.6	25.6	6.30	6.30		93.4	93.0		34.6	34.7	1.26	1.21		15.0	
MK2 B	11:16			9	25.4	25.4	5.84	5.80		5.82	88.9		89.0	89.0	34.8	34.8		1.28	
MK3 S	10:40	mid wave	6	1	25.7	25.7	6.73	6.69	6.45	103.4	103.4	98.7	34.6	34.6	0.95	1.16	1.10	<5.0	<5.0
MK3 M	10:43			3	25.5	25.5	6.20	6.17		94.0	94.0		34.8	34.8	1.08	1.02		<5.0	
MK3 B	10:46			5	25.4	25.4	5.97	5.98		5.98	89.3		88.8	89.1	34.8	34.8		1.30	
MK4 S	10:50	mid wave	10	1	25.7	25.7	6.80	6.80	6.56	106.7	106.8	100.9	34.6	34.6	1.39	1.21	1.13	<5.0	7.2
MK4 M	10:53			5	25.4	25.4	6.33	6.31		95.1	95.1		34.7	34.7	1.04	0.96		7.2	
MK4 B	10:56			9	25.3	25.3	5.98	5.90		5.94	87.8		88.0	87.9	34.8	34.8		1.08	
CK1 S	11:30	mid wave	18	1	25.6	25.6	6.58	6.61	6.21	98.8	98.7	92.0	34.5	34.5	1.30	1.25	1.15	6.0	7.9
CK1 M	11:33			9	25.3	25.3	5.84	5.82		85.5	85.1		34.8	34.8	1.08	1.13		8.8	
CK1 B	11:36			17	24.9	24.9	5.34	5.32		5.33	79.9		79.9	79.9	35.1	35.1		1.00	
CK2 S	11:20	mid wave	18	1	25.5	25.5	6.74	6.70	6.18	97.6	97.7	91.2	34.5	34.5	1.08	1.17	1.16	5.4	5.4
CK2 M	11:23			9	25.0	25.0	5.64	5.63		84.7	84.8		34.8	34.7	1.23	1.05		<5.0	
CK2 B	11:26			17	24.9	24.9	5.24	5.24		5.24	80.4		80.3	80.4	35.1	35.1		1.19	

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.7 NTU: 10.7 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.2 ppt: 35.2 Date: 20/4/2007
 Thermometer: EM 6167

Water Quality Monitoring Data Sheet (Ko Lau Wan)

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 16/4/2007

Weather Condition: sunny

Ambient Temperature, °C: 30

Tide State: Mid-Flood

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	Depth Average		
MK1 S	17:10	mid wave	9	1	27.0	27.0	6.08	6.08	5.86	91.8	91.8	89.7	34.2	34.2	1.63	1.68	9.0	7.9	
MK1 M	17:13			4.5	26.8	26.8	5.63	5.63	87.4	87.6	34.4	34.3	1.79	1.58	1.57	7.6			
MK1 B	17:16			8	26.6	26.6	5.31	5.33	5.32	82.6	82.5	82.6	34.5	34.5	1.33	1.41	7.2		
MK2 S	17:20	mid wave	11	1	26.9	26.9	5.83	5.82	5.61	90.5	90.5	88.3	34.2	34.2	1.55	1.51	<5.0	8.6	
MK2 M	17:23			5.5	26.8	26.8	5.40	5.40	86.1	86.1	34.3	34.3	1.85	1.80	1.70	9.6			
MK2 B	17:26			10	26.7	26.6	5.03	5.03	5.03	81.5	81.7	81.6	34.5	34.5	1.76	1.70	7.6		
MK3 S	16:50	mid wave	9	1	26.8	26.8	5.58	5.59	5.38	86.6	86.6	83.5	34.3	34.3	1.64	1.64	5.2	7.4	
MK3 M	16:53			4.5	26.6	26.6	5.17	5.17	80.5	80.4	34.5	34.5	1.34	1.36	1.50	7.4			
MK3 B	16:56			8	26.5	26.5	4.83	4.82	4.83	78.6	78.6	78.6	34.4	34.4	1.52	1.50	9.6		
MK4 S	17:00	mid wave	12	1	26.9	26.9	5.70	5.71	5.40	88.3	88.4	85.1	34.3	34.3	1.49	1.45	7.4	8.9	
MK4 M	17:03			6	26.6	26.6	5.08	5.09	81.8	81.7	34.4	34.4	1.38	1.49	1.38	9.6			
MK4 B	17:06			11	26.5	26.4	4.80	4.77	4.79	76.6	76.6	76.6	34.5	34.5	1.08	1.36	9.6		
CK1 S	17:40	mid wave	20	1	26.7	26.7	6.10	6.08	5.76	93.4	93.4	89.4	34.2	34.3	2.03	2.10	<5.0	6.4	
CK1 M	17:43			10	26.3	26.3	5.43	5.43	85.2	85.4	34.5	34.5	1.89	1.88	1.89	6.4			
CK1 B	17:46			19	26.1	26.1	4.76	4.76	4.76	78.6	78.8	78.7	34.7	34.7	1.75	1.70	<5.0		
CK2 S	17:30	mid wave	19	1	26.7	26.7	5.97	5.99	5.67	90.6	90.8	87.4	34.2	34.2	1.88	1.91	6.0	7.1	
CK2 M	17:33			9.5	26.4	26.4	5.37	5.36	84.0	84.0	34.6	34.6	1.75	1.78	1.75	<5.0			
CK2 B	17:36			18	26.1	26.1	4.88	4.88	4.88	75.3	75.4	75.4	34.7	34.6	1.56	1.60	8.2		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.5 NTU: 10.5 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.0 ppt: 35.0 Date: 23/4/2007
 Thermometer: EM 6167

Project: Contract No. CV/2004/02 Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Client: Kin Shing Construction Co., Ltd.

Job No.: J429

Date of Sampling: 16/4/2007

Weather Condition: sunny

Ambient Temperature, °C: 30

Tide State: Mid-Ebb

Station	Time	Sea Condition	Overall Depth, m	Sampling Depth, m	Temperature, °C				Dissolved Oxygen, mg/L	Dissolved Oxygen, %			Salinity, ppt		Turbidity, NTU		Suspended Solids, mg/L		Remarks
					a	b	a	b		Average	a	b	Average	a	b	Average	Depth Average		
MK1 S	12:15	mid wave	8	1	27.1	27.1	5.94	5.94	5.88	90.3	90.5	87.4	34.3	34.3	1.48	1.53	6.0	7.4	
MK1 M	12:18			4	26.9	26.9	5.43	5.40	84.4	84.4	34.5	34.5	1.66	1.75	1.53	8.4			
MK1 B	12:21			7	26.9	26.9	5.03	5.03	5.03	80.5	80.3	80.4	34.7	34.7	1.38	1.37	7.8		
MK2 S	12:25	mid wave	10	1	27.1	27.1	5.84	5.84	5.57	88.9	89.0	86.2	34.4	34.4	1.65	1.53	7.0	6.7	
MK2 M	12:28			5	26.9	26.9	5.30	5.30	83.3	83.4	34.5	34.5	1.74	1.70	1.64	6.4			
MK2 B	12:31			9	26.8	26.8	4.98	4.98	4.98	80.6	80.6	80.6	34.7	34.7	1.58	1.63	<5.0		
MK3 S	11:55	mid wave	7	1	27.3	27.3	6.04	6.04	5.88	91.4	91.5	90.0	34.3	34.3	1.70	1.68	<5.0	<5.0	
MK3 M	11:58			3.5	27.0	27.0	5.74	5.70	88.4	88.5	34.6	34.6	1.53	1.56	1.52	<5.0			
MK3 B	12:01			6	26.9	26.8	5.02	5.01	5.02	82.4	82.4	82.4	34.7	34.7	1.30	1.35	<5.0		
MK4 S	12:05	mid wave	10	1	27.3	27.6	5.99	6.00	5.72	90.7	90.8	87.3	34.4	34.4	1.68	1.71	6.4	6.7	
MK4 M	12:08			5	27.1	27.1	5.43	5.44	84.0	83.7	34.5	34.6	1.47	1.41	1.56	8.0			
MK4 B	12:11			9	26.9	26.9	4.85	4.90	4.88	79.5	79.6	79.6	34.7	34.8	1.58	1.50	5.8		
CK1 S	12:45	mid wave	19	1	27.2	27.1	5.70	5.73	5.35	89.3	89.0	84.6	34.3	34.3	1.73	1.70	<5.0	9.3	
CK1 M	12:48			9.5	26.6	26.6	4.98	4.99	80.6	79.4	34.6	34.6	1.65	1.68	1.60	11.0			
CK1 B	12:51			18	26.4	26.4	4.17	4.17	4.17	75.4	75.4	75.4	34.9	34.9	1.41	1.40	7.6		
CK2 S	12:35	mid wave	19	1	27.1	27.1	5.66	5.66	5.37	87.4	87.3	84.4	34.4	34.4	1.55	1.64	8.2	8.2	
CK2 M	12:38			9.5	26.7	26.6	5.08	5.09	81.4	81.5	34.6	34.6	1.78	1.81	1.59	<5.0			
CK2 B	12:41			18	26.4	26.4	4.43	4.41	4.42	74.3	74.3	74.3	34.9	34.9	1.34	1.40	<5.0		

Equipment used: Dissolved Oxygen Meter: EM 6167 Calibration Check: 100 100%: 100 Sampled By: Cheng Yi
 Turbidity Meter: EM 2365 Calibration Check: 10.6 NTU: 10.6 Checked By: Raymond Dai
 Salinity Meter: EM 6167 Calibration Check: 35.0 ppt: 35.0 Date: 23/4/2007
 Thermometer: EM 6167



Appendix E

Monitoring Schedule - Upcoming month

CEDD Construction No. CV/2004/02
Reconstruction of Wong Shek and Ko Lau Wan Public Piers

Water Quality Monitoring Schedule - Post-project
April - May 2007

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
15-Apr	16-Apr	17-Apr	18-Apr	19-Apr	20-Apr	21-Apr
			*WQM ³ (Ebb: 13:03) (Flood: 19:19)		*WQM ³ (Ebb: 14:32) (Flood: 07:53)	
22-Apr	23-Apr	24-Apr	25-Apr	26-Apr	27-Apr	28-Apr
	*WQM ³ (Ebb: 17:24) (Flood: 12:40)		*WQM ³ (Ebb: 19:42) No mid-flood tides		*WQM ³ (Ebb: 09:38) (Flood: 15:02)	
29-Apr	30-Apr	1-May	2-May	3-May	4-May	5-May
	Boat repair	Public Holiday	[Post-project] *WQM ³ (Ebb: 12:32) (Flood: 06:06)		[Post-project] *WQM ³ (Ebb: 12:06) (Flood: 20:06)	
6-May	7-May	8-May	9-May	10-May	11-May	12-May
	[Post-project] *WQM ³ (Ebb: 14:02) (Flood: 06:15)		[Post-project] *WQM ³ (Ebb: 10:29) No mid-flood tides		[Post-project] *WQM ³ (Ebb: 19:34) (Flood: 12:29)	
13-May	14-May	15-May	16-May	17-May	18-May	19-May
	[Post-project] *WQM ³ (Ebb: 10:19) (Flood: 16:27)		[Post-project] *WQM ³ (Ebb: 11:56) (Flood: 18:19)			

Notes:

1. WQM - water quality monitoring on mid-flood and mid-ebb tides at Wong Shek (CW1, CW2, MW1 & MW2)
 2. WQM - water quality monitoring on mid-flood and mid-ebb tides at Ko Lau Wan (CK1, CK2, MK1, MK2, MK3 & MK4)
 3. WQM - water quality monitoring on mid-flood and mid-ebb tides at Ko Lau (CK1, CK2, MK1, MK2, MK3 & MK4) and Wong Shek (CW1, CW2, MW1 & MW2)
 4. All monitoring shall be carried out 3 times a week due to pier demolition works.
- * Post-project monitoring will be commenced from 18 Apr onwards for 4 more weeks after the completion of pier demolition on 17 Apr 07.