

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)



Site Inspection Summary

Inspection Information

Date:	3 November 2009
Time:	15:00
Inspection No.:	083

Non-compliance

Nil

Observations

<p><u>Follow Up Observation</u></p> <p>Nil.</p> <p><u>New Observation</u></p> <p>Nil.</p>
--

Remarks

Nil.

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)



Site Inspection Summary

Inspection Information

Date:	10 November 2009
Time:	15:00
Inspection No.:	084

Non-compliance

Nil

Observations

<p><u>Follow Up Observation</u></p> <p>Nil.</p> <p><u>New Observation</u></p> <p>Nil.</p>
--

Remarks

Nil.

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)



Site Inspection Summary

Inspection Information

Date:	17 November 2009
Time:	15:00
Inspection No.:	085

Non-compliance

Nil

Observations

<p><u>Follow Up Observation</u></p> <p>Nil.</p> <p><u>New Observation</u></p> <p>Nil.</p>
--

Remarks

Nil.

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)



Site Inspection Summary

Inspection Information

Date:	24 November 2009
Time:	15:00
Inspection No.:	086

Non-compliance

Nil

Observations

Follow Up Observation

Nil.

New Observation

Nil.

Remarks

Nil.