

Lam Environmental Services Limited

#### CONTRACT NO: HY/2019/14

#### NEW WANG TONG RIVER BRIDGE

## UNDER ENVIRONMENTAL PERMIT NO. EP-555/2018/A

## MONTHLY ENVIRONMENTAL MONITORING & AUDIT REPORT

#### **SEPTEMBER 2023**

CLIENTS:

**Highways Department** 

#### PREPARED BY:

### Lam Environmental Services Limited

19/F Remex Centre, 42 Wong Chuk Hang Road, Hong Kong

Telephone: (852) 2882-3939 Facsimile: (852) 2882-3331 E-mail: <u>info@lamenviro.com</u> Website: <u>http://www.lamenviro.com</u>

## **CERTIFIED BY:**

Raymond Dai Environmental Team Leader

DATE:

16 October 2023



Highways Department Works Division 7th Floor, Trade and Industry Tower 3 Concorde Road Kowloon Hong Kong Your reference:

Our reference:

HKHYD202/50/109244

Date: 13 Octob

13 October 2023

Attention: Mr Kennick Ho

BY EMAIL & POST (email: e3-1.wd@hyd.gov.hk)

Dear Sirs

Agreement No. WD 23/2020 Environmental Monitoring and Audit for New Wang Tong River Bridge Monthly Environmental Monitoring & Audit Report (September 2023)

We refer to emails of 13 October 2023 attaching a Monthly Environmental Monitoring & Audit Report (September 2023) prepared by the Environmental Team (ET) of the captioned.

We have no further comment and hereby verified the Monthly Environmental Monitoring & Audit Report (September 2023) in accordance with Clause 3.4 of the Environmental Permit no. EP-555/2018/A.

Should you have any queries, please do not hesitate to contact the undersigned or our Mr Frankie Yuen on 2618 2831.

Yours faithfully ANEWR CONSULTING LIMITED

James Choi Independent Environmental Checker

CPSJ/LCCR/YCFF/lsmt

cc Lam Environmental Services Limited – Mr Raymond Dai (Fax no.: 2882 3331)

ANewR Consulting Limited Unit 1813, 1815-16, 18/F, Tower A, Regent Centre 63 Wo Yi Hop Road, Kwai Chung, Hong Kong Tel: (852) 2618 2831 Fax: (852) 3007 8648 Email: info@anewr.com Web: www.anewr.com





## TABLE OF CONTENTS

1	INT	RODUCTION	5
	1.1 1.2	Scope of the Report Structure of the Report	5 5
2	PR	OJECT BACKGROUND	7
	2.1 2.2 2.3	Background Project Organization and Contact Personnel Construction Activities	7 7 8
3	ST	ATUS OF REGULATORY COMPLIANCE	9
	3.1 3.2	Status of Environmental Licensing and Permitting under the Project Status of Submission under the EP-555/2018/A	9 9
4	MO	NITORING REQUIREMENTS	.10
	4.1 4.2 4.3	Noise Monitoring Air Monitoring Water Quality Monitoring	. 10 . 12 . 15
5	MOI	NITORING RESULTS	.20
	5.1 5.2 5.3 5.4	Noise Monitoring Results Air Monitoring Results Water Quality Monitoring Results Waste Management	.20 .20 .20 .20
6	CON	IPLIANCE AUDIT	.23
	6.1 6.2 6.3 6.4 6.5	Noise Monitoring. Air Quality Monitoring. Water Quality Monitoring Review of the Reasons for and the Implications of Non-compliance. Summary of action taken in the event of and follow-up on non- compliance	.23 .23 .23 .23 .23
7	EN	VIRONMENTAL SITE AUDIT	.24
8.	CON	IPLAINTS, NOTIFICATION OF SUMMONS AND PROSECUTION	.25
9.	CON	NCLUSION	.26



Lam Environmental Services Limited

#### LIST OF TABLES

- Table 2.2
   Contact Details of Key Personnel
- Table 3.1
   Summary of the current status on licences and/or permits on environmental protection pertinent to the Project
- Table 3.2 Summary of submission status under EP-555/2018/A
- Table 4.1
   Noise Monitoring Station
- Table 4.2
   Noise Monitoring Equipment
- Table 4.3
   Action and Limit Level for Noise Monitoring
- Table 4.4
   Air Monitoring Station
- Table 4.5 Air Quality Monitoring Equipment
- Table 4.6 Action and Limit Level for Air Quality Monitoring
- Table 4.7 Marine Water Quality Stations for Water Quality Monitoring
- Table 4.8 Water Quality Monitoring Equipment
- Table 4.9 Action and Limit Level for Water Quality Monitoring
- Table 5.1 Summary of Water Quality Exceedances
- Table 5.2 Summary of Quantities of Inert C&D Materials
- Table 5.3
   Summary of Quantities of C&D Wastes
- Table 8.1
   Cumulative Statistics on Complaints
- Table 8.2
   Cumulative Statistics on Successful Prosecutions
- Table 9.1
   Construction Activities and Recommended Mitigation Measures in Coming Reporting 3 Months

#### LIST OF FIGURES

- Figure 2.1 Project Layout
- Figure 2.2 Project Organization Chart
- Figure 4.1 Locations of Noise Monitoring Station
- Figure 4.2 Locations of Air Quality Monitoring Stations
- Figure 4.3 Locations of Water Quality Monitoring Stations

#### LIST OF APPENDICES

Appendix 3.1Environmental Mitigation Implementation ScheduleAppendix 4.1Action and Limit LevelAppendix 4.2Copies of Calibration CertificatesAppendix 4.3Wind data extracted from HKO Automatic Weather StationAppendix 5.1Monitoring Schedule for Reporting MonthAppendix 5.2Noise Monitoring Results and Graphical PresentationsAppendix 5.3Air Quality Monitoring Results and Graphical PresentationsAppendix 5.4Water Quality Monitoring Results and Graphical PresentationsAppendix 5.5Monthly Summary Waste Flow TableAppendix 6.1Event and Action PlansAppendix 6.2Summary for Notification of ExceedanceAppendix 8.1Complaint LogAppendix 9.1Construction Programme of Individual Contracts



## EXECUTIVE SUMMARY

- i. This is the Environmental Monitoring and Audit (EM&A) Monthly Report September 2023 of New Wang Tong River Bridge under Environmental Permit no. EP-555/2018/A (Hereafter as "the Project"). The construction works of the Project was commenced on 12 July 2021 and the tentative completion date is Q3 2024. This is the 27<sup>th</sup> EM&A report presenting the environmental monitoring findings and information recorded during the period of 1 September 2023 to 30 September 2023. The cut-off date of reporting is at the end of each reporting month.
- ii. In the reporting month, the principal work activities conducted are as follow:
  - Retaining Wall Construction Bay N1, N2 and N3
  - Preparation Works for Footbridge Demolition

## Noise Monitoring

- iii. Noise monitoring was conducted at one noise monitoring station once per week in the reporting month.
- iv. No action or limit level exceedance was recorded in this reporting period.

## Air Quality Monitoring

- v. 1-hour and 24-hour Total Suspended Particulates (TSP) monitoring was conducted at two monitoring station. 24-hour TSP shall be sampled at least once in every 6 days, while sampling for 1-hour TSP shall be at least 3 times in every 6 day in the reporting month.
- vi. No action or limit level exceedance was recorded in this reporting period.

## Water Quality Monitoring

- vii. Water quality monitoring was conducted at seven monitoring stations three days per week according to the schedule in the reporting month.
- viii. Owing to accessibility and safety issues, water quality monitoring at Station W3 was cancelled with verification from the IEC in November 2020 and approval from the EPD in December 2020.
- ix. No action or limit level exceedance was recorded in this reporting period.

## Site Inspections and Audit

- x. The Environmental Team (ET) conducted weekly site inspections on 6, 13, 20 and 26 September 2023. IEC attended the joint site inspection on 26 September 2023. No noncompliance was found during the site inspection while reminders on environmental measures were recommended.
- xi. The Environmental Team (ET) conducted monthly landscape site inspections on 26 September 2023. No non-compliance was found during the site inspection.



## Complaints, Notifications of Summons and Successful Prosecutions

xii. No environmental complaint, notification of summons and successful prosecution regarding the construction works was recorded in the reporting period.

## **Reporting Changes**

xiii. There are no particular reporting changes.

## Future Key Issues

xiv. In coming reporting 3 months, the scheduled construction activities and the recommended mitigation measures are listed as follows:

Key Construction Works	Recommended Mitigation Measures	
Footbridge demolition	• Dust control during dust generating works;	
Stage 2 Cofferdam Construction	• Implementation of proper noise pollution control;	
Stage 2 Pilling Works	• Covering noisy part of piling machine with proper sound insulation material;	
	<ul> <li>Provision of surface runoff collection and perimeter protection to properly treat runoff without direct discharge into Wang Tong River;</li> <li>Provision of water-tight cofferdam for piling construction in Wang Tong River; and</li> <li>Proper waste handling and storage.</li> </ul>	



### 1 Introduction

### 1.1 Scope of the Report

- 1.1.1. Lam Environmental Services Limited (LES) has been appointed to work as the Environmental Team (ET) under Environmental Permit (EP) no. EP-555/2018/A to implement the Environmental Monitoring and Audit (EM&A) programme as stipulated in the EM&A Manual of the approved Environmental Impact Assessment (EIA) Report for New Wang Tong River Bridge (Register No.: AEIAR-199/2016).
- 1.1.2. In accordance with Clause 3.4 stated in EP-522/2018/A, 1 hard copy and 1 electronic copy of Monthly EM&A Report shall be submitted to the Director within 10 working days after the end of each reporting month.
- 1.1.3. According to Section 10.3.1 of the Project EM&A Manual, the Monthly EM&A Report should be submitted within 10 working days of the end of each reporting month, with the first report due in the month after construction commences.

#### 1.2 Structure of the Report

- Section 1 *Introduction* details the scope and structure of the report.
- Section 2 *Project Background* summarizes background and scope of the project, site description, project organization and contact details of key personnel during the reporting period.
- Section 3 Status of Regulatory Compliance summarizes the status of valid Environmental Permits / Licenses during the reporting period.
- Section 4 *Monitoring Requirements* summarizes all monitoring parameters, monitoring methodology and equipment, monitoring locations, monitoring frequency, criteria and respective event and action plan and monitoring programmes.
- Section 5 *Monitoring Results* summarizes the monitoring results obtained in the reporting period.
- Section 6 Compliance Audit summarizes the auditing of monitoring results, all exceedances environmental parameters.
- Section 7 Environmental Site Audit summarizes the findings of weekly site inspections



undertaken within the reporting period, with a review of any relevant follow-up actions within the reporting period.

- Section 8 Complaints, Notification of summons and Prosecution summarizes the cumulative statistics on complaints, notification of summons and prosecution
- Section 9 Conclusion



## 2 Project Background

## 2.1 Background

- 2.1.1. Silver Mine Bay is a popular bathing beach in Mui Wo, Lantau that attracted 4,550 visitors on a peak day and over 69,000 visitors utilized the beach in 2012.
- 2.1.2. In order to relieve the overcrowding problem and the road safety concern of Wang Tong Bridge (hereafter called "Old Bridge"), two bridges (pedestrian bridge and cycle bridge) are proposed to replace the Old Bridge. The new pedestrian bridge and the new cycle bridge (hereafter called "New Bridge") are also designed to align with the future amenity development on the northern side of the Old Bridge. The location of the project site is shown in *Figure 2.1*.
- 2.1.3. The Project consists of a designated project under Part I, Schedule 2 of the Environmental Impact Assessment Ordinance (EIAO) which is Item C.12 (a)...a dredging operation which is less than 500m from the nearest boundary of an existing...(iii) bathing beach...
- 2.1.4. The major components of the Project under Environmental Permit (EP) (EP No. EP-555/2018/A) comprises: (i) demolition of the existing Wang Tong River Bridge; and (ii) construction of a new twin bridge with segregation for pedestrians and cyclists.

## 2.2 Project Organization and Contact Personnel

- 2.2.1 Highways Department is the overall project controllers for the Project. For the construction phase of the Project, Contractor(s), Environmental Team and Independent Environmental Checker are appointed to manage and control environmental issues.
- 2.2.2 The project organization and lines of communication with respect to environmental protection works are shown in <u>Figure 2.2</u>. Key personnel and contact particulars are summarized in **Table 2.2**:



Table 2.2 Contact	Details	of Key	Personnel
-------------------	---------	--------	-----------

Party	Role	Post	Name	Contact No.	Contact Fax
Highways	The Engineer for the Contract	Senior Engineer	Mr. Terry Chung	3903 6799	3188 3418
Department (HyD)	Engineer's Representative	Engineer	Mr. Yeung Sui Chung	3903 6813	3188 3418
Unison Construction	Contractor	Site Agent	Mr. Peter Lui	2690 2232	2363 3199
Engineering Limited	Environmental Officer	Ms. Rita			
ANewR Consulting Limited	Independent Environmental Checker (IEC)	Independent Environmental Checker (IEC)	Mr. James Choi	2618 2831	3007 8648
Lam Environmental Services Limited	Environmental Team (ET)	Environmental Team Leader (ETL)	Mr. Raymond Dai	2882 3939	2882 3331

## 2.3 Construction Activities

- 2.3.1 In the reporting month, the principal work activities conducted are as follow.
  - Utility Ducting Installation
  - Preparation Works for Footbridge Demolition
- 2.3.2 In coming reporting 3 months, the scheduled construction activities are listed as follows:
  - Footbridge demolition
  - Stage 2 Cofferdam Construction
  - Stage 2 Pilling Works



Lam Environmental Services Limited

## 3 Status of Regulatory Compliance

## 3.1 Status of Environmental Licensing and Permitting under the Project

3.1.1. A summary of the current status on licences and/or permits on environmental protection pertinent to the Project is shown in *Table 3.1*.

## Table 3.1 Summary of the current status on licences and/or permits on environmental protection pertinent to the Project

Permits and/or Licences	Permit. No. / Account No.	Valid From	Expiry Date	Status
Environmental Permit	EP-555/2018/A	16 Dec 2020	N/A	Valid
Billing Account for Disposal of Construction Waste	7038550	29 Mar 2021	End of the Project	Valid
Registration as a Chemical Waste Producer	5213-962-U2333-01	28 Jun 2021	N/A	Valid
Notification pursuant to Air Pollution Control (Construction Dust) Regulation	Form NA submitted to E	PD on 25 Jun 202	1.	
Discharge Licence	WT00040069-2021	10/1/2022	31/1/2027	Valid
Construction Noise Permit	N/A			

## 3.2 Status of Submission under the EP-555/2018/A

3.2.1. A summary of the current status on submission under EP-555/2018/A is shown in Table 3.2.

Table 3.2 Summary of submission status under EP-555/2018/A

EP Condition	Submission	Date of Latest Submission^ or Approval#
Condition 1.12	Notification of Commencement Date of Works	3 June 2021 ^
Condition 2.7	Submission of Management Organization of Main Construction Companies, the ET and the IEC	20 May 2021 ^
Condition 2.8	Submission of Construction Works Schedule and Location Plan	22 June 2021 #
Condition 2.9	Submission of Breeding Bird Survey Report	29 December 2020 #
Condition 3.3	Submission of Baseline Monitoring Report	24 June 2021 #
Condition 4.2	Setting up Dedicated Internet Website	28 April 2021 ^



### 4 Monitoring Requirements

#### 4.1 Noise Monitoring

#### NOISE MONITORING STATIONS

4.1.1. The noise monitoring stations for the Project are listed and shown in Table 4.1 and Figure 4.1.

#### Table 4.1 Noise Monitoring Station

Monitoring Station ID	Monitoring Location	Measurement Type	Level (in terms of no. of floor)
NMS1 A	1 Tung Wan Tau Road	Free-field	G/F

Remarks A: As discussed with the lot owner, a fine adjustment of location at the boundary of 1 Tung Wan Tau Road was proposed and approved in the Baseline Monitoring Report, in order to prevent access obstruction.

#### NOISE MONITORING PARAMETERS, FREQUENCY AND DURATION

4.1.2. For daytime construction work on normal weekdays (0700-1900 Monday to Saturday), one set of 30-min measurement shall be carried out at each NMS every week. Measurement procedures shall be referred to the Noise Control Ordinance-TM. Construction noise level shall be measured in terms of the A-weighted equivalent continuous sound pressure level (Leq). Leq 30min shall be used as the monitoring parameter. As supplementary information for data auditing, statistical results such as L10 and L90 shall also be obtained for reference.

#### MONITORING EQUIPMENT

4.1.3. Noise monitoring was performed using sound level meter at the designated monitoring locations. The sound level meters shall comply with the International Electrotechnical Commission Publications 651:1979 (Type 1) and 804:1985 (Type 1) specifications. Acoustic calibrator shall be deployed to check the sound level meters at a known sound pressure level. Brand and model of the equipment is given in *Table 4.2*.

## Table 4.2 Noise Monitoring Equipment

Equipment	Brand and Model	Series Number
Integrated Sound Level Meter	Larson Davis LxT	4797
Acoustic Calibrator	Larson Davis CAL200	13437

4.1.4. The calibration certificates of the noise monitoring equipment are attached in Appendix 4.2.

#### SAMPLING PROCEDURE AND MONITORING EQUIPMENT

#### 4.2.1. Monitoring Procedure

- (a) The monitoring station shall normally be at a point 1m from the exterior of the sensitive receiver's building façade and be at a position 1.2m above the ground.
- (b) Façade measurements were made at the monitoring locations. For free-field



measurement, a correction factor of +3 dB (A) would be applied.

- (c) The battery condition was checked to ensure the correct functioning of the meter.
- (d) Parameters such as frequency weighting, the time weighting and the measurement time were set as follows:
- (e) Frequency weighting: A, Time weighting: Fast, Measurement time set: continuous 5 mins
- (f) Prior and after to the noise measurement, the meter was checked using the acoustic calibrator for 94dB (A) at 1000 Hz. If the difference in the calibration level before and after measurement was more than ±1 dB (A), the measurement would be considered invalid and repeat of noise measurement would be required after re-calibration or repair of the equipment.
- 4.2.2. Maintenance and Calibration
  - (a) The microphone head of the sound level meter was cleaned with soft cloth at regular intervals.
  - (b) The sound level meter and calibrator were calibrated at yearly intervals.

## EVENT AND ACTION PLAN

4.1.5. Noise Standards for Daytime Construction Activities are specified under EIAO-TM. The Action and Limit levels for construction noise are defined in *Table 4.3* and <u>Appendix 4.1</u>. Should non-compliance of the criteria occurs, action in accordance with the Event and Action Plan in <u>Appendix 6.1</u> shall be carried out.

## Table 4.3 Action and Limit Level for Noise Monitoring

Monitoring Station	Action Level	Limit Level
NMS1	When one documented complaint is received	75 dB(A)



### 4.2 Air Monitoring

#### AIR QUALITY MONITORING STATIONS

4.2.3. The air monitoring stations for the Project are listed and shown in Table 4.4 and Figure 4.3.

#### Table 4.4 Air Monitoring Station

Monitoring Station	Location	Level (in terms of no. of floor)
AMS1 <sup>A</sup>	Silvermine Beach Resort	G/F
AMS2 <sup>B, C</sup>	1 Tung Wan Tau Road	G/F

Remarks A: AMS1 recommended under EM&A manual is at the north of boundary wall of Silvermine Beach Resort. Positioning of HVS on a narrow road at the northern boundary wall would obstruct access of passengers. After liaison with the resort owner, HVS is located near the eastern boundary wall, which is representative and suitable for air quality monitoring. Thus, fine adjustment of location at the boundary of Silvermine Beach Resort was therefore proposed and approved in the Baseline Monitoring Report.

Remarks B: As discussed with the lot owner, a fine adjustment of location at the boundary of 1 Tung Wan Tau Road was proposed and approved in the Baseline Monitoring Report, in order to prevent access obstruction and to minimize noise nuisance induced from HVS operation.

Remarks C: As the agreement of ER and IEC, a fine adjustment of location at the boundary of 1 Tung Wan Tau Road was proposed and approved in the impact monitoring since mid-September 2021, in order to prevent the interruption of GI working area conducted by contractor.

#### AIR MONITORING PARAMETERS, FREQUENCY AND DURATION

- 4.2.4. One-hour and 24-hour TSP levels should be measured to indicate the impacts of construction dust on air quality.
- 4.2.5. 24-hour TSP shall be sampled at least once in every 6 days, while sampling for 1-hour TSP shall be at least 3 times in every 6 days when the highest dust impact takes place.

#### SAMPLING PROCEDURE AND MONITORING EQUIPMENT

- 4.2.6. 24-hour TSP Measuring Installation (HVS)
  - (a) The HVS was installed in the vicinity of the air sensitive receivers. The following criteria were considered in the installation of the HVS.
  - (b) No furnace or incinerator flues were nearby.
  - (c) Airflow around the sampler was unrestricted
  - (d)  $0.6 1.7 \text{ m}^3$  per minute adjustable flow range
  - (e) Equipped with a timing / control device with +/- 5 minutes accuracy for 24 hours operation;
  - (f) Installed with elapsed-time meter with +/- 2 minutes accuracy for 24 hours operation;
  - (g) Equipped with a shelter to protect the filter and sampler;
  - (h) Capable of operating continuously for a 24-hour period.
- 4.2.7. 24-hour Measuring Procedures
  - (a) The power supply was checked to ensure the HVS works properly.
  - (b) The filter holder and the area surrounding the filter were cleaned.
  - (c) The filter holder was removed by loosening the four bolts and a new filter, with stamped number upward, on a supporting screen was aligned carefully.



- (d) The filter was properly aligned on the screen so that the gasket formed an airtight seal on the outer edges of the filter.
- (e) The swing bolts were fastened to hold the filter holder down to the frame. The pressure applied should be sufficient to avoid air leakage at the edges.
- (f) Then the shelter lid was closed and was secured with the aluminum strip.
- (g) The HVS was warmed-up for about 5 minutes to establish run-temperature conditions.
- (h) A new flowrate record sheet was set into the flow recorder.
- (i) The flow rate of the HVS was checked and adjusted at around 1.2 m<sup>3</sup> /min. The range specified in the EM&A Manual was between 0.6-1.7 m<sup>3</sup> /min.
- (j) The programmable timer was set for a sampling period of 24 hrs + 1 hr, and the starting time, weather condition and the filter number were recorded.
- (k) The initial elapsed time was recorded.

Lam Environmental Services Limited

- (I) At the end of sampling, the sampled filter was removed carefully and folded in halflength so that only surfaces with collected particulate matter were in contact.
- (m) It was then placed in a clean plastic envelope and sealed.
- (n) All monitoring information was recorded on a standard data sheet.
- (o) Filters were sent to laboratory for further testing.
- 4.2.8. 1-hour Measuring Procedures
  - (a) Check the calibration period of portable direct reading dust meter prior to monitoring (The direct reading dust meter was calibrated at 2-years interval and checked with High Volume Sampler (HVS) yearly, details refer to Section 2.5.4)
  - (b) Record the site condition near / around the monitoring stations.
  - (c) Install the portable direct reading dust meter to the monitoring location.
  - (d) Slide the power switch to turn the power on.
  - (e) Check of portable direct reading dust meter to ensure the equipment operation in normal condition.
  - (f) Select the period of measurement to 60mins.
  - (g) Check and set the correct time.
  - (h) Select the appropriate unit display for the equipment.
  - (i) Slide the power switch to turn the power off when the monitoring period ended (3 times 1 hour TSP monitoring per day).
  - (j) Uninstall the portable direct reading dust meter
  - (k) Collected the sampled data for analysis.

Remark: Procedures (c) to (h) may be different subject to the brands and models of portable direct reading dust.

- 4.2.9. Maintenance and Calibration
  - (a) The direct reading dust meter was calibrated at 2-years interval and checked with High Volume Sampler (HVS) yearly to determine the accuracy and validity of the results measured.
  - (b) Checking of direct reading dust meter will be carried out in order to determine the conversion factor between the direct reading dust meter and the standard equipment, HVS. The comparison check is to be considered valid based on correlation coefficient checked by HOKLAS laboratory



4.2.10. High Volume Sampler (HVS – Model TE-5170) completed with the appropriate sampling inlets were installed for the 24-hour TSP sampling. 1-hour TSP air quality monitoring was performed by using portable direct reading dust meters at each designated monitoring station, which was verified by IEC and approved by the Engineer's Representative (ER) on 4 December 2020 according to Section 3.4.5 and 3.3.2 of the Project EM&A Manual. The brand and model of the equipment are given in *Table 4.5*.

## Table 4.5 Air Quality Monitoring Equipment

Equipment	Brand and model	Series Number
Portable direct reading dust meter	Met One Aerocet 831	W15449, Y23153
High Volume Sampler	TE-5170	HVS019 HVS020

4.2.11. The calibration certificates of the air quality monitoring equipment are attached in <u>Appendix</u> <u>4.2</u>.

## WIND DATA

4.2.12. Hong Kong Observatory (HKO) meteorological information is widely accepted to be used in various environmental monitoring practices within HKSAR due to its professional quality and precision. Therefore, the daily wind data including Prevailing Wind Direction (degrees) and Mean Wind Speed (km/h) were obtained from Peng Chau Automatic Weather Station to serve as the representative data for meteorological condition during monitoring. The method was agreed by the IEC and approved by the ER on 4 December 2020. The representative wind data from Peng Chau Station were obtained covering the 1-hour and 24-hour TSP monitoring periods. The wind data were extracted and shown in <u>Appendix 4.3</u>.

## EVENT AND ACTION PLAN

4.2.13. The Action and Limit levels for construction air quality are defined in *Table 4.6* and <u>Appendix</u>
 <u>4.1</u>. Should non-compliance of the air quality criteria occur, action in accordance with the Event and Action Plan in <u>Appendix 6.1</u> shall be carried out.

Parameter	Monitoring Station	Action Level (µg/m <sup>3</sup> )	Limit Level (µg/m³)
24-bour TSP Level	AMS1	176.0	260.0
	AMS2	176.0	260.0
1-hour TSP Level	AMS1	276.5	500.0
	AMS2	283.7	500.0

Table 16 Action and	Limit Lovel for Air	Quality Monitoring
1 abie 4.0 Action anu	LIIIIIL LEVELIUL AII	



## 4.3 Water Quality Monitoring

## WATER QUALITY MONITORING STATIONS

4.3.1. Water quality monitoring was undertaken at 7 monitoring stations in the reporting month. The proposed water quality monitoring stations of the Project are shown in *Table 4.7* and *Figure* 4.3.

Station	Description	Monitoring Period	Monitoring Station	Easting	Northing	
Wang Tong River		Mid-Flood	Impact	917747	044540	
VVI	(Major tributary)	Mid-Ebb	Control	01/747	014319	
\M/2	Wang Tong River	Mid-Flood	Impact	817775	81//71	
VVZ	(Major tributary)	Mid-Ebb	Control	01775	014471	
\ <b>\/</b> /3 *	Wang Tong River	Mid-Flood	Impact	817803	011527	
005	(Minor tributary to Tai Wai Yuen)	Mid-Ebb	Control	017005	014007	
10/4	Wang Tong River	Mid-Flood	Impact	817825	911191	
VV4	(Minor tributary to Tai Wai Yuen)	Mid-Ebb	Control	017025	014401	
\M/5	Silvermine Bay	Mid-Flood	Control	817000	811152	
vv5	(Near Silvermine Bay Beach)	Mid-Ebb	Impact	017909	014452	
We	Silvermine Bay	Mid-Flood	Control	919024	911117	
000	(Near Silvermine Bay Beach)	Mid-Ebb	Impact	010024	014447	
\\/7	Silvermine Bay		Control	919061	91/077	
VV7	(Open Water)	Mid-Ebb	Impact	010001	014277	
14/0	Silvermine Bay	Mid-Flood	Control	010001	814444	
۷۷O	(Open Water)	Mid-Ebb	Impact	010224		

Table 4.7	Marine Wat	er Quality Sta	ations for Wate	er Quality	/ Monitorina

Remark \*: Water quality monitoring at Station W3 was cancelled with verification from the IEC and approval from the EPD.

## WATER QUALITY PARAMETERS, FREQUENCY AND DURATION

- 4.3.2. The levels of dissolved oxygen (DO), turbidity, salinity and pH shall be measured in situ while suspended solids (SS) is determined by laboratory analysis at all the designated monitoring stations.
- 4.3.3. In association with the water quality parameters, other relevant data shall also be recorded, such as monitoring location / position, time, water temperature, DO saturation, weather conditions, and any special phenomena underway near the monitoring station.
- 4.3.4. Impact Monitoring shall be carried out 3 days per week, at mid-flood and mid-ebb tides (within ± 1.75 hour of the predicted time). The interval between two sets of monitoring shall not be less than 36 hours. The monitoring period should avoid concurrent marine project in the vicinity.
- 4.3.5. The sampling frequency of at least three days per week should be undertaken when the highest dust impact occurs. Upon completion of the construction works, the monitoring exercise at the designated monitoring locations should be continued for four weeks in the same manner as the impact monitoring. In case exceedance of Action/Limit Level is recorded, the frequency shall be increased as per the Event and Action Plan.



4.3.6. To ensure the robustness of in-situ measurement, parameters shall be measured in duplicate. In case the difference between duplicates is larger than 25%, a third set of measurement shall be carried out.

## SAMPLING PROCEDURES AND MONITORING EQUIPMENT

## Dissolved Oxygen, pH And Temperature Measuring Equipment

- 4.3.7. The instrument should be a portable, weatherproof dissolved oxygen and pH measuring instrument complete with cable, sensor, comprehensive operation manuals, and use a DC power source. It should be capable of measuring:
  - a dissolved oxygen level in the range of 0-20 mg/l and 0-200% saturation
  - a pH level in the range of 0 to 14 units
  - a temperature of 0-45 degree Celsius
- 4.3.8. It should have a membrane electrode with automatic temperature compensation complete with a cable. Sufficient stocks of spare electrodes and cables should be available for replacement where necessary. Salinity compensation shall be build-in in the DO equipment

## Turbidity Measurement Instrument

4.3.9. Nephelometric method shall be used in measuring turbidity in-situ. The instrument shall be portable, weatherproof complete with a cable, sensor, comprehensive operation manuals and DC power source. It shall have a photoelectric sensor capable of measuring turbidity between 0-1000 NTU and complete with a cable with at least 25 m in length. The meter shall be calibrated in order to establish the relationship between NTU units and suspended solids level. Turbidity shall be measured on split water sample collected from the same depths of suspended solid samples.

## Sampler

4.3.10. A water sampler, consisting of a transparent PVC or glass cylinder of a capacity of not less than two litres which can be effectively sealed with cups at both ends shall be used. The water sampler shall have a positive latching system to keep it open and prevent premature closure until released by a messenger when the sampler is at the selected water depth.

## Sampler Container and Storage

4.3.11. A water sampler, Water samples for suspended solids measurement should be collected in high-density polythene bottles, packed in ice (cooled to 4°C without being frozen), and delivered to ALS Technichem (HK) Pty Ltd. as soon as possible after collection for analysis.



## Water Depth Detector

4.3.12. A portable, battery-operated echo sounder shall be used for the determination of water depth at each designated monitoring station. This unit can either be handheld or affixed to the bottom of the workboat, if the same vessel is to be used throughout the monitoring programme.

## <u>Salinity</u>

4.3.13. A portable salinometer capable of measuring salinity in the range of 0-40% shall be provided for measuring salinity of the water at each of monitoring location.

## Monitoring Position Equipment

4.3.14. A hand-held or boat-fixed type digital Global Positioning System (GPS) with waypoint bearing indication or other equivalent instrument of similar accuracy shall be provided and used during monitoring to ensure the monitoring vessel is at the correct location before taking measurements.

## MONITORING METHODOLOGY

- 4.2.14. Monitoring Procedure
  - (a) The condition near the monitoring stations shall be observed and recorded on the data log sheet.
  - (b) Check of sensors and electrodes with certified standard solutions before each use.
  - (c) Wet bulb calibration for a DO meter should be carried out before measurement.
  - (d) Water depth should be recorded by detector before sampling.
  - (e) Sample would be taken using bucket sampler at surface level.
  - (f) Transfer the sampled water carefully into cleaned water bottles (2x 1000ml) provided by the laboratory at the spot after the collection of the water sample for the subsequent laboratory Suspended Solid testing.
  - (g) Transfer the sampled water from the bucket sampler to the rinsed water container for in-situ measurement (In case of the in-situ measurement cannot be carried at spot due to safety and adverse weather condition, sampled water from the bucket sampler will be transfer to cleaned water bottles provided by laboratory. Then, In-situ measurement will be conducted at a safe location which sampled water inside cleaned water bottle will be transfer to the rinsed water container for in-situ measurement) In-situ measurement shall be measured in duplicate.
  - (h) Parameters including Water Temperature (°C), pH (units), Salinity (ppt), DO (mg/L), DO saturation (%) will be measured by the Multifunctional Meter and Turbidity (NTU) will be measured by turbid meter. (Water Temperature and Salinity will be measured as reference parameters)
  - (i) Record the result on the data log sheet and record any special finding during / after in-situ measurement.
  - (j) The water sample bottles will be stored in a cool box (at cooled to 4°C without being frozen), which shall be delivered to HOKLAS laboratory (ALS Technichem (HK) Pty Ltd) for further testing to determine the level of SS.



Lam Environmental Services Limited

## 4.2.15. Maintenance and Calibration

- (a) The responses of sensors and electrodes of the water quality monitoring equipment were cleaned and checked at regular intervals.
- (b) DO meter (Multifunctional Meter) and turbid meter was certified by a laboratory accredited under HOKLAS or any other international accreditation scheme, and subsequently re-calibrated at three monthly intervals.
- 4.3.15. Brand and model of the equipment are given in Table 4.8.

## Table 4.8 Water Quality Monitoring Equipment

Equipment	Brand and model	Series Number
Multifunctional Meter	YSI Professional Plus	20M100002
Turbid meter	Xin Rui WGZ-3B	2209057

4.3.16. Calibration certificates of the water quality monitoring equipment attached in <u>Appendix 4.2</u> will be prepared in the reporting month during commencement of monitoring.

## LABORATORY MEASUREMENT / ANALYSIS

4.3.17. Analysis of suspended solids will be carried out in a HOKLAS accredited laboratory, which is ALS Technichem (HK) Pty Ltd.

## EVENT AND ACTION PLAN

4.3.18. The Action and Limit levels for construction water quality are defined in **Table 4.9** and <u>Appendix 4.1</u>. Should the monitoring results of the water quality parameters at any designated monitoring station exceed the water quality criteria, action in accordance with the Event and Action Plan in <u>Appendix 6.1</u> shall be carried out.



Monitoring		DO (mg/L) *		Turbidity (NTU) ~		SS (mg/L) ~	
Station	Depth	Action	Limit	Action	Limit	Action	Limit Loval
Station		Level	Level	Level	Level	Level	Linnt Level
				7.7 NTU or	12.4 NTU	8.9 mg/L or	11.3 mg/L
W1				120% of	or 130% of	120% of	or 130% of
				upstream	upstream	unstream	upstream
	Surface			control	control	control	control
14/0	Middle			station's	station's	station's SS	station's
VV2	۱۷۱۱۵۵۱۵ ۶	6.5	5.3	turbidity at	turbidity at	at the same	SS at the
	Bottom			the same	the same	tide of the	same tide
	Dottom			tide of the	tide of the	same day, whichever is higher	of the
W4				same day,	same day,		same day,
•••				whichever	whichever		whichever
				is higher	is higher		is higher
W5	Surface,			9.8 NTU or	10.5 NTU	12.6	15.0 mg/L
W6	Middle			120% of	or 130% of	mg/L or	or 130% of
14/7	&			upstream	upstream	120% of	upstream
VV /	Bottom			control	control	upstream	control
	Surface & Middle	5.9	5.5	station's	station's	control	station's
				turbidity at	turbidity at	station's SS	SS at the
				the same	the same	at the same	same tide
W8				tide of the	tide of the	tide of the	of the
				same day,	same day,	same day,	same day,
	Datta	5.0		whichever	whichever	whichever	whichever
	Bottom	5.9	5.5	is higher	is higher	is higher	is higher

## Table 4.9 Action and Limit Level for Water Quality Monitoring

Lam Environmental Services Limited

Remarks +: For DO, non-compliance occurs when monitoring results is lower than the limits. Remarks ~: For SS and Turbidity, non-compliance occurs when monitoring results is larger than the limits



## 5 Monitoring Results

- 5.0.1 The environmental monitoring will be implemented based on the division of works areas of each designed projects. Overall layout showing work areas and monitoring stations is shown in *Figure 2.1* and *Figure 4.1 4.3* respectively.
- 5.0.2 The environment monitoring schedules for reporting month and coming month are presented in <u>Appendix 5.1</u>.

#### 5.1 Noise Monitoring Results

- 5.1.1 Noise monitoring results measured in this reporting period are reviewed and summarized. Details of noise monitoring results and graphical presentation can be referred in <u>Appendix 5.2</u>.
- 5.1.2 No action or limit level exceedance was recorded in this reporting month.

#### 5.2 Air Monitoring Results

- 5.2.1 Air quality monitoring results measured in this reporting period are reviewed and summarized. Details of air monitoring results and graphical presentation can be referred in <u>Appendix 5.3</u>.
- 5.2.2 No action or limit level exceedance was recorded in this reporting month.

### 5.3 Water Quality Monitoring Results

- 5.3.1 Water quality monitoring results measured in this reporting period are reviewed and summarized. Details of water quality monitoring results and graphical presentation can be referred in *Appendix 5.4*.
- 5.3.2 No exceedances were recorded in this reporting month. Event and Action Plan has been implemented with appropriate action taken as referred to corresponding notification of exceedance. Summary of exceedances recorded during the reporting month are summarized in *Table 5.3*.



#### Contract No: HY/2019/14 New Wang Tong River Bridge Monthly EM&A Report (September 2023)

	Parameter	DO (S	S&M)	DO (Bo	ttom)	Tur	bidity	S	S	Excee	edance
										CO	unt
Station	Level	Mid Ebb	Mid	Mid Ebb	Mid	Mid Ebb	Mid Flood	Mid Ebb	Mid Flood	Mid	Mid
	exceeded		Flood		Flood					Ebb	Flood
W1	Action	N/A	-	N/A	-	N/A	-	N/A	-	N/A	-
	Limit	N/A	-	N/A	-	N/A	-	N/A	-	N/A	-
W2	Action	N/A	-	N/A	-	N/A	-	N/A	-	N/A	-
	Limit	N/A	-	N/A	-	N/A	-	N/A	-	N/A	-
W4	Action	N/A	-	N/A	-	N/A	-	N/A	-	N/A	-
	Limit	N/A	-	N/A	-	N/A	-	N/A	-	N/A	-
W5	Action	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
	Limit	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
W6	Action	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
	Limit	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
W7	Action	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
	Limit	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
W8	Action	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
Surface	Limit	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
W8	Action	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
Bottom	Limit	-	N/A	-	N/A	-	N/A	-	N/A	-	N/A
Total	Action	-	-	-	-	-	-	-	-	-	-
	Limit	-	-	-	-	-	-	-	-	-	-

## Table 5.1 Summary of Water Quality Exceedances

Lam Environmental Services Limited

5.3.3 No action or limit level exceedance was recorded in this reporting period.

## 5.4 Waste Management

5.4.1 The quantities of waste for disposal in the Reporting Period are summarized in *Table 5.2* and *Table 5.3*. The Monthly Summary Waste Flow Table is shown in <u>Appendix 5.5</u>. Whenever possible, materials were reused on-site as far as practicable.



Lam Environmental Services Limited

Waste Type	Quantity (this month)	Quantity (Project commencement to the end of last month)	Cumulative Quantity-to-Date
Hard Rock and Large Broken Concrete (Inert) (in '000m³)	0	0.007	0.007
Reused in this Contract (Inert) (in '000m³)	0	0	0
Reused in other Projects (Inert) (in '000m <sup>3</sup> )	0	0	0
Disposal as Public Fill (Inert) (in '000m³)	0.01687	0.45567	0.47254

## Table 5.2 Summary of Quantities of Inert C&D Materials

## Table 5.3 Summary of Quantities of C&D Wastes

Waste Type	Quantity (this month)	Quantity (Project commencement to the end of last month)	Cumulative Quantity-to-Date
Metals (in '000kg)	0	0	0
Paper / Cardboard Packing (in '000kg)	0	0	0
Plastics (in '000kg)	0	0.03	0.03
Chemical Wastes (in '000kg)	0	0	0
General Refuses (in '000m³)	0.0312	0.1827	0.2139



## 6 Compliance Audit

- 6.1.1 The Event Action Plan for construction noise, air quality and water quality are presented in *Appendix 6.1*.
- 6.1.2 The summary of exceedance is presented in <u>Appendix 6.2</u>.

#### 6.2 Noise Monitoring.

6.2.1 No action or limit level exceedance was recorded in this reporting period.

#### 6.3 Air Quality Monitoring

6.3.1 No action or limit level exceedance was recorded in this reporting period.

#### 6.4 Water Quality Monitoring

6.4.1 No action or limit level exceedance was recorded in this reporting period.

#### 6.5 Review of the Reasons for and the Implications of Non-compliance

6.5.1 No environmental non-compliance was recorded in the reporting month.

#### 6.6 Summary of action taken in the event of and follow-up on non-compliance

6.6.1 There was no particular action taken since no non-compliance was recorded in the reporting period.



## 7 Environmental Site Audit

- 7.0.1. Within this reporting month, weekly environmental site audits were conducted on 6, 13, 20 and 26 September 2023. IEC attended the joint site inspection on 26 September 2023.
- 7.0.2. No non-compliance was found during the site inspection while reminders on environmental measures were recommended. Results and findings of these inspections in this reporting month are listed below in *Table 7.1*.

## **Table 7.1 Summary of Environmental Inspections**

ltem	Date	Reminder(s)/ Observation(s)	Action taken by Contractor	Outcome
20230906_1	06 Sept 2023	NRMM label should be provided for the excavator.	NRMM label provided immediately.	Completed.
20230913_1	13 Sept 2023	Nil.	Nil.	Nil.
20230920_1	20 Sept 2023	Nil.	Nil.	Nil.
20230926_1	26 Sept 2023	Nil.	Nil.	Nil.

- 7.0.3. Within this reporting month, monthly landscape site audits were conducted on 26 September 2023.
- 7.0.4. No non-compliance was found during the landscape site inspection. Results and findings of these inspections in this reporting month are listed below in *Table 7.2*.

## Table 7.2 Summary of Landscape site inspections

ltem	Date	Reminder(s)/ Observation(s)	Action taken by Contractor	Outcome
-	-	-	-	-



## 8. Complaints, Notification of Summons and Prosecution

- 8.0.1. No environmental complaint, notification of summons and successful prosecution regarding construction works was recorded in the reporting period.
- 8.0.2. The details of cumulative complaint log and updated summary of complaints are presented in *Appendix 8.1*.
- 8.0.3. Cumulative statistic on complaints and successful prosecutions are summarized in *Table 8.1* and *Table 8.2* respectively.

## Table 8.1 Cumulative Statistics on Complaints

Reporting Period	No. of Complaints
September 2023	0
Project commencement to the end of last reporting month	-
Total	0

## Table 8.2 Cumulative Statistics on Successful Prosecutions

Environmental Parameters	Cumulative No. Brought Forward	No. of Successful Prosecutions this month (Offence Date)	Cumulative No. Project-to-Date
Air	-	0	0
Noise	-	0	0
Water	-	0	0
Waste	-	0	0
Total	-	0	0



Lam Environmental Services Limited

### 9. Conclusion

- 9.0.1. The EM&A programme was carried out in accordance with the EM&A Manual requirements, minor alterations to the programme proposed were made in response to changing circumstances.
- 9.0.2. Mitigation measures according to the environmental mitigation implementation schedule and the EIA were generally implemented by the Contractor. Hence, the EM&A programme was considered effective and shall be maintained.
- 9.0.3. The scheduled construction activities and the recommended mitigation measures for the coming 3 months are listed in *Table 9.1*. The construction programmes of the Project are provided in *Appendix 9.1*.

# Table 9.1 Construction Activities and Recommended Mitigation Measures in ComingReporting 3 Months

Key Construction Works	Recommended Mitigation Measures		
<ul> <li>Key Construction Works</li> <li>Footbridge demolition</li> <li>Stage 2 Cofferdam Construction</li> <li>Stage 2 Pilling Works</li> </ul>	<ul> <li>Recommended Mitigation Measures</li> <li>Dust control during dust generating works;</li> <li>Implementation of proper noise pollution control;</li> <li>Covering noisy part of piling machine with proper sound insulation material;</li> <li>Provision of surface runoff collection and perimeter protection to properly treat runoff without direct discharge into Wang Tong River;</li> <li>Provision of water-tight cofferdam for piling</li> </ul>		
	<ul><li>construction in Wang Tong River; and</li><li>Proper waste handling and storage.</li></ul>		
1			



Figure 2.1

Project Layout



N N	<ol> <li>NOTES</li> <li>ALL LEVELS ARE IN METRES ABOVE HONG KONG PRINCIPAL DATUM.</li> <li>CO-ORDINATES ARE OF HONG KONG 1980 GRID SYSTEM.</li> <li>ALL LEVELS ALONG KERB ARE KERB BOTTOM LEVEL.</li> <li>CHANNELS ARE U SHAPED EXCEPT WHERE STATED, WIDTHS ARE GIVEN.</li> <li>DATE OF SURVEY FOR HIGH WATER MARK : NOV 2020</li> </ol>		
	LEGEND:		
I		LIMIT OF WORKS SITE	
	<u> </u>	HIGH WATER MARK (AS AT NOV.2020)	
		PROPOSED PILECAP AND SOCKETED H PILES	
		EXCAVATION AND PILING WC AREA WITHIN COFFERDAM	RKS
		EXCAVATION AREAS BELOW HIGH WATER MARK	
		PROPOSED BRIDGE PIERS	
		EXTENT OF ABUTMENTS	
		WORKS LAYOUT	
	SOURCE		
		× / 1 /	
	HI/ZUIS	7/14	
	NEW WA BRIDGE	NG TONG RIVER	
	DRAWING TITLE		
	LOC	CATION PLAN	
	SCALE	A1 59-	4X841
	drawing no. CLF	P-EP-01	REV. -
	Į		



Figure 2.2

Project Organization Chart



## Project Organization Chart





Figure 4.1 to Figure 4.3

Locations of Monitoring Stations








Appendix 3.1

Environmental Mitigation Implementation Schedule

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
Air Qual	ity Impact					•
Construct	ion Phase			1	•	
A1	Good housekeeping to minimize dust generation, e.g. by properly handling and storing dusty materials	To minimize dust generation	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A2	Adopt dust control measures, such as dust suppression using water spray on exposed soil, in areas with dusty construction activities, and during material handling	To minimize dust generation due to erosion	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A3	Dust suppression shall be applied to the working area immediately before, during and immediately after site clearance, excavation or earth moving operation to keep the surface wet.	To minimize dust generation due to erosion	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A4	Use water spray to wet the remaining dusty materials on the floor after removing stockpile. The surface of roads or streets shall be free from dust	To minimize dust generation due to erosion	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A5	Storage of dusty materials and debris shall be either entirely covered by impervious sheeting or stored in a three-side and top enclosed area. Alternatively, it should be sprayed with water or a dust suppression chemical to maintain the entire surface wet	To minimize dust generation due to erosion	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A6	All demolished items (e.g. trees, vegetation, structures, debris and rubbish) that may dislodge dust particles shall be covered entirely by impervious sheeting or placed in a three-side and top enclosed area within a day of demolition.	To minimize dust generation	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A7	Store cement bags in shelter with 3 sides and the top covered by impervious materials if the stack exceeds 20 bags	To prevent leakage of cement	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A8	Cement bag shall be debagged, batched and mixed in a three- side and top enclosed area	To minimize dust generation	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A9	Maintain a reasonable height when dropping excavated materials to limit dust generation	To minimize dust generation during movement of excavated materials	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A10	Minimize exposed earth after completion of work in a certain area by hydroseeding, vegetating, soil compacting or paving	To minimize dust generation due to erosion	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO

Appendix 3.1 - Implementation Schedule of Recommended Mitigation Measures

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
A11	Cover materials on trolleys and trucks before leaving the site to prevent debris from dropping during traffic movement or being blown away by wind	To prevent falling of debris during traffic movement and by wind	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A12	Water or a dust suppression chemical shall be continuously sprayed on the surface where any pneumatic or power-driven drilling, cutting, polishing or other mechanical breaking operation is carried out, unless the process is accompanied by the operation of an effective dust extraction and filtering device	To minimize dust emission	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A13	Regular maintenance of plant equipment to prevent black smoke emission	To minimize black smoke emission	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A14	Throttle down or switch off unused machines or machine in intermittent use	To minimize unncessary emission	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A15	Minimize excavation area as far as possible	To minimize dust emission and potential release of odour from exposed ground	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A16	Cover open stockpiles of construction materials (e.g. aggregates, sand and fill materials) with impermeable materials such as tarpaulin during rainstorms.	To prevent soil erosion under rainstorm	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A17	Hoarding of not less than 2.4 m high shall be erected from ground level to surround the work area except for a site entrance or exit	To minimize dust emission	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO
A18	Carry out air quality monitoring throughout the construction period	To monitor construction dust level	HyD's Contractor	At representative ASRs	Prior to and throughout construction phase	EIAO-TM
A19	Carry out regular site inspection to audit the implementation of mitigation measures	To check the implemenation status and effectiveness of mitigation measures	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
Noise Im	pact					
Construct	tion Phase			** 71 1	<b>T</b> 1	
N1	Schedule noisy activities to minimise exposure of nearby NSRs to high levels of construction noise	To minimize construction noise level	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N2	Use hand-held plant equipment or manual equipment as far as possible	To minimize construction noise level	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N3	Use Quality Powered Mechanical Equipment (QPME) which produces lower noise level	To minimize construction noise level	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N4	In the direction of noise sensitive receivers, erect mobile barriers with 3m in height from a few metres of stationary plants, and from about 5m of more mobile plant such as hydraulic breaker to prevent direct view. The barrier should have skid footing and a small cantilevered upper portion. The minimum surface density of the movable noise barrier is 7 kg/m <sup>2</sup> and provide with noise absorbing material.	To lower noise transmission	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N5	Position mobile noisy equipment in location and direction away from NSR	To minimize noise transmission to NSR	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N6	Use silencer or muffler on plant equipment and should be properly maintained	To minimize noise transmission	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N7	Operate noisy plant equipment such as air compressor, generator and concrete pump within enclosure	To minimize noise transmission	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N8	Cover the noisy part of piling machine with acoustic mat	To minimize noise transmission	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N9	Throttle down or switch off unused machines or machine in intermittent use between work	To mimize noise production	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N10	Avoid carrying out noisy activities at the same time	To mimize noise production	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
N11	Reduce the percentage on-time for some noisy PMEs	To mimize noise production	HyD's Contractor	Whole construction site	Throughout construction phase	NCO, EIAO-TM
N12	Carry out noise monitoring throughout the construction period	To monitor construction noise level	HyD's Contractor	At representative NSRs	Prior to and throughout construction phase	EIAO-TM

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
Water Q	uality Impact			-		
W1	Works in the river (excavation within highwater mark and cutting of pier of Old Bridge) shall be carried out inside the watertight cofferdam. The cofferdam can only be removed after completion of work.	To prevent the excavated materials or cuttings from falling into the water and being carried into the sea	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM
W2	Install sheet piles by vibratory action.	To minimize dispersion of sand	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W3	Erect water-tight temporary working platform that can contain falling debris above Wang Tong River. The platform shall be sheltered by tarpaulin for directing rainwater away from the working platform.	To prevent falling of debris and generation of surface runoff into the river	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W4	Water removed from the cofferdam should be desilted before discharge.	To prevent discharge of silty water	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM
W5	Set up sedimentation tank for settling suspended solids in wastewater before discharge into storm drains. Sand/silt removal facilities such as sand traps, silt traps and sedimentation basin should be provided with adequate capacity.	To reduce the amount of suspended solid in wastewater	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W6	Maintain silt removal facilities, channels, manholes before and after rainstorm.	To prevent failure that may lead to flooding	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W7	Remove silt and grit from silt trap at regular interval.	To prevent blockage that may lead to flooding	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W8	Design works program carefully to minimize work areas, hence minimize soil exposure and site runoff.	To minimize surface runoff and chance of erosion	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W9	Arrange excavation works outside rainy seasons (April to September) as far as possible. If this cannot be achieved, the following measures should be implemented: - Cover temporary exposed slope surfaces with impermeable materials, e.g. tarpaulin	To minimize surface runoff and chance of erosion	HyD's Contractor	Whole construction	Throughout construction	ProPECC PN 1/94, EIAO-TM
	<ul> <li>Protect temporary access roads by crushed stone or gravel</li> <li>Carry out adequate surface protection measures well before the arrival of a rainstorm</li> </ul>	chance of closion		site	phase	

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
W10	Minimize exposed earth after completion of work in a certain area by hydroseeding, vegetating, soil compacting or paving	To prevent soil erosion under rainstorm	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W11	Cover open stockpiles of construction materials (e.g. aggregates, sand and fill materials) with impermeable materials such as tarpaulin during rainstorms.	To prevent soil erosion under rainstorm	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W12	Cover and temporary seal manholes to prevent silt, construction materials or debris and surface runoff from entering foul sewers.	To prevent overloading of foul sewers	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W13	Placing equipment, materials and wastes away from Wang Tong River and Silver Mine Bay	To prevent water contamination	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM
W14	Remove waste from the site regularly.	To prevent waste accumulation	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
W15	Apply discharge license for effluent discharge. Treat the discharge to comply with the requirement in TM-DSS.	To ensure compliance with effluent discharge requirement	HyD's Contractor	Whole construction site	Throughout construction phase	WPCO, TM-DSS, EIAO-TM
W16	Reuse treated effluent onsite, e.g. dust suppression and general cleaning.	To minimize wastewater generation	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
W17	Monitor effluent water quality.	To ensure compliance with effluent discharge requirement	HyD's Contractor	Whole construction site	Throughout construction phase	WPCO, EIAO-TM
W18	Register as chemical waste producer if chemical waste will be generated.	To control chemical waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal (Chemical Waste) (General) Regulation, EIAO-TM
W19	Perform maintenance of vehicles and equipment that have oil leakage and spillage potential on hard standings within a bunded area with sumps and oil interceptors.	To prevent oil leakage or spillage	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal (Chemical Waste) (General) Regulation, EIAO-TM
W20	Dispose chemical waste in accordance to Waste Disposal Ordinance. Follow the <i>Code of Practice on the Packaging,</i> <i>Labelling and Storage of Chemical Wastes</i> , examples as follows: - Store chemical wastes at designated safe location with adequate space	To avoid accident in waste storage and handling	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
W21	Placing chemical toilet away from waterbodies as far as possible and on stable, impermeable surface	To minimize accidental leakage of sewage into waterbodies	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
W22	Carry out water quality monitoring at water sensitive receivers	To identify any water quality impact due to the project	HyD's Contractor	Whole construction site	Before, throughout and after construction phase	EIAO-TM
W23	Carry out regular site inspection to audit the implementation of mitigation measures	To check the implemenation status and effectiveness of mitigation measures	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM, APCO

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
Ecologic	al Impact					
Construc	tion Phase					
E1	Before site clearance, the work area should be inspected by ecologist to confirm no active bird nest is present. If any active bird nest is identified, suitable size of buffer area should be established until the nest is abandoned.	To minimize direct impact on the breeding activity of Black- collared Starling	HyD's Contractor	Whole construction site	Before site clearance	EIAO-TM
E2	Erection of hoarding, fencing or provision of clear demarcation of work zones	To minimize direct impact outside work boundary	HyD's Contractor	Whole construction site	Throughout construction phase	EIAO-TM

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
Waste M	anagement					
Construct	tion Phase			1	1	
WM1	Allocate an area for waste sorting and storage of C&D materials into the following categories for reuse, recycle or disposal if possible. Remove waste from the Site for sorting once generated if no suitable space can be identified.	To minimize waste generation	HyD's	Whole	Throughout	Waste Disposal Ordinance, EIAO-
VV IVI I	- excavated material suitable for reuse		Contractor	site	phase	TM
	- inert C&D materials for reuse/disposal offsite				phase	
	- non-inert C&D materials for disposal at landfills					
	- chemical waste					
	- general refuse					
	Adopt good site practice as follows: - Provide training to workers on site cleanliness, waste management (waste reduction, reuse and recycle) and chemical handling procedures	To proper handling of waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
WM2	- Provide sufficient waste collection points and regular removal					
	- Cover waste materials with tarpaulin or in enclosure during transportation					
	<ul> <li>Maintain drainage systems, sumps and oil interceptors</li> <li>Sort out chemical waste for proper handling and treatment onsite or offsite</li> </ul>					
	Adopt waste reduction measures as follows:					
WM3	- Allocate area/containers for sorting, recovering and storing waste for reuse, recycle or disposal (e.g. demolition debris and excavated materials, general refuse like aluminium cans). Remove waste from the Site for sorting once generated if no suitable space can be identified.	To minimize waste generation	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
	- Allocate area for proper storage of construction materials to prevent contamination					

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
WM4	Prepare and implement a site specific Waste Management Plan (WMP) as part of Environmental Management Plan (EMP) in accordance with ETWB TCW No. 19/25. Detail waste management method in the form of avoidance, reuse, recovery, recycling, storage, collection, treatment and disposal according to the recommendations on the EIA and EM&A Manual. It should be approved by the ER and regularly reviewed.	To provide guidance to waste management	HyD's Contractor	Whole construction site	Throughout construction phase	ETWB TCW No. 19/2005, EIAO- TM
WM5	<ul> <li>Store waste materials properly as follows:</li> <li>Avoid contamination by proper handling and storing waste</li> <li>Prevent erosion by covering waste</li> <li>Maintain and clean storage area regularly</li> <li>Sort and stockpile different materials at designated location to enhance reuse</li> </ul>	To properly store waste	HyD's Contractor	Whole construction site	Throughout construction phase	ProPECC PN 1/94, EIAO-TM
WM6	Apply for relevant waste disposal permits in accordance with the Waste Disposal Ordinance (Cap. 354), Waste Disposal (Charges for Disposal of Construction Waste) Regulation (Cap. 345) and the Land (Miscellaneous Provisions) Ordinance (Cap. 28).	To properly dispose waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance (Cap. 354), Waste Disposal (Charges for Disposal of Construction Waste) Regulation (Cap. 345) and the Land (Miscellaneous Provisions) Ordinance (Cap. 28), Dumping at Sea Ordinance (Cap. 466), EIAO- TM
WM7	Implement trip-ticket system for recording the amount of waste generated, recycled and disposed, including chemical wastes	To monitor movement of waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal (Chemical Waste) (General) Regulation, Waste Disposal Ordinance, EIAO-TM
WM8	Reduce water content in wet spoil generated from piling work by mixing with dry materials. Only dispose treated spoil with less than 25% dry density to Public Fill Reception Facilities	To minimize load to reception facilities	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
WM9	Dispose dry waste or waste with less than 70% water content by weight to landfill	To minimize load to reception facilities	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
WM10	<ul> <li>Follow the Code of Practice on the Packaging, Labelling and Storage of Chemical Waste as follows:</li> <li>Store chemical wastes with suitable containers. Seal and maintain the container to avoid leakage or spillage during storage, handling and transport</li> <li>Label chemical waste containers in both English and Chinese with instructions in accordance to Schedule 2 of the Waste Disposal (Chemical Waste) (General) Regulation</li> <li>The container capacity should be smaller than 450 litres unless</li> </ul>	To avoid accident in waste storage and handling	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
W11	agreed by the EPD Comply with the requirement of the chemical storage area: - Store only chemical waste and label clearly the chemical characters of the waste - Have at least 3 sides enclosed and protected from rainfall with cover - Provide sufficient ventilation - Have impermeable floor and has bunds to contain 110% of the capacity of the largest container or 20% of the total volume of the stored waste in the area, whichever is larger - Adequately spaced incompatible materials	To ensure proper storage of chemical waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
W12	Transfer used lubricants, waste oils and other chemicals to oil recycling companies, if possible, and empty oil drums for reuse or refill. No direct or indirect discharge is permitted	To ensure proper disposal of chemical waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal (Chemical Waste) (General) Regulation, EIAO-TM
W13	Hire licensed chemical waste disposal contractors for waste collection and removal. Dispose chemical waste at the approved CWTC at Tsing Yi or other licensed facility	To ensure proper disposal of chemical waste	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal (Chemical Waste) (General) Regulation, EIAO-TM
W14	Provide recycling bins for sorting out recyclables for collection by recycling companies. Non-recyclables should be removed to designated landfills every day by licensed collectors to prevent environmental and health nuisance.	To ensure proper recycling and disposal of general refuse	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM
W15	Terminate excavation work if contaminated soil is found. Prepare Land Contamination Plan (CAP) in accordance with EPD's Guidance Note for Contaminated Land Assessment and Remediation for identifying soil and groundwater sampling locations, followed by testing and remediation where necessary.	To identify presence of contaminated soil and provide proper remediation	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
W16	Marine sediment shall be cement solidified and and sent to laboratory for Toxicity Characteristics Leaching Procedure (TCLP) test according to USEPA Method 1311 and 6020. The results are considered satisfactory if Universal Treatment Standards (UTS) are being met as per Table 4.6 of Practice Guide of Investigation and Remediation of Contaminated Land. The Unconfined Compressive Strength (UCS) of the solidified sediment shall also reach 1000kPa according to the above Practice Guide. If the TCLP and UCS testing results cannot meet the criteria, the sediment shall be retreated by cement solidification. After passing the tests, the solidified sediment shall be backfilled on land after the piling work (e.g. for construction of new piers and abutments). Alternatively, the solidified sediment shall be delivered to public fill reception facilities for beneficial reuse as the last resort.	To prevent leakage of contaminants to water.	HyD's Contractor	Whole construction site	Throughout construction phase	Waste Disposal Ordinance, EIAO- TM, Practice Guide of Investigation and Remediation of Contaminated Land

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
Landsca	pe and Visual					
Construct	ion Phase					
CM1	The construction area and contractor's temporary works areas should be minimised to avoid impacts on adjacent landscape. (Measure for mitigating Landscape and Visual impacts)	To minimise landscape footprint and reduce potential for visual impact	HyD's Contractor	Adjacent to existing bridge	Construction Phase	To approved Detailed Design and RLA's Approval
CM2	Reduction of construction period to practical minimum. (Measure for mitigating Visual impact)	To reduce duration of impacts	HyD's Contractor	N/A	Construction Phase	To approved Detailed Design and RLA's Approval
СМ3	Construction traffic (land and sea) including construction plant, construction vessels and barges should be kept to a practical minimum. (Measure for mitigating Visual impact)	To minimise temporary visual impacts	HyD's Contractor	Connecting roads to site and Silver Mine Bay	Construction Phase	To approved Detailed Design and RLA's Approval
CM4	Erection of decorative mesh screens or construction hoardings around works areas in visually unobtrusive colours. (Measure for mitigating Visual impact)	To screen works sites and plant	HyD's Contractor	Around works areas	Construction Phase	To approved Detailed Design and RLA's Approval
CM5	Avoidance of excessive height and bulk of site buildings and structures. (Measure for mitigating Visual impact)	To reduce temporary visual impacts	HyD's Contractor	Within works sites	Construction Phase	To approved Detailed Design and RLA's Approval
CM6	Control of night-time lighting by hooding all lights and through minimisation of night working periods. (Measure for mitigating Visual impact)	To reduce temporary visual impacts	HyD's Contractor	Within works sites	Construction Phase	To approved Detailed Design and RLA's Approval

EM&A Ref.	Recommended Mitigation Measures	Objectives of the Recommended Measure & Main Concerns to address	Who to Implement the measure	Location of the measure	When to implement the measure	What requirements or standard for the measure to achieve
CM7	All existing trees shall be carefully protected before, during construction and after construction. A Detailed Tree Protection Specification shall be provided in the Contract Specification. Under this specification, the Contractor shall be required to submit a detailed working method statement for the protection of trees prior to undertaking any works adjacent to all retained trees or trees to be transplanted, including trees in contractor's works areas for approval by the Registered Landscape Architect (RLA). This method statement for tree protection and transplanting shall make reference to "Guidelines on Tree Preservation during Construction" and "Guidelines on Tree Transplanting" published by GLTM of the DEVB. Early preparation of trees to be transplanted shall be undertaken to increase their likely survival rate following transplanting. (Measure for mitigating Landscape impact)	To minimise tree impacts and maximise tree preservation	HyD's Contractor	Within and adjacent to works sites	Construction Phase	To approved Detailed Design and RLA's Approval
CM8	Minimisation of Impacts to Wang Tong River through minimised and carefully controlled dredging for pile/abutment removal/construction works. (Measure for mitigating Landscape impact)	To minimise contamination of Wang Tong River	HyD's Contractor	Wang Tong River	Construction Phase	To approved Detailed Design and RLA's Approval



Appendix 4.1

Action and Limit Level



### Action and Limit Level

### Action and Limit Level for Noise Monitoring

Monitoring Station ID	Time Period	Parameter	Action Level	Limit Level dB(A)
NMS1	0700-1900 hrs on normal weekdays	Leq, 30min	When one documented complaint is received	75

#### Baseline Level for Noise Monitoring (For reference and calculation of Construction Noise Levels (CNLs))

Monitoring		0700-1900 hrs on normal weekdays			
Station ID	Monitoring Station	L <sub>eq (30min)</sub> , dB(A)		L <sub>eq (30min)</sub> , dB(A)	
otation ib		Average	Range		
NMS1	1 Tung Wan Tau Road	60.1	52.7 – 64.4		

Remark:

Each of daily 30-minute sampling period includes six consecutive Leq (5min) readings.

Due to free-field measurement, a correction factor of +3 dB(A) is adopted.

All the Construction Noise Levels (CNLs) reported in this report were adjusted with the corresponding baseline level (i.e. Measured Leq – Baseline Leq = CNL), in order to facilitate the interpretation of the noise exceedance.

#### Action and Limit Level for Air Quality Monitoring

Monitoring Station	1-hour T	SP Level	24-hour TSP Level		
ID	Action Level (µg/m³)	Limit Level (µg/m³)	Action Level (µg/m³)	Limit Level (µg/m³)	
AMS1	276.5	500.0	176.0	260.0	
AMS2	283.7	500.0	176.0	260.0	



## Action and Limit Level for Water Monitoring

Monitoring StationDepthAction LevelLimit LevelAction LevelLimit LevelAction LevelLimit LevelW1Middle6.55.37.7 NTU or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher12.4 NTU or 130% of upstream control12.4 NTU or 130% of upstream control8.9 mg/L or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher8.9 mg/L or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher11.3 mg/L or 130% of upstream control station's turbidity at the same tide of the same day, whichever is higher11.3 mg/L or 130% of upstream control station's SS at the same tide of the same day, whichever is higher11.3 mg/L or 130% of upstream controlW46.55.35.37.7 NTU or tool turbidity at the same day, whichever is higher8.9 mg/L or tation's SS at the same tide of the same day, whichever is higher11.3 mg/L or tation's SS at the same tide of the same the same tide of the same tide of the same day, whichever is higherW8Surface & Middle5.95.59.8 NTU or turbidity at the same day, whichever is higher10.5 NTU or tation's SS at turbidity at the same tide of the same day, whichever is 	Monitoring		DO (m	ng/L) +	Turbidity (NTU) ~		SS (mg/L) ~	
StationLevelLevelLevelLevelLevelLevelLevelW1Middle6.55.37.7 NTU or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher7.7 NTU or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher8.9 mg/L or 120% of upstream control station's turbidity at the same tide of the same tide of the same day, whichever is higher11.3 mg/L or 130% of upstream control station's turbidity at the same tide of the same tide of the same the same tide of the same tide of the same day, whichever is higher11.3 mg/L or 130% of upstream control station's station's	Station	Depth	Action	Limit	Action	Limit	Action	Limit
W1Middle6.55.37.7 NTU or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher12.4 NTU or 130% of upstream control station's turbidity at the same tide of the same day, whichever is higher12.4 NTU or 130% of upstream control station's turbidity at the same tide of the same day, whichever is higher8.9 mg/L or 120% of upstream control station's station's SS at the same tide of the same day, whichever is higher11.3 mg/L or 130% of upstream controlW46.55.35.37.7 NTU or 120% of upstream control12.4 NTU or 130% of upstream control13.0% of upstream day, whichever is higher11.3 mg/L or 130% of upstream controlW46.55.95.59.8 NTU or 120% of upstream control12.6 mg/L or 130% of upstream control15.0 mg/L or 130% of upstream controlW8Surface & Middle5.95.59.8 NTU or 120% of upstream control10.5 NTU or 130% of upstream control12.6 mg/L or 12.0% of upstream control15.0 mg/L or 130% of upstream controlW8Surface & Middle5.95.55.59.8 NTU or turbidity at the same tide of the same day, whichever is higher10.5 NTU or turbidity at the same tide of the same day, whichever is higher12.6 mg/L or to mg/L or<	Station		Level	Level	Level	Level	Level	Level
W2Middle6.55.3station's turbidity at the same tide of the same day, whichever is higherstation's SS at turbidity at the same tide of the same day, whichever is higherstation's SS at turbidity at the same tide of the same day, whichever is higherstation's SS at turbidity at the same tide of the same day, whichever is higherstation's SS at turbidity at the same tide of the same day, whichever is higherstation's SS at <b< th=""><th>W1</th><th></th><th></th><th></th><th>7.7 NTU or 120% of upstream control</th><th>12.4 NTU or 130% of upstream control</th><th>8.9 mg/L or 120% of upstream control</th><th>11.3 mg/L or 130% of upstream control</th></b<>	W1				7.7 NTU or 120% of upstream control	12.4 NTU or 130% of upstream control	8.9 mg/L or 120% of upstream control	11.3 mg/L or 130% of upstream control
W5       Middle       9.8 NTU or       10.5 NTU or       12.6 mg/L or       15.0 mg/L or         W6       Middle       5.9       5.5       9.8 NTU or       130% of       upstream       control         W8       Surface       5.9       5.5       5.5       station's       turbidity at the same tide of the same day, whichever is higher       the same day, whichever is higher       the same day, whichever is higher       whichever is higher       whichever is higher	W2 W4	Middle	6.5	5.3	station's turbidity at the same tide of the same day, whichever is higher	station's turbidity at the same tide of the same day, whichever is	station's SS at the same tide of the same day, whichever is higher	station's SS at the same tide of the same day, whichever is higher
W6Middle9.8 NTU or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher10.5 NTU or 130% of upstream control station's turbidity at the same tide of the same day, whichever is higher10.5 NTU or 130% of upstream control station's turbidity at the same tide of the same day, whichever is higher12.6 mg/L or 120% of upstream control station's station's turbidity at the same tide of the same day, whichever is higher15.0 mg/L or 130% of upstream control station's station's turbidity at the same tide of the same day, whichever is higher10.5 NTU or 120% of upstream control station's turbidity at the same tide of the same day, whichever is higher15.0 mg/L or 130% of upstream control station's station's station's turbidity at the same tide of the same day, whichever is higher10.5 NTU or 120% of upstream control station's station's station's turbidity at the same tide of the same day, whichever is higher15.0 mg/L or 130% of upstream control station's station's station's station's station's the same tide of the same day, whichever is higher	W5					nighei		
W7       120% of upstream       120% of       130% of       130% of         W8       Surface       \$5.9       5.5       5.5       \$5.5       \$5.5       \$120% of       upstream       control       station's       station's       station's SS at       station's SS at       station's SS       station's SS       at the same       the same tide       of the same       day,       same day,       whichever is       whichever is       higher       h	W6	Middle			9.8 NTU or	10.5 NTU or	12.6 mg/L or	15.0 mg/L or
W8Surface & Middle5.95.5upstream control station's turbidity at the same tide of the same day, whichever is higherupstream control station's turbidity at the same tide of the same day, whichever is higherupstream control station's turbidity at the same tide of the same 	W7	inidate			120% of	upstream	120% of	130% of
I Bottom 50 55 5	W8	Surface & Middle	5.9	5.5	upstream control station's turbidity at the same tide of the same day, whichever is higher	control station's turbidity at the same tide of the same day, whichever is higher	upstream control station's SS at the same tide of the same day, whichever is higher	upstream control station's SS at the same tide of the same day, whichever is higher

Remarks +: For DO, non-compliance occurs when monitoring results is lower than the limits. Remarks ~: For SS and Turbidity, non-compliance occurs when monitoring results is larger than the limits.



Appendix 4.2

**Copies of Calibration Certificates** 



Tel: (852) 2873 6860 Fax: (852) 2555 7533 E-mail: smec@cigismec.com Website: www.cigismec.com



## **CERTIFICATE OF CALIBRATION**

Certificate No.:	22CA1101 02-02		Page:	1 0	of 2
Item tested					
Description:	Acoustical Calibr	ator (Class 1)			
Manufacturer:	Larson Davis				
Type/Model No.:	CAL200				
Serial/Equipment No.:	13437				
Adaptors used:	-				
Item submitted by					
Curstomer:	Lam Environmen	tal Services Ltd.			
Address of Customer:	-				
Request No.:	-				
Date of receipt:	01-Nov-2022				
Date of test:	04-Nov-2022				
Reference equipment	used in the cali	bration			
Description:	Model:	Serial No.	Expiry Date:	Tra	aceable to:
Lab standard microphone	B&K 4180	2412857	23-May-2023	SC	L
Preamplifier	B&K 2673	2743150	28-Jun-2023	CE	PREI
Measuring amplifier	B&K 2610	2346941	30-Jun-2023	CE	PREI
Signal generator	DS 360	33873	21-Jan-2023	CE	PREI
Digital multi-meter	34401A	US36087050	30-May-2023	CE	PREI
Audio analyzer	8903B	GB41300350	06-Jul-2023	CE	PREI
Universal counter	53132A	MY40003662	13-Jun-2023	CE	PREI

#### Ambient conditions

Temperature:	22 ± 1 °C
Relative humidity:	55 ± 10 %
Air pressure:	1005 ± 5 hPa

#### **Test specifications**

- The Sound Calibrator has been calibrated in accordance with the requirements as specified in IEC 60942 1997 Annex B and the lab calibration procedure SMTP004-CA-156.
- 2. The calibrator was tested with its axis vertical facing downwards at the specific frequency using insert voltage technique.
- 3. The results are rounded to the nearest 0.01 dB and 0.1 Hz and have not been corrected for variations from a reference pressure of 1013.25 hectoPascals as the maker's information indicates that the instrument is insensitive to pressure changes.

#### **Test results**

This is to certify that the sound calibrator conforms to the requirements of annex B of IEC 60942: 1997 for the conditions under which the test was performed. This does not imply that the sound calibrator meets IEC 60942 under any other conditions.

Date:

05-Nov-2022

Details of the performed measurements are presented on page 2 of this certificate.



Comments: The results reported in this certificate refer to the conditon of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument. The results apply to the item as received.

1

Feng Junqi

© Soils & Materials Engineering Co., Ltd.

Approved Signatory:

Form No.CARP156-1/Issue 1/Rev.D/01/03/2007

**Company Chop:** 

HKAS has accredited this laboratory (Reg. No. HOKLAS 028) under HOKLAS for specific calibration activities as listed in the HOKLAS directory of accredited laboratories. The results shown in this certificate are traceable to the International System of Units (SI) or recognised measurement standards. The results relate only to the item(s) calibrated. This certificate shall not be reproduced except in full without approval of the laboratory.



#### 综合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD.

香港新界葵涌永基路22-24號好爸爸創科大廈

Good Ba Ba Hitech Building, Nos. 22-24 Wing Kei Road, Kwai Chung, New Territories, Hong Kong Tel: (852) 2873 6860 Fax: (852) 2555 7533 E-mail: smec@cigismec.com Website: www.cigismec.com



## **CERTIFICATE OF CALIBRATION**

(Continuation Page)

Certificate No.:

22CA1101 02-02

Page: 2 of

of

2

#### 1, Measured Sound Pressure Level

The output Sound Pressure Level in the calibrator head was measured at the setting and frequency shown using a calibrated laboratory standard microphone and insert voltage technique. The results are given in below with the estimated uncertainties.

Frequency	Output Sound Pressure	Measured Output	Estimated Expanded
Shown	Level Setting	Sound Pressure Level	Uncertainty
Hz	dB	dB	dB
1000	94.00	93.76	0.10

#### 2, Sound Pressure Level Stability - Short Term Fluctuations

The Short Term Fluctuations was determined by measuring the maximum and minimum of the fast weighted DC output of the B&K 2610 measuring amplifier over a 20 second time interval as required in the standard. The Short Term Fluctuation was found to be:

At 1000 Hz	STF = 0.011 dB
Estimated expanded uncertainty	0.005 dB

#### 3, Actual Output Frequency

The determination of actual output frequency was made using a B&K 4180 microphone together with a B&K 2673 preamplifier connected to a B&K 2610 measuring amplifier. The AC output of the B&K 2610 was taken to an universal counter which was used to determine the frequency averaged over 20 second of operation as required by the standard. The actual output frequency at 1 KHz was:

At 1000 Hz	Actual Frequency = 1000.0 Hz	
Estimated expanded uncertainty	0.1 Hz	Coverage factor k = 2.2

#### 4, Total Noise and Distortion

For the Total Noise and Distortion measurement, the unfiltered AC output of the B&K 2610 measuring amplifier was connected to an Agilent Type 8903 B distortion analyser. The TND result at 1 KHz was:

At 1000 Hz	TND = 0.7%
Estimated expanded uncertainty	0.7 %

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

	Λ	- End -	1
Calibrated by:	1~Y	Checked by:	Ac
	ung Chi Yip	Chan Y	fuk Yiu
Date:	04-Nov-2022	Date: 05-Nov	1-2022

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP156-2/Issue 1/Rev.C/01/05/2005

HKAS has accredited this laboratory (Reg. No. HOKLAS 028) under HOKLAS for specific calibration activities as listed in the HOKLAS directory of accredited laboratories. The results shown in this certificate are traceable to the International System of Units (SI) or recognised measurement standards. The results relate only to the item(s) calibrated. This certificate shall not be reproduced except in full without approval of the laboratory.



#### 綜合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD.

香港新界葵涌永基路22-24號好爸爸創科大廈 Good Ba Ba Hitech Building, Nos. 22-24 Wing Kei Road, Kwai Chung, New Territories, Hong Kong Tel: (852) 2873 6860 Fax: (852) 2555 7533 E-mail: smec@cigismec.com Website: www.cigismec.com



## **CERTIFICATE OF CALIBRATION**

Certificate No.:	22CA1101 02-01		Page	1	of	2
Item tested						
Description:	Sound Level Mete	r (Type 1)	Microphone		Preamp	)
Manufacturer:	Larson Davis		PCB		PCB '	
Type/Model No.:	LxT1		377B02		PRMLx	T1L
Serial/Equipment No.:	0004797		340739		042622	
Adaptors used:	-		-		-	
Item submitted by						
Customer Name:	Lam Environment	al Services Limited.				
Address of Customer:	-					
Request No.:	-					
Date of receipt:	01-Nov-2022					
Date of test:	04-Nov-2022					
Reference equipment	used in the calib	ration				
Description:	Model:	Serial No.	Expiry Date:		Tracea	ble to:
Multi function sound calibrator	B&K 4226	2288444	23-Aug-2023		CIGISM	EC
Signal generator	DS 360	33873	21-Jan-2023		CEPREI	
Ambient conditions						
Temperature:	22 ± 1 °C					
Relative humidity:	55 ± 10 %					
Air pressure:	1005 ± 5 hPa					
Test specifications						

- 1, The Sound Level Meter has been calibrated in accordance with the requirements as specified in BS 7580: Part 1: 1997 and the lab calibration procedure SMTP004-CA-152.
- 2, The electrical tests were performed using an electrical signal substituted for the microphone which was removed and replaced by an equivalent capacitance within a tolerance of ±20%.
- 3. The acoustic calibration was performed using an B&K 4226 sound calibrator and corrections was applied for the difference between the free-field and pressure responsess of the Sound Level Meter.

#### **Test results**

This is to certify that the Sound Level Meter conforms to BS 7580: Part 1: 1997 for the conditions under which the test was performed.

Details of the performed measurements are presented on page 2 of this certificate.

Actual Measurement data are documented on worksheets.

Approved Signatory: Date: 05-Nov-2022 **Company Chop:** Fera Junai

**Comments:** The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument. The results apply to the item as received.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP152-1/Issue 1/Rev.C/01/02/2007

HKAS has accredited this laboratory (Reg. No. HOKLAS 028) under HOKLAS for specific calibration activities as listed in the HOKLAS directory of accredited laboratories. The results shown in this certificate are traceable to the International System of Units (SI) or recognised measurement standards. The results relate only to the item(s) calibrated. This certificate shall not be reproduced except in full without approval of the laboratory.



#### 綜 合 試 驗 有 限 公 司 SOILS & MATERIALS ENGINEERING CO., LTD.

香港新界葵涌永基路22-24號好爸爸創科大廈 Good Ba Ba Hitech Building, Nos. 22-24 Wing Kei Road, Kwai Chung, New Territories, Hong Kong Tel: (852) 2873 6860 Fax: (852) 2555 7533 E-mail: smec@cigismec.com Website: www.cigismec.com



2

## **CERTIFICATE OF CALIBRATION**

(Continuation Page)

Certificate No.:

22CA1101 02-01

2 of

Page

#### 1, **Electrical Tests**

The electrical tests were perfomed using an equivalent capacitance substituted for the microphone. The results are given in below with test status and the estimated uncertainties. The "Pass" means the result of the test is inside the tolerances stated in the test specifications. The "-" means the result of test is outside these tolerances.

			Expanded	Coverage
Test:	Subtest:	Status:	Uncertanity (dB)	Factor
Self-generated noise	Α	Pass	0.3	
Son generated heree	C C	Pass	0.8	21
	Lin	Pass	1.6	22
Linearity range for Leg	At reference range Step 5 dB at 4 kHz	Pass	0.3	
Enfoundy range for Eeq	Reference SPL on all other ranges	Pass	0.0	
	2 dB below upper limit of each range	Pass	0.3	
	2 dB above lower limit of each range	Pass	0.3	
Linearity range for SPI	At reference range Step 5 dB at 4 kHz	Pass	0.3	
Frequency weightings	A	Pass	0.3	
i iequeney noightinge	C	Pass	0.3	
	Lin	Pass	0.3	
Time weightings	Single Burst Fast	Pass	0.3	
	Single Burst Slow	Pass	0.3	
Peak response	Single 100us rectangular pulse	Pass	0.3	
R.M.S. accuracy	Crest factor of 3	Pass	0.3	
Time weighting I	Single burst 5 ms at 2000 Hz	Pass	0.3	
	Repeated at frequency of 100 Hz	Pass	0.3	
Time averaging	1 ms burst duty factor 1/10 <sup>3</sup> at 4kHz	Pass	0.3	
	1 ms burst duty factor 1/10 <sup>4</sup> at 4kHz	Pass	0.3	
Pulse range	Single burst 10 ms at 4 kHz	Pass	0.4	
Sound exposure level	Single burst 10 ms at 4 kHz	Pass	0.4	
Overload indication	SPL	Pass	0.3	
	Leq	Pass	0.4	

#### 2, Acoustic tests

The complete sound level meter was calibrated on the reference range using a B&K 4226 acoustic calibrator with 1000Hz and SPL 94 dB. The sensitivity of the sound level meter was adjusted. The test result at 125 Hz and 8000 Hz are given in below with test status and the estimated uncertainties.

			Expanded	Coverage
Test:	Subtest	Status	Uncertanity (dB)	Factor
Acoustic response	Weighting A at 125 Hz	Pass	0.3	
	Weighting A at 8000 Hz	Pass	0.5	

#### 3, Response to associated sound calibrator

N/A

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

	1	- End -	71
Calibrated by:	1~~/	Checked by:	Jan
	Fung Chi Yip		Chan Yuk Yiu
Date:	04-Nov-2022	Date:	05-Nov-2022

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP152-2/Issue 1/Rev.C/01/02/2007

HKAS has accredited this laboratory (Reg. No. HOKLAS 028) under HOKLAS for specific calibration activities as listed in the HOKLAS directory of accredited laboratories. The results shown in this certificate are traceable to the International System of Units (SI) or recognised measurement standards. The results relate only to the item(s) calibrated. This certificate shall not be reproduced except in full without approval of the laboratory.





Test Data for Sound Level Meter						
Sound level me	eter type:	LxT1	Serial No.	0004797	Date 04-Nov-2022	
Microphone	type:	377B02	Serial No.	340739		
Preamp	type:	PRMLxT1L	Serial No.	042622	Report: 22CA1101 02-01	_

## SELF GENERATED NOISE TEST

The noise test is performed in the most sensitive range of the SLM with the microphone replaced by an equivalent impedance.

Noise level in A weighting	8.7	dB
Noise level in C weighting	12.1	dB
Noise level in Lin	20.4	dB

## LINEARITY TEST

The linearity is tested relative to the reference sound pressure level using a continuous sinusoidal signal of frequency 4 kHz. The measurement is made on the reference range for indications at 5 dB intervals starting from the 94 dB reference sound pressure level. And until within 5 dB of the upper and lower limits of the reference range, the measurements shall be made at 1 dB intervals.(SLM set to LEQ/SPL)

Reference/Expected level	Actual level		Tolerance	Devia	Deviation		
Hororonoon Expected Toron	non-integrated	integrated		non-integrated	integrated		
dB	dB	dB	+/- dB	dB	dB		
94.0	94.0	94.0	0.7	0.0	0.0		
99.0	99.0	99.0	0.7	0.0	0.0		
104.0	104.0	104.0	0.7	0.0	0.0		
109.0	109.0	109.0	0.7	0.0	0.0		
114.0	114.0	114.0	0.7	0.0	0.0		
115.0	115.0	115.0	0.7	0.0	0.0		
116.0	116.0	116.0	0.7	0.0	0.0		
117.0	117.0	117.0	0.7	0.0	0.0		
118.0	118.0	118.0	0.7	0.0	0.0		
119.0	119.0	119.0	0.7	0.0	0.0		
120.0	120.0	120.0	0.7	0.0	0.0		
89.0	89.0	89.0	0.7	0.0	0.0		
84.0	84.0	84.0	0.7	0.0	0.0		
79.0	79.0	79.0	0.7	0.0	0.0		
74.0	74.0	74.0	0.7	0.0	0.0		
69.0	69.0	69.0	0.7	0.0	0.0		
64.0	64.0	64.0	0.7	0.0	0.0		
59.0	59.0	59.0	0.7	0.0	0.0		
54.0	54.0	54.0	0.7	0.0	0.0		
49.0	49.0	49.0	0.7	0.0	0.0		
44.0	44.0	44.0	0.7	0.0	0.0		
39.0	38.9	38.9	0.7	-0.1	-0.1		
34.0	34.0	34.0	0.7	0.0	0.0		
33.0	33.0	33.0	0.7	0.0	0.0		

(c)Soils Materials Eng. Co., Ltd.





Page 2 of 5

Test Data for Sound Level Meter

Sound level me	eter type:	LxT1		Seria	I No.	0004797	Date	e 04-Nov	/-2022
Microphone Preamp	type: type:	377B02 PRMLxT1L		Seria Seria	il No. il No.	340739 042622	Rep	ort: 22CA11	101 02-01
32.0		32.0	32.0		0.7		0.0	0.0	
31.0		30.9	30.9		0.7		-0.1	-0.1	
30.0		30.0	30.0		0.7		0.0	0.0	

Measurements for an indication of the reference SPL on all other ranges which include it

Other ranges	Expected level	Actual level	Tolerance	Deviation
dB	dB	dB	+/- dB	dB
20-120	94.0	94.0	0.7	0.0

Measurements on all level ranges for indications 2 dB below the upper limit and 2 dB above the lower limit

Ranges	Reference/Expected level	Actual level	Tolerance	Deviation
dB	dB	dB	+/- dB	dB
20-120	30.0	30.0	0.7	0.0
	118.0	118.0	0.7	0.0

## FREQUENCY WEIGHTING TEST

The frequency response of the weighting netwoks are tested at octave intervals over the frequency ranges 31.5 Hz to 12500 Hz. The signal level at 1000 Hz is set to give an indication of the reference SPL. Frequency weighting A:

Frequency	Ref. level	Expected level	Actual level	Tolerar	nce(dB)	Deviation
Hz	dB	dB	dB	+	-	dB
1000.0	94.0	94.0	94.0	0.0	0.0	0.0
31.6	94.0	54.6	54.6	1.5	1.5	0.0
63.1	94.0	67.8	67.8	1.5	1.5	0.0
125.9	94.0	77.9	77.9	1.0	1.0	0.0
251.2	94.0	85.4	85.4	1.0	1.0	0.0
501.2	94.0	90.8	90.7	1.0	1.0	-0.1
1995.0	94.0	95.2	95.2	1.0	1.0	0.0
3981.0	94.0	95.0	95.0	1.0	1.0	0.0
7943.0	94.0	92.9	92.9	1.5	3.0	0.0
12590.0	94.0	89.7	89.7	3.0	6.0	0.0

Frequency weighting C:

Frequency	Ref. level	Expected level	Actual level	Tolera	nce(dB)	Deviation
Hz	dB	dB	dB	+	-	dB
1000.0	94.0	94.0	94.0	0.0	0.0	0.0
31.6	94.0	91.0	91.0	1.5	1.5	0.0
63.1	94.0	93.2	93.1	1.5	1.5	-0.1
125.9	94.0	93.8	93.8	1.0	1.0	0.0
251.2	94.0	94.0	94.0	1.0	1.0	0.0
501.2	94.0	94.0	94.0	1.0	1.0	0.0

(c)Soils Materials Eng. Co., Ltd.



**SMECLab** 

Page 3 of 5

Test Data for Sound Level Meter

Sound level meter	er type:	LxT	1	Serial No.	000	4797	Date	04-Nov-2022
Microphone	type:	377	B02	Serial No.	340	739		
Preamp	type:	PRI	MLxT1L	Serial No.	042	622	Report:	22CA1101 02-01
1995.0	94.0		93.8	93.8	1.0	1.0	0.0	
3981.0	94.0		93.2	93.2	1.0	1.0	0.0	
7943.0	94.0		91.0	91.0	1.5	3.0	0.0	
12590.0	94.0		87.8	87.7	3.0	6.0	-0.1	
Frequency weigh	nting Lin:					I		
Frequency	Ref. lev	/el	Expected level	Actual level	Tolerar	nce(dB)	Deviatio	n
Hz	dB		dB	dB	+	-	dB	
1000.0	94.0		94.0	94.0	0.0	0.0	0.0	
31.6	94.0		94.0	93.9	1.5	1.5	-0.1	
63.1	94.0		94.0	94.0	1.5	1.5	0.0	
125.9	94.0		94.0	94.0	1.0	1.0	0.0	
251.2	94.0		94.0	94.0	1.0	1.0	0.0	
501.2	94.0		94.0	94.0	1.0	1.0	0.0	
1995.0	94.0		94.0	94.0	1.0	1.0	0.0	
3981.0	94.0		94.0	94.0	1.0	1.0	0.0	
7943.0	94.0		94.0	94.0	1.5	3.0	0.0	
12590.0	94.0		94.0	94.0	3.0	6.0	0.0	

## TIME WEIGHTING FAST TEST

Time weighting F is tested on the reference range with a single sinusoidal burst of duration 200 ms at a frequency 2000 Hz and an amplitude which produces an indication 4 dB below the upper limit of the primary indicator range when the signal is continuous. (Weight A. Maximum hold)

Ref. level	Expected level	Actual level	Tolera	nce(dB)	Deviation
dB	dB	dB	+	-	dB
116.0	115.0	114.9	1.0	1.0	-0.1

#### TIME WEIGHTING SLOW TEST

Time weighting S is tested on the reference range with a single sinusoidal burst of duration 500 ms at a frequency 2000 Hz and an amplitude which produces an indication 4 dB below the upper limit of the primary indicator range when the signal is continuous. (Weight A, Maximum hold)

Ref. level	Expected level	Actual level	Tolera	nce(dB)	Deviation
dB	dB	dB	+	-	dB
116.0	111.9	111.8	1.0	1.0	-0.1

#### PEAK RESPONSE TEST

The onset time of the peak detector is tested on the reference range by comparing the response to a 100 us rectangular test pulse with the response to a 10 ms reference pulse of the same amplitude. The amplitude of the 10 ms reference pulse is such as to produce an indication 1 dB below the upper limit of the primary indicator range. Positive polarities: (Weighting Z, set the generator signal to single, Lzpeak)

Ref. level	Response to 10 ms	Response to 100 us	Tolerance	Deviation
dB	dB	dB	+/- dB	dB
119.0	119.0	118.5	2.0	-0.5

(c)Soils Materials Eng. Co., Ltd.



#### 綜合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD. 香港新界葵涌永基路22-24號好爸爸創科大廈 Good Ba Ba Hitech Building, Nos. 22-24 Wing Kei Road, Kwai Chung, New Territories, Hong Kong

Tel: (852) 2873 6860 Fax: (852) 2555 7533 E-mail: smec@cigismec.com Website: www.cigismec.com



Test Data for Sc	ound Level M	eter					Page 4 of 5
Sound level m	eter type:	LxT	1	Serial No.	0004797	Date	04-Nov-2022
Microphone Preamp	type: type:	3778 PRN	302 /LxT1L	Serial No. Serial No.	340739 042622	Report	: 22CA1101 02-01
Negative polar	rities:						
Re	ef. level		Response to 10 ms	Response to 100 us	Tolerance	Deviatio	n
	dB		dB	dB	+/- dB	dB	
-	119.0		119.0	118.5	2.0	-0.5	
RMS ACCUR	ACY TEST						

The RMS detector a	accuracy is tested	d on the reference ra	inge for a crest factor	of 3.					
Test frequency:		2000 Hz	2000 Hz						
Amplitude:		2 dB below the up	2 dB below the upper limit of the primary indicator range.						
Burst repetition	n frequency:	40 Hz							
Tone burst sig	nal:	11 cycles of a sine	e wave of frequency 2	000 Hz. (Set	to INT)				
	Ref. Level	Expected level	Tone burst signal	Tolerance	Deviation				
Time wighting	dB	dB	indication(dB)	+/- dB	dB				
Slow	114.0+6.6	114.0	113.9	0.5	-0.1				

## TIME WEIGHTING IMPULSE TEST

Time weighting I is tested on the reference range (Set the SLM to LAImax) Test frequency: 2000 Hz Amplitude:

The upper limit of the primary indicator range.

Single sinusoidal burst of duration 5 ms:

Ref. Level	Single burst indication		Tolerance	Deviation
dB	Expected (dB)	Actual (dB)	+/~ dB	dB
120.0	111.2	111.1	2.0	-0.1

#### Repeated at 100 Hz

Ref. Level	Repeated bu	Repeated burst indication		Repeated burst indication		Deviation	
dB	Expected (dB)	Actual (dB)	+/- dB	dB			
120.0	117.3	117.1	1.0	-0.2			

## TIME AVERAGING TEST

This test compares the SLM reading for continuous sine signals with readings obtained from a sine tone burst sequence having the same RMS level. The test level is 30 dB below the upper limit of the linearity range and repeated for Type 1 SLM with 40 dB below the upper limit of the linearity.

Frequency of tone burst: 4000 Hz Duration of tone burst: 1 mc

Repetition Time	Level of	Expected	Actual	Tolerance	Deviation	Remarks
	tone burst	Leq	Leq			
msec	dB	dB	dB	+/- dB	dB	
1000	90.0	90.0	89.9	1.0	-0.1	60s integ.
10000	80.0	80.0	79.9	1.0	-0.1	6min. intec

## PULSE RANGE AND SOUND EXPOSURE LEVEL TEST

The test tone burst signal is superimposed on a baseline signal corresponding to the lower limit of reference range

Test frequency: 4000 Hz Integration time: 10 sec

(c)Soils Materials Eng. Co., Ltd.



SMECLab

Page 5 of 5

Test Data for Sound Level Meter

							e
Sound level me	eter type:	LxT1		Serial No.	0004797	Date	04-Nov-2022
Microphone Preamp	type: type:	377B PRM	02 LxT1L	Serial No. Serial No.	340739 042622	Report:	22CA1101 02-01
The integrating	sound level r	neter s	et to Leq:				
Duration	Rms leve	el of	Expected	Actual	Tolerance	Deviatio	n
msec	tone burst	(dB)	dB	dB	+/- dB	dB	
10	90.0		60.0	60.0	17	0.0	

The integrating sound level meter set to SEL:

Duration	Rms level of	Expected	Actual	Tolerance	Deviation
msec	tone burst (dB)	dB	dB	+/- dB	dB
10.0	90.0	70.0	70.0	1.7	0.0

#### **OVERLOAD INDICATION TEST**

For SLM capable of operating in a non-integrating mode.

Test frequer	ncy:						
Amplitude:		2 dB below the upper limit of the primary indicator range.					
Burst repetit	ion frequency:	40 Hz					
Tone burst s	signal:	11 cycles of a sine	e wave of freque	ency 2000 Hz.			
Level	Level reduced by	Further reduced	Difference	Tolerance	Deviation		
at overload (dB)	1 dB	3 dB	dB	dB	dB		
113.2 112.2		109.2	3.0	1.0	0.0		

For integrating SLM, with the instrument indicating Leq.

118.9

For integrating SLM, with the instrument indicating Leq and set to the reference range. The test signal as following: The test tone burst signal is superimposed on a baseline signal corresponding to the lower limit of reference range Test frequency: 4000 Hz Integration time: 10 sec Single burst duration: 1 msec Rms level Level reduced by Expected level Actual level Tolerance Deviation at overload (dB) 1 dB dB dB dB dB

78.9

2.2

0.0

78.9

## ACOUSTIC TEST

119.9

The acoustic test of the complete SLM is tested at the frequency 125 Hz and 8000 Hz using a B&K type 4226 Multifunction Acoustic Calibrator. The test is performed in A weighting.

Frequency	Expected level	Actual level	Tolera	nce (dB)	Deviation
Hz	dB	Measured (dB)	+	-	dB
1000	94.0	94.0	0.0	0.0	0.0
125	77.9	77.9	1.0	1.0	0.0
8000	92.9	93.9	1.5	3.0	1.0

-----END------

(c)Soils Materials Eng. Co., Ltd.



Tisch Environmental, Inc.

145 South Miami Avenue Village of Cleves, OH 45002 www.tisch-env.com TOLL FREE: (877)263-7610 FAX: (513)467-9009



Lam Environmental Services Limited

## Calibration Data for High Volume Sampler (TSP Sampler)

Location	:	AMS1	Calbration Date	:	4-Sep-23
Equipment no.	:	HVS020	Calbration Due Date	:	4-Nov-23

#### CALIBRATION OF CONTINUOUS FLOW RECORDER

Ambient Condition									
Temperature, T <sub>a</sub>		302.9 Kelvin Pressure, P <sub>a</sub> 1002 mmHg					mmHg		
Orifice Transfer Standard Information									
Equipment No.		3166		Slope, m <sub>c</sub>	2.29643		Intercept, bc	-0.004	51
Last Calibration Date		31-Mar-2	3		(Hx	r P <sub>a</sub> / 10	13.3 x 298 /	′Τ <sub>a</sub> ) <sup>1/2</sup>	
Next Calibration Date		31-Mar-2	4		=	m <sub>c</sub> >	$(Q_{std} + b_c)$		
				Calibratio	n of TSP				
Calibration	Mar	nometer R	eading	c	۱ std	Contin	uous Flow		IC
Point	Н (і	inches of v	water)	(m <sup>3</sup>	/ min.)	Rec	order, W	(W(P <sub>a</sub> /1013.3	3x298/T <sub>a</sub> ) <sup>1/2</sup> /35.31)
	(up)	(down)	(difference)	X-	axis	(	CFM)	Y	-axis
1	1.2	1.2	2.4	0.0	6674		32	31	.5642
2	2.5	2.5	5.0	0.9	9624		46	45	5.3736
3	3.2	3.2	6.4	1.(	0886		52	51	.2918
4	4.8	4.8	9.6	1.3	3328		62	61	.1557
5	5.3	5.3	10.6	1.4	4004		66	65	5.1012
By Linear Regression of	Y on X								
	Slope, m = 45.0454 Intercept, b = 1.7833								
Correlation Co	pefficient*	=	0.99	994					-
Calibration	Accepted	=	Yes/	<del>\o</del> **					

 $^{\ast}$  if Correlation Coefficient < 0.990, check and recalibration again.

\*\* Delete as appropriate.

Remarks :						
Calibrated by	:	Harry Po		Checked by	:	Alan Ng
Date	:	4-Sep-23	_	Date	:	4-Sep-23



Lam Environmental Services Limited

## Calibration Data for High Volume Sampler (TSP Sampler)

Location	:	AMS2	Calbration Date	:	4-Sep-23
Equipment no.	:	HVS019	Calbration Due Date	:	4-Nov-23

#### CALIBRATION OF CONTINUOUS FLOW RECORDER

Ambient Condition									
Temperature, T <sub>a</sub>		302.9 Kelvin <b>Pressure, P</b> a 1002 m					002 mmHg		
	Orifice Transfer Standard Information								
Equipment No.		3166		Slope, m <sub>c</sub>	1.2964	43	Intercept, bc	-0.00451	
Last Calibration Date		31-Mar-2	3		(Hx	P <sub>a</sub> / 10	)13.3 x 298 /	(T <sub>a</sub> ) <sup>1/2</sup>	
Next Calibration Date		31-Mar-2	4		=	m <sub>c</sub>	$x Q_{std} + b_c$		
				Calibratio	on of TSP				
Calibration	Mar	ometer R	eading	c	Q <sub>std</sub>	Conti	nuous Flow	IC	
Point	Н (	inches of v	water)	(m <sup>3</sup>	/ min.)	nin.) Recor		(W(P <sub>a</sub> /1013.3x298/T <sub>a</sub> ) <sup>1/2</sup> /35.31)	
	(up)	(down)	(difference)	X-	axis		(CFM)	Y-axis	
1	1.2	1.2	2.4	1.	1822		22	21.7004	
2	1.8	1.8	3.6	1.4	4471		30	29.5915	
3	2.6	2.6	5.2	1.	7385		38	37.4825	
4	3.6	3.6	7.2	2.	0450		46	45.3736	
5	4.5	4.5	9.0	2.:	2860		52	51.2918	
By Linear Regression of	Y on X								
	Slope, m = 26.7230 Intercept, b = -9.4035								
Correlation Co	Correlation Coefficient* = 0.9994								
Calibration	Accepted	=	Yes/	<del>\</del> 0**					

 $^{\ast}$  if Correlation Coefficient < 0.990, check and recalibration again.

\*\* Delete as appropriate.

Remarks :						
Calibrated by	:	Harry Po		Checked by	:	Alan ng
Date	:	4-Sep-23	_	Date	:	4-Sep-23



Certificate No.	211035		Page	1 of 2 Pages
Customer :	Lam Environmental Services Lir	nited		
Address :	19/F, Remex Centre, 42 Wong	Chuk Hang Road, H	ong Kong	
Order No. :	Q24331		Date of receipt	t : 24-Nov-22
Item Tested		8		
Description	: Aerosol Mass Monitor			
Manufacturer	: Met One		I.D.	: -
Model :	Aerocet 831		Serial No.	: W15449
Test Condit	ions			
Date of Test :	13-Dec-22		Supply Voltage	e :
Ambient Temp	perature : (23 ± 3)°C		Relative Humic	dity: (50 ± 25) %
Test Specifi	cations			
Calibration cher	<u>ck</u>			
Calibration proc	edure : Manufacturer recom	mended method (ar	avimetric) 728	
ounoration proc		mended method (gr	uviinotno), 220.	
Test Results	3			
All results were	within the tolerance(s).			
The results are	shown in the attached page(s).			
Main Test equip	oment used:			
Equipment No.	Description	Cert. No.		Traceable to
S136B	Stop Watch	201879		SCL-HKSAR
S238	Micro Balance	108228		NIM-PRC
S201	Std. Test Dust	61291		NIST
S207B	Std. Flowmeter	LL-2104002489		NIM-PRC
The values given in will not include allow overloading, mis-ha for any loss or dam The test equipment	this Calibration Certificate only relate to f wance for the equipment long term drift, v indling, or the capability of any other labo age resulting from the use of the equipment used for calibration are traceable to Inter	the values measured at t ariations with environme ratory to repeat the meas ent. national System of Units	he time of the test ar ntal changes, vibratic surement. Hong Kon , (SI), or by reference	nd any uncertainties quoted on and shock during transportation, ng Calibration Ltd. shall not be liable e to a natural constant.
The test results app	bly to the above Unit-Under-Test only			
Calibrated by	: Kin Wong	App Date:	roved by :	Steve Kwan
Hong Kong Calibration Ltc Unit 8B, 24/F., Well Fung Tel: 2425 8801 Fax: 2425	d. Industrial Centre, No. 58-76, Ta Chuen Ping Street,Kw 5 8646	ai Chung, NT,Hong Kong.		
The copyright of this certif	icate is owned by Hong Kong Calibration Ltd It may no	ot be reproduced except in full.		0

The copyright of this certificate is owned by Hong Kong Calibration Ltd.. It may not be reproduced except in full.



## Certificate No. 211035

Page 2 of 2 Pages

Results :

## 1. General

Internal Filters : checked and found clean.

## 2. Flow Meter

UUT Nominal	Measured Value	Tolerance	
Value (LPM)	(LPM)	(LPM)	Uncertainty
2.83	2.80	± 0.15	± 0.05

### 3. Timer

Reference Value	UUT Reading	Tolerance	Uncertainty
10' 00" 18	10 min	± 2 sec/hr	$\pm 0.5$ sec/hr

## 4. Dust Particle (PM10)

Applied Value	UUT Reading (µg/m <sup>3</sup> )		
$(\mu g/m^3)$	K Factor : 0.62	Tolerance	Uncertainty
280	254	± 20 %	± 10 %

Remark : 1. UUT: Unit-Under-Test

2. The uncertainty claimed is for a confidence probability of not less than 95%.

3. ISO 12103-1 A1 respirable standard test dust was used for the calibration.

4. The K Factor had been adjusted from 1.00 to 0.62.

----- END -----



Certificate No	. 211036		Page	1 of 2 Pages
Customer :	Lam Environmental Services Li	mited		
Address :	19/F, Remex Centre, 42 Wong	Chuk Hang Road, H	long Kong	
Order No. :	Q24331		Date of receip	t : 24-Nov-22
Item Tested	1			
Description	: Aerosol Mass Monitor			
Manufacturer	: Met One		I.D.	:
Model	: Aerocet 831		Serial No.	: Y23153
Test Condit	tions	1		
Date of Test :	13-Dec-22		Supply Voltag	e :
Ambient Tem	perature: (23 ± 3)°C		Relative Humi	dity:(50 ± 25) %
Test Specif	ications		ana an ing ang ang ang ang ang ang ang ang ang a	
Calibration che	ck.			
Calibration prod	cedure : Manufacturer recom	nmended method (ar	ravimetric), Z28.	
		10	,,	
Test Result	S			
All results were The results are	within the tolerance(s). shown in the attached page(s).			
Main Test equi	pment used:			
Equipment No.	Description	Cert. No.		Traceable to
S136B	Stop Watch	201879		SCL-HKSAR
S238	Micro Balance	108228		NIM-PRC
S201	Std. Test Dust	61291		NIST
S207B	Std. Flowmeter	LL-2104002489		NIM-PRC
The values given in this Calibration Certificate only relate to the values measured at the time of the test and any uncertainties quoted will not include allowance for the equipment long term drift, variations with environmental changes, vibration and shock during transportation, overloading, mis-handling, or the capability of any other laboratory to repeat the measurement. Hong Kong Calibration Ltd. shall not be liable for any loss or damage resulting from the use of the equipment.				
The test equipment used for calibration are traceable to International System of Units (SI), or by reference to a natural constant. The test results apply to the above Unit-Under-Test only				
		- 1		\$
<b>A</b> 111	K La			
Calibrated by	Kin Wong	Арр	roved by :	Steve Kwan
This Certificate is issued I	tvir vvorig	Date:	13-Dec-22	Sieve (Wall
Hong Kong Calibration Ltd	d.	Dale.	10-060-22	
Unit 88, 24/F., Well Fung Tel: 2425 8801 Fax: 242	Industrial Centre, No. 58-76, Ta Chuen Ping Street,Kw 5 8646	/ai Chung, NT,Hong Kong.		

The copyright of this certificate is owned by Hong Kong Calibration Ltd.. It may not be reproduced except in full.



## Certificate No. 211036

Page 2 of 2 Pages

Results :

## 1. General

Internal Filters : checked and found clean.

## 2. Flow Meter

UUT Nominal	Measured Value	Tolerance	Uncertainty
Value (LPM)	(LPM)	(LPM)	
2.83	2.80	± 0.15	± 0.05

## 3. Timer

Reference Value	UUT Reading	Tolerance	Uncertainty
10' 00" 40	10 min	$\pm 2$ sec/hr	$\pm 0.5$ sec/hr

## 4. Dust Particle (PM10)

Applied Value (µg/m <sup>3</sup> )	UUT Reading (µg/m <sup>3</sup> ) K Factor : 1.26	Tolerance	Uncertainty
350	364	± 20 %	± 10 %

## Remark : 1. UUT: Unit-Under-Test

- 2. The uncertainty claimed is for a confidence probability of not less than 95%.
- 3. ISO 12103-1 A1 respirable standard test dust was used for the calibration.
- 4. The K Factor had been adjusted from 3.00 to 1.26.

----- END -----



ALS Technichem (HK) Pty Ltd 11/F., Chung Shun Knitting Centre, 1 - 3 Wing Yip Street, Kwai Chung, N.T., Hong Kong **T:** +852 2610 1044 **F:** +852 2610 2021 www.alsglobal.com

## **REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION**

CONTACT:	DEREK LO	WORK ORDER:	HK2333034
CLIENT:	LAM ENVIRONMENTAL SERVICES LTD		
ADDRESS:	19/F, REMEX CENTRE,	SUB-BATCH:	0
	42 WONG CHUK HANG ROAD,	LABORATORY:	HONG KONG
	HONG KONG	DATE RECEIVED:	17-Aug-2023
		DATE OF ISSUE:	25-Aug-2023

## SPECIFIC COMMENTS

Equipment information (Brand name, Model No., Serial No. and Equipment No.) is provided by client. The performance of the equipment stated in this report is checked with independent reference material and results compared against a calibrated secondary source.

The "Tolerance Limit" quoted is the acceptance criteria applicable for similar equipment used by the laboratory or quoted from relevant international standards.

The "Next Calibration Date" is recommended according to best practice principle as practised by the

laboratory or quoted from relevant international standards.

The validity of equipment/ meter performance only applies to the result(s) stated in the report.

Equipment Type:	Multifunctional Meter
Service Nature:	Performance Check
Scope:	Dissolved Oxygen, pH Value, Salinity and Temperature
Brand Name/ Model No.:	[YSI]/ [ProQuatro]
Serial No./ Equipment No.:	[20M100002/20M101455]/ [N/A]
Date of Calibration:	22-August-2023

## **GENERAL COMMENTS**

This report superseded any previous report(s) with same work order number.

Ms. Lin Wai Yu, Iris Assistant Manager - Inorganics

This report may not be reproduced except with prior written approval from ALS Technichem (HK) Pty Ltd.
# **REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION**



WORK ORDER:	HK2333034		
SUB-BATCH: DATE OF ISSUE: CLIENT:	0 25-Aug-2023 LAM ENVIRONMENTAL SERVICI	ES LTD	
Equipment Type: Brand Name/ Model No.: Serial No./ Equipment No.: Date of Calibration:	Multifunctional Meter [YSI]/ [ProQuatro] [20M100002/20M101455]/ [N/A 22-August-2023	ן Date of Next Calibration:	22-November-2023

# **PARAMETERS:**

# Dissolved Oxygen Method Ref: APHA (23rd edition), 4500O: G

Expected Reading (mg/L)	Displayed Reading (mg/L)	Tolerance (mg/L)
1.94	1.78	-0.16
4.96	4.81	-0.15
7.84	7.69	-0.15
	Tolerance Limit (mg/L)	±0.20

# pH Value

# Method Ref: APHA (23rd edition), 4500H: B

Expected Reading (pH unit)	Displayed Reading (pH unit)	Tolerance (pH unit)
4.0	4.08	+0.08
7.0	7.14	+0.14
10.0	9.96	-0.04
	Tolerance Limit (pH unit)	±0.20

# Salinity

# Method Ref: APHA (23rd edition), 2520B

Expected Reading (ppt)	Displayed Reading (ppt)	Tolerance (%)
0	0.00	
10	10.06	+0.6
20	19.93	-0.4
30	29.02	-3.3
	Tolerance Limit (%)	±10.0

Remark: "Displayed Reading" presents the figures shown on item under calibration / checking regardless of equipment precision or significant figures.

Ms. Lin Wai Yu, Iris Assistant Manager - Inorganics

# **REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION**



WORK ORDER:	HK2333034		
SUB-BATCH: DATE OF ISSUE: CLIENT:	0 25-Aug-2023 LAM ENVIRONMENTAL SERVICI	ES LTD	
Equipment Type: Brand Name/ Model No.: Serial No./ Equipment No.:	Multifunctional Meter [YSI]/ [ProQuatro] [20M100002/20M101455]/ [N/A	.]	
Date of Calibration:	22-August-2023	Date of Next Calibration:	22-November-2023

# **PARAMETERS:**

# Temperature

# Method Ref: Section 6 of International Accreditation New Zealand Technical Guide No. 3 Second edition March 2008: Working Thermometer Calibration Procedure.

Expected Reading (°C)	Displayed Reading (°C)	Tolerance (°C)
6.0	4.8	-1.2
25.0	23.3	-1.7
50.0	48.1	-1.9
	Tolerance Limit (°C)	±2.0

Remark: "Displayed Reading" presents the figures shown on item under calibration / checking regardless of equipment precision or significant figures.

Ms. Lin Wai Yu, Iris Assistant Manager - Inorganics



# **Calibration Report**

Calibration No.	:	52508051- G07D3002					
Laboratory	4	FT LaboratoriesLtd.					
Address	1	Lot No. DD77 Section 1552 S.Ass 1RP, Ng Chow South Road, Ping Che, Fanling, New Territories					
Telephone		(852) 2758 4861					
Facsimile	:	(852) 2758 8962					
Customer		Lam Environmental Ser	vices Limited				
Address	2	19/F., Remex Centre, 42	Wong Chuk Hang Road, Hong Kong				
Item Calibrated	:	Name/Description:	Turbidimeter				
		Manufacturer:	Shanghai Xinrui Instruments & Meters co.,Ltd				
		Model no:	WGZ-3B				
		Equipment no.:	2209057				
<b>Reference Standard</b>	.7	: C23/01 under NC	CRM reference material number GBW(E) 120125.				
Major Measuremen	t	Standard Solution	n of Formazine Turbidity				
Equipment							
Calibration Method	l	: In-house calibrat	ion method according to Ref: APHA22nd ed 213 OB				
Date of item receive	d	: 07 Jul.,2023					
Date of Calibration		: 14 Jul.,2023					
Location of Calibra	tion	: Chemical Labora	atory of FT LaboratoriesLtd.				
Calibration Conditi	ions						
Temperature		: $20 \pm 3 ^{\circ}\mathrm{C}$					
Relative Humidity		: 30% to 80%					
Test Results		: The test results a	are detailed in the subsequent page(s).				
Certified by :	J	Date of Issue: <u>24 JUL 2023</u> CHAN Joseph Nicolas (Senior Technical Engineer)					
Notes: (1) Th (2) Th	ne above nis certi	e equipment has been calibrated a ficate shall not be reproduced, or	against standards which are traceable to internationally recognized standards. acept in full, without the written approval of FT LaboratoriesLtd.				



# Calibration No. 52508051- G07D3002

## Results

Solution used	Measured value (NTU)	Error (%)
0	0	
4	4.02	0.5%
10	9.98	-0.2%
40	40.02	0.1%
100	99.97	0.0%
400	399.1	-0.2%
1000	998.8	-0.1%

#### Remarks:

- (A) Each reported result is the mean of three measurements on UUT (unit-under-test).
- (B) The values given in this Calibration Report only relate to the unit-under-test and the values measured at the time of the test. Any uncertainties quoted will not include allowances for the environmental changes, variation and shock during transportation, or the capability of any other laboratory to repeat the measurement.
- (C) Before calibration, UUT and reference equipment was placed in the laboratory for at least one hour.

# < End of Report >

Calibrated by: Date: Wong Ting Hei 14 Jul.,2023

Checked by:

Date:



Appendix 4.3

Wind data extracted from HKO Automatic Weather Station



# A. Wind Direction extracted from Peng Chau Automatic Weather







# B. Wind Speed extracted from Peng Chau Automatic Weather Station







Appendix 5.1

Monitoring Schedules for Reporting Month



#### Contract No. HY/2019/14 New Wang Tong River Bridge

# Tentative Impact Air Quality, Noise and Water Quality Monitoring Schedule Sep 2023

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
27 Aug	28 Aug	29 Aug	30 Aug	31 Aug	01 Sep	02 Sep
					WQM	
					Mid-Ebb 13:11	
					Mid-Flood 7:36	
03 Sep	04 Sep	05 Sep	06 Sep	07 Sep	08 Sep	09 Sep
		24-hr TSP	1-hr TSP			
			NM			
	WQM		WQM		WQM	
	Mid-Ebb 15:13		Mid-Ebb 16:46		Mid-Ebb 7:26	
	Mid-Flood 9:09		Mid-Flood 11:30		Mid-Flood 17:00	
10 Sen	11 Sen	12 Sen	13 Sen	14 Sen	15 Sen	16 Sep
10 000	24-hr TSP	1-hr TSP	10 000	11000	10 000	24-hr TSP
		NM				
	WOM		WOM		WOM	
	Mid-Ebb 10:26		Mid-Ebb 11:40		Mid-Ebb 12:41	
	Mid-Flood 18:02		Mid-Flood 18:34		Mid-Flood 18:30	
17 Sep	18 Sep	19 Sep	20 Sep	21 Sep	22 Sep	23 Sep
	NM				24-hr ISP	NM
	WQM		WQM		WQM	
	Mid-Ebb 14.13 Mid-Elood 8:05		Mid-Elood 9:38		Mid-Elood 16:30	
24 Sep	25 Sep	26 Sep	27 Sep	28 Sep	29 Sep	30 Sep
				24-hr TSP	1-hr TSP	
					NM	
	WQM		WQM		WQM	
	Mid-Ebb 8:41		Mid-Ebb 10:32		Mid-Ebb 12:06	
	Mid-Flood 16:54		Mid-Flood 17:46		Mid-Flood 18:35	

Remarks:

24-hr TSP stands for 24-hour Total Suspended Particulates Monitoring;

1-hr TSP stands for 1-hour Total Suspended Particulate Monitoring;

NM stands for Noise Monitoring;

WQM stands for Water Quality Monitoring tenatively scheduled and

Based on previous discussion with contractor and IEC, all monitoring will not be scheduled on any public holidays and Sundays as there will be no construction works.



#### Contract No. HY/2019/14 New Wang Tong River Bridge

#### Tentative Impact Air Quality, Noise and Water Quality Monitoring Schedule Oct 2023

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
01 Oct	02 Oct	03 Oct	04 Oct 24-hr TSP	05 Oct 1-hr TSP NM	06 Oct	07 Oct
		WQM Mid-Ebb 14:48 Mid-Flood 9:05		WQM Mid-Ebb 15:30 Mid-Flood 11:00		WQM Mid-Ebb 7:05 Mid-Flood 16:30
08 Oct	09 Oct	10 Oct	11 Oct	12 Oct	13 Oct	14 Oct
	Mid-Ebb 8:54 Mid-Flood 17:00		Mid-Ebb 10:33 Mid-Flood 17:25		Mid-Ebb 11:41 Mid-Flood 17:53	
15 Oct	16 Oct	17 Oct	18 Oct	19 Oct	20 Oct	21 Oct
	Mid-Ebb 13:18 Mid-Flood 7:21		Mid-Ebb 14:24 Mid-Flood 8:49		Mid-Ebb 16:00 Mid-Flood 11:00	
22 Oct	23 Oct	24 Oct	25 Oct	26 Oct	27 Oct 1-hr TSP NM	28 Oct
		WQM Mid-Ebb 8:12 Mid-Flood 16:03		WQM   Mid-Ebb 10:11   Mid-Flood 16:56		WQM Mid-Ebb 11:45 Mid-Flood 17:49
29 Oct	30 Oct	31 Oct	01 Nov	02 Nov	03 Nov	04 Nov
	Mid-Ebb 13:10 Mid-Flood 18:30					

Remarks:

24-hr TSP stands for 24-hour Total Suspended Particulates Monitoring;

1-hr TSP stands for 1-hour Total Suspended Particulate Monitoring;

NM stands for Noise Monitoring;

WQM stands for Water Quality Monitoring tenatively scheduled and

Based on previous discussion with contractor and IEC, all monitoring will not be scheduled on any public holidays and Sundays as there will be no construction works.



Appendix 5.2

Noise Monitoring Results and Graphical Presentations

# Noise Monitoring Result

# Day Time (0700 - 1900hrs on normal weekdays)

Location: NMS1 - 1 Tung Wan Tau Road

			Measure	ement Nois	se Level	Average Noise Level#	Baseline Level	Construction Noise Level	Limit Level
Date	Weather	Time	L <sub>eq</sub>	L <sub>10</sub>	L <sub>90</sub>	L <sub>eq</sub>	L <sub>eq</sub>	L <sub>eq</sub>	L <sub>eq</sub>
			Unit: dB(A), (30-min)		-min)		Unit: di	B(A), (30-min)	
6 Sep 2023	Sunny	10:30	54.9	59.2	45.8	54.9	60.1	<baseline level<="" td=""><td>75</td></baseline>	75
12 Sep 2023	Sunny	10:30	59.1	64.4	47.3	59.1	60.1	<baseline level<="" td=""><td>75</td></baseline>	75
18 Sep 2023	Cloudy	10:30	53.2	58.5	45.3	53.2	60.1	<baseline level<="" td=""><td>75</td></baseline>	75
29 Sep 2023	Sunny	10:30	57.3	62.6	46.8	57.3	60.1	<baseline level<="" td=""><td>75</td></baseline>	75





Appendix 5.3

Air Quality Monitoring Results and Graphical Presentations



Report on 1-hour TSP monitoring at AMS1 - Slivermine Beach Resort Limit Level ( $\mu g/m^3)$  -

500.0

Date	Weather Condition	Time	TSP Level (µg/m³)
6-Sep-23	Cloudy	9:56	44.2
6-Sep-23	Cloudy	10:56	39.8
6-Sep-23	Cloudy	11:56	43.9
12-Sep-23	Cloudy	8:59	23.1
12-Sep-23	Cloudy	9:59	25.2
12-Sep-23	Cloudy	10:59	20.8
18-Sep-23	Sunny	9:21	29.6
18-Sep-23	Sunny	10:21	30.1
18-Sep-23	Sunny	11:21	30.1
23-Sep-23	Sunny	9:17	52.1
23-Sep-23	Sunny	10:17	42.6
23-Sep-23	Sunny	11:17	51.4
29-Sep-23	Sunny	9:22	60.7
29-Sep-23	Sunny	10:22	68.6
29-Sep-23	Sunny	11:22	65.3



# Report on 1-hour TSP monitoring at AMS2 - 1 Tung Wan Tau Road Limit Level ( $\mu g/m^3)$ -

500.0

Date	Weather Condition	Time	TSP Level (µg/m³)
6-Sep-23	Cloudy	9:43	14.9
6-Sep-23	Cloudy	10:43	13.2
6-Sep-23	Cloudy	11:43	18.8
12-Sep-23	Cloudy	8:51	21.6
12-Sep-23	Cloudy	9:51	17.4
12-Sep-23	Cloudy	10:51	16.1
18-Sep-23	Sunny	9:15	19.6
18-Sep-23	Sunny	10:15	18.1
18-Sep-23	Sunny	11:15	11.1
23-Sep-23	Sunny	9:00	68.4
23-Sep-23	Sunny	10:00	32.1
23-Sep-23	Sunny	11:00	33.0
29-Sep-23	Sunny	9:19	42.8
29-Sep-23	Sunny	10:19	45.9
29-Sep-23	Sunny	11:19	46.7



#### Contract No. HY/2019/04

### New Wang Tong River Bridge

	Dato	Sampling	Weather	Eilter paper po	Filter W	/eight, g	Elapse	Time, hr	Sampling	FI	ow Rate, m <sup>3</sup> /n	nin	Total	TSP Level,
	Date	Time	Condition	The paper no.	Initial	Final	Initial	Final	Time, hr	Initial, Qsi	Final, Qsf	Average	Volume, m <sup>3</sup>	µg/m³
AMS1	05/09/23	8:00	Cloudy	009711	2.7872	2.8445	4215.05	4239.05	24.00	0.58	0.64	0.61	875	65.5
AMS1	11/09/23	8:00	Cloudy	009712	2.7920	2.8231	4239.05	4263.05	24.00	0.53	0.64	0.59	843	36.9
AMS1	16/09/23	8:00	Sunny	009713	2.7966	2.8276	4263.05	4287.05	24.00	0.57	0.64	0.60	867	35.8
AMS1	22/09/23	8:00	Sunny	009714	2.7948	2.8343	4311.28	4335.28	24.00	0.60	0.64	0.62	888	44.5
AMS1	28/09/23	8:00	Sunny	009715	2.7914	2.8368	4335.28	4359.28	24.00	0.59	0.64	0.61	884	51.4
AMS2	05/09/23	8:00	Cloudy	009705	2.7971	2.8392	4720.39	4744.39	24.00	1.63	1.63	1.63	2350	17.9
AMS2	11/09/23	8:00	Cloudy	009706	2.8004	2.8252	4744.39	4768.39	24.00	1.64	1.64	1.64	2359	10.5
AMS2	16/09/23	8:00	Sunny	009707	2.7951	2.8391	4768.39	4792.39	24.00	1.64	1.64	1.64	2360	18.6
AMS2	22/09/23	8:00	Sunny	009708	2.8014	2.9018	4792.39	4816.39	24.00	1.63	1.63	1.63	2353	42.7
AMS2	28/09/23	8:00	Sunny	009709	2.7942	2.8738	4816.39	4840.39	24.00	1.63	1.64	1.63	2354	33.8

Remarks:

















Appendix 5.4

Water Quality Monitoring Results and Graphical Presentations

Lam Environmental Services Limited	
Water Quality Monitoring Results	

am

#### Water Quality Monitoring at Station W1 (Middle) - Ebb Tide

	Compling		Compling	Water	Sampling	Sampling	Te	emperatur	re		pН			Salinity		DC	) Saturatio	n		DO			Turbidity		SS	S
Station Reference	Date	Weather	Time	Depth		Depth		°C			-			ppt			%			mg/L			NTU		mg	J/L
	Duic		TIME	m	LOVOI	m	Valu	le	Average	Value		Average	Valu	ie	Average	Valu	ue	Average	Va	lue	Average	Valu	Je	Average	Value	Average
	4/0/2022	Suppy	14:30	0.50		0.25	27.20	27.20	27.2	7.39	7.39	74	0.58	0.58	0.6	78.70	78.00	79.4	6.49	6.40	64	3.76	3.76	3.8	2.70	27
	4/3/2023	Sunny	14:35	0.50		0.25	27.20	27.20	21.2	7.39	7.39	7.4	0.58	0.58	0.0	78.70	78.00	70.4	6.49	6.40	0.4	3.76	3.76	0.0	2.60	2.1
	6/0/2023	Suppy	16:00	0.50		0.25	27.60	27.60	27.6	7.03	7.03	7.0	0.20	0.20	0.2	90.90	90.40	90.7	7.78	7.74	78	4.58	4.58	46	3.00	3.2
	0/3/2023	Guility	16:05	0.50		0.25	27.60	27.60	21.0	7.03	7.03	1.0	0.20	0.20	0.2	90.90	90.40	30.7	7.78	7.74	7.0	4.58	4.58	4.0	3.40	0.2
	11/0/2023	Rainny	9:45	0.50		0.25	25.50	25.50	25.5	7.31	7.31	73	0.18	0.18	0.2	79.50	79.00	70.3	7.00	6.93	7.0	6.00	6.00	60	4.50	4.4
	11/3/2023	realitity	9:50	0.50		0.25	25.50	25.50	20.0	7.31	7.31	1.5	0.18	0.18	0.2	79.50	79.00	13.5	7.00	6.93	1.0	6.00	6.00	0.0	4.30	4.4
	13/0/2023	Suppy	10:45	0.50		0.25	25.00	25.00	25.0	7.38	7.38	74	0.30	0.30	0.3	84.70	83.80	8/1 3	7.67	7.61	7.6	4.40	4.40	44	3.10	3.0
	10/0/2020	Gainty	10:50	0.50		0.25	25.00	25.00	20.0	7.38	7.38		0.30	0.30	0.0	84.70	83.80	01.0	7.67	7.61		4.40	4.40		2.80	0.0
	15/9/2023	Sunny	11:45	0.50		0.25	25.60	25.60	25.6	7.48	7.48	7.5	0.24	0.24	0.2	88.70	87.40	88.1	7.70	7.62	7.7	5.07	5.06	5.1	3.60	3.5
10/4	10/0/2020	Gainty	11:50	0.50		0.25	25.60	25.60	20.0	7.48	7.48	1.0	0.24	0.24	0.2	88.70	87.40	00.1	7.70	7.62		5.07	5.06		3.40	0.0
Wang Tong River	18/9/2023	Sunny	13:15	0.50	Middle	0.25	27.40	27.40	27.4	7.43	7.43	74	0.10	0.10	0.1	94.90	94.30	94.6	8.00	7.94	8.0	5.07	5.07	5.1	3.70	3.9
(Major tributary)	10/0/2020	ounny	13:20	0.50	maano	0.25	27.40	27.40	2000	7.43	7.43		0.10	0.10	0.1	94.90	94.30	01.0	8.00	7.94		5.07	5.07		4.10	0.0
	20/9/2023	Sunny	14:30	0.50		0.25	27.50	27.40	27.5	7.42	7.42	7.4	0.09	0.09	0.1	82.00	81.50	81.8	6.25	6.17	6.2	4.78	4.78	4.8	2.60	2.8
		÷2,	14:35	0.50		0.25	27.50	27.40		7.42	7.42		0.09	0.09		82.00	81.50		6.25	6.17		4.78	4.78		3.00	
	22/9/2023	Sunny	6:45	0.50		0.25	25.30	25.30	25.3	7.44	7.44	7.4	0.11	0.11	0.1	80.80	80.20	80.5	7.18	7.12	7.2	3.77	3.77	3.8	2.90	3.1
		,	6:50	0.50		0.25	25.30	25.30		7.44	7.44		0.11	0.11		80.80	80.20		7.18	7.12		3.77	3.77		3.20	
	25/9/2023	Sunny	8:00	0.50		0.25	26.50	26.50	26.5	7.38	7.38	7.4	0.41	0.41	0.4	85.30	84.80	85.1	7.29	7.23	7.3	3.67	3.67	3.7	3.40	3.4
		÷,	8:05	0.50		0.25	26.50	26.50		7.38	7.38		0.41	0.41		85.30	84.80		7.29	7.23		3.67	3.67		3.30	
	27/9/2023	Sunny	9:30	0.50		0.25	26.60	26.60	26.6	7.47	7.47	7.5	2.38	2.38	2.4	83.50	82.50	83.0	7.28	7.17	7.2	3.69	3.69	3.7	2.50	2.4
		÷,	9:35	0.50		0.25	26.60	26.60		7.47	7.47		2.38	2.38		83.50	82.50		7.28	7.17		3.69	3.69		2.20	
	29/9/2023	Sunny	11:00	0.50		0.25	26.40	26.40	26.4	7.46	7.46	7.5	1.36	1.36	1.4	77.10	76.70	76.9	7.27	7.19	7.2	4.58	4.58	4.6	2.20	2.2
	29/9/2023	22.009	11:05	0.50		0.25	26.40	26.40		7.46	7.46		1.36	1.36		77.10	76.70		7.27	7.19	-	4.58	4.58		2.20	

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W1 (Middle) - Flood Tide

	Complian		Complian	Water	Complian	Sampling	Te	emperatur	е		pН			Salinity		DC	Saturatio	on		DO		Turb	dity		SS
Station Reference	Date	Weather	Time	Depth	Denth	Depth		°C			-			ppt			%			mg/L		N	U		ng/L
	Date		TIME	m	Depai	m	Val	ue	Average	Value		Average	Valu	le	Average	Valu	Ie	Average	Va	lue	Average	Value	Averag	e Value	Average
	4/0/2022	Suppy	8:30	0.50		0.25	25.80	25.80	25.9	7.29	7.29	7.2	0.18	0.18	0.2	76.80	76.20	76 5	6.97	6.90	6.0	4.54	4.54	5.3	) 51
	4/3/2023	Sunny	8:35	0.50		0.25	25.80	25.80	23.0	7.29	7.29	7.5	0.18	0.18	0.2	76.80	76.20	70.5	6.97	6.90	0.5	4.54	4.54	.5 4.9	J 3.1
	6/9/2023	Sunny	10:30	0.50		0.25	27.10	27.10	27.1	7.52	7.52	75	0.22	0.22	0.2	94.00	93.70	93.9	7.91	7.84	79	4.24	4.24	2 2.8	30
	0/3/2023	Outility	10:35	0.50		0.25	27.10	27.10	21.1	7.52	7.52	1.5	0.22	0.22	0.2	94.00	93.70	55.5	7.91	7.84	1.5	4.24	4.24	3.1	J 3.0
	11/9/2023	Rainny	17:00	0.50		0.25	25.20	25.20	25.2	7.38	7.38	74	0.17	0.17	0.2	84.90	84.20	84.6	7.57	7.47	7.5	5.65	5.65	7 5.1	) 53
	11/3/2023	rearing	17:05	0.50		0.25	25.20	25.20	20.2	7.38	7.38	7.4	0.17	0.17	0.2	84.90	84.20	04.0	7.57	7.47	7.5	5.65	5.65	5.4	J 3.5
	13/0/2023	Rainny	17:30	0.50		0.25	25.50	25.50	25.5	7.55	7.55	76	0.22	0.22	0.2	81.90	81.10	81.5	7.33	7.23	73	4.55	4.55	6 3.5	) 37
	10/0/2020	rearrity	17:35	0.50		0.25	25.50	25.50	20.0	7.55	7.55	7.0	0.22	0.22	0.2	81.90	81.10	01.5	7.33	7.23	7.0	4.55	4.55	3.8	J 3.7
	15/9/2023	Rainny	17:30	0.50		0.25	26.00	26.00	26.0	7.32	7.32	73	0.22	0.22	0.2	79.70	79.20	79.5	6.86	6.80	6.8	4.40	4.40	4 2.2	) 23
10/4	10/0/2020	rtainiy	17:35	0.50		0.25	26.00	26.00	20.0	7.32	7.32	1.0	0.22	0.22	0.2	79.70	79.20	10.0	6.86	6.80	0.0	4.40	4.40	2.4	J
Wang Tong River	18/9/2023	Suppy	7:00	0.50	Middle	0.25	26.30	26.30	26.3	7.27	7.27	73	0.11	0.11	0.1	88.10	87.70	87.0	7.48	7.41	74	4.12	4.12	1 2.8	) 30
(Major tributary)	10/3/2023	Odniny	7:05	0.50	wilduic	0.25	26.30	26.30	20.5	7.27	7.27	7.5	0.11	0.11	0.1	88.10	87.70	07.5	7.48	7.41	7.4	4.12	4.12	3.1	J 3.0
( ), ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	20/9/2023	Sunny	8:45	0.50		0.25	27.20	27.20	27.2	7.72	7.72	77	0.12	0.12	32	87.80	86.80	87.3	7.70	7.63	77	7.16	7.16 7	2 5.8	56
	20/0/2020	ounny	8:50	0.50		0.25	27.20	27.20	27.2	7.72	7.72		0.12	12.51	0.2	87.80	86.80	07.0	7.70	7.63		7.16	7.16	5.4	J
	22/0/2023	Suppy	15:15	0.50		0.25	26.40	26.40	26.4	7.50	7.50	75	0.24	0.24	0.2	87.70	87.00	87.4	7.68	7.61	76	4.36	4.36	3.0	) 29
	22/3/2023	Odniny	15:20	0.50		0.25	26.40	26.40	20.4	7.50	7.50	7.5	0.24	0.24	0.2	87.70	87.00	07.4	7.68	7.61	7.0	4.36	4.36	2.7	J 2.5
	25/0/2023	Suppy	16:00	0.50		0.25	26.60	26.60	26.6	7.45	7.45	75	0.38	0.38	0.4	80.60	80.00	80.3	7.19	7.11	7.2	4.81	4.81	8 3.8	) 30
	20/0/2020	Outility	16:05	0.50		0.25	26.60	26.60	20.0	7.45	7.45	1.5	0.38	0.38	0.4	80.60	80.00	00.5	7.19	7.11	1.2	4.81	4.81	4.0	J 3.5
	27/9/2023	Suppy	16:45	0.50		0.25	26.30	26.30	26.3	7.40	7.40	74	0.55	0.55	0.6	77.80	77.30	77.6	6.88	6.83	6.9	3.16	3.16	2 2.1	) 23
	2113/2023	Ouniny	16:50	0.50		0.25	26.30	26.30	20.5	7.40	7.40	7.4	0.55	0.55	0.0	77.80	77.30	11.0	6.88	6.83	0.5	3.16	3.16	2.4	J 2.0
	29/9/2023	Sunny	17:30	0.50		0.25	26.40	26.40	26.4	7.41	7.41	74	0.76	0.76	0.8	83.80	83.00	83.4	7.47	7.40	74	3.77	3.77	8 2.0	) 20
	23/3/2023	Gunny	17:35	0.50		0.25	26.40	26.40	20.4	7.41	7.41	7.4	0.76	0.76	0.0	83.80	83.00	03.4	7.47	7.40	7.4	3.77	3.77	2.0	J 2.0

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

lam	I am Environmental Service
	Lan Livionnental Service.

#### Water Quality Monitoring at Station W2 (Middle) - Ebb Tide

	0		0	Water	0	Sampling	Т	emperatur	е		pН			Salinity		DC	) Saturatio	on		DO			Turbidity		S	S
Station Reference	Sampling	Weather	Sampling	Depth	Sampling	Depth		°C			-			ppt			%			mg/L			NTU		mg	J/L
	Date		THIC	m	LOVOI	m	Val	ue	Average	Value	•	Average	Valu	le	Average	Val	le	Average	Value		Average	Va	lue	Average	Value	Average
	4/0/2022	Suppy	14:45	0.50		0.25	27.60	27.60	27.6	7.26	7.26	7.2	2.23	2.23	2.2	84.20	83.80	94.0	7.26	7.20	7.2	6.17	6.17	6.2	5.00	5.1
	4/3/2023	Sunny	14:50	0.50		0.25	27.60	27.60	27.0	7.26	7.26	7.5	2.23	2.23	2.2	84.20	83.80	04.0	7.26	7.20	1.2	6.17	6.17	0.2	5.10	3.1
	6/9/2023	Suppy	16:15	0.50		0.25	28.30	28.30	28.3	7.45	7.45	75	0.89	0.89	0.9	73.70	72.80	73.3	6.88	6.78	6.8	6.13	6.13	61	5.40	57
	0/0/2020	Gainty	16:20	0.50		0.25	28.30	28.30	20.0	7.45	7.45	1.0	0.89	0.89	0.0	73.70	72.80	70.0	6.88	6.78	0.0	6.13	6.13	0.1	5.90	0.1
	11/9/2023	Rainny	10:00	0.50		0.25	25.90	25.90	25.9	7.18	7.18	7.2	0.72	0.72	0.7	84.00	83.10	83.6	7.54	7.49	7.5	6.81	6.80	6.8	7.70	7.6
			10:05	0.50		0.25	25.90	25.90		7.18	7.18		0.72	0.72		84.00	83.10		7.54	7.49		6.81	6.80		7.40	
	13/9/2023	Sunny	11:00	0.50		0.25	25.20	25.20	25.2	7.25	7.25	7.3	1.49	1.49	1.5	81.30	80.90	81.1	7.46	7.39	7.4	4.71	4.70	4.7	3.10	3.3
		÷2,	11:05	0.50		0.25	25.20	25.20		7.25	7.25		1.49	1.49		81.30	80.90	•	7.46	7.39		4.71	4.70		3.40	0.0
	15/9/2023	Sunny	12:00	0.50		0.25	25.80	25.80	25.8	7.27	7.27	7.3	1.96	1.96	2.0	84.60	83.80	84.2	7.52	7.43	7.5	5.65	5.65	5.7	5.30	5.4
W2			12:05	0.50		0.25	25.80	25.80		7.27	7.27		1.96	1.96		84.60	83.80		7.52	7.43		5.65	5.65		5.50	
Wang Tong River	18/9/2023	Sunny	13:30	0.50	Middle	0.25	28.40	28.40	28.4	7.34	7.34	7.3	0.65	0.65	0.7	83.10	82.40	82.8	7.14	7.07	7.1	6.59	6.59	6.6	7.10	7.4
(Major tributary)		÷,	13:35	0.50		0.25	28.40	28.40		7.34	7.34		0.65	0.65		83.10	82.40		7.14	7.07		6.59	6.59		7.60	
	20/9/2023	Sunny	14:45	0.50		0.25	27.10	27.10	27.1	7.24	7.24	7.2	0.61	0.61	0.6	78.30	77.80	78.1	6.85	6.77	6.8	4.36	4.36	4.4	3.70	3.9
		÷,	14:50	0.50		0.25	27.10	27.10		7.24	7.24		0.61	0.61		78.30	77.80		6.85	6.77		4.36	4.36		4.00	
	22/9/2023	Sunny	7:00	0.50		0.25	25.50	25.50	25.5	7.34	7.34	7.3	0.50	0.50	0.5	81.00	80.10	80.6	7.23	7.17	7.2	3.37	3.37	3.4	4.20	4.4
		,	7:05	0.50		0.25	25.50	25.50		7.34	7.34		0.50	0.50		81.00	80.10		7.23	7.17		3.37	3.37		4.60	
	25/9/2023	Sunny	8:15	0.50		0.25	27.60	27.60	27.6	7.36	7.36	7.4	1.19	1.19	1.2	78.30	77.50	77.9	7.10	7.04	7.1	4.36	4.36	4.4	3.60	3.8
		,	8:20	0.50		0.25	27.60	27.60		7.36	7.36		1.19	1.19		78.30	77.50		7.10	7.04		4.36	4.36		4.00	
	27/9/2023	Sunny	9:45	0.50		0.25	28.80	28.80	28.8	7.54	7.54	7.5	4.62	4.62	4.6	82.00	81.60	81.8	6.85	6.81	6.8	6.35	6.35	6.4	6.00	5.8
		,	9:50	0.50		0.25	28.80	28.80		7.54	7.54		4.62	4.62		82.00	81.60		6.85	6.81		6.35	6.35		5.60	
	29/9/2023	Sunny	11:15	0.50		0.25	26.80	26.80	26.8	7.41	7.41	7.4	3.01	3.01	3.0	77.20	76.70	77.0	7.10	7.02	7.1	5.46	5.46	5.5	2.30	2.4
	29/9/2023		11:20	0.50		0.25	26.80	26.80		7.41	7.41		3.01	3.01		77.20	76.70		7.10	7.02		5.46	5.46		2.50	-

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W2 (Middle) - Flood Tide

	Complian		Complian	Water	Complian	Sampling	T	emperatu	re		pН			Salinity		D	O Saturatio	on	[	00		Turbidity		S	S
Station Reference	Date	Weather	Time	Depth	Depth	Depth		°C			-			ppt			%		rr	ng/L		NTU		mç	g/L
	Date		Time	m	Depai	m	Val	ue	Average	Value	e	Average	Valu	ie	Average	Va	ue	Average	Value	Avera	je V	alue	Average	Value	Average
	4/0/2022	Suppy	8:45	0.50		0.25	26.10	26.10	26.1	7.19	7.19	7.2	1.01	1.01	1.0	81.70	81.10	91.4	7.12	7.02	11.00	11.00	11.0	24.10	24.6
	4/3/2023	Sunny	8:50	0.50		0.25	26.10	26.10	20.1	7.19	7.19	1.2	1.01	1.01	1.0	81.70	81.10	01.4	7.12	7.02	11.00	11.00	11.0	25.00	24.0
	6/0/2022	Suppy	10:45	0.50		0.25	27.90	27.90	27.0	7.46	7.46	7.5	0.93	0.93	0.0	87.50	86.60	97.1	7.75	7.70	5.67	5.67	57	3.50	2.2
	0/9/2023	Sunny	10:50	0.50		0.25	27.90	27.90	21.5	7.46	7.46	7.5	0.93	0.93	0.5	87.50	86.60	07.1	7.75	7.70	./ 5.67	5.67	5.7	3.10	3.3
	11/0/2023	Rainny	17:15	0.50		0.25	25.40	25.40	25.4	7.20	7.20	7.2	0.61	0.61	0.6	82.30	81.30	81.8	7.12	7.06	5.86	5.86	5.0	8.10	8.0
	11/3/2023	realitity	17:20	0.50		0.25	25.40	25.40	20.4	7.20	7.20	1.2	0.61	0.61	0.0	82.30	81.30	01.0	7.12	7.06	5.86	5.86	0.5	7.80	0.0
	13/9/2023	Rainny	17:45	0.50		0.25	25.70	25.70	25.7	7.41	7.41	74	0.57	0.57	0.6	78.90	78.10	78 5	7.07	7.00	4.75	4.75	4.8	4.80	46
	10/3/2023	realitity	17:50	0.50		0.25	25.70	25.70	20.7	7.41	7.41	7.4	0.57	0.57	0.0	78.90	78.10	70.5	7.07	7.00	4.75	4.75	4.0	4.40	4.0
	15/9/2023	Rainny	17:45	0.50		0.25	26.20	26.20	26.2	7.30	7.30	73	0.53	0.53	0.5	77.90	77.30	77.6	6.77	6.67	4.46	4.45	4.5	3.00	3.2
10/2	10/0/2020	Realitity	17:50	0.50		0.25	26.20	26.20	20.2	7.30	7.30	1.5	0.53	0.53	0.5	77.90	77.30	11.0	6.77	6.67	4.46	4.45	4.5	3.30	0.2
Wang Tong River	18/0/2023	Suppy	7:15	0.50	Middle	0.25	26.60	26.60	26.6	7.23	7.23	7.2	0.62	0.62	0.6	89.80	89.20	89.5	7.87	7.81	4.78	4.78	4.8	5.30	54
(Major tributary)	10/3/2023	Odinity	7:20	0.50	maaro	0.25	26.60	26.60	20.0	7.23	7.23	1.2	0.62	0.62	0.0	89.80	89.20	00.0	7.87	7.81	4.78	4.78	4.0	5.50	0.4
( ), ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	20/9/2023	Sunny	9:00	0.50		0.25	27.70	27.70	27.7	7.46	7.46	75	0.39	0.39	0.4	85.90	85.40	85.7	7.44	7.37	5.12	5.12	51	4.40	43
	20/0/2020	ounny	9:05	0.50		0.25	27.70	27.70	2	7.46	7.46	1.0	0.39	0.39	0.1	85.90	85.40	00.7	7.44	7.37	5.12	5.12	0.1	4.10	1.0
	22/9/2023	Sunny	15:30	0.50		0.25	27.60	27.60	27.6	7.49	7.49	7.5	0.43	0.43	0.4	83.20	82.60	82.9	7.51	7.43	4.11	4.10	41	2.00	20
	22/0/2020	ounny	15:35	0.50		0.25	27.60	27.60	27.0	7.49	7.49	1.0	0.43	0.43	0.1	83.20	82.60	02.0	7.51	7.43	4.11	4.10		2.00	2.0
	25/9/2023	Sunny	16:15	0.50		0.25	27.10	27.10	27.1	7.41	7.41	7.4	0.58	0.58	0.6	79.40	79.00	79.2	7.24	7.16	3.89	3.89	3.9	2.70	2.6
			16:20	0.50		0.25	27.10	27.10		7.41	7.41		0.58	0.58		79.40	79.00		7.24	7.16	3.89	3.89		2.40	
	27/9/2023	Sunny	17:00	0.50		0.25	26.60	26.60	26.6	7.34	7.34	7.3	1.32	1.32	1.3	80.70	80.00	80.4	7.00	6.94	3.02	3.02	3.0	2.60	2.8
			17:05	0.50		0.25	26.60	26.60		7.34	7.34		1.32	1.32		80.70	80.00		7.00	6.94	3.02	3.02		2.90	
	29/9/2023	Sunny	17:45	0.50		0.25	26.90	26.90	26.9	7.35	7.35	7.4	1.47	1.47	1.5	78.20	77.40	77.8	6.87	6.80	3.39	3.39	3.4	2.00	2.0
	20.0.2020	22/11/9	17:50	0.50		0.25	26.90	26.90	20.0	7.35	7.35		1.47	1.47		78.20	77.40		6.87	6.80	3.39	3.39	0.1	2.00	2.0

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

am	Lam Environmental Service
	Water Ovelity Meniterian D

#### Water Quality Monitoring at Station W4 (Middle) - Ebb Tide

	Complian		Complian	Water	Complian	Sampling	Т	emperatur	e		pН			Salinity		DC	) Saturatio	n		DO			Turbidity		S	S
Station Reference	Date	Weather	Time	Depth	Level	Depth		°C			-			ppt			%		-	mg/L			NTU		mg	j/L
	Duto			m	2010.	m	Val	ue	Average	Value	e	Average	Val	ue	Average	Valu	le	Average	Value		Average	Va	ue	Average	Value	Average
	4/0/2022	Suppy	15:00	0.50		0.25	28.70	28.70	29.7	7.43	7.43	74	3.70	3.70	27	80.00	79.20	70.6	7.40	6.92	7.2	12.23	12.23	12.2	13.80	14.1
	4/9/2023	Sunny	15:05	0.50		0.25	28.70	28.70	20.7	7.43	7.43	7.4	3.70	3.70	3.7	80.00	79.20	79.0	7.40	6.92	1.2	12.23	12.23	12.2	14.30	14.1
	6/9/2023	Suppy	16:30	0.50		0.25	29.00	29.00	29.0	7.53	7.53	7.5	1.51	1.51	15	89.00	88.70	88.9	7.47	7.39	74	6.09	6.09	61	7.00	71
	0/0/2020	Gainty	16:35	0.50		0.25	29.00	29.00	20.0	7.53	7.53	1.0	1.51	1.51		89.00	88.70	00.0	7.47	7.39	7.11	6.09	6.09	0.1	7.20	
	11/9/2023	Rainny	10:15	0.50		0.25	26.20	26.20	26.2	7.32	7.32	7.3	2.60	2.60	2.6	77.00	76.20	76.6	6.55	6.45	6.5	7.44	7.43	7.4	17.00	17.3
			10:20	0.50		0.25	26.20	26.20		7.32	7.32		2.60	2.60		77.00	76.20		6.55	6.45		7.44	7.43		17.60	
	13/9/2023	Sunny	11:15	0.50		0.25	25.10	25.10	25.1	7.38	7.38	7.4	2.06	2.06	2.1	82.30	81.50	81.9	8.20	8.10	8.2	4.85	4.85	4.9	3.80	4.0
		÷2,	11:20	0.50		0.25	25.10	25.10		7.38	7.38		2.06	2.06		82.30	81.50		8.20	8.10		4.85	4.85		4.20	
W4	15/9/2023	Sunny	12:15	0.50		0.25	26.30	26.30	26.3	7.55	7.55	7.6	7.77	7.77	7.8	88.80	88.10	88.5	7.56	7.48	7.5	5.18	5.18	5.2	6.10	6.1
			12:20	0.50		0.25	26.30	26.30		7.55	7.55		7.77	7.77		88.80	88.10		7.56	7.48		5.18	5.18		6.00	***
Wang Tong River	18/9/2023	Sunny	13:45	0.50	Middle	0.25	28.70	28.70	28.7	7.43	7.43	7.4	1.13	1.13	1.1	79.70	79.10	79.4	7.03	6.96	7.0	6.75	6.75	6.8	11.60	11.5
(Minor tributary to Tai		÷,	13:50	0.50		0.25	28.70	28.70		7.43	7.43		1.13	1.13		79.70	79.10		7.03	6.96		6.75	6.75	0.0	11.30	
vvai vuen)	20/9/2023	Sunny	15:00	0.50		0.25	27.30	27.30	27.3	7.35	7.35	7.4	1.08	1.08	1.1	79.50	78.60	79.1	7.00	6.92	7.0	4.35	4.35	4.4	2.50	2.7
		÷,	15:05	0.50		0.25	27.30	27.30		7.35	7.35		1.08	1.08		79.50	78.60		7.00	6.92		4.35	4.35		2.90	
	22/9/2023	Sunny	7:15	0.50		0.25	25.80	25.80	25.8	7.43	7.43	7.4	0.48	0.48	0.5	83.60	82.70	83.2	7.50	7.41	7.5	3.62	3.62	3.6	4.20	4.3
		÷,	7:20	0.50		0.25	25.80	25.80		7.43	7.43		0.48	0.48		83.60	82.70		7.50	7.41		3.62	3.62	0.00	4.40	
	25/9/2023	Sunny	8:30	0.50		0.25	28.40	28.40	28.4	7.45	7.45	7.5	1.70	1.70	1.7	83.00	82.60	82.8	7.00	6.94	7.0	5.30	5.30	5.3	4.70	4.8
25		÷,	8:35	0.50		0.25	28.40	28.40		7.45	7.45		1.70	1.70		83.00	82.60		7.00	6.94		5.30	5.30	0.0	4.80	
27/9/	27/9/2023	Sunny	10:00	0.50		0.25	28.70	28.70	28.7	7.51	7.51	7.5	11.31	11.31	11.3	76.90	76.20	76.6	6.16	6.11	6.1	5.76	5.76	5.8	15.00	15.3
		÷2,	10:05	0.50		0.25	28.70	28.70		7.51	7.51		11.31	11.31		76.90	76.20		6.16	6.11		5.76	5.76	0.0	15.60	
	29/9/2023	Sunny	11:30	0.50		0.25	27.30	27.30	27.3	7.49	7.79	7.6	5.27	5.27	5.3	79.60	79.20	79.4	6.81	6.74	6.8	4.40	4.40	4.4	2.10	2.3
	20.0.2020	22.009	11:35	0.50		0.25	27.30	27.30		7.49	7.79		5.27	5.27	2.0	79.60	79.20	. 511	6.81	6.74	2.0	4.40	4.40		2.40	2.0

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W4 (Middle) - Flood Tide

	0		0	Water	0	Sampling	T€	emperatur	e		pН			Salinity		D	O Saturatio	on	DC			Turbidity		S	S
Station Reference	Sampling	Weather	Sampling	Depth	Depth	Depth		°C			-			ppt			%		mg	L		NTU		mç	j/L
	Date		Time	m	Depai	m	Valu	le	Average	Value	е	Average	Value	e	Average	Va	lue	Average	Value	Average	e Va	ue	Average	Value	Average
	4/9/2023	Suppy	9:00	0.50		0.25	26.10	26.10	26.1	7.30	7.30	73	1.19	1.19	12	70.10	69.50	60.8	6.71 6	.61 6.7	13.72	13.72	13.7	25.00	26.0
	4/3/2023	Sunny	9:05	0.50		0.25	26.10	26.10	20.1	7.30	7.30	1.5	1.19	1.19	1.2	70.10	69.50	09.0	6.71 6	.61	13.72	13.72	13.7	26.90	20.0
	6/0/2023	Suppy	11:00	0.50		0.25	28.60	28.60	28.6	7.56	7.56	76	2.08	2.08	21	74.60	74.00	74.3	7.35	.26 7 3	9.41	9.41	9.4	10.40	10.3
	0/9/2023	Sunny	11:05	0.50		0.25	28.60	28.60	20.0	7.56	7.56	7.0	2.08	2.08	2.1	74.60	74.00	74.5	7.35	.26	9.41	9.41	5.4	10.20	10.3
	11/0/2023	Rainny	17:30	0.50		0.25	25.70	25.70	25.7	7.34	7.34	73	1.71	1.71	17	83.00	82.60	82.8	7.14	.04 7.1	9.09	9.08	0.1	18.60	18.8
	11/3/2023	Realitity	17:35	0.50		0.25	25.70	25.70	20.1	7.34	7.34	1.5	1.71	1.71	1.7	83.00	82.60	02.0	7.14	.04	9.09	9.08	5.1	19.00	10.0
	13/9/2023	Rainny	18:00	0.50		0.25	25.80	25.80	25.8	7.52	7.52	75	1.71	1.71	17	73.90	73.40	73 7	7.10	.03 7 1	4.47	4.47	4.5	5.60	5.6
	13/9/2023	Raininy	18:05	0.50		0.25	25.80	25.80	23.0	7.52	7.52	1.5	1.71	1.71	1.7	73.90	73.40	13.1	7.10	.03	4.47	4.47	4.5	5.60	5.0
	15/9/2023	Rainny	18:00	0.50		0.25	26.20	26.20	26.2	7.30	7.30	73	0.53	0.53	0.5	77.90	77.30	77.6	6.77 6	.67	4.46	4.45	4.5	3.70	37
W4	10/0/2020	rearring	18:05	0.50		0.25	26.20	26.20	20.2	7.30	7.30	1.5	0.53	0.53	0.0	77.90	77.30	11.0	6.77 6	.67	4.46	4.45	4.5	3.60	0.7
Wang Tong River	18/0/2023	Suppy	7:30	0.50	Middle	0.25	26.60	26.60	26.6	7.36	7.36	74	0.65	0.65	0.7	73.30	72.60	73.0	6.78 6	.73 6.5	5.47	5.47	5.5	7.40	73
(Minor tributary to Tai	10/3/2023	Odniny	7:35	0.50	wilduic	0.25	26.60	26.60	20.0	7.36	7.36	1.4	0.65	0.65	0.7	73.30	72.60	70.0	6.78 6	.73	5.47	5.47	5.5	7.20	7.5
Wai Yuen)	20/0/2023	Suppy	9:15	0.50		0.25	28.10	28.10	28.1	7.43	7.43	74	0.76	0.76	0.8	81.50	80.60	81.1	6.99 6	.89 6.0	5.18	5.18	5.2	3.20	33
	20/3/2023	Odniny	9:20	0.50		0.25	28.10	28.10	20.1	7.43	7.43	1.4	0.76	0.76	0.0	81.50	80.60	01.1	6.99 6	.89	5.18	5.18	0.2	3.40	0.0
	22/0/2023	Suppy	15:45	0.50		0.25	27.70	27.70	27.7	7.50	7.50	75	0.77	0.77	0.8	78.70	78.30	78.5	7.10	.02 7 1	4.46	4.46	4.5	4.40	43
	22/3/2023	Odniny	15:50	0.50		0.25	27.70	27.70	21.1	7.50	7.50	1.5	0.77	0.77	0.0	78.70	78.30	70.5	7.10	.02	4.46	4.46	4.5	4.10	4.5
	25/0/2023	Suppy	16:30	0.50		0.25	27.40	27.40	27.4	7.45	7.45	75	0.87	0.87	0.0	81.00	80.30	80.7	7.18	.09 7 1	4.12	4.13	4.1	3.00	3.1
	20/3/2023	Odniny	16:35	0.50		0.25	27.40	27.40	21.4	7.45	7.45	1.5	0.87	0.87	0.5	81.00	80.30	00.7	7.18	.09	4.12	4.13	4.1	3.10	0.1
	27/9/2023	Suppy	17:15	0.50		0.25	26.90	26.90	26.9	7.42	7.42	74	2.47	2.47	25	71.90	71.60	71.8	6.88 6	.84 6.9	3.33	3.33	33	2.40	27
	2110/2020	ounny	17:20	0.50		0.25	26.90	26.90	20.0	7.42	7.42		2.47	2.47	2.0	71.90	71.60	11.0	6.88 6	.84	3.33	3.33	0.0	2.90	2
	20/0/2023	Suppy	18:00	0.50		0.25	27.00	27.00	27.0	7.41	7.41	74	3.07	3.07	3.1	85.60	85.00	85.3	6.57 6	.50 64	3.35	3.35	34	2.00	2.0
	29/9/2023	Guility	18:05	0.50		0.25	27.00	27.00	21.0	7.41	7.41	7.4	3.07	3.07	3.1	85.60	85.00	05.5	6.57 6	.50	3.35	3.35	3.4	2.00	2.0

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

am	Lam Environmental Servic
	Water Ovelity Manitarian D

#### ces Limited Water Quality Monitoring Results

Contract No. HY/2019/14 New Wang Tong River Bridge

#### Water Quality Monitoring at Station W5 (Middle) - Ebb Tide

	Complian		Complian	Water	Complian	Sampling	T	emperatu	re		pН			Salinity		D	O Saturatio	on		DO			Turbidity		SS	S
Station Reference	Date	Weather	Time	Depth	Sampling Level	Depth		°C			-			ppt			%			mg/L			NTU		mg	/L
	Bato			m	2010.	m	Val	ue	Average	Value	е	Average	Valu	ue	Average	Va	lue	Average	Value	е	Average	Va	ue	Average	Value	Average
	4/9/2023	Suppy	15:15	0.50		0.25	27.90	27.90	27.0	7.47	7.47	7.5	5.55	5.55	5.6	70.60	70.10	70.4	6.71	6.64	67	7.12	7.12	71	8.30	8.4
	4/3/2023	Odriny	15:20	0.50		0.25	27.90	27.90	21.5	7.47	7.47	1.5	5.55	5.55	5.0	70.60	70.10	70.4	6.71	6.64	0.7	7.12	7.12	7.1	8.50	0.4
	6/9/2023	Sunny	16:45	0.50		0.25	28.80	28.80	28.8	7.65	7.65	7.7	1.41	1.41	1.4	74.60	74.20	74.4	7.00	6.90	7.0	6.18	6.18	6.2	5.10	5.1
	0/0/2020	ounny	16:50	0.50		0.25	28.80	28.80	20.0	7.65	7.65		1.41	1.41		74.60	74.20		7.00	6.90	1.0	6.18	6.18	0.2	5.00	0.1
	11/9/2023	Rainny	10:30	0.50		0.25	25.70	25.70	25.7	7.58	7.58	7.6	1.34	1.34	1.3	74.10	73.70	73.9	6.73	6.57	6.7	8.57	8.57	8.6	11.80	11.6
			10:35	0.50		0.25	25.70	25.70		7.58	7.58		1.34	1.34		74.10	73.70		6.73	6.57	•	8.57	8.57		11.30	
	13/9/2023	Sunny	11:30	0.50		0.25	25.10	25.10	25.1	7.39	7.39	74	3.59	3.59	3.6	92.20	91.60	91.9	7.87	7.81	78	4.81	4.81	4.8	5.80	57
	10/0/2020	ounny	11:35	0.50		0.25	25.10	25.10	20.1	7.39	7.39		3.59	3.59	0.0	92.20	91.60	01.0	7.87	7.81	1.0	4.81	4.81	1.0	5.50	0.1
	15/9/2023	Sunny	12:30	0.50		0.25	26.10	26.10	26.1	7.68	7.68	77	9.63	9.63	9.6	75.80	75.00	75.4	6.64	6.54	6.6	5.22	5.21	5.2	6.70	6.6
W5	10/0/2020	ounny	12:35	0.50		0.25	26.10	26.10	20.1	7.68	7.68		9.63	9.63	0.0	75.80	75.00	10.1	6.64	6.54	0.0	5.22	5.21	0.2	6.50	0.0
Silvermine Bay	18/0/2023	Suppy	14:00	0.50	Middle	0.25	28.70	28.70	28.7	7.52	7.52	75	1.61	1.61	16	75.90	75.40	75 7	6.20	6.13	62	7.01	7.00	7.0	9.20	0 1
(Near Silvermine Bay	10/3/2023	Ouniny	14:05	0.50	Wilduic	0.25	28.70	28.70	20.7	7.52	7.52	7.5	1.61	1.61	1.0	75.90	75.40	75.7	6.20	6.13	0.2	7.01	7.00	7.0	8.90	3.1
Beach)	20/0/2023	Suppy	15:15	0.50		0.25	27.40	27.40	27.4	7.42	7.42	74	1.16	1.16	12	79.90	79.10	79.5	6.98	6.91	6.9	5.03	5.03	5.0	6.80	6.6
	20/3/2023	Ouniny	15:20	0.50		0.25	27.40	27.40	21.4	7.42	7.42	1.4	1.16	1.16	1.2	79.90	79.10	75.5	6.98	6.91	0.5	5.03	5.03	5.0	6.30	0.0
	22/0/2023	Suppy	7:30	0.50		0.25	26.00	26.00	26.0	7.48	7.48	75	0.93	0.93	0.9	86.00	85.40	85.7	7.65	7.60	7.6	3.49	3.49	3.5	7.40	72
	22/3/2023	Ouniny	7:35	0.50		0.25	26.00	26.00	20.0	7.48	7.48	7.5	0.93	0.93	0.5	86.00	85.40	00.7	7.65	7.60	7.0	3.49	3.49	0.0	7.00	1.2
	25/0/2023	Suppy	8:45	0.50		0.25	27.90	27.90	27.0	7.52	7.52	75	1.78	1.78	1.8	83.90	83.20	83.6	7.18	7.10	71	4.72	4.72	47	4.20	4.1
	20/3/2023	Ouniny	8:50	0.50		0.25	27.90	27.90	21.5	7.52	7.52	7.5	1.78	1.78	1.0	83.90	83.20	00.0	7.18	7.10	7.1	4.72	4.72	4.7	3.90	4.1
	27/0/2023	Suppy	10:15	0.50		0.25	28.20	28.20	28.2	7.56	7.56	7.6	7.21	7.21	7.2	75.30	74.90	75.1	6.20	6.10	62	5.71	5.71	5.7	16.10	16.4
	2113/2023	Odniny	10:20	0.50		0.25	28.20	28.20	20.2	7.56	7.56	7.0	7.21	7.21	1.2	75.30	74.90	73.1	6.20	6.10	0.2	5.71	5.71	5.1	16.60	10.4
	29/9/2023	Sunny	11:45	0.50		0.25	27.20	27.20	27.2	7.75	7.75	7.8	15.02	15.02	15.0	83.80	83.30	83.6	6.92	6.82	69	4.80	4.80	4.8	3.60	34
	20,0,2020	Ganny	11:50	0.50		0.25	27.20	27.20	27.2	7.75	7.75		15.02	15.02	. 5.0	83.80	83.30	00.0	6.92	6.82	0.0	4.80	4.80		3.20	0.4

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W5 (Middle) - Flood Tide

	Complian		Complian	Water	Complian	Sampling	Te	emperatur	e		pН			Salinity		D	O Saturatio	n	[	00		Turbidit	/	S	S
Station Reference	Date	Weather	Time	Depth	Depth	Depth		°C			-			ppt			%		m	ig/L		NTU		m	g/L
	Dute		Time	m	Depai	m	Valu	ue	Average	Value	е	Average	Value	е	Average	Val	ue	Average	Value	Avera	ge	Value	Average	Value	Average
	4/0/2022	Suppy	9:15	0.50		0.25	26.10	26.10	26.1	7.34	7.34	7.2	2.18	2.18	2.2	71.10	70.60	70.0	6.54	6.44	11	79 11.79	11.0	25.80	25.2
	4/3/2023	Sunny	9:20	0.50		0.25	26.10	26.10	20.1	7.34	7.34	7.5	2.18	2.18	2.2	71.10	70.60	70.9	6.54	6.44	11	79 11.79	) 11.0	24.80	20.0
	6/0/2022	Suppy	11:15	0.50		0.25	28.00	28.00	28.0	7.64	7.64	76	1.78	1.78	1.0	78.00	77.50	77 0	7.10	7.04	6	05 6.04	60	4.60	10
	0/9/2023	Sunny	11:20	0.50		0.25	28.00	28.00	20.0	7.64	7.64	7.0	1.78	1.78	1.0	78.00	77.50	11.0	7.10	7.04	6	05 6.04	L 0.0	4.90	4.0
	11/9/2023	Rainny	7:45	0.50		0.25	25.50	25.50	25.5	7.50	7.50	75	1.05	1.05	11	76.40	75.80	76.1	6.77	6.67	3 7 10	01 10.0	) 10.0	21.30	21.6
	11/3/2023	rearring	7:50	0.50		0.25	25.50	25.50	20.0	7.50	7.50	7.5	1.05	1.05		76.40	75.80	70.1	6.77	6.67	10	01 10.00	) 10.0	21.90	21.0
	12/0/2022	Rainny	18:15	0.50		0.25	25.70	25.70	25.7	7.58	7.58	76	1.13	1.13	1.1	74.30	74.00	74.2	6.71	6.67	3 3	90 3.9	) 20	5.30	5.5
	13/9/2023	Raininy	18:20	0.50		0.25	25.70	25.70	23.7	7.58	7.58	7.0	1.13	1.13	1.1	74.30	74.00	74.2	6.71	6.67	3.7	90 3.9	) 3.5	5.60	5.5
	15/9/2023	Rainny	18:15	0.50		0.25	26.30	26.30	26.3	7.40	7.40	74	1.08	1.08	11	75.10	74.40	74.8	6.49	6.42	5 5	20 5.19	52	4.70	10
W5	13/3/2023	rearring	18:20	0.50		0.25	26.30	26.30	20.5	7.40	7.40	7.4	1.08	1.08		75.10	74.40	74.0	6.49	6.42	5.5	20 5.19	) 3.2	5.10	4.5
Silvermine Bay	19/0/2022	Suppy	7:45	0.50	Middlo	0.25	26.50	26.50	26.5	7.34	7.34	7.2	4.15	4.15	4.2	80.00	79.60	70.9	6.88	6.80	4	77 4.7	10	4.40	12
(Near Silvermine Bay	10/9/2023	Sunny	7:50	0.50	wildule	0.25	26.50	26.50	20.5	7.34	7.34	7.5	4.15	4.15	4.2	80.00	79.60	79.0	6.88	6.80	4	77 4.7	, 4.0	4.10	4.5
Beach)	20/9/2023	Suppy	9:30	0.50		0.25	27.70	27.70	27.7	7.52	7.52	75	0.59	0.59	0.6	80.30	79.60	80.0	6.79	6.70	5 5	65 5.6	57	5.90	61
	20/3/2023	Odinity	9:35	0.50		0.25	27.70	27.70	21.1	7.52	7.52	7.5	0.59	0.59	0.0	80.30	79.60	00.0	6.79	6.70	5.7 5	65 5.6	5	6.30	0.1
	22/0/2023	Suppy	16:00	0.50		0.25	27.70	27.70	27.7	7.60	7.60	76	0.55	0.55	0.6	78.30	77.80	78 1	6.77	6.72	4	36 4.3	5 44	2.70	20
	22/3/2023	Odinity	16:05	0.50		0.25	27.70	27.70	21.1	7.60	7.60	7.0	0.55	0.55	0.0	78.30	77.80	70.1	6.77	6.72	4	36 4.3	3 7.4	3.10	2.5
	25/0/2023	Suppy	16:45	0.50		0.25	27.20	27.20	27.2	7.58	7.58	76	1.43	1.43	1.4	88.70	88.10	88.4	7.80	7.72	7.8 4	57 4.5	, 16	5.20	5.4
·	20/0/2020	Odinity	16:50	0.50		0.25	27.20	27.20	21.2	7.58	7.58	7.0	1.43	1.43	1.4	88.70	88.10	00.4	7.80	7.72	4	57 4.5	, 4.0	5.60	0.4
	27/9/2023	Suppy	17:30	0.50		0.25	26.60	26.60	26.6	7.55	7.55	76	2.32	2.32	23	77.20	76.50	76.9	6.60	6.51	3.6 4	36 4.3	6 44	5.20	55
	2110/2020	ounny	17:35	0.50		0.25	26.60	26.60	20.0	7.55	7.55	1.0	2.32	2.32	2.0	77.20	76.50	10.0	6.60	6.51	4	36 4.3	3	5.80	0.0
	29/9/2023	Suppy	18:15	0.50		0.25	27.00	27.00	27.0	7.51	7.51	7.5	3.46	3.46	35	75.40	74.70	75.1	6.37	6.32	3.3 4	13 4.13	3 41	3.20	34
	23/3/2023	Guility	18:20	0.50		0.25	27.00	27.00	21.0	7.51	7.51	1.5	3.46	3.46	3.5	75.40	74.70	73.1	6.37	6.32	4	13 4.13	4.1	3.50	3.4

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

am	Lam Environmental Service
	Water Quality Manitoring R

#### Water Quality Monitoring at Station W6 (Middle) - Ebb Tide

				Water		Sampling	Т	emperatu	re		pН			Salinity		D	O Saturatio	on		DO			Turbidity		S	s
Station Reference	Sampling	Weather	Sampling	Depth	Sampling	Depth		°C			-			ppt			%		r	ng/L			NTU		mg	J/L
	Date		Time	m	Level	m	Va	ue	Average	Value	е	Average	Val	ue	Average	Val	ue	Average	Value	A	verage	Va	lue	Average	Value	Average
	4/0/2022	Cuppu	15:30	1.90		0.95	27.40	27.40	27.4	7.99	7.99		31.41	31.41	21.4	78.70	78.00	70.4	6.25	6.15	6.2	5.40	5.40	5.4	7.00	6.0
	4/9/2023	Sunny	15:35	1.90		0.95	27.40	27.40	27.4	7.99	7.99	0.0	31.41	31.41	31.4	78.70	78.00	/0.4	6.25	6.15	0.2	5.40	5.40	5.4	6.50	0.0
	6/0/2023	Suppy	17:00	1.80		0.90	27.20	27.20	27.2	8.13	8.13	8.1	31.36	31.36	31.4	75.60	75.20	75.4	7.00	6.91	7.0	8.57	8.59	86	6.30	61
	0/3/2023	Odinity	17:05	1.80		0.90	27.20	27.20	21.2	8.13	8.13	0.1	31.36	31.36	51.4	75.60	75.20	73.4	7.00	6.91	7.0	8.57	8.59	0.0	5.90	0.1
	11/9/2023	Rainny	10:45	1.90		0.95	25.50	25.50	25.5	7.91	7.91	79	15.72	15.72	15.7	78.00	77.20	77.6	7.15	7.04	71	5.00	4.99	5.0	4.70	49
	1110/2020	rtainiy	10:50	1.90		0.95	25.50	25.50	20.0	7.91	7.91	1.0	15.72	15.72	10.1	78.00	77.20	11.0	7.15	7.04		5.00	4.99	0.0	5.00	1.0
	13/9/2023	Sunny	11:45	1.90		0.95	26.40	26.40	26.4	7.89	7.89	7.9	21.58	21.58	21.6	80.70	79.80	80.3	6.80	6.71	6.8	2.91	2.90	2.9	4.80	4.7
			11:50	1.90		0.95	26.40	26.40		7.89	7.89		21.58	21.58		80.70	79.80		6.80	6.71		2.91	2.90		4.50	
	15/9/2023	Sunny	12:45	1.80		0.90	28.10	28.10	28.1	8.08	8.08	8.1	22.46	22.47	22.5	86.90	86.20	86.6	6.99	6.89	6.9	4.27	4.26	4.3	5.00	4.9
W6		,	12:50	1.80		0.90	28.10	28.10		8.08	8.08		22.46	22.47		86.90	86.20		6.99	6.89		4.27	4.26		4.80	
Silvermine Bay	18/9/2023	Sunny	14:15	1.80	Middle	0.90	28.80	28.80	28.8	8.19	8.19	8.2	21.90	21.90	21.9	80.90	80.40	80.7	6.32	6.25	6.3	3.99	3.99	4.0	4.60	4.8
(Near Silvermine Bay		,	14:20	1.80		0.90	28.80	28.80		8.19	8.19		21.90	21.90		80.90	80.40		6.32	6.25		3.99	3.99		5.00	
Deacii)	20/9/2023	Sunny	15:30	1.80		0.90	27.00	27.00	27.0	8.44	8.44	8.4	27.69	27.69	27.7	88.80	88.20	88.5	6.96	6.91	6.9	5.03	5.03	5.0	4.40	4.7
			15:35	1.80		0.90	27.00	27.00		8.44	8.44		27.69	27.69		88.80	88.20		6.96	6.91		5.03	5.03		4.90	
	22/9/2023	Sunny	7:45	1.80		0.90	25.70	25.70	25.7	8.32	8.32	8.3	25.33	25.33	25.3	90.00	89.60	89.8	6.46	6.37	6.4	4.37	4.37	4.4	6.50	6.7
			7:50	1.80		0.90	25.70	25.70		8.32	8.32		25.33	25.33		90.00	89.60		6.46	6.37	-	4.37	4.37		6.80	
	25/9/2023	Sunny	9:00	1.80		0.90	27.80	27.80	27.8	8.35	8.35	8.4	23.89	23.89	23.9	81.50	80.50	81.0	6.19	6.12	6.2	3.46	3.46	3.5	2.70	2.9
		,	9:05	1.80		0.90	27.80	27.80		8.35	8.35	-	23.89	23.89		81.50	80.50		6.19	6.12		3.46	3.46		3.00	
	27/9/2023	Sunny	10:30	1.90		0.95	27.90	27.90	27.9	8.25	8.25	8.3	25.19	25.19	25.2	77.90	77.10	77.5	6.18	6.09	6.1	3.00	3.00	3.0	2.00	2.0
	27/9/2023	,	10:35	1.90		0.95	27.90	27.90		8.25	8.25		25.19	25.19		77.90	77.10		6.18	6.09		3.00	3.00		2.00	
	29/9/2023		12:00	1.90		0.95	28.70	28.70	28.7	8.25	8.25	8.3	25.54	25.54	25.5	81.90	81.30	81.6	6.61	6.59	6.6	4.57	4.57	4.6	3.80	3.6
1		· · ·	12:05	1.90		0.95	28.70	28.70		8.25	8.25		25.54	25.54		81.90	81.30		6.61	6.59		4.57	4.57		3.30	

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W6 (Middle) - Flood Tide

	Complian		Complian	Water	Complian	Sampling	Te	emperatur	e		pН			Salinity		D	O Saturatio	n	DO			Turbidity		S	S
Station Reference	Date	Weather	Time	Depth	Depth	Depth		°C			-			ppt			%		mg/L			NTU		mg	g/L
	Date		Time	m	Dopan	m	Val	ue	Average	Valu	e	Average	Valu	ie	Average	Val	ue	Average	Value	Average	Val	ue	Average	Value	Average
	4/0/2022	Suppy	9:30	2.10		1.05	26.40	26.40	26.4	7.96	7.96	0.0	31.00	31.00	21.0	79.70	78.90	70.2	6.19 6.	5	4.25	4.25	12	4.90	5.0
	4/9/2023	Sunny	9:35	2.10		1.05	26.40	26.40	20.4	7.96	7.96	0.0	31.00	31.00	31.0	79.70	78.90	79.5	6.19 6.	5	4.25	4.25	4.5	5.10	5.0
	6/0/2022	Suppy	11:30	2.20		1.10	27.60	27.60	27.6	8.05	8.05	0.1	31.13	31.13	21.1	93.80	93.30	02.6	7.00 6.	2 70	3.47	3.47	2.5	3.40	27
	0/3/2023	Sunny	11:35	2.20		1.10	27.60	27.60	27.0	8.05	8.05	0.1	31.13	31.13	31.1	93.80	93.30	53.0	7.00 6.	12	3.47	3.47	3.5	3.90	3.7
	11/0/2023	Rainny	18:00	2.10		1.05	25.50	25.50	25.5	7.81	7.81	7.8	15.58	15.58	15.6	93.40	92.70	03.1	7.37 7.	50 7 S	7.69	7.68	77	8.50	83
	11/3/2023	rearring	18:05	2.10		1.05	25.50	25.50	20.0	7.81	7.81	7.0	15.58	15.58	10.0	93.40	92.70	55.1	7.37 7.	10	7.69	7.68	1.1	8.10	0.5
	13/9/2023	Rainny	18:30	2.20		1.10	27.30	27.30	27.3	8.12	8.12	8.1	19.05	19.05	10.1	80.60	80.10	80.4	7.05 7.	0 7 (	4.12	4.12		4.00	4.1
	13/3/2023	rearring	18:35	2.20		1.10	27.30	27.30	21.5	8.12	8.12	0.1	19.05	19.05	13.1	80.60	80.10	00.4	7.05 7.	00	4.12	4.12	7.1	4.20	
	15/9/2023	Rainny	18:30	2.20		1.10	26.80	26.80	26.8	8.24	8.24	8.2	18.82	18.82	18.8	88.40	87.40	87.0	6.75 6.	1 67	4.62	4.62	4.6	6.60	64
W6	13/3/2023	reaminy	18:35	2.20		1.10	26.80	26.80	20.0	8.24	8.24	0.2	18.82	18.82	10.0	88.40	87.40	07.5	6.75 6.	'1	4.62	4.62	4.0	6.20	0.4
Silvermine Bay	18/0/2023	Suppy	8:00	2.20	Middle	1.10	26.90	26.90	26.0	8.08	8.08	8.1	27.54	27.54	27.5	81.60	81.10	81.4	6.79 6.	0 67	5.00	4.99	5.0	4.80	5.0
(Near Silvermine Bay	10/3/2023	Odinity	8:05	2.20	Middle	1.10	26.90	26.90	20.5	8.08	8.08	0.1	27.54	27.54	21.5	81.60	81.10	01.4	6.79 6.	0	5.00	4.99	0.0	5.20	0.0
Beach)	20/9/2023	Suppy	9:45	2.20		1.10	28.30	28.30	28.3	8.40	8.40	84	26.83	26.83	26.8	90.80	90.00	90.4	7.21 7.	6 73	5.51	5.51	5.5	5.90	5.8
	20/0/2020	ou,	9:50	2.20		1.10	28.30	28.30	20.0	8.40	8.40	0.1	26.83	26.83	20.0	90.80	90.00	00.1	7.21 7.	6	5.51	5.51	0.0	5.60	0.0
	22/9/2023	Suppy	16:45	2.20		1.10	28.80	28.80	28.8	8.44	8.44	84	23.47	23.47	23.5	90.30	89.80	90.1	6.80 6.	2 68	4.12	4.12	4 1	3.20	34
	22/0/2020	ou,	16:50	2.20		1.10	28.80	28.80	20.0	8.44	8.44	0.1	23.47	23.47	20.0	90.30	89.80	00.1	6.80 6.	2	4.12	4.12		3.60	0.1
	25/9/2023	Suppy	17:00	2.20		1.10	28.50	28.50	28.5	8.38	8.28	83	23.00	23.00	23.0	89.90	89.30	89.6	6.78 6.	2 68	4.85	4.85	49	3.50	3.6
	20/0/2020	Ganny	17:05	2.20		1.10	28.50	28.50	20.0	8.38	8.28	0.0	23.00	23.00	20.0	89.90	89.30	00.0	6.78 6.	2	4.85	4.85	1.0	3.70	0.0
	27/9/2023	Sunny	17:45	2.20		1.10	28.30	28.30	28.3	8.33	8.33	8.3	22.90	22.90	22.9	95.10	94.80	95.0	6.87 6.	6.6	5.98	5.98	6.0	6.20	6.4
		,	17:50	2.20		1.10	28.30	28.30		8.33	8.33	0.0	22.90	22.90		95.10	94.80		6.87 6.	0	5.98	5.98		6.50	
	29/9/2023	Sunny	18:30	2.20		1.10	28.80	28.80	28.8	8.36	8.36	8.4	25.65	25.65	25.7	82.00	81.60	81.8	6.44 6.	6.4	4.79	4.79	4.8	4.60	4.8
	20/0/2020	Ganny	18:35	2.20		1.10	28.80	28.80	20.0	8.36	8.36	0.1	25.65	25.65	20.1	82.00	81.60	01.0	6.44 6.4	-0	4.79	4.79		4.90	

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

am	
alli	Lam Environmental Servic
	Mater Ovelity Manitarian D

#### ces Limited Nater Quality Monitoring Results

Contract No. HY/2019/14 New Wang Tong River Bridge

#### Water Quality Monitoring at Station W7 (Middle) - Ebb Tide

	Complian		Complian	Water	Complian	Sampling	Te	emperatu	re		pН			Salinity		DO	Saturatio	n		DO			Turbidity		S	S
Station Reference	Date	Weather	Time	Depth	Level	Depth		°C			-			ppt			%			mg/L			NTU		mg	J/L
	Duto			m	20101	m	Val	le	Average	Value		Average	Valu	е	Average	Value	9	Average	Value		Average	Va	lue	Average	Value	Average
	4/0/2022	Suppy	15:45	2.90		1.45	27.60	27.60	27.6	8.07	8.07	0.1	30.36	30.36	20.4	76.00	75.20	75.6	6.05	5.98	60	4.48	4.48	4.5	6.00	6.1
	4/9/2023	Sunny	15:50	2.90		1.45	27.60	27.60	27.0	8.07	8.07	0.1	30.36	30.36	30.4	76.00	75.20	75.0	6.05	5.98	0.0	4.48	4.48	4.5	6.20	0.1
	6/9/2023	Sunny	17:15	2.80		1.40	27.50	27.50	27.5	8.13	8.13	81	31.05	31.05	31.1	81.00	80.10	80.6	6.29	6.19	62	7.30	7.30	73	6.70	69
	0/0/2020	ounny	17:20	2.80		1.40	27.50	27.50	21.0	8.13	8.13	0.1	31.05	31.05	01.11	81.00	80.10	00.0	6.29	6.19	0.2	7.30	7.30	1.0	7.00	0.0
	11/9/2023	Rainny	11:00	2.90		1.45	25.50	25.50	25.5	7.99	7.99	8.0	23.71	23.71	23.7	80.70	80.20	80.5	6.42	6.32	6.4	4.38	4.37	4.4	4.40	4.2
			11:05	2.90		1.45	25.50	25.50		7.99	7.99		23.71	23.71		80.70	80.20		6.42	6.32		4.38	4.37		4.00	
	13/9/2023	Sunny	12:00	2.90		1.45	26.40	26.40	26.4	8.03	8.03	8.0	26.68	26.68	26.7	76.70	75.90	76.3	6.47	6.37	6.4	3.38	3.38	3.4	6.70	6.5
			12:05	2.90		1.45	26.40	26.40		8.03	8.03		26.68	26.68		76.70	75.90		6.47	6.37		3.38	3.38		6.30	
	15/9/2023	Sunny	13:00	2.80		1.40	27.80	27.80	27.8	8.16	8.16	8.2	27.76	27.76	27.8	83.80	83.20	83.5	6.56	6.49	6.5	3.51	3.50	3.5	4.30	4.4
W7			13:05	2.80		1.40	27.80	27.80		8.16	8.16		27.76	27.76		83.80	83.20		6.56	6.49		3.51	3.50		4.50	
Silvermine Bay	18/9/2023	Sunny	14:30	2.80	Middle	1.40	28.40	28.40	28.4	8.34	8.34	8.3	28.10	28.10	28.1	82.00	81.40	81.7	7.27	7.20	7.2	3.63	3.63	3.6	3.80	3.8
(Open Water)		-	14:35	2.80		1.40	28.40	28.40		8.34	8.34		28.10	28.10		82.00	81.40		7.27	7.20		3.63	3.63		3.70	
	20/9/2023	Sunny	15:45	2.80		1.40	27.00	27.00	27.0	8.41	8.41	8.4	27.98	27.98	28.0	87.00	86.20	86.6	6.97	6.92	6.9	3.99	3.99	4.0	4.00	3.8
			15:50	2.80		1.40	27.00	27.00		8.41	8.41		27.98	27.98		87.00	86.20		6.97	6.92		3.99	3.99		3.60	
	22/9/2023	Sunny	8:00	2.80		1.40	26.10	26.10	26.1	8.52	8.52	8.5	27.27	27.27	27.3	85.20	84.70	85.0	6.84	6.77	6.8	1.99	1.98	2.0	3.70	3.9
			8:05	2.80		1.40	26.10	26.10		8.52	8.52		21.21	21.21		85.20	84.70		6.84	6.77		1.99	1.98		4.00	
	25/9/2023	Sunny	9:15	2.80		1.40	27.70	27.70	27.7	8.50	8.50	8.5	26.96	26.96	27.0	84.00	83.20	83.6	6.55	6.45	6.5	2.73	2.73	2.7	2.00	2.0
			9.20	2.00		1.40	27.70	27.70		0.30	0.00		20.90	20.90		87.80	03.20		6.55	0.45		2.73	2.73		2.00	
	27/9/2023	Sunny	10.45	2.90		1.45	20.10	20.10	28.1	0.31	0.31	8.3	20.03	20.03	26.8	87.80	97.20	87.5	6.61	6.62	6.6	2.94	2.94	2.9	2.00	2.0
			10:50	2.90		1.45	20.10	20.10		0.31	0.31		20.03	20.03		84.00	94.50		6.27	6.22		2.94	2.94		2.00	
	29/9/2023	Sunny	12:15	2.90		1.45	29.10	29.10	29.1	8.32	8.32	8.3	28.44	28.44	28.4	84.90	84.50	84.7	6.37	6.32	6.3	4.71	4.71	4.7	3.40	3.6

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W7 (Middle) - Flood Tide

	Complian		Complian	Water	Complian	Sampling	Te	emperatur	е		pН			Salinity		DC	O Saturatio	n		DO			Turbidity		S	S
Station Reference	Sampling	Weather	Sampling	Depth	Sampling	Depth		°C			-			ppt			%			mg/L			NTU		mç	g/L
	Date		Time	m	Deptil	m	Val	Je	Average	Value	е	Average	Val	ue	Average	Val	ue	Average	Val	ue	Average	Val	ue	Average	Value	Average
	4/0/2022	Suppy	9:45	3.10		1.55	26.30	26.30	26.2	8.01	8.01	<u>ه</u> ۵	30.61	30.61	20.6	89.60	89.10	90.4	6.54	6.44	6.5	3.51	3.51	2.5	3.70	20
	4/3/2023	Sunny	9:50	3.10		1.55	26.30	26.30	20.5	8.01	8.01	0.0	30.61	30.61	30.0	89.60	89.10	03.4	6.54	6.44	0.5	3.51	3.51	3.5	4.00	3.5
	6/0/2022	Suppy	11:45	3.20		1.60	27.60	27.60	27.6	8.05	8.05	0.1	30.24	30.24	20.2	84.30	83.50	92.0	6.20	6.11	6.2	5.29	5.29	5.2	6.80	7.0
	0/9/2023	Sunny	11:50	3.20		1.60	27.60	27.60	27.0	8.05	8.05	0.1	30.24	30.24	30.2	84.30	83.50	03.9	6.20	6.11	0.2	5.29	5.29	5.5	7.20	7.0
	11/0/2022	Rainny	18:15	3.10		1.55	25.60	25.60	25.6	7.96	7.98	<u>ه</u> ۵	19.19	19.19	10.2	92.60	92.00	02.2	7.27	7.21	7.2	4.46	4.46	4.5	3.40	2.2
	11/3/2023	ixaiririy	18:20	3.10		1.55	25.60	25.60	23.0	7.96	7.98	0.0	19.19	19.19	13.2	92.60	92.00	52.5	7.27	7.21	1.2	4.46	4.46	4.5	3.00	3.2
	12/0/2022	Painny	18:45	3.20		1.60	27.40	27.40	27.4	8.23	8.23	0.2	23.76	23.76	22.0	93.70	93.10	02.4	7.02	6.98	7.0	4.13	4.13	4.1	4.60	19
	13/9/2023	Raininy	18:50	3.20		1.60	27.40	27.40	21.4	8.23	8.23	0.2	23.76	23.76	23.0	93.70	93.10	53.4	7.02	6.98	7.0	4.13	4.13	4.1	5.00	4.0
	15/0/2022	Rainny	18:45	3.20		1.60	26.90	26.90	26.0	8.32	8.32	0.2	24.95	24.95	25.0	90.40	89.80	00.1	6.95	6.87	60	6.95	6.95	7.0	7.70	7.0
14/7	13/9/2023	Raininy	18:50	3.20		1.60	26.90	26.90	20.9	8.32	8.32	0.5	24.95	24.95	23.0	90.40	89.80	30.1	6.95	6.87	0.5	6.95	6.95	7.0	8.10	1.5
W/ Silvermine Bay	19/0/2022	Suppy	8:15	3.20	Middlo	1.60	26.80	26.80	26.9	8.16	8.16	0.2	28.52	28.52	29.5	79.30	78.70	70.0	6.10	5.99	60	3.83	3.83		4.50	12
(Open Water)	10/9/2023	Sunny	8:20	3.20	Midule	1.60	26.80	26.80	20.0	8.16	8.16	0.2	28.52	28.52	20.5	79.30	78.70	73.0	6.10	5.99	0.0	3.83	3.83	3.0	4.00	4.5
()	20/9/2023	Suppy	10:00	3.20		1.60	28.20	28.20	28.2	8.55	8.55	86	28.27	28.27	28.3	91.70	91.10	01.4	7.01	6.94	7.0	3.60	3.60	36	3.40	36
	20/3/2023	Odinity	10:05	3.20		1.60	28.20	28.20	20.2	8.55	8.55	0.0	28.27	28.27	20.5	91.70	91.10	51.4	7.01	6.94	7.0	3.60	3.60	0.0	3.80	0.0
	22/0/2022	Suppy	16:30	3.20		1.60	28.50	28.50	29.5	8.60	8.60	9.6	26.98	26.98	27.0	88.70	88.30	99.5	7.18	7.13	7.2	3.62	3.62	26	3.60	2.5
	22/9/2023	Sunny	16:35	3.20		1.60	28.50	28.50	20.5	8.60	8.60	0.0	26.98	26.98	27.0	88.70	88.30	00.0	7.18	7.13	1.2	3.62	3.62	3.0	3.40	3.3
	25/9/2023	Suppy	17:15	3.20		1.60	28.50	28.50	28.5	8.50	8.50	85	26.41	26.41	26.4	90.90	90.40	90.7	7.14	7.04	71	2.88	2.88	20	2.60	2.8
	20/3/2023	Odinity	17:20	3.20		1.60	28.50	28.50	20.5	8.50	8.50	0.5	26.41	26.41	20.4	90.90	90.40	50.7	7.14	7.04	7.1	2.88	2.88	2.5	3.00	2.0
	27/0/2023	Suppy	18:00	3.20		1.60	28.40	28.40	28.4	8.44	8.44	8.4	27.11	27.11	27.1	85.50	84.90	85.2	6.44	6.36	64	3.60	3.60	36	5.20	5.4
	2113/2023	Ganny	18:05	3.20		1.60	28.40	28.40	20.4	8.44	8.44	0.4	27.11	27.11	27.1	85.50	84.90	00.2	6.44	6.36	0.4	3.60	3.60	0.0	5.50	0.4
	20/0/2023	Suppy	18:45	3.20		1.60	29.00	29.00	20.0	8.40	8.40	8.4	28.54	28.54	28.5	86.10	85.50	85.8	6.51	6.44	65	4.13	4.12		5.20	5.4
	23/3/2023	Sunny	18:50	3.20		1.60	29.00	29.00	29.0	8.40	8.40	0.4	28.54	28.54	20.3	86.10	85.50	00.00	6.51	6.44	0.5	4.13	4.12	4.1	5.60	5.4

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

am	Lam Environmental Servic
	Mater Ovelity Meniterian I

Water Quality Monitoring at Station W8 (Surface) - Ebb Tide

	Complian		Complian	Water	Complian	Sampling	T	emperatui	е		pН			Salinity		DO	Saturatio	on		DO			Turbidity		SS	s
Station Reference	Date	Weather	Time	Depth	Level	Depth		°C			-			ppt			%			mg/L			NTU		mg	J/L
	Duto			m	2010.	m	Val	ue	Average	Value	е	Average	Val	ue	Average	Valu	е	Average	Valu	le	Average	Va	lue	Average	Value	Average
	4/0/2023	Suppy	16:00	3.90		1.00	27.40	27.40	27 4	8.13	8.13	8.1	31.83	31.83	31.8	76.50	76.10	76.3	6.06	5.99	6.0	4.72	4.72	47	5.50	5.8
	4/3/2023	Gainty	16:05	3.90		1.00	27.40	27.40	21.4	8.13	8.13	0.1	31.83	31.83	51.0	76.50	76.10	70.5	6.06	5.99	0.0	4.72	4.72	4.7	6.00	0.0
	6/9/2023	Suppy	17:30	3.80		1.00	27.40	27.40	27.4	8.15	8.15	82	31.67	31.67	31.7	78.40	77.90	78.2	6.13	6.03	61	4.83	4.83	4.8	3.90	41
	0/0/2020	Gainty	17:35	3.80		1.00	27.40	27.40	2000	8.15	8.15	0.2	31.67	31.67	01.1	78.40	77.90	10.2	6.13	6.03	0.1	4.83	4.83	1.0	4.20	
	11/9/2023	Rainny	11:15	3.90		1.00	25.50	25.50	25.5	8.03	8.03	8.0	22.37	22.37	22.4	81.80	80.80	81.3	6.90	6.90	69	3.41	3.40	3.4	2.00	23
	1110/2020	rearry	11:20	3.90		1.00	25.50	25.50	20.0	8.03	8.03	0.0	22.37	22.37		81.80	80.80	01.0	6.90	6.90	0.0	3.41	3.40	0.1	2.50	2.0
	13/9/2023	Suppy	12:15	3.90		1.00	26.60	26.60	26.6	8.08	8.08	8.1	24.07	24.07	24.1	83.00	82.20	82.6	6.94	6.88	69	2.42	2.41	24	3.00	29
	10/0/2020	oumy	12:20	3.90		1.00	26.60	26.60	20.0	8.08	8.08	0.1	24.07	24.07	2	83.00	82.20	02.0	6.94	6.88	0.0	2.42	2.41	2.1	2.70	2.0
	15/9/2023	Suppy	13:15	3.80		1.00	28.00	28.00	28.0	8.20	8.20	82	27.71	27.71	27.7	88.10	87.40	87.8	6.47	6.40	64	3.05	3.05	3.1	4.70	49
14/9		,	13:20	3.80		1.00	28.00	28.00		8.20	8.20		27.71	27.71		88.10	87.40		6.47	6.40	••••	3.05	3.05		5.00	
Silvermine Bay	18/9/2023	Suppy	14:45	3.80	Surface	1.00	28.50	28.50	28.5	8.39	8.39	84	28.14	28.14	28.1	88.30	87.80	88.1	7.60	7.53	7.6	3.15	3.15	32	5.20	5.5
(Open Water)	10/0/2020	Gainty	14:50	3.80	Ganado	1.00	28.50	28.50	20.0	8.39	8.39	0.1	28.14	28.14	20.1	88.30	87.80	00.1	7.60	7.53	1.0	3.15	3.15	0.2	5.70	0.0
	20/9/2023	Suppy	16:00	3.80		1.00	27.10	27.10	27.1	8.48	8.48	8.5	28.01	28.01	28.0	89.80	89.00	89.4	7.03	6.95	7.0	3.01	3.01	3.0	3.40	3.6
	20/0/2020	Gainty	16:05	3.80		1.00	27.10	27.10	2	8.48	8.48	0.0	28.01	28.01	20.0	89.80	89.00	00.1	7.03	6.95	1.0	3.01	3.01	0.0	3.80	0.0
	22/9/2023	Suppy	8:15	3.80		1.00	25.70	25.70	25.7	8.55	8.55	8.6	27.18	27.18	27.2	88.20	87.50	87.9	6.98	6.90	69	2.20	2.20	22	4.00	3.8
	22/0/2020	Gainty	8:20	3.80		1.00	25.70	25.70	20.1	8.55	8.55	0.0	27.18	27.18	27.12	88.20	87.50	07.0	6.98	6.90	0.0	2.20	2.20		3.60	0.0
	25/9/2023	Suppy	9:30	3.80		1.00	27.80	27.80	27.8	8.56	8.56	8.6	27.12	27.12	27.1	84.50	83.40	84.0	6.70	6.62	67	2.07	2.07	21	2.40	23
	20/0/2020	Gainty	9:35	3.80		1.00	27.80	27.80	21.0	8.56	8.56	0.0	27.12	27.12	2	84.50	83.40	01.0	6.70	6.62	0.1	2.07	2.07	2.1	2.20	2.0
	27/9/2023	Suppy	11:00	3.90		1.00	28.00	28.00	28.0	8.37	8.37	84	27.20	27.20	27.2	92.00	91.50	91.8	6.30	6.25	6.3	2.58	2.58	2.6	2.00	2.0
	27/9/2023	Gainty	11:05	3.90		1.00	28.00	28.00	20.0	8.37	8.37	0.1	27.20	27.20	27.12	92.00	91.50	0110	6.30	6.25	0.0	2.58	2.58	2.0	2.00	2.0
	29/9/2023	Sunny	12:30	3.90		1.00	29.00	29.00	29.0	8.41	8.41	8.4	28.09	28.09	28.1	88.80	88.10	88.5	6.64	6.57	6.6	3.40	3.40	3.4	3.10	3.3
	29/9/2023		12:35	3.90		1.00	29.00	29.00	20.0	8.41	8.41	0.4	28.09	28.09	20.1	88.80	88.10	00.0	6.64	6.57	0.0	3.40	3.40	0.4	3.50	0.0

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W8 (Surface) - Flood Tide

	0		0	Water	0	Sampling	Temperatu	lite		pН			Salinity		DC	) Saturati	on		DO			Turbidity		S	S
Station Reference	Sampling	Weather	Sampling	Depth	Depth	Depth	°C			-			ppt			%			mg/L			NTU		m	₀g/L
	Dute		TIME	m	Dopai	m	Value	Average	Val	ue	Average	Va	lue	Average	Val	ue	Average	Value	е	Average	Va	ue	Average	Value	Average
	4/0/2022	Suppy	10:00	4.10		1.00	26.30 26.30	) 26.2	8.05	8.05	0.1	31.60	31.60	21.6	90.20	89.80	00.0	6.66	6.60	6.6	2.90	2.90	2.0	4.40	16
	4/3/2023	Sunny	10:05	4.10		1.00	26.30 26.30	) 20.3	8.05	8.05	0.1	31.60	31.60	31.0	90.20	89.80	50.0	6.66	6.60	0.0	2.90	2.90	2.5	4.80	4.0
	6/0/2023	Suppy	12:00	4.20		1.00	27.70 27.70	) 27.7	8.10	8.10	8.1	31.65	31.65	317	86.10	85.50	85.8	6.30	6.21	63	4.72	4.72	47	5.60	53
	0/3/2023	Guility	12:05	4.20		1.00	27.70 27.70	) 27.7	8.10	8.10	0.1	31.65	31.65	51.7	86.10	85.50	00.0	6.30	6.21	0.0	4.72	4.72	4.7	5.00	0.0
	11/0/2023	Rainny	18:30	4.10		1.00	25.50 25.50	) 25.5	8.05	8.05	8.1	22.51	22.51	22.5	83.30	82.50	82.0	7.00	6.94	7.0	3.34	3.34	33	4.00	3.0
	11/3/2023	rtearing	18:35	4.10		1.00	25.50 25.50	) 20.0	8.05	8.05	0.1	22.51	22.51	22.5	83.30	82.50	02.5	7.00	6.94	7.0	3.34	3.34	5.5	3.70	0.5
	12/0/2022	Painny	19:00	4.20		1.00	27.50 27.50	) 27.5	8.29	8.29	0.2	22.34	22.34	22.2	86.00	85.40	95.7	6.72	6.66	67	3.02	3.02	2.0	4.80	4.0
	13/9/2023	Raininy	19:05	4.20		1.00	27.50 27.50	) 27.5	8.29	8.29	0.5	22.34	22.34	22.3	86.00	85.40	00.7	6.72	6.66	0.7	3.02	3.02	3.0	5.00	4.5
	15/0/2022	Painny	19:00	4.20		1.00	26.90 26.90	) 26.0	8.45	8.45	9.5	25.91	25.91	25.0	87.10	86.40	96.9	7.70	7.60	77	3.61	3.61	26	6.10	6.2
14/0	13/9/2023	Raininy	19:05	4.20		1.00	26.90 26.90	20.9	8.45	8.45	0.5	25.91	25.91	23.5	87.10	86.40	00.0	7.70	7.60	1.1	3.61	3.61	3.0	6.40	0.5
W8 Silvermine Bay	18/0/2023	Suppy	8:30	4.20	Surface	1.00	26.60 26.60	) 26.6	8.22	8.22	8.2	28.37	28.37	28.4	74.80	74.00	74.4	6.27	6.22	6.2	3.21	3.20	3.2	2.90	3.1
(Open Water)	10/3/2023	Outility	8:35	4.20	Gunace	1.00	26.60 26.60	) 20.0	8.22	8.22	0.2	28.37	28.37	20.4	74.80	74.00	74.4	6.27	6.22	0.2	3.21	3.20	0.2	3.30	0.1
()	20/0/2023	Suppy	10:15	4.20		1.00	28.00 28.00	28.0	8.40	8.40	8.4	27.77	27.77	27.8	90.80	90.40	9.00	7.35	7.30	73	4.01	4.01	4.0	3.50	37
	20/3/2023	Outility	10:20	4.20		1.00	28.00 28.00	) 20.0	8.40	8.40	0.4	27.77	27.77	21.0	90.80	90.40	50.0	7.35	7.30	7.5	4.01	4.01	4.0	3.90	0.7
	22/9/2023	Sunny	16:45	4.20		1.00	28.60 28.60	28.6	8.65	8.65	87	27.17	27.17	27.2	83.00	82.30	82.7	7.79	7.71	7.8	3.36	3.36	34	4.50	47
	22/0/2020	ounny	16:50	4.20		1.00	28.60 28.60	)	8.65	8.65	0.1	27.17	27.17	27.12	83.00	82.30	02.1	7.79	7.71	1.0	3.36	3.36	0.1	4.80	
	25/0/2023	Suppy	17:30	4.20		1.00	28.50 28.50	28.5	8.54	8.54	85	26.84	26.84	26.8	92.80	92.00	92.4	6.97	6.93	7.0	2.04	2.04	2.0	2.70	20
	20/3/2023	Outility	17:35	4.20		1.00	28.50 28.50	) 20.0	8.54	8.54	0.5	26.84	26.84	20.0	92.80	92.00	52.4	6.97	6.93	7.0	2.04	2.04	2.0	3.10	2.5
	27/9/2023	Sunny	18:15	4.20		1.00	28.30 28.30	28.3	8.55	8.55	86	27.31	27.31	27.3	84.10	83.40	83.8	6.50	6.42	6.5	2.44	2.44	24	2.80	26
	2110/2020	ounny	18:20	4.20		1.00	28.30 28.30	) 20.0	8.55	8.55	0.0	27.31	27.31	21.0	84.10	83.40	00.0	6.50	6.42	0.0	2.44	2.44	2	2.40	2.0
	29/9/2023	Sunny	19:00	4.20		1.00	29.10 29.10	29.1	8.48	8.48	85	28.34	28.34	28.3	88.90	88.10	88.5	7.27	7.20	72	3.17	3.17	32	3.10	29
	20,0/2020	Canny	19:05	4.20		1.00	29.10 29.10	) 23.1	8.48	8.48	0.0	28.34	28.34	20.5	88.90	88.10	00.0	7.27	7.20	1.2	3.17	3.17	0.2	2.70	2.5

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

	om	
I		Lam Environmental Services Limit
	_	Water Quality Monitoring Results

#### Water Quality Monitoring at Station W8 (Bottom) - Ebb Tide

	Sampling	Weather	0	Water	0	Sampling	Temperature			рН			Salinity			DO Saturation			DO			Tur	SS		
Station Reference			Sampling	Depth	Sampling	Depth	°C			-			ppt			%			mg/L			NTU		mg/L	
	Date		Time	m	LOVOI	m	Value		Average	Value	•	Average	Valu	le	Average	Val	ue	Average	Value	e	Average	Value	Average	Value	Average
W8 Silvernine Bay (Open Water)	4/9/2023	Sunny	16:10	3.90	3.90 3.90	2.90	27.30	27.30 27.30 27.3	8.11	8.11	0.1	31.93	31.93	21.0	70.40	70.00	70.2	6.04	5.96	6.0	4.46	4.46	6.60	6.4	
			16:15	3.90		2.90	27.30	27.30	27.5	8.11	8.11	0.1	31.93	31.93	31.9	70.40	70.00	70.2	6.04	5.96	6.0	4.46	4.46	6.20	0.4
	6/9/2023	Sunny	17:40	3.80		2.80	29.40	27.40	28.4	8.16	8.15	8.2	31.71	31.71	31.7	83.70	83.10	83.4	6.38	6.30	63	5.54	5.54 5.5	3.60	3.4
			17:45	3.80		2.80	29.40	27.40	20.4	8.16	8.15		31.71	31.71	51.7	83.70	83.10		6.38	6.30	0.5	5.54	5.54	3.20	0.4
	11/9/2023	Rainny	11:25	3.90		2.90	25.50	25.50	25.5	8.01	8.01	8.0	25.62	25.62	25.6	80.90	80.30	80.6	6.91	6.84	69	3.89	3.88 3.9	6.00	6.00 5.9
		rtainity	11:30	3.90	3.90	2.90	25.50	25.50		8.01	8.01		25.62	25.62	20.0	80.90	80.30		6.91	6.84	0.0	3.89	3.88	5.80	0.0
	13/9/2023	Sunny	12:25	3.90		2.90	26.50	26.50	26.5	8.09	8.09	8.1	25.98	25.98	26.0	82.40	81.80	82.1	6.49	6.42	6.5	2.20	2.19 2.2	3.30	.30 3.2
			12:30	3.90	1	2.90	26.50	26.50		8.09	8.09		25.98	25.98	20.0	82.40	81.80	02.1	6.49	6.42	0.0	2.20	2.19	3.00	0.2
	15/9/2023	Sunny	13:25	3.80		2.80	27.70	27.70	27.7	8.20	8.20	8.2	27.02	27.02	27.0	86.00	85.10	85.6	6.61	6.51	6.6	3.61	3.61 3.6	4.20	.20 4.0
			13:30	3.80		2.80	27.70	27.70		8.20	8.20		27.02	27.02		86.00	85.10		6.61	6.51		3.61	3.61	3.80	
	18/9/2023	Suppy	14:55	3.80	Bottom	2.80	28.10	28.10	28.1	8.42	8.42	8.4	28.81	28.81	28.8	91.50	91.00	91.3	6.70	6.60	67	3.63	3.62 3.6	4.10	43
		ou,	15:00	3.80	Dottom	2.80	28.10	28.10		8.42	8.42		28.81	28.81	20.0	91.50	91.00	01.0	6.70	6.60	└───	3.63	3.62	4.50	1.0
	20/9/2023	Suppy	16:10	3.80		2.80	27.00	27.00	27.0	8.45	8.45	8.5	28.52	28.52	28.5	86.30	85.70	86.0	6.88	6.78	6.8	3.70	3.70 3.7	4.60	4.60 4.8
	20/0/2020	ou,	16:15	3.80		2.80	27.00	27.00	21.0	8.45	8.45	0.0	28.52	28.52	20.0	86.30	85.70	00.0	6.88	6.78	0.0	3.70	3.70	5.00	
	22/0/2023	Sunny	8:25	3.80	) ) )	2.80	25.80	25.80	25.8	8.56	8.56	86	27.37	27.37	27.4	89.00	88.40	88 7	6.99	6.93	7.0	2.29	2.29 2.3	2.70	2.70 2.6
	22/0/2020	Sunny	8:30	3.80		2.80	25.80	25.80	20.0	8.56	8.56	0.0	27.37	27.37	27.11	89.00	88.40	55.7	6.99	6.93		2.29	2.29	2.40	2.0
	25/9/2023		9:40	3.80		2.80	27.70	27.70	27.7	8.57	8.57	8.6	27.41	27.41	27.4	81.00	80.30	80.7	6.52	6.48	6.5	1.86	1.86 1.9	3.00	29
	20/0/2020		9:45	3.80		2.80	27.70	27.70	2	8.57	8.57	0.0	27.41	27.41 27.41 81.00 80.30	00.1	6.52	6.48	0.0	1.86	1.86	2.80	2.0			
	27/9/2023	Sunny	11:10	3.90	) ) )	2.90	27.90	27.90	) 27.9	8.37	8.37	84	27.88	27.88	27.9	77.60	77.00	77.3	6.19	6.10	61	2.45	2.45 2.5	2.5 <u>2.80</u> 2.8 2.80 2.8	28
			11:15	3.90		2.90	27.90	27.90	21.0	8.37	8.37	3.4	27.88	27.88		77.60	77.00		6.19	6.10	5.1	2.45	2.45		2.0
	29/9/2023	Sunny	12:40	3.90		2.90	28.80	28.80	28.8	8.37	8.37	84	29.03	29.03	29.0	90.30	89.80	90.1	6.49	6.45	6.5	4.15	4.15 4.2	4.30	44
			12:45	3.90		2.90	28.80	28.80	.80	8.37	8.37	0.4	29.03	29.03		90.30	89.80		6.49	6.45	0.0	4.15	4.15	4.50	

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning

#### Water Quality Monitoring at Station W8 (Bottom) - Flood Tide

	0	Weather	Complian	Water	0	Sampling	Temperature			pН			Salinity			DO Saturation			DO			Turbidity			SS	
Station Reference	Sampling		Sampling	Depth	Sampling	Depth	°C				-			ppt		%			mg/L			NTU			mg	g/L
	Date		Time	m	Depin	m	Value Average		Value		Average	Val	ue	Average	Val	ue	Average	Va	lue	Average	Val	ue	Average	Value	Average	
W8 Silvernine Bay (Open Water)	4/9/2023	Sunny	10:10	4.10		3.10	26.30 26.30	26.2	8.08	8.08	0.1	31.73	31.73	21.7	88.80	88.10	99 F	6.65	6.61	6.6	3.29	3.29	2.2	4.20	4.0	
			10:15	4.10		3.10	26.30	26.30	20.3	8.08	8.08	0.1	31.73	31.73	31.7	88.80	88.10	00.5	6.65	6.61	0.0	3.29	3.29	3.5	3.80	4.0
	6/9/2023	Sunny	12:10	4.20		3.20	27.40	27.40	27.4	8.11	8.11	0 1	8 1 31.73	31.73	31.7	78.70	77.70	70.2	6.10	6.01	61	4.95	4.95	5.0	6.60	6.5
			12:15	4.20		3.20	27.40	27.40		8.11	8.11	0.1	31.73	31.73		78.70	77.70	10.2	6.10	6.01	6.1	4.95	4.95	5.0	6.40	0.5
	11/9/2023	Rainny	18:40	4.10	)	3.10	25.60	25.60	25.6	8.07	8.07	0 1	24.50	24.49	24.5	82.70	81.70	82.2	7.03	6.98	7.0	2.41	2.41	2.4	3.00	2.2
			18:45	4.10		3.10	.10 25.60 25.6	25.60		8.07	8.07	0.1	24.50	24.49	24.3	82.70	81.70		7.03	6.98	7.0	2.41	2.41	2.4	3.50	3.3
	13/9/2023	Rainny	19:10	4.20		3.20	27.20	27.20	) 27.2 ) 26.5	8.31	8.31	8.3 8.4	26.40	26.40	26.4	91.90	91.20	01.6	7.02	6.97	7.0	2.92	2.91	2.0	3.40	3.40 3.6
			19:15	4.20		3.20	27.20	27.20		8.31	8.31		26.40	26.40	20.4	91.90	91.20	51.0	7.02	6.97		2.92	2.91	2.9	3.80	3.0
	15/9/2023	Rainny	19:10	4.20		3.20	26.50	26.50		26.5 8.39 8 8.39 8	8.39		28.67	28.67	28.7	88.90	88.10	99.5	6.91	6.84		6.49	6.49	6.5	9.20	0.4
			19:15	4.20		3.20	26.50	26.50			8.39		28.67	28.67		88.90	88.10	00.0	6.91	6.84	0.5	6.49	6.49	0.5	9.60	5.4
	18/9/2023	Suppy	8:40	4.20	Dettern	3.20	3.20 26.80	26.80	26.0	8.21	8.21	8.21 8.21 8.2	29.07	29.07	29.1	79.40	78.40	79.0	6.31	6.24	6.2	3.63	3.63	2.6	4.30	4.5
		Sunny	8:45	4.20	DOLLOITI	3.20	26.80	26.80	20.0	8.21	8.21		29.07	29.07		79.40	78.40	76.9	6.31	6.24	0.3	3.63	3.63	3.0	4.70	4.5
(000111100)	20/9/2023	Sunny	10:25	4.20		3.20	28.10	28.10	29.1	28.1 8.53 8	8.53	3 85	28.46	28.46	29.5	89.10	88.60	00 O	7.17	7.07	71	3.90	3.90	2.0	4.70	4.0
			10:30	4.20		3.20	28.10	28.10	20.1	8.53 8.53	28.46 28.46 89.1	20.5	89.10	88.60	00.9	7.17	7.07	7.1	3.90	3.90	3.5	5.10	4.5			
	22/9/2023	Sunny	16:55	4.20		3.20	3.20 28.40	28.40	28.4	8.67	8.67	7 0.7	27.41	27.41	27.4	87.50	87.10	97.2	6.96	6.91	6.0	3.01	3.00	2.0	3.60	25
			17:00	4.20		3.20	28.40	28.40		8.67 8.67 0.7	27.41	27.41	27.4	87.50	87.10	07.3	) 07.3	6.96	6.91	0.9	3.01	3.00	3.0	3.40	3.5	
	25/9/2023	Sunny	17:40	4.20		3.20	28.40 28.40	20.4	8.56	8.56		26.95	26.95	27.0	88.70	88.20	00 5	6.84	6.76	6.9	2.39	2.39	2.4	2.00	2.0	
			17:45	4.20		3.20	28.40	28.40	20.4	8.56 8.5	.56 8.56	8.6	26.95	26.95	27.0	88.70	88.20	00.J	6.84	6.76	0.0	2.39	2.39	2.4	2.00	2.0
	27/9/2023	Sunny	18:25	4.20		3.20	28.30	28.30	28.3	8.51	8.51	0.5	27.84	27.84	27.0	91.90	91.20	01.6	6.90	6.87	60	2.99	2.99	2.0	3.40	2.2
			18:30	4.20		3.20	28.30	28.30		8.51	8.51	27.84	27.84	27.0	91.90	91.20	31.0	6.90	6.87	0.5	2.99	2.99	3.0	3.00	3.2	
	29/9/2023	Sunny	19:10	4.20		3.20	29.00	29.00	20.0	8.50	8.50	8.5	28.57	28.57	28.6	88.30	87.80	88.1	7.09	7.02	7.4	3.48	3.48	2.5	4.90	4.0
			19:15	4.20		3.20	29.00	29.00	29.0	8.50	8.50		28.57	28.57		88.30	87.80		7.09	7.02	7.1	3.48	3.48	3.5	4.80	4.9

Remarks: WQM on 1 September was suspended due to typhoon

WQM on 8 September was suspended due to Black Rainstorm warning


































































Appendix 5.5

Monthly Summary Waste Flow Table

Name of Department: ArchSD/CEDD/HA/EMSD/HyD/WSD

Contract No.: <u>HY/2019/14</u>

(Notes: The following Waste Flow Table should be used for contracts either not included under the Pay for Safety and Environment Scheme or exempted from the full requirement for environmental management)

		Actual Quan	tities of Inert	C&D Materia	lls Generated	-	A	ctual Quantiti	es of C&D W	Wastes Generated2)Chemical WasteOthers, e.g. general refuse2)(in'000 kg)(in'000m³)000		
Monthly ending	Total Quantity Generated	Broken Concrete (see Note 3)	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see Note 2)	Chemical Waste	Others, e.g. general refuse	
	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in'000 kg)	(in'000 kg)	(in'000 kg)	(in'000 kg)	(in'000m <sup>3</sup> )	
Jan	0	0	0	0	0	0	0	0	0	0	0	
Feb	0	0	0	0	0	0	0	0	0	0	0	
Mar	0.01	0	0	0	0.01	0	0	0	0	0	0	
Apr	0.01	0	0	0	0.01	0	0	0	0	0	0	
May	0.019	0	0	0	0.019	0	0	0	0	0	0.015	
Jun	0	0	0	0	0	0	0	0	0	0	0	
Sub Total	0.039	0	0	0	0.039	0	0	0	0	0	0.015	
Jul	0.009	0	0	0	0.009	0	0	0	0	0	0	
Aug	0.056	0	0	0	0.056	0	0	0	0	0	0.0672	
Sept	0.25	0	0	0	0.25	0	0	0	0	0	0	
Oct	0.022	0	0	0	0.022	0	0	0	0	0	0	
Nov	0.004	0	0	0	0.004	0	0	0	0	0	0.0111	
Dec	0.013	0	0	0	0.013	0	0	0	0	0	0.0114	
Total	0.393	0	0	0	0.393	0	0	0	0	0	0.1047	

### Monthly Summary Waste Flow Table for 2022

Notes: (1) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.

(2) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material.

(3) Broken concrete for recycling into aggregates.

Name of Department: ArchSD/CEDD/HA/EMSD/HyD/WSD

Contract No.: <u>HY/2019/14</u>

(Notes: The following Waste Flow Table should be used for contracts either not included under the Pay for Safety and Environment Scheme or exempted from the full requirement for environmental management)

		Actual Quan	tities of Inert	C&D Materia	ls Generated		A	ctual Quantiti	ties of C&D Wastes Generated		
Monthly ending	Total Quantity Generated	Broken Concrete (see Note 3)	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see Note 2)	Chemical Waste	Others, e.g. general refuse
	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in'000 kg)	(in'000 kg)	(in'000 kg)	(in'000 kg)	(in'000m <sup>3</sup> )
Jan	0	0	0	0	0	0	0	0	0	0	0
Feb	0	0	0	0	0	0	0	0	0	0	0
Mar	0	0	0	0	0	0	0	0	0	0	0.0183
Apr	0	0	0	0	0	0	0	0	0	0	0.0134
May	0.008	0	0	0	0.008	0	0	0	0	0	0.0125
Jun	0	0	0	0	0	0	0	0	0	0	0
Sub Total	0.401	0	0	0	0.401	0	0	0	0	0	0.1489
Jul	0.0132	0	0	0	0.0132	0	0	0	0	0	0.0092
Aug	0.04147	0	0	0	0.04147	0	0	0	0	0	0
Sept	0.01687	0	0	0	0.01687	0	0	0	0	0	0.0312
Oct											
Nov											
Dec											
Total	0.4725	0	0	0	0.4725	0	0	0	0	0	0.1893

### Monthly Summary Waste Flow Table for 2023

Notes: (1) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.

(2) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material.

(3) Broken concrete for recycling into aggregates.



Appendix 6.1

**Event Action Plans** 

# Event and Action Plan for Construction Air Quality

FVFNT	ACTION								
	ET	IEC	ER	CONTRACTOR					
ACTION LEVE									
<ol> <li>Exceedance for one sample</li> <li>Exceedance</li> </ol>	<ol> <li>Inform IEC, ER and Contractor;</li> <li>Identify source, investigate the causes of exceedance and propose remedial measures;</li> <li>Repeat measurement to confirm finding.</li> <li>Inform IEC, ER and Contractor;</li> </ol>	<ol> <li>Check monitoring data submitted by ET;</li> <li>Check Contractor's working method.</li> <li>Check monitoring data submitted</li> </ol>	<ol> <li>Notify Contractor.</li> <li>1. Confirm receipt of</li> </ol>	<ol> <li>Rectify any unacceptable practice;</li> <li>Amend working methods if appropriate.</li> <li>Submit proposals for remedial to ER</li> </ol>					
for two or more consecutive samples	<ol> <li>Identify source;</li> <li>Advise the ER on the effectiveness of the proposed remedial measures;</li> <li>Repeat measurements to confirm findings;</li> <li>Increase monitoring frequency to daily;</li> <li>Discuss with IEC, ER and Contractor on remedial actions required;</li> <li>If exceedance continues, arrange meeting with IEC and ER;</li> <li>If exceedance stops, cease additional monitoring.</li> </ol>	<ul> <li>by ET;</li> <li>2. Check Contractor's working method;</li> <li>3. Discuss with ET and Contractor on possible remedial measures;</li> <li>4. Advise the ET/ER on the effectiveness of the proposed remedial measures;</li> <li>5. Supervise Implementation of remedial measures.</li> </ul>	notification of failure in writing; 2. Notify Contractor; 3. Ensure remedial measures properly implemented.	<ul><li>and IEC within 3 working days of notification;</li><li>2. Implement the agreed proposals;</li><li>3. Amend proposal if appropriate.</li></ul>					

# **Event and Action Plan for Construction Air Quality**

EVENT		A	CTION	
	ЕТ	IEC	ER	CONTRACTOR
LIMIT LEVEL				
1.Exceedance for one sample	<ol> <li>Inform IEC, ER, Contractor and EPD;</li> <li>Identify source, investigate the causes of exceedance and propose remedial measures;</li> <li>Repeat measurement to confirm finding;</li> <li>Increase monitoring frequency to daily;</li> <li>Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results.</li> </ol>	<ol> <li>Check monitoring data submitted by ET;</li> <li>Check Contractor's working method;</li> <li>Discuss with ET and Contractor on possible remedial measures;</li> <li>Advise the ER on the effectiveness of the proposed remedial measures;</li> <li>Supervise implementation of remedial measures.</li> </ol>	<ol> <li>Confirm receipt of notification of failure in writing;</li> <li>Notify Contractor;</li> <li>Ensure remedial measures properly implemented.</li> </ol>	<ol> <li>Take immediate action to avoid further exceedance;</li> <li>Discuss with ET and IEC on remedial actions</li> <li>Submit proposals for remedial actions to IEC within 3 working days of notification;</li> <li>Implement the agreed proposals;</li> <li>Amend proposal if appropriate.</li> </ol>
2.Exceedance for two or more consecutive samples	<ol> <li>Notify IEC, ER, Contractor and EPD;</li> <li>Identify source;</li> <li>Repeat measurement to confirm findings;</li> <li>Increase monitoring frequency to daily;</li> <li>Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented;</li> <li>Arrange meeting with IEC and ER and Contractor to discuss the remedial actions to be taken;</li> <li>Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results;</li> <li>If exceedance stops, cease additional monitoring.</li> </ol>	<ol> <li>Check monitoring data submitted by ET;</li> <li>Check Contractor's working method;</li> <li>Discuss amongst ER, ET, and Contractor on the potential remedial actions;</li> <li>Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly;</li> <li>Supervise the implementation of remedial measures.</li> </ol>	<ol> <li>Confirm receipt of notification of failure in writing;</li> <li>Notify Contractor;</li> <li>In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented;</li> <li>Ensure remedial measures properly implemented;</li> <li>If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to terminate that portion of work until the exceedance ceases.</li> </ol>	<ol> <li>Take immediate action to avoid further exceedance;</li> <li>Discuss with ET and IEC on remedial actions</li> <li>Submit proposals for remedial actions to ER and IEC within 3 working days of notification;</li> <li>Implement the agreed proposals;</li> <li>Resubmit proposals if problem still not under control;</li> <li>Stop the relevant portion of works as determined by the ER until the exceedance ceases.</li> </ol>

#### **Event and Action Plan for Construction Noise**

EVENT	ACTION									
	ET	IEC	ER	CONTRACTOR						
Action Level	<ol> <li>Notify IEC, ER and Contractor of exceedance;</li> <li>Identify source</li> <li>Investigate the causes of exceedance and propose remedial measures;</li> <li>Report the results of investigation to the IEC, ER and Contractor;</li> <li>Discuss with the IEC, ER and Contractor and formulate remedial measures;</li> <li>Increase monitoring frequency to check mitigation effectiveness.</li> </ol>	<ol> <li>Review the analysed results submitted by the ET;</li> <li>Review the proposed remedial measures by the Contractor and advise the ER accordingly;</li> <li>Supervise the implementation of remedial measures.</li> </ol>	<ol> <li>Confirm receipt of notification of failure in writing;</li> <li>Notify Contractor;</li> <li>Require Contractor to propose remedial measures for the analysed noise problem;</li> <li>Ensure remedial measures are properly implemented</li> </ol>	<ol> <li>Submit noise mitigation proposals to ER with copy to ET and IEC;</li> <li>Implement noise mitigation proposals.</li> </ol>						
Limit Level	<ol> <li>Inform IEC, ER, EPD and Contractor;</li> <li>Identify source;</li> <li>Repeat measurements to confirm findings;</li> <li>Increase monitoring frequency;</li> <li>Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented;</li> <li>Inform IEC, ER and EPD the causes and actions taken for the exceedances;</li> <li>Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results;</li> <li>If exceedance stops, cease additional monitoring.</li> </ol>	<ol> <li>Discuss amongst ER, ET, and Contractor on the potential remedial actions;</li> <li>Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly;</li> <li>Supervise the implementation of remedial measures.</li> </ol>	<ol> <li>Confirm receipt of notification of failure in writing;</li> <li>Notify Contractor;</li> <li>Require Contractor to propose remedial measures for the analysed noise problem;</li> <li>Ensure remedial measures are properly implemented;</li> <li>If exceedance continues, investigate what portion of the work is responsible and instruct the Contractor to terminate that portion of work until the exceedance ceases.</li> </ol>	<ol> <li>Take immediate action to avoid further exceedance;</li> <li>Submit proposals for remedial actions to ER with copy to ET and IEC within 3 working days of notification;</li> <li>Implement the agreed proposals;</li> <li>Resubmit proposals if problem still not under control;</li> <li>Terminate the relevant portion of works as determined by the ER until the exceedance ceases.</li> </ol>						

# **Event and Action Plan for Water Quality**

TATAN		ACTION								
EVENI	ET Leader	IEC	ER	Contractor						
ACTION LEVEL										
Action level being exceeded by one sampling day	<ol> <li>Repeat in situ measurement on next day of exceedance to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC, contractor and ER;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods</li> </ol>	1. Check monitoring data submitted by ET and Contractor's working methods.	<ol> <li>Confirm receipt of notification of non-compliance in writing;</li> <li>Notify Contractor.</li> </ol>	<ol> <li>Inform the ER and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Amend working methods if appropriate.</li> </ol>						
Action level being exceeded by two or more consecutive sampling days	<ol> <li>Repeat measurement on next day of exceedance to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC, contractor, ER and EPD;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with IEC, ER and Contractor;</li> <li>Ensure mitigation measures are implemented;</li> <li>Increase the monitoring frequency to daily until no exceedance of Action level.</li> </ol>	<ol> <li>Check monitoring data submitted by ET and Contractor's working method;</li> <li>Discuss with ET and Contractor on possible remedial actions;</li> <li>Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly;</li> <li>Supervise the implementation of mitigation measures.</li> </ol>	<ul> <li>Discuss with IEC on the proposed mitigation measures;</li> <li>Ensure mitigation measures are properly implemented;</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ul>	<ol> <li>Inform the ER and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Check all plant and equipment and consider changes of working methods;</li> <li>Submit proposal of additional mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER;</li> <li>Implement the agreed mitigation measures.</li> </ol>						

# **Event and Action Plan for Water Quality**

ΓΥΓΕΝΙΤ			ACTION	
EVENI	ET Leader	IEC	ER	Contractor
LIMIT LEVEL				
Limit level being exceeded by one sampling day	<ol> <li>Repeat measurement on next day of exceedance to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC, contractor, ER and EPD;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with IEC, ER and Contractor.</li> </ol>	<ol> <li>Check monitoring data submitted by ET and Contractor's working method;</li> <li>Discuss with ET and Contractor on possible remedial actions;</li> <li>Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly.</li> </ol>	<ol> <li>Confirm receipt of notification of failure in writing;</li> <li>Discuss with IEC, ET and Contractor on the proposed mitigation measures;</li> <li>Request Contractor to review the working methods.</li> </ol>	<ol> <li>Inform the ER and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Check all plant and equipment and consider changes of working methods;</li> <li>Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER.</li> </ol>
Limit level being exceeded by two or more consecutive sampling days	<ol> <li>Repeat measurement on next day of exceedance to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC, contractor, ER and EPD;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with IEC, ER and Contractor;</li> <li>Ensure mitigation measures are implemented;</li> <li>Increase the monitoring frequency to daily until no exceedance of Limit level for two consecutive days.</li> </ol>	<ol> <li>Check monitoring data submitted by ET and Contractor's working method;</li> <li>Discuss with ET and Contractor on possible remedial actions;</li> <li>Review the Contractor's mitigation measures whenever necessary to assure their effectiveness and advise the ER accordingly;</li> <li>Supervise the implementation of mitigation measures.</li> </ol>	<ol> <li>Discuss with IEC, ET and Contractor on the proposed mitigation measures;</li> <li>Request Contractor to critically review the working methods;</li> <li>Make agreement on the mitigation measures to be implemented;</li> <li>Ensure mitigation measures are properly implemented;</li> <li>Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the construction activities until no exceedance of Limit level.</li> </ol>	<ol> <li>Take immediate action to avoid further exceedance;</li> <li>Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER;</li> <li>Implement the agreed mitigation measures;</li> <li>Resubmit proposals of mitigation measures if problem still not under control;</li> <li>As directed by the Supervising Officer, to slow down or to stop all or part of the construction activities until no exceedance of Limit level.</li> </ol>



Appendix 6.2

Summary for Notification of Exceedance



#### Summary for Notification of Exceedance

Ref No.	Date	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up Action
-	-	-	-	-	-	-	-

Ref. No.	Date	Time	Location	Construction Noise Level	Parameter	Action Level	Limit Level	Follow-up action
-	-	-	-	-	-	-	-	-



Appendix 8.1

Complaint Log



# Environmental Complaints Log

Complaint Log No.	Date of Complaint	Received From and Received By	Location of Complainant	Nature of Complaint	Outcome	Status
-	-	-	-	-	-	-



Appendix 9.1

**Construction Programme of Individual Contracts** 

						Contract No. HY/201 3-Mont	9/14 - New Wang Tong th Rolling Programme	River Bridge		
識別碼	Task Name				Period	Start	End		2023年下半年	
1	Watermains diversion				1 day	9月21日星期四	9月21日星期四		21/9 21/9	
2	Utilities diversion				29 days	8月28日星期一	9月29日星期五	28/8	29/9	
3	Demolition of Existing Fo	ootbridge deck			6 days	10月3日星期二	10月9日星期一		3/10 9/10	
4	Construction of cofferda	im MP3			2 days	10月10日星期二	10月11日星期三		10/10 🚺11/10	0
5	Demolition of Abutment	and Pile Cap of th	e Existing Footbridge	e (MP3)	3 days	10月12日星期四	10月14日星期六		12/10 👗 14/1	.0
6	Construction of cofferda	im MP2			2 days	10月16日星期一	10月17日星期二		16/10 17/	10
7	Demolition of Pier and P	ile Cap of the Exist	ing Footbridge (MP2	)	3 days	10月18日星期三	10月20日星期五		18/10 20	/10
8	Construction of cofferda	ım MP1			2 days	10月21日星期六	10月24日星期二		21/10 🍸 2	4/10
9	Demolition of Abutment	and Pile Cap of th	e Existing Footbridge	e (MP1)	3 days	10月25日星期三	10月27日星期五		25/10 🍸	27/10
10	Construction of cofferda	m existing pier			2 days	10月28日星期六	10月30日星期一		28/10	30/10
11	Demolition of pier				3 days	10月31日星期二	11月2日星期四		31/10	2/11
12	Piling works preparation				4 days	10月16日星期一	10月19日星期四		16/10 👗 19	/10
13	Piling works for MP3				26 days	10月20日星期五	11月20日星期一		20/10	20/11
14	Piling works for MP2				26 days	11月3日星期五	12月2日星期六		3/11	2/12
15	Piling works for MP1				26 days	11月21日星期二	12月20日星期三		2	21/11
16	Pile Cap Construction M	Р3			10 days	11月21日星期二	12月1日星期五		2	1/11 1/12
17	Abutment Construction	MP3			10 days	12月2日星期六	12月13日星期三			2/12 📩 13
18	Pile Cap Construction M	P2			10 days	12月14日星期四	12月27日星期三			14/12
19	Pier Construction MP2				10 days	12月28日星期四	1月9日星期二			28/12
20	Pile Cap Construction M	P1			10 days	1月10日星期三	1月20日星期六			1
21	Abutment Construction	MP1			10 days	1月22日星期一	2月1日星期四			
22	Northern side retaining	wall construction w	vorks		14 days	2月2日星期五	2月21日星期三			
23	Bearing Installation				7 days	2月2日星期五	2月9日星期五			
HV/2010	9/14	 任務 要徑任務		上顯型要徑任務 上顯型里程碑	\$	事案摘要摘要	<b>▼</b>	非作用中的摘要 手動任務	 ¢	僅定義開始日期 僅包含完成時間
3-Month Rolling Programme     里程碑     ◆ 上顯型進度				非作用中的任	務	僅包含工期		外部任務		
	JZ3 1003	摘要		· 分割		非作用中的里	程碑 📍	手動上顯型摘要	•	外部里程碑
		上顯型任務		▶ 外部任務		非作用中的里	程碑	手動摘要	•	進度
							Page 1			

