

Annex 3 Water Quality Monitoring Programme for Impact Monitoring during Operation Phase

附件 3 為在營辦階段進行影響監測而實施的水質監測計劃

Item 項目	Details 詳情			
Monitoring Period 監測期	First year of the operation phase. The Permit Holder shall, no later than two months before the end of the monitoring period, submit a Review Report on the need, if any, of extending the operation phase water quality monitoring programme with full justifications under Condition 3.2 of this Permit. 營辦階段的頭一年。許可證持有人須在監測期完結前至少兩個月，根據本許可證條件第 3.2 項，就延長營辦階段的水質監測計劃的需要（如有）提交檢討報告，並提供充分理據支持。			
Monitoring Frequency 監測次數	Bi-weekly 每兩周一次			
Monitoring Locations 監測站	Monitoring Station ID 監測站編號	Description 說明	Easting 座標東	Northing 座標北
	WM-1	South of Project Site near Coral Sites 工程項目範圍以南近珊瑚區	838145	834573
	WM-2	West of Yim Tin Tsai Fish Culture Zone 鹽田仔魚類養殖區以西	839362	834856
	WM-3	Water storage tanks 儲水缸	838444	835279
	WM-4	Bypass point at Tolo Harbour 吐露港的分流點	838387	834786
	WM-5	Southeast of the bypass point 分流點以東南	839362	833994
Monitoring Parameters 監測參數	The monitoring parameters shall be based on the approved Turfgrass Management Plan under Condition 2.26 of this Permit, and should include Total inorganic nitrogen (TIN), total phosphorus (TP), specific fungicide (e.g. chlorothalonil (active ingredient of Daconil)) and specific insecticide (e.g. chlorpyrifos). 監測參數須以本許可證條件第 2.26 項所述的核准草地管理計劃作為根據，並須包括總無機氮、總磷、特定除真菌劑（例如百菌清（達科寧的活性成分））及特定殺蟲劑（例如毒死蜱）。			

[This annex was prepared based on EM&A Manual Tables 7.6 and 7.7 of the approved

EIA Report (Register No.: AEIAR-221/2019)

[本附件根據核准環評報告（登記冊編號：AEIAR-221/2019）所載的環監手冊表 7.6 及 7.7 擬備。]