



Reprovisioning of Diamond Hill Crematorium
 重置鑽石山火葬場
Environmental Permit number EP-179/2004/A
 環境許可証 EP-179/2004/A

Note :
 Extracted from
 Figure 6.2 of the
 Approved EIA report
 (AEIAR-076/2004)

Figure 6 : S1 to S6 - Subsurface Soil sampling locations for confirmatory contamination analysis
 圖六 S1至S6 - 地下土採樣位置(以供進行污泥驗證分析)

Scale : NTS