



(Additional air quality monitoring station pursuant to the EIA Report - Approval Condition 4)

- Delineated Site Boundary
- A1 to A2 air quality monitoring stations
- N1 to N3 noise monitoring stations

地鐵有限公司尖沙咀站改建工程
Modifications to MTRC TST Station
 環境許可證 EP-113/2001/A
Environmental Permit number EP-113/2001/A

Note:
 Site and Indicative Positions of monitoring stations Extracted from Figure 3-1 of the EIA Report

Figure 1 : Limit of Site Boundary and Location of Air Quality Monitoring Stations and Noise Monitoring Stations

