


**Existing Condition (Without Emergency Bypass Culvert)**

Status of Facilities (✓ = Normal Operation, ✗ = Totally Out of Operation)			Effluent	Discharge Location
San Wai STW	Ha Tsuen PS	NWNT Tunnel		
✓	✓	✓	Treated Effluent	Urmston Road Outfall
✓	✓	✗	Raw Sewage	TSW Drainage Channel/Deep Bay
✗	✓	✓	Raw Sewage	Urmston Road Outfall
✓	✗	✓	Raw Sewage	TSW Drainage Channel/Deep Bay



**Figure 1.6**  
Emergency Discharge Scenarios  
for the Existing San Wai STW  
and Ha Tsuen PS

Agreement No. CE62/2000  
EIA Study for the Upgrading and  
Expansion of San Wai Sewage  
Treatment Works and the Expansion  
of Ha Tsuen Pumping Station

