

**Existing Conditions** 



Upon completion with landscape mitigation (Slope profile retained. Grass and shrub vegetation reinstated)



Upon completion without landscape mitigation (Slope stabilised by shotcrete)



After 10 years operation with landscape mitigation (Similar to view upon completion)



Project: Tung Chung Cable Car Project Environmental Impact Assessment Title:

Photomontage – Tower 4 (Sheet 7 of 7)

Scale: N.T.S.

Figure no: 8.24

File name:

 $N:\ \ 203842\ Eia\ Report\ Figures\ Figure8\_24(sht.\ 7\ of\ 7).ppt$