



---

**APPENDIX 4.7**

**COMPARISON OF HISTORIC WATER  
QUALITY DATA WITH CLOSURE PERIODS  
OF THEES**

---





Title Agreement No. CE 43/2001  
 Tai Po Sewage Treatment Works - Stage V EIA Study  
**Station TM3 - Depth-averaged  
 DO Concentration**

Scale N.T.S.  
 Date Jun 2004



Project No. A04202  
 Figure No. 1







|   |       |          |             |        |
|---|-------|----------|-------------|--------|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM3 - Bottom<br/>         DO Concentration</b> | Scale | N.T.S.   | Project No. | A04202 |
|   | Date  | Jun 2004 | Figure No.  | 2      |







|  |                  |                       |  |
|--|------------------|-----------------------|--|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM3 - Depth-averaged<br/>         BOD Concentration</b> | Scale<br>N.T.S.  | Project No.<br>A04202 |  |
|  | Date<br>Jun 2004 | Figure No.<br>3       |  |





|   |       |          |             |        |
|---|-------|----------|-------------|--------|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM3 - Depth-averaged<br/>         E.coli Concentration</b> | Scale | N.T.S.   | Project No. | A04202 |
|   | Date  | Jun 2004 | Figure No.  | 4      |







|   |       |          |             |        |
|---|-------|----------|-------------|--------|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM3 - Depth-averaged<br/>         SS Concentration</b> | Scale | N.T.S.   | Project No. | A04202 |
|   | Date  | Jun 2004 | Figure No.  | 5      |







|  |       |          |             |        |
|--|-------|----------|-------------|--------|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM3 - Depth-averaged<br/>         Chlorophyll Concentration</b> | Scale | N.T.S.   | Project No. | A04202 |
|  | Date  | Jun 2004 | Figure No.  | 6      |







|       |  |       |          |             |        |  |
|-------|--|-------|----------|-------------|--------|--|
| Title | Agreement No. CE 43/2001   | Scale | N.T.S.   | Project No. | A04202 |  |
|       | Tai Po Sewage Treatment Works - Stage V EIA Study<br>Station TM3 - Depth-averaged<br>TIN Concentration | Date  | Jun 2004 | Figure No.  | 7      |  |









|   |                  |                       |  |
|---|------------------|-----------------------|--|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM3 - Depth-averaged<br/>         NH<sub>3</sub> Concentration</b> | Scale<br>N.T.S.  | Project No.<br>A04202 |  |
|   | Date<br>Jun 2004 | Figure No.<br>8       |  |



|   |                  |                       |  |
|---|------------------|-----------------------|--|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>         DO Concentration</b> | Scale<br>N.T.S.  | Project<br>No. A04202 |  |
|   | Date<br>Jun 2004 | Figure<br>No. 9       |  |





|   |                  |                       |  |
|---|------------------|-----------------------|--|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Bottom<br/>         DO Concentration</b> | Scale<br>N.T.S.  | Project<br>No. A04202 |  |
|   | Date<br>Jun 2004 | Figure<br>No. 10      |  |





|  |       |          |             |        |
|--|-------|----------|-------------|--------|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>         BOD Concentration</b> | Scale | N.T.S.   | Project No. | A04202 |
|  | Date  | Jun 2004 | Figure No.  | 11     |







|  |                  |                       |   |
|--|------------------|-----------------------|---|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>E.coli Concentration</b> | Scale<br>N.T.S.  | Project<br>No. A04202 | <b>Maunsell</b><br>MAUNSELL ENVIRONMENTAL<br>MANAGEMENT CONSULTANTS LTD |
|  | Date<br>Jun 2004 | Figure<br>No. 12      |   |





|  |                  |                       |   |
|--|------------------|-----------------------|---|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>SS Concentration</b> | Scale<br>N.T.S.  | Project<br>No. A04202 | <b>Maunsell</b><br>MAUNSELL ENVIRONMENTAL<br>MANAGEMENT CONSULTANTS LTD |
|  | Date<br>Jun 2004 | Figure<br>No. 13      |   |





|  |       |          |             |        |
|--|-------|----------|-------------|--------|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>         Chlorophyll Concentration</b> | Scale | N.T.S.   | Project No. | A04202 |
|  | Date  | Jun 2004 | Figure No.  | 14     |





|   |                  |                       |   |
|---|------------------|-----------------------|---|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>TIN Concentration</b> | Scale<br>N.T.S.  | Project<br>No. A04202 | <b>Maunsell</b><br>MAUNSELL ENVIRONMENTAL<br>MANAGEMENT CONSULTANTS LTD |
|   | Date<br>Jun 2004 | Figure<br>No. 15      |   |





|  |                  |                       |   |
|--|------------------|-----------------------|---|
| Title<br>Agreement No. CE 43/2001<br>Tai Po Sewage Treatment Works - Stage V EIA Study<br><b>Station TM4 - Depth-averaged<br/>NH<sub>3</sub> Concentration</b> | Scale<br>N.T.S.  | Project<br>No. A04202 | <b>Maunsell</b><br>MAUNSELL ENVIRONMENTAL<br>MANAGEMENT CONSULTANTS LTD |
|  | Date<br>Jun 2004 | Figure<br>No. 16      |   |