


Map reproduced with permission of The Director of Lands. (C) Hong Kong Government.



Legend :

- Location of drillhole identified as contamination
- Extent of remediation works (within 7m diameter circle around drillhole)

REV	DATE	BY	SUB	APP	DESCRIPTION
▲	DEC2003	SW	FC	ST	EIA REPORT
▲	NOV2003	SW	FC	ST	EIA REPORT
▲	JUNE2003	SW	FC	ST	EIA REPORT
▲	TMAR2003	SW	FC	ST	EIA REPORT (2ND DRAFT)
▲	11OCT2002	SW	FC	ST	EIA REPORT (1ST DRAFT)

DESIGNED BY	SW
DRAWN BY	JF
CHECKED BY	FC
IN CHARGE	ST
DATE	5 DEC 2003



New Railway Projects
新鐵路策劃

Ove Arup & Partners Hong Kong Limited



KOWLOON SOUTHERN LINK KSL GSA-5100
EIA & ASSOCIATED SERVICES

LOCATION OF DRILLHOLE
OF CONTAMINATION

DRAWING NUMBER	FIGURE A 14-4
SCALE	N.T.S.
SHEET NO	P
STAGE CODE	REV
FILENAME	5 DEC 2003