


VIEW 1

Lantau South Country Park (LR 1, 2 & 10 within LCA 2)
Abandoned agricultural land (LR 3 within LCA 7)



VIEW 2

A well grown tree along a maintenance path towards existing water tunnel. (LR 1 within LCA 2)



VIEW 3

Bui O Public School (LCA 6)



VIEW 4


Bui O Public School (LCA 6) Lo Uk Tsuen (LCA 5)



VIEW 5

Lantau South Country Park (LR 1 & 2 within LCA 2)


Football ground (LR 8 within LCA 6)



VIEW 6

Lantau South Country Park (LR 1 & LR 10 within LCA 2)
Ham Tin Sun Tsuen (LCA 5)
Chi Ma Wan Road (part of Lantau Trail) (LR 9)

River course (LR 5 within LCA 3)



VIEW 7

Pui O Lo Wai Tsuen (LCA 5)
Lantau South Country Park (LR 1, 2 & 10 within LCA 2)

Agricultural Land (LR 3 within LCA 7)



VIEW 8

Roadside Trees (LR 8 within LCA 2) Pui O Lo Wai Tsuen (LCA 5)

South Lantau Road (LR 9 within LCA 1) incl. part of Lantau Trail along school footpath.

South Lantau Road (LCA 1)



VIEW 9

South Lantau Road (LCA 1)

Pui O Lo Wai Tsuen Sitting Out Area (LR 8 within LCA 2)



VIEW 10

Roadside Trees (LR 8 within LCA 2)


South Lantau Road (LCA 1)



VIEW 11

Pui O Lo Wai Tsuen (LCA 5) Lantau South Country Park (LR 1, 2 & 10 within LCA 2)

Plantation woodland (LR 1 within LCA 2)

 水務署 WATER SUPPLIES DEPARTMENT			
SCALE	As Shown	DATE	AUG 2004
CHECK	—	DRAWN	AKYL
JOB No.	71503	DRAWING No.	7.3d
		REV	—

Agreement No. CE 75/2002 (WS)
Extension of Siu Ho Wan Water Treatment Works – Investigation

BASELINE STUDY – LANDSCAPE PHOTOGRAPHIC RECORD OF PUI O (SHEET 2 OF 3)