

**AGREEMENT NO. CE 67/98
Yuen Long, Kam Tin, Ngau Tam Mei &
Tin Shui Wai Drainage Improvement
Stage 1, Phase 2B – Kam Tin
Secondary Drainage Channel KT13**

**ENVIRONMENTAL IMPACT ASSESSMENT
Final Report
[382047/E/EIA/Issue 9]**

May 2006

Report Authorized For
Issue By:

.....
For and on Behalf of
Black & Veatch Hong Kong Limited

**Black & Veatch Hong Kong Limited
Room 1201-11, Millennium City 5
418 Kwun tong Road
Kowloon
Hong Kong**

**Drainage Services Department
Project Management Division
42/F, Revenue Tower
5 Gloucester Road
Wan Chai
Hong Kong**

CONTENTS

	Page
1. INTRODUCTION	
1.1 Background	1-1
1.2 Yuen Long, Kam Tin, Ngau Tam Mei & Tin Shui Wai Drainage Improvement, Stage 1	1-1
1.3 Secondary Drainage Channel KT13	1-5
2. DESCRIPTION OF THE PROJECT	
2.1 Location of Designated Project and Existing Environment	2-1
2.2 Secondary Drainage Channel KT13	2-1
2.3 Justifications, Needs and Benefits of the Project	2-4
2.4 Consideration of Alternative Alignments, Channel Lining Options and Construction Methods	2-7
2.5 Design and Construction Programme	2-16
2.6 Concurrent Projects and Potential Cumulative Impacts	2-16
2.7 Public Consultation	2-17
3. EIAO REQUIREMENTS AND APPROACH TO ASSESSMENT	
3.1 Requirements under Environmental Impact Assessment Ordinance	3-1
3.2 Purpose of the EIA Study	3-1
3.3 Approach of the EIA Study	3-2

	Name	Signature	Date
Prepared	Various compiled by M. Chua		
Checked	K.I. Lo		
Reviewed	Kelvin N.F. Lau		

CONTENTS (*cont'd*)

	Page
4. ECOLOGICAL ASSESSMENT	
4.1 Introduction	4-1
4.2 Baseline Ecological Conditions	4-1
4.3 Floral Survey Results	4-6
4.4 Fauna Survey Results	4-9
4.5 Egretty and Flight-line Survey Results of Ho Pui and Ma On Kong Egrettries	4-24
4.6 Ecological Evaluation of Different Habitats	4-41
4.7 Potential Ecological Impacts	4-47
4.8 General Recommendations on Ecological Impact Mitigation	4-57
4.9 Proposed Ecological Impact Mitigation Measures at KT13	4-60
4.10 Conclusions	4-65
5. NOISE IMPACT ASSESSMENT	
5.1 Introduction	5-1
5.2 Study Area	5-1
5.3 Noise Assessment Criteria	5-2
5.4 Representative Noise Sensitive Receivers	5-3
5.5 Construction Noise Assessment and Mitigation	5-3
5.6 Residual Impact	5-11
5.7 Cumulative Construction Noise Impact	5-12
5.8 Monitoring and Audit Requirements	5-12
5.9 Summary	5-13
6. AIR QUALITY ASSESSMENT	
6.1 Introduction	6-1
6.2 Air Quality Assessment Criteria	6-1
6.3 Air Sensitive Receivers	6-2
6.4 Baseline Air Quality	6-2
6.5 Impact Assessment and Mitigation	6-4
6.6 Residual Impacts	6-8
6.7 Monitoring and Audit Requirements	6-8
6.8 Summary	6-8

CONTENTS (*cont'd*)

	Page
7. WATER QUALITY ASSESSMENT	
7.1 Introduction	7-1
7.2 Sensitive Receivers and Baseline Water Quality Conditions	7-1
7.3 Identification and Evaluation of Potential Impacts	7-8
7.4 Potential Impacts During Construction Phase	7-8
7.5 Mitigation Measures for Construction Activities	7-10
7.6 Potential Impacts During Operation Phase	7-15
7.7 Mitigation Measures for Operation Phase	7-16
7.8 Residual Impacts	7-18
7.9 Monitoring and Audit Requirements	7-18
7.10 Summary	7-18
8. WASTE MANAGEMENT	
8.1 Introduction	8-1
8.2 Sources and Types of Construction and Demolition Materials	8-2
8.3 Quantity of Construction and Demolition Material Arising from DP	8-8
8.4 Responsibilities for Construction Waste Management	8-11
8.5 Summary	8-16
9. CULTURAL HERITAGE IMPACT ASSESSMENT	
9.1 Project Background	9-1
9.2 Objectives of the Cultural Heritage Impact Assessment	9-1
9.3 Outline of the Assessment Approach	9-1
9.4 Study Area	9-2
9.5 Archaeological Field Evaluation	9-4
9.6 Historical Buildings and Structures Survey and Assessment	9-13
9.7 Monitoring and Audit Requirements	9-26
9.8 Cultural Heritage Impact Assessment Summary	9-26

CONTENTS (cont'd)

	Page
10. LANDSCAPE AND VISUAL IMPACT ASSESSMENT	
10.1 Introduction	10-1
10.2 Environmental Legislation and Guidelines	10-2
10.3 Assessment Methodology	10-2
10.4 Scope and Content of the Study	10-7
10.5 Planning and Development Control Framework	10-8
10.6 Comments on Landscape and Visual Issues received during Previous Consultants	10-8
10.7 Baseline Study	10-9
10.8 Landscape Impact Assessment	10-16
10.9 Visual Impact Assessment	10-26
10.10 Conclusion	10-34
11. ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS	
11.1 Introduction	11-1
11.2 EM&A Requirements	11-2
11.3 Construction Program	11-7
11.4 Monitoring Locations	11-7
12. CONCLUSIONS AND RECOMMENDATIONS	
12.1 Location of Designated Project and Existing Environment	12-1
12.2 Secondary Drainage Channel KT13	12-1
12.3 Consideration of Alternative Alignments and Channel Lining Options	12-1
12.4 Design and Construction Programme	12-3
12.5 Key Environmental Issues	12-3
12.6 Conclusion	12-10

END OF TEXT

CONTENTS (*cont'd*)

APPENDICES

Appendix A	EIA Study Brief
Appendix B	Evaluation of Possible Alignment Options for the Bypass Culvert
Appendix C	Ecological Forms for Field Survey
Appendix D	NOT USED
Appendix E	Floral Species and their Relative Abundance found within the Study Area
Appendix F	Construction Noise Information and Calculations
Appendix G1	Results of Sediment and Water Quality Sampling in 2000
Appendix G2	Results of Sediment Sampling in 2005
Appendix H	Test Pit Excavation Results and Section Drawings
Appendix I1	Auger Testing Results
Appendix I2	Historical Buildings and Structure Catalogue
Appendix J	Mitigation Measures Implementation Schedule
Appendix K	Construction and Demolition Material Management Plan (C&D MMP) for Secondary Drainage Channel KT13

LIST OF TABLES

Table 2.1	Evaluation of Alignment Options for Section of Bypass Channel
Table 2.2	Concurrent Projects
Table 2.3	Summary of Continuous Public Involvement
Table 2.4	Summary of the Comments and Recommendations received during the Public Consultation
Table 3.1	Environmental Issues Addressed in this EIA Report
Table 4.1	Habitat Types and Areas within the Study Area
Table 4.2	Habitat Types and Areas within the Project Area
Table 4.3a	Belt Transect Floral Survey Results (Upstream Section)
Table 4.3b	Belt Transect Floral Survey Results (Mid Section)
Table 4.4	Faunal Surveys of KT13 - Summary of Methodologies
Table 4.5a	Bird Species Recorded in the KT13 Study Area during the Present Study and in the HKBWS Breeding Bird Survey and Their Probable Status
Table 4.5b	Characteristic Habitat Utilization and Status of Bird Species Recorded from the Study Area
Table 4.6	Wetland Dependent Species Recorded in the Study Area
Table 4.7	Odonates Observed in the Study Area

CONTENTS (*cont'd*)

LIST OF TABLES (*cont'd*)

Table 4.8	Butterfly Species Observed in the Study Area
Table 4.9	Bird Species of Potential and Actual Conservation Concern with respect to their Use of the Study Area
Table 4.10	Number of Pairs of Breeding Egrets at Ho Pui during Summer 2000
Table 4.11	Number of Pairs of Breeding Egrets at Ma On Kong during Summer 2000
Table 4.12	Brood Size and Frequency at Ho Pui Egrettry during June 2000
Table 4.13	Brood Size and Frequency at Ma On Kong Egrettry during June 2000
Table 4.14	Number of Pairs of Breeding Egrets at Kam Tin during Summer 2000
Table 4.15	Summary of Brood Size in Hong Kong Egrettries during 1999
Table 4.16	Number of Pairs of Breeding Egrets at Ho Pui 2000 – 2005
Table 4.17	Number of Pairs of Breeding Egrets at Ma On Kong 2000 – 2005
Table 4.18	Number of Pairs of Breeding Egrets at Kam Tin Shui Mei 2000 – 2005
Table 4.19	Number of Pairs of Breeding Egrets at Tung Shing Lei (Au Tau) 2000 – 2005
Table 4.20	Total Number of Pairs of Breeding Egrets in the Kam Tin Area 2000 – 2005
Table 4.21	Details of Distances Flown by Egrets at Ho Pui and Ma On Kong Egrettries, Summer 2000
Table 4.22	Habitat Selection of Egrets at Ho Pui and Ma On Kong Egrettries, Summer 2000
Table 4.23	Ecological Evaluation of Woodlands
Table 4.24	Ecological Evaluation of Shrublands
Table 4.25	Ecological Evaluation of Marsh
Table 4.26	Ecological Evaluation of Fishponds
Table 4.27	Ecological Evaluation of Stream (KT13)
Table 4.28	Ecological Evaluation of Low-lying Grasslands/ Fallow Land
Table 4.29	Ecological Evaluation of Hillside Grasslands
Table 4.30	Ecological Evaluation of Agricultural Lands
Table 4.31	Ecological Evaluation of Orchard/ Horticultural Land
Table 4.32	Ecological Evaluation of Urban and Industrial Area (UIA)/Bare Ground/ Works in Progress
Table 4.33	Ecological Evaluation of Drainage Channel
Table 4.34	Direct habitat loss arising from construction of the Secondary Drainage Channel KT13
Table 4.35	Tree and bamboo species to be used in compensatory planting area

CONTENTS (*cont'd*)

LIST OF TABLES (*cont'd*)

Table 5.1	Technical Memorandum on EIA Process Daytime Construction Noise Standards
Table 5.2	Details of the Existing NSRs Close to KT13
Table 5.3	Predicted (Unmitigated) Construction Noise Levels
Table 5.4a	Predicted (Mitigated) Construction Noise Levels for Site Clearance
Table 5.4b	Predicted (Mitigated) Construction Noise Level for Excavation of Channel
Table 5.4c	Predicted (Mitigated) Construction Noise Level for Formwork Construction
Table 5.4d	Predicted (Mitigated) Construction Noise Level for Concreting Works
Table 5.5	Summary of Proposed Construction Noise Mitigation Measures
Table 6.1	Hong Kong Air Quality Objectives (AQOs)
Table 6.2	Representative Air Sensitive Receivers (ASRs)
Table 6.3	Air Pollutants Concentrations at Yuen Long EPD Station (2003)
Table 7.1	Field Observations at Existing Streams to be Modified under Ma On Kong
Table 7.2a	Summary of EPD Water Quality Data for Yuen Long Creek in 1998 to 2000
Table 7.2b	Summary of EPD Water Quality Data for Yuen Long Creek in 2001 to 2003
Table 7.3a	Summary of EPD Water Quality Data for Kam Tin River and Tin Shui Wai Nullah in 1998 to 2000
Table 7.3b	Summary of EPD Water Quality Data for Kam Tin River and Tin Shui Wai Nullah in 2001 to 2003
Table 7.4	Summary of Impacts from Construction Activities
Table 7.5	Summary of Mitigation measures for Construction Impacts
Table 7.6	Summary of Mitigation Measures for Minimising Operational Impacts
Table 8.1a	Breakdown of Surplus Material Types and Volumes Likely to Arise During Construction of KT13
Table 8.1b	Method and Programme of the Disposal of Construction and Demolition Materials (m ³)
Table 8.1c	Summary of Estimated Quantity of Construction and Demolition Materials (m ³) Arising from this Designated Project
Table 8.2	Construction Wastes Generated by the Proposed Works
Table 8.3	Potential for Recycling and Reuse and Disposal Options for Different Construction Waste Type
Table 8.4	Responsibilities for Waste Collection, Recycling and Disposal during the Construction Phase

CONTENTS (*cont'd*)

LIST OF TABLES (*cont'd*)

Table 9.1	Summary of the Archaeological Findings in Each Unit
Table 9.2	Distance and Orientation of the Cultural Heritage Features to the Proposed Development, Existing Land Use in the Area and Future Land Use Plans
Table 9.3	Mitigation Recommendations for the Cultural Heritage Resources in the Study Area
Table 10.1	Relationship between Receptor Sensitivity and Impact Magnitude in Defining Impact Significance
Table 10.2	Proposed Construction Phase Landscape Mitigation Measures
Table 10.3	Proposed Operation Phase Landscape Mitigation Measures
Table 10.4	Significance of Landscape Impacts in Construction and Operation Phases
Table 10.5	Significance of Visual Impacts in Construction and Operation Phases
Table 11.1	Summary of EM&A Requirements
Table 11.2	Framework for Environmental Monitoring Plan
Table 11.3	Air Quality Monitoring Stations
Table 11.4	Noise Monitoring Stations
Table 11.5	Water Quality Monitoring Stations
Table 11.6	Sediment Quality Monitoring Stations
Table 11.7	Cultural Heritage Resources Requiring Condition Survey during Construction Phase
Table 11.8	Ecological Resources Requiring EM&A Under this Project

LIST OF FIGURES

Figure 1.1	Locations of Drainage Improvement Works
Figure 2.1	KT13 and its Relation with Catchments in Northwest New Territories
Figure 2.2a	Ma On Kong Channel KT13 Proposed Layout Plan (Sheet 1 of 2)
Figure 2.2b	Ma On Kong Channel KT13 Proposed Layout Plan (Sheet 2 of 2)
Figure 2.3	Physical and Planning Constraints to the Possible Alignment of KT13
Figure 2.4	Typical Gabion Bank Construction for Trapezoidal Channel

CONTENTS (*cont'd*)

LIST OF FIGURES (*cont'd*)

- Figure 4.1 Habitat Map for KT13
- Figure 4.2 Sampling Locations and Significant Findings for Flora and Fauna Survey (KT13)
- Figure 4.3 Locations of Ecological Sensitive Receivers
[Figure 4.4 – 4.12 can be found within the main text]
- Figure 4.4 Number of Pairs of Egrets Breeding at Ho Pui during 1991-2000
- Figure 4.5 Number of Pairs of Egrets Breeding at Ma On Kong during 1995-2000
- Figure 4.6 Number of Chinese Pond Herons Breeding at Ho Pui, Ma On Kong and Kam Tin Shui Mei during 1991-2000
- Figure 4.7 Distance from Egretty and Number of Birds for Ho Pui and Ma On Kong, Summer 2000
- Figure 4.8 Flight Direction and Distance Flown from the Egretty
- Figure 4.9 Direction of Flight and Distance Traveled for Little Egret
- Figure 4.10 Direction of Flight and Distance Traveled for Cattle Egret
- Figure 4.11 Direction of Flight and Distance Traveled for Chinese Pond Heron (Ho Pui)
- Figure 4.12 Direction of Flight and Distance Traveled for Chinese Pond Heron (Ma On Kong)
- Figure 4.13 Proposed Mitigation Measures for Ecological Impact
-
- Figure 5.1 Location and Extent of Noise Study Area (300 m from Proposed Works)
- Figure 5.2 Locations of Representative Noise Sensitive Receivers
- Figure 5.3 Locations of Proposed Temporary Noise Barriers
-
- Figure 6.1 Locations of Representative Air Sensitive Receivers
- Figure 6.2 Wind Rose for Shek Kong Station
-
- Figure 7.1 Previous Water Quality Sediment Quantity Monitoring Locations used in Year 2000 Survey with respect to Current Proposed KT13 Alignment
- Figure 7.2 Typical Section of Sedimentation Area
- Figure 7.3 Schematic Design for Temporary Drainage Diversion
-
- Figure 8.1 Sediment Sampling Locations, Sediment Classification and Sediment Disposal Type for KT13
-
- Figure 9.1 Map of the Study Area (1:7000)
- Figure 9.2 Map of the Study Area Showing the Location of the Archaeological Units 1 to 3 with relationship to historical villages in close proximity and the Ho Pui Archaeological Site (1:7000)

CONTENTS (cont'd)

LIST OF FIGURES (cont'd)

- Figure 9.3 Map of the Study Area Showing Portions where Surface Field Scan was Possible and carried out, with relationships to historical villages in close proximity and the Ho Pui Archaeological Site (1:7000)
- Figure 9.4 Map Showing the location of the run KT13-02-01 and the two graves KT13-02-02 and KT13-02-03
- Figure 9.5 Map of Unit 1 Showing Location of Auger Holes 1-27 and Test Pits 1 and 2
- Figure 9.6 Map of Unit 2 Showing Locations of Auger Holes 28-54 and Test Pits 3 and 4
- Figure 9.7 Map Showing the Auger Hole Tests and Test Pit 5 and 6 Locations in Unit 3
- Figure 9.8 North Section of Test Pit Number 5
- Figure 9.9 North Section of Test Pit Number 6
- Figure 9.10 Map of Ho Pui Showing the Location of Each of the Historical Buildings and Structures
- Figure 9.11 Map of Tai Kek Showing the Location of Each of the Historical Buildings and Structures
- Figure 9.12 Map of Ma On Kong Showing the Location of Each of the Historical Buildings and Structures
- Figure 9.13 Map of the Area West of Ho Pui Showing the Location of Each of the Historical Buildings and Structures
- Figure 9.14 Map of the Area East of Ma On Kong Showing the Location of the Shrine Located there
- Figure 9.15a Location of All Cultural Heritage Features within the Study Area
- Figure 9.15b Location of All Cultural Heritage Features within the Study Area
- D-001 Ma On Kong Channel KT13 - Planning and Development Control Framework Review
- LR-001 Ma On Kong Channel KT13 - Landscape Resource Baseline
- PR-001 Ma On Kong Channel KT13 - Landscape Resource Photos (Sheet 1 of 2)
- PR-002 Ma On Kong Channel KT13 - Landscape Resource Photos (Sheet 2 of 2)
- LRI-001 Ma On Kong Channel KT13 - Residue Impact on Landscape Resource - Construction Phase
- LRI-002 Ma On Kong Channel KT13 - Residue Impact on Landscape Resource - Operation Phase (day 1)
- LRI-003 Ma On Kong Channel KT13 - Residue Impact on Landscape Resource - Operation Phase (10 Years)
- LC-001 Ma On Kong Channel KT13 - Landscape Character Baseline
- PC-001 Ma On Kong Channel KT13 - Landscape Character Photos (Sheet 1 of 2)
- PC-002 Ma On Kong Channel KT13 - Landscape Character Photos (Sheet 2 of 2)

CONTENTS (*cont'd*)

LIST OF FIGURES (*cont'd*)

LCI-001	Ma On Kong Channel KT13 - Residue Impact on Landscape Character - Construction Phase
LCI-002	Ma On Kong Channel KT13 - Residue Impact on Landscape Character - Operation Phase (day 1)
LCI-003	Ma On Kong Channel KT13 - Residue Impact on Landscape Character - Operation Phase (10 Years)
V-001	Ma On Kong Channel KT13 - VSRs baseline for Primary ZVI
V-002	Ma On Kong Channel KT13 - VSRs baseline for Secondary ZVI
PV-001	Ma On Kong Channel KT13 - VSRs Photos (Sheet 1 of 2)
PV-002	Ma On Kong Channel KT13 - VSRs Photos (Sheet 2 of 2)
VI-001	Ma On Kong Channel KT13 - Residue Visual Impact - Construction Phase
VI-002	Ma On Kong Channel KT13 - Residue Visual Impact - Operation Phase (day 1)
VI-003	Ma On Kong Channel KT13 - Residue Visual Impact - Operation Phase (10 Years)
LP-001	Ma On Kong Channel KT13 - Landscape Mitigation Plan (Sheet 1 of 2)
LP-002	Ma On Kong Channel KT13 - Landscape Mitigation Plan (Sheet 2 of 2)
PM-001	Ma On Kong Channel KT13 - Photomontages
PM-002	Ma On Kong Channel KT13 - Photomontages
PM-003	Ma On Kong Channel KT13 - Photomontages
PM-004	Ma On Kong Channel KT13 - Photomontages
Figure 11.1	Proposed Air Monitoring Locations and Representative Air Sensitive Receivers
Figure 11.2	Proposed Noise Monitoring Locations and Representative Noise Sensitive Receivers
Figure 11.3a	Locations of Water Quality and Sediment Quality Monitoring Stations
Figure 11.3b	Locations of Water Quality and Sediment Quality Monitoring Stations
Figure 11.4	Locations of Cultural Heritage Resources Monitoring
Figure 11.5	Ecology Monitoring Areas Recommended for Construction Phase and Operation Phase
Figure B1	Possible Alternative Alignments for the Bypass Culvert and Physical and Planning Constraints
Figure F1	Cross Section View of Construction Site and Proposed Noise Barriers
Figure K1	KT13 and its relation with catchments in Northwest New Territories
Figure K2a	Ma On Kong Channel KT13 Proposed Layout Plan (Sheet 1 of 2)
Figure K2b	Ma On Kong Channel KT13 Proposed Layout Plan (Sheet 2 of 2)

CONTENTS (cont'd)

LIST OF PLATES

- Plate 4.1 Woodland north of the Ho Pui Egrettry
Plate 4.2 Shrubland behind Ma On Kong
Plate 4.3 Marsh Showing Two of the Dominant Plants, *Colocasia esculenta*, and
Commelina nudiflora
Plate 4.4 An abandoned pond at the upstream section of the KT13
The water surface was covered with *Eichhornia crassipes*
Plate 4.5 A stream section, southwest of the Ho Pui Village
Plate 4.6 Grassland east of the Ho Pui Village
Plate 4.7 Hillside grassland behind Ma On Kong
Plate 4.8 Agricultural land east of Cheung Po Village
Plate 4.9 Orchard north of the Ho Pui Village
Plate 4.10 *Michelia elba* in Cheung Po
Plate 4.11 *Michelia figo* in Ma On Kong
Plate 4.12 *Rhododendron championae* in the Shrubland behind Ma On Kong
Plate 4.13 Dead Chinese Cobra *Naja atra* at KT13
Plate 4.14 Dead Musk Shrew *Suncus murinus* at KT13
Plate 4.15 Top: Cattle Egret standing on a pile of mud in the Ho Pui Egrettry
Bottom: The overview of the Ho Pui Egrettry
Plate 4.16 Ma On Kong Egrettry
Plate 4.17 A Breeding Chinese Pond Heron *Aideola bacchus* standing on a Fruit Tree
in the Egrettry
Plate 4.18 Le Seine River near Giverny, France
Rocks on Channel Margin for Protection against Erosion
Plate 4.19 Gabion Lined River Banks in Maryland, US
Plate 4.20 Gabion Lined Stream Bank and Bottom in Scidy, Italy
Plate 4.21 Channel Improvement with Gabions at Spadina Canal, Toronto, Canada
Scenes 1 to 3 show Establishment of Habitat in Progress
Plate 4.22 Gabion Channels in Mui Wo, Lantau Island
- Plate 9.1 Finds from Auger hole tests 14 (right) and 15 (left) in Unit 3
Plate 9.2 Test Pit 5, context 2
Plate 9.3 Test Pit 5, context 4 (left) and context 5 (right)
Plate 9.4 Test Pit 6, context 1
Plate 9.5 Test Pit 6, context 2
Plate 9.6 Test Pit 6, large vessel recorded in context 3
Plate 9.7 Test Pit 6, context 4
Plate 9.8 Test Pit 6, context 4. Sherd from within the large vessel

CONTENTS (*cont'd*)

LIST OF PLATES (*cont'd*)

Plate 9.9	Aerial View of the Study Area, 8.5.49 (Y 01904, sheet no.6)
Plate 9.10	Aerial View of the Study Area, 20.10.64 (Y 11598, sheet no.6)
Plate 9.11	Aerial View of the Study Area, 20.10.64 (Y 11599, sheet no.6)
Plate 9.12	Aerial View of the Study Area, 8.2.99 (CN 22574, sheet no.6)