Appendix K1: Preliminary Site Appraisal Checklist

(Based on Guidance Notes for Investigation Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards, and Car Repair/Dismantling Workshop)

Name of company: Shou Cheong Sawmill Ltd

Site address: No. 87-91, Ho Yeung Street, Pillar Point, Tuen Mun

Date: since around 1988 to present

Checklist for Site Appraisal:

1. What are your company's main current activities/operations in the above address?

   Loading and unloading of timber; sawing and cutting of timber; storage of timber

2. Area of your site?

   ~4,700 m^2

3. Length of operation?

   Since around 1988

4. Do you know the type of land use before you took over the site? (If yes, please give details.)

   Unoccupied land formed by sea reclamation

5. Have you ever received any notices of violation of environmental regulations or public complaints? (If yes, please give details.)

   No

6. Do you have regular check for any spillage and monitoring of chemicals handled? (If yes, please give details.)

   Not applicable

7. Did any tank/truck spillage or leakage happen in your site? Do you have any internal records about the type, duration and quantities? (If yes, please give details.)

   No

8. Do you have any registered hazardous installations as defined under relevant ordinances? (If yes, please give details.)

   No

9. Do you have any underground storage tank? (If yes, please give details.)

   No

10. Do you have any records of major renovation of your site or rearrangement of underground utilities, pipework/underground tanks? (If yes, please give details.)

    Not applicable

Appendix K2: Preliminary Site Appraisal Checklist

(Based on Guidance Notes for Investigation Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards, and Car Repair/Dismantling Workshop)

Name of company: Wai Sang Sawmill Ltd

Site address: No. 93-95, Ho Yeung Street, Pillar Point, Tuen Mun

Date: since around 1988 to present

Checklist for Site Appraisal:

1. What are your company's main current activities/operations in the above address?

   Loading and unloading of timber; sawing and cutting of timber; storage of timber

2. Area of your site?

   ~3,100 m^2

3. Length of operation?

   Since around 1988

4. Do you know the type of land use before you took over the site? (If yes, please give details.)

   Unoccupied land formed by sea reclamation

5. Have you ever received any notices of violation of environmental regulations or public complaints? (If yes, please give details.)

   No

6. Do you have regular check for any spillage and monitoring of chemicals handled? (If yes, please give details.)

   Not applicable

7. Did any tank/truck spillage or leakage happen in your site? Do you have any internal records about the type, duration and quantities? (If yes, please give details.)

   No

8. Do you have any registered hazardous installations as defined under relevant ordinances? (If yes, please give details.)

   No

9. Do you have any underground storage tank? (If yes, please give details.)

   No

10. Do you have any records of major renovation of your site or rearrangement of underground utilities, pipework/underground tanks? (If yes, please give details.)

    Not applicable