



New Territories

Kwun Tong Line Extension

Contract No. NEX/2207

Environmental Impact Assessment


(EIA) Study for KTE

Environmental Monitoring & Audit Manual

June 2010

Lantau Island

Hong Kong Island



Meinhardt Infrastructure and Environment Ltd
邁進基建環保工程顧問有限公司

MTR Corporation

Contract No. NEX/2207 Kwun Tong Line Extension Environmental Impact Assessment (EIA) Study for KTE

Environmental Monitoring & Audit Manual

Meinhardt Infrastructure and Environment Ltd

Document Rev: 0
Document Status: Final
Document Ref.: 91135/016




Prepared By:		Date:	14.6.2010
	(Various)		
Checked By:		Date:	14.6.2010
	(Tom Chapman)		
Approved By:		Date:	14.6.2010
	(Helen Cochrane)		

Table of Contents

	<u>Page</u>
<u>1. INTRODUCTION</u>	<u>1-1</u>
1.1 Project Description.....	1-1
1.2 Purpose of this EM&A Manual.....	1-2
1.3 Project Organisation.....	1-3
1.4 Structure of this EM&A Manual.....	1-5
<u>2. CULTURAL HERITAGE ASSESSMENT</u>	<u>2-1</u>
2.1 Introduction.....	2-1
2.2 Mitigation Measures.....	2-1
2.3 Audit Requirements.....	2-1
<u>3. LANDSCAPE AND VISUAL ASSESSMENT</u>	<u>3-1</u>
3.1 Introduction.....	3-1
3.2 Audit Requirements.....	3-1
3.3 Construction and Operational Phase Audit.....	3-1
3.4 Mitigation Measures.....	3-5
<u>4. AIR QUALITY</u>	<u>4-1</u>
4.1 Introduction.....	4-1
4.2 Monitoring Requirements.....	4-1
4.3 Mitigation Measures.....	4-9
<u>5. AIR-BORNE NOISE</u>	<u>5-1</u>
5.1 Introduction.....	5-1
5.2 Monitoring Requirements.....	5-1
5.3 Mitigation Measures.....	5-6
<u>6. GROUND-BORNE NOISE</u>	<u>6-1</u>
6.1 Introduction.....	6-1
6.2 Monitoring Requirements.....	6-1
6.3 Mitigation Measures.....	6-3
<u>7. WATER QUALITY</u>	<u>7-1</u>
7.1 Introduction.....	7-1
7.2 Monitoring Requirements.....	7-1
7.3 Mitigation Measures.....	7-1
7.4 Audit Requirements.....	7-1
<u>8. WASTE MANAGEMENT</u>	<u>8-1</u>
8.1 Introduction.....	8-1
8.2 Mitigation Measures.....	8-1
8.3 Audit Requirements.....	8-2
<u>9. HAZARD TO LIFE</u>	<u>9-1</u>
9.1 Introduction.....	9-1
9.2 Mitigation Measures.....	9-1

10.	ENVIRONMENTAL AUDIT	10-1
10.1	Site Inspection	10-1
10.2	Compliance with Statutory and Contractual Requirements	10-1
10.3	Environmental Complaints	10-2
11.	REPORTING	11-1
11.1	Introduction	11-1
11.2	Baseline Monitoring Report	11-1
11.3	Monthly EM&A Reports	11-2
11.4	Data Keeping	11-9
11.5	Real-Time Reporting	11-9
11.6	Interim Notification of Environmental Exceedances	11-9
12.	TERMINATION OF EM&A PROGRAMME	12-1

FIGURES

Figure 1.1	Project Organisation and Lines of Communication
Figure 4.1	Location of Dust Monitoring Stations (Sheet 1 of 4)
Figure 4.2	Location of Dust Monitoring Stations (Sheet 2 of 4)
Figure 4.3	Location of Dust Monitoring Stations (Sheet 3 of 4)
Figure 4.4	Location of Dust Monitoring Stations (Sheet 4 of 4)
Figure 5.1	Location of Air-borne Noise Monitoring Stations (Sheet 1 of 3)
Figure 5.2	Location of Air-borne Noise Monitoring Stations (Sheet 2 of 3)
Figure 5.3	Location of Air-borne Noise Monitoring Stations (Sheet 3 of 3)
Figure 6.1	Location of Ground-borne Noise Monitoring Stations (Sheet 1 of 4)
Figure 6.2	Location of Ground-borne Noise Monitoring Stations (Sheet 2 of 4)
Figure 6.3	Location of Ground-borne Noise Monitoring Stations (Sheet 3 of 4)
Figure 6.4	Location of Ground-borne Noise Monitoring Stations (Sheet 4 of 4)

APPENDICES

Appendix 1.1	Implementation Schedule for Environmental Mitigation Measures
Appendix 4.1	Template for Data Record Sheet for TSP Monitoring
Appendix 5.1	Template for Noise Monitoring Field Record Sheet
Appendix 10.1	Complaint Handling Procedure
Appendix 11.1	Template for Interim Notification of Environmental Quality Limits Exceedances